

TRANS-CAB AUTO SERVICES PTE LTD

N0.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5272M - AXA

AAD1801-127

Not Authored

11 Sep \$12,300

Vehicle No.:	SHC 5272M - CANDY
Chassis No.:	VF1ABL15AUC276718
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	10.01.2018
Third Party Insurer :	AXA

		PART		LIST
1	1	BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46 ✓
2	1	BUMPER LOWER REAR	\$	<i>Bu</i> 768.84 ✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47 ✓
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97 X
5	1	BUMEPR RETAINER RH REAR	\$	<i>Sn</i> 44.99 X
6	1	BUMPER REFLECTOR RH	\$	<i>CM</i> 43.61 ✓
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97 X
8	1	BUMEPR RETAINER LH REAR	\$	<i>Sn</i> 44.99 X
9	1	BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61 X
10	1	BUMPER BEAM REAR	\$	<i>Bu</i> 777.52 ✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95 X
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>Bu</i> 225.95 ✓
13	1	BOOT REAR	\$	<i>Bu</i> 2,872.68 ✓
14	1	BOOT FINISHER	\$	<i>Sn</i> 470.06 X
15	1	BOOT WHEATERSTRIP	\$	<i>161.5252</i> <i>11/1/18</i> 323.05 <i>50bin</i>
16	1	BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35 X
17	1	BOOT REFLECTOR LAMP RH	\$	<i>RU</i> 493.35 ✓
18	1	BOOT BADGE 'RENAULT'	\$	<i>RU</i> 225.36 ✓
19	1	BOOT BADGE	\$	<i>RU</i> 225.36 ✓
20	1	BOOT STRUT LH	\$	<i>Sn</i> 276.08
21	1	BOOT STRUT RH	\$	<i>Sn</i> 276.08
22	1	BOOT HINGE LH	\$	<i>R</i> 367.84
23	1	BOOT HINGE RH	\$	<i>R</i> 367.84
24	1	BOOT INNER TRIM	\$	<i>Sn</i> 586.45 } X
25	1	BOOT SWITCH	\$	<i>R</i> 168.13
26	1	BOOT LOCK	\$	<i>R</i> 202.67
27	1	BOOT LOCK CATCH	\$	<i>R</i> 74.40
28	2	LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52
29	2	BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81
30	1	FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13
31	1	FENDER PANEL INNER TRIM REAR RH	\$	<i>Sn</i> 671.45
32	1	FENDER PANEL REAR RH	\$	<i>Bu</i> 3,299.13 ✓
33	1	WHEELARCH REAR RH	\$	<i>Sn</i> 543.47 X
34	1	TAILLAMP RH	\$	<i>MSCM</i> 552.55 ✓

TRANS-CAB AUTO SERVICES PTE LTD

N0.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5272M - AXA

AAD1801-127

35	1	TAILLAMP PANEL RH	\$	<i>Pr</i>	986.70 ✓
36	1	TAILLAMP LH	\$	<i>Sn</i>	552.55 X
37	1	TAILLAMP PANEL LH	\$	<i>n</i>	986.70 ^
38	1	OUTER PANEL REAR (End Panel)	\$	<i>Pr</i>	1,471.77 ✓
39	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sn</i>	404.56 X
40	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>n</i>	2,189.88 X
41	1	SPARE WHEEL PANEL TRIM	\$	<i>Sn</i>	612.21 X
42	1	EXHAUST REAR	\$	<i>n</i>	7,489.05 X
43	1	EXHAUST CAP REAR	\$	<i>n</i>	230.49 X
TOTAL			\$		34,654.02
10%			\$		3,465.40
			\$		31,188.62

Special Nett

1	1SET	PARKING AID	\$	<i>Sea/shot</i>	700.00 ✓
2	1SET	REAR BUMPER CLIP	\$	<i>n</i>	66.00 ✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>n</i>	33.00 ✓
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	<i>n</i>	10.00 X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	<i>n</i>	20.00 X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	<i>n</i>	10.00 X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	<i>n</i>	20.00 X
8	1SET	BUMPER LOWER REAR RIVET	\$	<i>n</i>	22.00 X
9	1SET	BUMPER LOWER REAR CLIP	\$	<i>n</i>	66.00 ✓
10	1	EXHAUST MOUNTING REAR	\$	<i>Sn</i>	17.82 X
11	1SET	BOOT FINISHER CLIP	\$	<i>n</i>	24.20 X
12	1	BOOT STICKER "Trans-cab"	\$	<i>n</i>	30.00 ✓
13	1	BOOT STICKER "6555-3333"	\$	<i>n</i>	30.00 ✓
14	1	BOOT INNER TRIM CLIP	\$	<i>n</i>	45.00 X
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	<i>n</i>	35.00 X
16	1	FENDER INNER TRIM CLIP RH	\$	<i>n</i>	28.00 X
17	1	TAILLAMP CLIP RH	\$	<i>n</i>	5.00 X
18	1	TAILLAMP CLIP LH	\$	<i>n</i>	5.00 X
19	2	REAR WINDSCREEN SELANT	\$	<i>n</i>	80.00 <i>40sn</i>
20	1	WINDSCREEN MOULDING	\$	<i>n</i>	100.00 ✓
21	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>n</i>	100.00 <i>30sn</i>
22	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>Sn</i>	385.00 X
23	1	SPARE TYRE	\$	<i>Sn</i>	330.00 X
TOTAL			\$		2,162.02
TOTAL PARTS			\$		33,350.64

TRANS-CAB AUTO SERVICES PTE LTD

AAD1801-127

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5272M - AXA

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	8801
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	12001
To Rust-Proofing Of The Affected Areas.	\$	170.00	901
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	170.00	nn X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	nn X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	X } 1001
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	nn X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	nn X
Towing Fees	\$	120.00	nn X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	1201
To check steering geometry and computer wheel alignment	\$	220.00	nn X

LKK Auto Consultants hence notify the Repairer of the following:	\$	220.00	X
• To resurvey before/after spray painting	\$	11,160.00	
• To display damaged parts during resurvey	\$		
• Part sales subject to confirmation	\$	44,510.64	
• Third party survey is on a "Without Prejudice" basis			
• No illegal modification(s) is allowed			
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			

Over All Total \$ 44,510.64

(PARTS BY PARTS) Repair Days 15 Days

Acknowledged by Repairer
Signature: _____
Date: _____