

REF: Asm (AXA)

ASSIGNMENT

From: _____ Date: 18/01/2018

Estimated Cost: _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHC 7777K

at Workshop m/s Comfort Delgro

of 55 Luyang Drive

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Lany

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 7777K Yr Regn: 30 Jan 2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Santa 1991

Colour: Yellow A/C: Insured / Std / NI / NA

Sp. Reading: 68696 T/Radio: Insured / Std / NI / NA

Eng. No: _____

C/No: KM HET 41VM CA 831597

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In Good / Jammed / Leaked / Burnt or

Brake: In Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front

Rear

R/Bal: 2 mm R/Bal: 2 mm

L/Bal: 2 mm L/Bal: 2 mm

D.O.A. 12/1/8 D.O.I. 16/1/8

Survey held at: (OAE (Lany))

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

18/1/18 Check up to 3500 / 4 days.

43 - \$3500+ (Red: \$ 3058.94 / 47 %)

Date/Time: File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Survey Fee: _____

Date/Time: File Return to?

Transportation: _____

2)

Add Fee: ☐ : Site Insp (\$)

(\$ - \$ - \$)

☐ : Interview (\$)

Photos: _____

☐ : Tech. Insp (\$)

Others: _____

☐ : Weekend (\$)

Report Format: _____

Lump Sum / I.B.I: (\$)

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18000855/K1ub3		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 15-01-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GW 4410U	Veh. Inspected	SHC 7777K	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	15/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/01/2018	Inspection Date	16/01/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Team: ARC Repair TP(CFSO)1

JOB CARD Sales Order:

JC NO. 305106374

CUSTOMER
CITYCAB PTE LTD
VMS 7010070
CUSTOMER NO. 383 SIN MING DRIVE
ADDRESS Singapore SINGAPORE 575717
65551188
L. (R) (O)
(P)

REGN NO. SHC7777K	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL SONATA	DATE/TIME IN 12.01.2018 12:50
YR OF MANU. 30.01.2013	TARGET DATE
CHASSIS CODE KMHET41VMCA831597	COMPLETION DATE/TIME:

SCOUNT CARD NO.

JOB DESCRIPTION

Accident Date: 12.01.2018
NATURE: 3P 12.01.2018

S/L LABOR CODE DESCRIPTION
AXA - taxi Rear Damage

CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Signature:
No.: SHC7777K LARRY
Plate No.:

Larry Ng

Signature of Service Advisor

Signature/Date

Exit Pass

Vehicle No.: SHC7777K

Name of Service Advisor

Date

To be returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305106374
Date : 18.01.2018

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No : SHC7777K

Date of Accident: 12/01/18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: **AXA** **GW4410U**
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost**
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less:
Final Lumpsum Repair cost **\$3,500.00**

3. Estimated normal period for repairs: **4** working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature : 

Name : Larry Ng

Tel : 6214 8316

Fax : 6546 8156

Signature : 

Name : Kaly

Date : 18/1/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 7777K

MAKE :

MODEL : HYUNDAI SONATA

DATE 12/1/2018 16:06

DVA: 12.01.2018

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid			\$ 1,349.50
	Boot Lid Rubber			\$ 110.90
	Boot Lid Lock Upper			\$ 132.10
	Boot Lid Lock Lower			\$ 30.30
	Boot Lid Sonata Plate			\$ 43.60
	Boot Lid Hyundai Plate			\$ 24.20
	Boot Lid 'H' Emblem			\$ 26.10
	Boot Lid CRDI Plate			\$ 22.70
	Boot Lid Lamp (LH)			\$ 230.20
	Licence Lamp (LH/RH)		\$ 32.50	\$ 65.00
	Boot Lid Trimboard			\$ 165.40
	Boot Lid Trimboard Clips (10pcs)			\$ 10.00
	Rear Bumper			\$ 578.40
	Rear Bumper Reinforcement			\$ 483.30
	Rear Bumper Clip			\$ 22.00
	Rear Bumper Bracket		\$ 49.00	\$ 98.00
	Rear Bumper Sponge			\$ 137.40
	Rear Bumper Under Cover			\$ 185.80
	Rear Bumper Protector (LH/RH)		\$ 38.00	\$ 76.00
	Tail Lamp (LH/RH)		\$ 344.00	\$ 688.00
	Tail Lamp Quarter Panel (LH)			\$ 93.80
	Rear Panel			\$ 391.80
	Rear Panel Garnish			\$ 95.80
	SUB TOTAL			\$ 5,060.30
	LESS 20%			\$ 1,012.06
	DISCOUNTED TOTAL			\$ 4,048.24
	Boot Lid City Cab Logo & Tel No. Sticker			\$ 30.00
	Boot Lid Advertisement Logo			\$ 100.00
	Rear No. Plate			\$ 25.00
	Rear Bumper Reverse Sensor			\$ 135.70
	Rear Fender Advertisement Logo (LH/RH)			\$ 200.00
	Labour Charge			\$ 490.70
	Panel Beating- Repair Rear LH Fender			\$ 1,000.00
	Spray Painting Charge			\$ 800.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 2,020.00
	ESTIMATE TOTAL			\$ 6,558.94

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a surveyor appointed by the insurance company.

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 7777K

DATE 12/1/2018 16:06

MAKE :

RPA: 12-01-2018

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid ✓			\$ 1,349.50
	Boot Lid Rubber ✕			\$ 110.90
	Boot Lid Lock Upper ✕			\$ 132.10
	Boot Lid Lock Lower ✕			\$ 30.30
	Boot Lid Sonata Plate ✓			\$ 43.60
	Boot Lid Hyundai Plate ✓			\$ 24.20
	Boot Lid 'H' Emblem ✓			\$ 26.10
	Boot Lid CRDI Plate ✓			\$ 22.70
	Boot Lid Lamp (LH) ✓			\$ 230.20
	Licence Lamp (LH/RH) LH✓ RH✓	\$	32.50	\$ 65.00 ✕✓
	Boot Lid Trimboard ✕			\$ 165.40
	Boot Lid Trimboard Clips (10pcs) ✕			\$ 10.00
	Rear Bumper ✓			\$ 578.40
	Rear Bumper Reinforcement ✓			\$ 483.30
	Rear Bumper Clip ✓			\$ 22.00
	Rear Bumper Bracket ?	\$	49.00	\$ 98.00
	Rear Bumper Sponge ?			\$ 137.40
	Rear Bumper Under Cover ?			\$ 185.80
	Rear Bumper Protector (LH/RH) ✕ repair	\$	38.00	\$ 76.00
	Tail Lamp (LH/RH) LH✓ RH✓	\$	344.00	\$ 688.00 ✓✕
	Tail Lamp Quarter Panel (LH) ✕ repair			\$ 93.80
	Rear Panel ✕ repair			\$ 391.80
	Rear Panel Garnish ?			\$ 95.80
	SUB TOTAL			\$ 5,060.30
	LESS 20%			\$ 1,012.06
	DISCOUNTED TOTAL			\$ 4,048.24
	Boot Lid City Cab Logo & Tel No. Sticker ✓			\$ 30.00 Nett
	Boot Lid Advertisement Logo ✓			\$ 100.00 Nett
	Rear No. Plate ✓			\$ 25.00 Nett
	Rear Bumper Reverse Sensor ✓			\$ 135.70 Nett
	Rear Fender Advertisement Logo (LH/RH) ✓	\$	100.00	\$ 200.00 Nett
	Labour Charge			\$ 490.70
	Panel Beating- Repair Rear LH Fender			\$ 1,000.00
	Spray Painting Charge			\$ 800.00 720
	Wiring Charge			\$ 50.00 20
	Tuff Kote			\$ 50.00 20
	Remove/Refix Reverse Sensor			\$ 120.00 20
	TOTAL LABOUR			\$ 2,020.00
	ESTIMATE TOTAL			\$ 6,558.94
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Surveyor appointed by the insurance company.				

Larry Ng

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey to the repairer's satisfaction
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modifications shall be made
- Supplemental repairs must be resurveyed and is subject to approval from insurance Company

Acknowledged by Repairer

Signature:

Date: 16/1/18

16/1/18

16/1/18

16/1/18

16/1/18

16/1/18

16/1/18

16/1/18

16/1/18

16/1/18

16/1/18

16/1/18

16/1/18

16/1/18

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GW 4410U (Insd veh)	Model:	HYUNDAI
	SHC 7777K (TP veh)		SONATA NF 2.0 CRDI AT
Date of Accident:	12/01/2018		ABS 2WD 4DR TURBO

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	7,018.07
Final Repair Cost	:	\$	3,745.00
Loss of Token Sum	:	\$	300.00
Rental (if any)	:	\$	653.70
LTA / GIA Search Fee	:	\$	7.49

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum (GLOBAL SUM)	:	\$	4,700.00

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	COMFORTDELGRO ENGINEERING PTE LTD	:	\$ 4,700.00

NUR SHAQILAH BTE ABDOL
WAHAB

16/03/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



Service Request Details

Claim

S8M00752

Reference

None 

Loss Date

January 12, 2018

Request Date

January 29, 2018

Due Date

January 15, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Finish the work

Complete Work

More

Vehicle Information

Incident Vehicle Registration #

SHC7777K

Others

LKK AUTO CONSULTANTS PTE LTD (TP)

March 16, 2018

WORKSHOP INVOICE.pdf

Invoice

Repairer

LKK AUTO CONSULTANTS PTE LTD (TP)

March 16, 2018

DISCHARGE VOUCHER.pdf

Forms / Claim Documents

Satisfaction / Discharge Voucher

LKK AUTO CONSULTANTS PTE LTD (TP)

March 16, 2018

AUTHORISATION TO ACT.pdf

Forms / Claim Documents

POA / Authority Letter

LKK AUTO CONSULTANTS PTE LTD (TP)

March 16, 2018

LETTER TO OI.pdf

Letters and Correspondence

INSD GIA.PDF

Reports & Statement

GIA Report

LOH Cynthia

January 24, 2018

TP ESTIMATE- MARKED.pdf

Forms / Claim Documents

Estimate / Quotation

LKK AUTO CONSULTANTS PTE LTD (TP)

January 17, 2018

Preliminary Advice.pdf

Forms / Claim Documents

Estimate / Quotation

LKK AUTO CONSULTANTS PTE LTD (TP)

January 17, 2018

EMAIL.msg

Letters and Correspondence

Workshop

KADRI Mateen

January 15, 2018



Service Request Details

Claim

S8M00752

Reference

None 

Loss Date

January 12, 2018

Request Date

January 29, 2018

Due Date

January 15, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Finish the work

Complete Work

More

Vehicle Information

Incident Vehicle Registration #

SHC7777K

LOH Cynthia

1/15/18 3:19 PM

\$4,395.90

\$4,395.90

Open

Share

Clone



Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)[General Details](#)

Involving

TPVD HYUNDAI SONATA (SHC7777K)

Date of Loss

January 12, 2018

Time of Loss

10.00

Loss Description

GW4410U (INSD) HIT IN THE REAR OF SHC7777K (TP)

Comment

Workshop Details

Total Rebate Amount

Nett Loss Amount

\$0.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (TP)

Target Date of Completion *

mm/dd/yyyy

Days of work completion *



Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)[Vehicle & Driver Details](#)

Vehicle Registration#

SHC7777K

Registration State

Mileage

Purchase Date

mm/dd/yyyy

Registration Date *

mm/dd/yyyy

Age of Vehicle

4

Manufacturing Year

Make

TPVD HYUNDAI

Driver Details

Driver Name

LOW SWEE KHAI

Date of Birth

January 24, 1954

mm/dd/yyyy

Age

64

Occupation

Unknown

Education Qualification

Other

Primary ▼

Driving Experience

Female ▼

Marital status

Unknown

Single ▼

Identification #

S0101139A



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary
- Detailed Assessment

Inspection Date *

mm/dd/yyyy

Total Loss

Towing Charges

Voluntary Excess

Compulsory Excess

Young/Inexperienced/Unnamed Driver Excess

Other Excess

Condition of Vehicle at time of survey

General condition

Excellent ▼

Steering (Serviceable)



Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)[Tax Eligibility & Additional Deduction for Parts](#)

Depr./Bttr%

Discount%

Salvage%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts



1

1

BOOT LID

Damaged

1349.5

20

1079.6

Reviewing



Serviceable

0

20

0

Reviewing



4

1

BOOT LID LOCK LOWER

Serviceable

0

20

0

Necessary

24.2

20

19.36

Reviewing



7

1

BOOT LID 'H' EMBLEM

Necessary

26.1

20

BOOT LID LAMP (LH)

Cracked

230.2

20

184.16

Reviewing



10

1

LICENCE LAMP (LH/RH) (N/S)

Serviceable

-

12

1

BOOT LID TRIMBOARD

Serviceable

0

20

0

Reviewing



13

10

BOOT LID TRIMBOARD CLIPS



15

1

REAR BUMPER REINFORCEMENT

Cracked

483.3

20

386.64

Reviewing



16

10

-

Reviewing



18

1

REAR BUMPER SPONGE

Serviceable

0

20

0

Reviewing



20

0

Reviewing



21

1

TAIL LAMP (LH/RH) (N/S)

Cracked

344

20

275.2

Reviewing



repair

0

20

0

Reviewing



24

1

REAR PANEL

Repair

0

20

0

600

0

0

Reviewing



2

SPRAY PAINTING CHARGE.

720

0

0

Reviewing



3

0

0

Reviewing





Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

1

DAYS OF REPAIR

Reviewing

4



2

BOOT LID CITY CAB LOGO & TEL NO. STICKER

Reviewing

30

NECESSARY





6

REAR FENDER ADVERTISEMENT LOGO (LH/RH)

Reviewing

200

NECESSARY





Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio
Parts & Labour	Miscellaneous	Summary	Claim Amount \$4,395.90

Labour
\$1,380.00
\$1,380.00
Spare Parts
\$2,525.20
\$2,525.20
Miscellaneous
\$490.70
\$490.70

Submit for Review



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary
- Add
- Approve
- Deny



1

FINAL LUMP SUM

Reviewing

3500

