

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 200006262-D

Not Delivered
2/5 = 7000/-
6 day.

Estimate : 22-12-54

Date : 10.01.218

Vehicle Num : SJU7427C

Make/Model : TOYOTA Premio 1.5

Chassis/Engine no :

Accident Date : 09.01.2018

Claim No : 0118-20080

Reference :

Policy No :

Qty	Particular	Amount S\$
<u>List Item :</u>		
1 pc	Rear boot lid	1,079.50 ✓
1 pc	Rear boot lid inner lock	427.00 ✓
1 pc	Rear boot lid chrome moulding	325.00 ✓
1 pc	Rear boot lid logo	68.30 ✓
1 pc	Rear boot lid Premio emblem	72.40 ✓
1 pc	Rear boot lid Emblem	48.20 ✓
2 pc	Rear boot lid reflector @ 255.70	511.40 ✓
2 pc	Rear number plate lamp @ 75.20	150.40 x
1 pc	Rear boot lid inner board	222.70 x
2 pc	Rear boot lid hinge @ 79.10	158.20 x
1 pc	Rear boot rubber	307.10 ✓
2 pc	Rear tail lamp @ 357.40	714.80 ✓
2 pc	Rear tail lamp panel @ 285.10	570.20 ✓
2 pc	Rear fender @ 1492	2,984.00 a
2 pc	Rear fender inner trim @ 477.10	954.20 ✓
1 pc	Rear bumper 1250.10	1,840.00 ✓
2 pc	Rear bumper retainer @ 42.20	84.40 ✓
2 pc	Rear bumper bracket @ 75.10	150.20 ✓
1 pc	Rear end panel	433.50 ✓
1 pc	Rear end panel top garnish	305.00 ✓
1 pc	Rear spare tyre board panel	792.70 x
1 pc	Rear spare tyre panel cover board	545.00 ✓
1 pc	Rear spare tool tyre	318.00 x
2 pc	Rear spare tool corner tyre @ 204	408.00 x
1 pc	Rear exhaust silencer box	985.00 x
List item total :		\$
Discount 25 % :		\$

- 7846.3
+ 884.72

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 200006262-D

Estimate : 22-12-54

Date : 10.01.218

Vehicle Num : SJU7427C

Make/Model : TOYOTA Premio 1.5

Chassis/Engine no :

Accident Date : 09.01.2018

Claim No : 0118-20080

Qty	Particular	Amount S\$
<u>Special Nett Item :</u>		
1 pc	Rear number plate	\$ <i>Surf</i> 45.00 <i>40</i>
10 pc	Rear tail gate trim board clip @ 5.00	\$ <i>11</i> 50.00 <i>x</i>
1 pc	Rear tail gate windscreen sealant	\$ <i>11</i> 100.00 <i>x</i>
8 pc	Rear fender <i>inner trim</i> clip @ 5.00	\$ <i>ru</i> 40.00 ✓
10 pc	Rear bumper clip @ 5.00	\$ <i>ru</i> 50.00 ✓
1 set	Rear bumper reverse sensor	\$ <i>shh</i> 300.00 <i>200</i>
6 pc	Rear end panel garnish clip @ 5.00	\$ <i>11</i> 30.00 <i>x</i>
1 pc	Rear end panel sealant	\$ <i>ru</i> 80.00 <i>SD</i>
Special Nett Total :		\$ 695.00
<u>Labour charge :</u>		
	To check wiring	\$ 100.00 <i>30</i>
	Tuff kote	\$ 200.00 <i>60</i>
	Towing charge	\$ <i>11</i> 100.00 <i>x</i>
	Remove and refix rear windscreen	\$ <i>11</i> 160.00 <i>x</i>
	Remove and refix upholstery	\$ 160.00 <i>100</i>
	Remove and replace exhaust pipe	\$ <i>11</i> 160.00 <i>x</i>
	Remove and replace reverse sensor	\$ 150.00 <i>50</i>
	Transfer of tail gate mechanism	\$ 160.00 <i>60</i>
	To remove and replace spare part and panel beating	\$ 1,500.00 <i>1000</i>
	To spray paint affected portion	\$ 1,500.00 <i>120</i>
Labour charge total :		\$ 4,190.00

E & O . E

Total Amount : \$

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

KIM CHWEE AUTO PTE LTD