

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 18 Jan 2018

Preliminary Advice

Insured Vehicle No	: SKV1809G	Accident Date	: 18/12/2017
TP Vehicle No	: FBF2615H	Assignment Date	: 15/01/2018
Make	: YAMAHA T135	Est. Duration of Repair	: 5.00
Date of Inspection	: 16/01/2018		
Inspection At	: UNIQUE MOTORSPORTS PTE LTD (TANNERY LANE) 11 TANNERY LANE SINGAPORE 347774		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,094.00
Revised Amount	:S\$	1,488.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,488.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.