

1. 100

2. 100

3. 100 CS/MSG18000861/ 4/10/302

4. 100
Merimen

Marcus

5. 100 ASSIGNMENT 100100

6. 100 Fievel Foo

MSIG

15/01/2018 @ 11:38am

7. 100 Estimated Cost

8. 100 OD (1) WS/D RES. OD LES. EVA INV MV CS

9. 100 To Inspect Vehicle No

FBF 2615H

SKV 1809G

10. 100 at Workshop with

Unique Motorsports

62925578

11. 100 at 11 Tannery Lane, 34777 4

12. 100 Policy No

B28875686MCCY

13. 100 Claim No

541833

14. 100 Sum Insured

15. 100 Excess

16. 100 Make of Veh

(Client's Record)

16/01/2018

18/12/17

17. 100 CA / REV / REP / REV 24 HRS

18. 100 'wp'

19. 100 BCI Endorsement

20. 100 Date Time

12:12pm @ 15/1/18

21. 100 Name of Insured

Alvin

22. 100 Vehicle (1) OUT

23. 100 Date Time	24. 100 Action/Description	25. 100 EFT/Other
	FBF 2615H-NA/GAII7024502/24	D.O.A: 18/12/2017
	SKV 1809G-NA/GAII7024502/24	D.O.A: 15/12/2017

18/1/18 Send preli revised by merimen

MSIG

Date 16/01/2018

FBF2615H

4 11

Estimated Cost

CD RES TR RES CD RES EVA

FBF2615H

Unique Motorsports

11 turnery lane, 34777 4

Insured

Policy No

Class No

Sum Insured


Excess

Claims Record

Vehicle

Policy Condition

Remark: The veh had commenced its repair at the time of inspection.



Balance Market Value

3500

DAD Accident Report

Consistent? Yes or No

SW - PP Seen

Consistent? Yes or No

Est Repairs

5

days

Res: Yes or No

Est Sum

20

days

Res: Yes or No

CD RES

REP. 24 HRS

Wp

0027D

Under IN / OUT

Date

Person Contacted

20/4/2011

Date Time

Action Instruction

L1A8u

9/2/18 4/3 @ 1150 contact with Alvin. (Red 944, 457)

Vehicle Make / Model / Year / Bus / Van / Motor / Taxi / Private / Other

Truck / The engine

Make

Yamaha

1BR125

124

Colour

white

4000 cc Insured Std A / No

St Register

1831

7 Pass Insured Std A / No

Eng No

Chassis

L1BPK E 1281A0052715

Gen Cond Good / Fair / Poor / Burnt

Steering / Ins / Jammed / Leaked / Burnt or

Brakes / Ins / Jammed / Leaked / Burnt or

Mech / All / Std / STD A / Rm / or

Tyre Size

F

2.75-18

R

3.00-18

BS / DUN / EXNOVA / GY / FS / LIZA / MIO / OHTSU / P / SUM

TOYO / YOKO / or

Front

Rear

R Bal

6

R Bal

6

L Bal

L Bal

DCA

18/12/17

DCA

16/1/18

Survey report

Des of Damages Front / Rear / O/S / NS / U/O / Roof / or

Reor 1 125 25

The U/O / Chassis frame / Body Structure affected due to collision

One Time Fee /



Prelim Report

Final Report

One Time Fee /

Days Of Repair

5

Reserve, No. of Tols

1

Sum Fee

200

Insured

Insured

Insured

Insured

Insured


Insured

Insured

Insured

9/2- typist

Add Fee



Insured

Insured

Insured

Insured

Insured

Insured

Insured

menmen

LS \$1150/p

210

Survey Department Check List (Case Handler)

Reference No.: CS / MSG 18000 861 / Uvd3

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Min (): Case handler to make sure all Information created by the assignment team are ACCURATE.

Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

I) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)		Y-Date	N-Date	Y-Date	N-Date
C	Damaged Vehicle Photographs Uploaded	✓			

(3) Workshop Estimate/Assignment Form		Y-Date	N-Date	Y-Date	N-Date
N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)		Y-Date	N-Date	Y-Date	N-Date
C	Resurvey photo Uploaded	✓			

Check By: VERON 9/2/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18000861/Uvd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 15-01-2018	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKV 1809G	Veh. Inspected	FBF 2615H
Policy No.	B28875680MCY	Coverage (\$)	0.00
Claim No.	541833	Excess (\$)	0.00
Assign From	MERIMEN (FIEVEL FOO)	Assign Date	15/01/2018
2. Vehicle Particulars & Condition			
Make & Model	c.c 0		
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	Colour		
Odometer	-	Steering	
Brakes	Modification		
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	18/12/2017	Inspection Date	
Survey held at	11 TANNERY LANE		
Repairer	UNIQUE MOTORSPORTS		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Dec 2017		15 Jan 2018 11:38 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	CYCLE & CARRIAGE INDUSTRIES PTE LTD, ID: S7807645C			[Created by insurer]
Main Claimant:	CERTIS CISCO SECURITY PTE LTD, Co. Reg. No.: 200900882K			
Vehicle Reg. No.:	FBF2615H	Date of Loss:	18/12/2017 09:00 - :59	
Claim Type:	TP / 541833	Policy/Cover Note No.:	B28875680MCY (Comprehensive) Coverage: 01/01/2017 - 31/12/2017	
Vehicle Reg. No. (Insured):	SKV1809G	Policy No. (Claimant):		
		Excess:	S\$1,000.00	
Repairer:	Unique Motorsports Pte Ltd (Tannery Lane) 11 Tannery Lane, 347774 Macpherson - Tel: 62925578			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wen Yao - 6643 1316]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 16/01/2018]			
Driver/Custodian (Insured):	TAN CHEN LIANG (CHEN ZHENGLIANG) (), NRIC: S7807645C, Tel: +6594518806			
Adj Asg. Remarks:	request Marcus Chua for survey			

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#) [Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 18 Jan 2018

Preliminary Advice

Insured Vehicle No	: SKV1809G	Accident Date	: 18/12/2017
TP Vehicle No	: FBF2615H	Assignment Date	: 15/01/2018
Make	: YAMAHA T135	Est. Duration of Repair	: 5.00
Date of Inspection	: 16/01/2018		
Inspection At	: UNIQUE MOTORSPORTS PTE LTD (TANNERY LANE) 11 TANNERY LANE SINGAPORE 347774		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,094.00
Revised Amount	:S\$	1,488.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,488.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Statutory Board

Owner ID: 0027D

Vehicle Details

Vehicle No.: FBF2615H

Vehicle to be Exported: No

Intended De-registration Date: 22 Jan 2018

Vehicle Make: YAMAHA

Vehicle Model: YBR125

Primary Colour: White

Manufacturing Year: 2010

Engine No.: E3D6E004296

Chassis No.: LBPKE1281A0052715

Maximum Power Output: -

Open Market Value: \$1,129.00

Original Registration Date: 20 Apr 2011

First Registration Date: 20 Apr 2011

Transfer Count: 1

Actual ARF Paid: \$170.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 19 Apr 2021

COE Category: D - Motorcycle

COE Period(Years): 10

QP Paid: \$2,534.00

COE Rebate Amount: \$821.00

Total Rebate Amount: \$821.00

The information contained herein is correct as at 22 Jan 2018

OK

REG/CS/PAY/FA
15 JAN 2018

EA

15 JAN 2018



UNIQUE MOTORSPORTS PTE LTD

GST REG. NO.: 200907910H

11 Tannery Lane Singapore 347774 (Head Office)
 1007/1009 Serangoon Road Singapore 328168 (Show Room)
 1 Kaki Bukit Ave 6 #02-54/55 Autobay @ Kaki Bukit Singapore 417883
 48 Toh Guan Road East #02-140 Enterprise Hub Singapore 608586
 280 Woodlands Industrial Park E5 #01-43 Harvest Singapore 757322

Tel: 6292 5578 (3 lines) Fax: 6295 5579
 Tel: 6341 5378 / 6677 8999 Fax: 6341 7379
 Tel: 6844 6378 (3 lines) Fax: 6844 6379
 Tel: 6515 4978 (3 lines) Fax: 6515 4979
 Tel: 6339 2178 (3 lines) Fax: 6339 3379

Our Ref: ACCUM.TL.FBF2615H

Your Ref:

Please quote your reference number when replying

Date: 13/01/2018

MSIG Insurance Singapore Pte Ltd

4 Shenton Way, #21-01 SGX Centre 2

Singapore 068807

WITHOUT PREJUDICE

BY FAX & POST

Fax No: 62256371

Attention: Motor Claims Department

Dear Sirs,

ACCIDENT INVOLVING FBF2615H & SKV1809G OUTSIDE HILLBROOKS CONDOMINIUM ON 18TH
 DECEMBER 2017 AT ABOUT 0950 HOURS

1. We act for the owner of motor vehicle: **FBF2615H** in the above mentioned accident.
2. Pursuant to NIMA protocol, we hereby give you notice to conduct pre-repair inspection of our client's motorcycle at the under-stated workshop

UNIQUE MOTORSPORTS PTE LTD

11 Tannery Lane Singapore 347774

Tel: 62925578 (Ext 307) / Fax: 62955579

Email: alvin@uniquemotorsports.com.sg

Person-in-charge: Alvin Koh

3. **TAKE NOTICE** that you are required to respond to us **within 2 working days** (excluding Saturday, Sunday and Public Holiday) of receipt of this notice as to whether you wish to carry out or waive a pre-repair inspection. If we do not hear from you in this regard by the stipulated time, we shall construe your silence as waiver of the requirement for a pre-repair inspection and proceed to repair our client's motor bike.

Yours faithfully

UNIQUE MOTORSPORTS PTE LTD

Name of Surveyor & Signature

Date: _____

Time: _____

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/12/2017 15:29
Date Of Accident	18/12/2017 09:50
Exact Location Of Accident	OUTSIDE HILLBROOKS CONDOMINIUM
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBF2615H
Insured/Policyholder	
Name Of Registered Owner	CERTIS CISCO SECURITY PTE LTD
Co Reg No	200900882K
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81882199
Alternative Phone No	OFFICE-81882199

Vehicle Particulars

Manufacturer	YAMAHA
Model	-
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MOMVM000001676-00-000
Cover Note Number	

Driver

Name of Driver	ANAND RAJ SHANMUGAM
Passport No/FIN	G2622885P
Date Of Birth	08/10/1988
Occupation	OUTDOOR
Date Of Driving Pass	05/10/2017
Driving Experience	0 YEAR AND 2 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-86785116
Fax Number	
Contact Number	OFFICE-86785116
EMail Address	NOEMAIL

No. Of Passenger (Including Driver) 1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SHA2853S

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category TAXI

Name of Driver CHUA AH TEE

NRIC/Passport Number

Contact Number 91468529

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver) 1

Accident Sketch Plan

SKETCH PLAN

SKETCH PLAN

A: PSE 1015H
B: PSE 10095
C: PSE 1015B

HATCH AREA

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report - T/2017018/2071

DECLARATION

DECLARATION
I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

REMARKS:

NRIC/FIN No.:

Police Report



**SINGAPORE
POLICE FORCE**



T/20171218/2071

2 of 4

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
650040
Tel No: 1800-6659999

Report No. T/20171218/2071

CONTINUATION OF REPORT

Rider			
Name	ANAND RAJ SHANMUGAM		ID No. G2822885P
Related Vehicle	FBF2815H (Motorcycle)		Contact No. 86785116
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	CHUA AH TEE		ID No. NIL
Related Vehicle	SHA2853S (Car)		Contact No. 91468528
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	TAN CHEN LIANG		ID No. 97807848C
Related Vehicle	SKV1809G (Car)		Contact No. 94518806
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 18/12/17 at about 0945hrs, I was travelling along Hillview Ave when V2) SHA2853S, was making a turn into Hillbrokes Condominium at a slow speed. I stopped directly behind V2 and was about to change lane. Subsequently, V3) SKV1809G, banged into my motorcycle, V1) FBF2815H, causing me to fall to the left side. I felt pain on my right knee, thigh and hip. V3's front bumper was dented and broke, its number plate came off and the bonnet had scratches.

Due to the collision, V1 had some damages. The clutch lever broke, brake light was damaged, the number plate and storage box came off and the front side of V1 near the wheels had scratches too. Due to the collision between V1 and V3, V1 bumped into V2, causing V2's right rear bumper to be scratched. This is the first time such incident happen to me.

Police Report



**SINGAPORE
POLICE FORCE**



T/20171218/2071

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659640
Tel No: 1800-6659999

4 of 4

Report No. T/20171218/2071

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J/
AHMAD ZAKI ZUHAIRI BIN AYUB

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

18/12/2017 13:10

Officer In Charge Of Case:

TP / AEIT /
Sr Staff Sgt LEE SOON LYE
Contact No.: 65476289

Classification Of Case:

Authentication Stamp

NP188

Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo





Tel: 6339 2178 (3 lines) Fax: 6339 3379

c/s 8/150

S/N	Description	Condition	Qty	Unit Price	Total Price
1	FRONT COWLING	BROKEN	1	\$79.00	\$79.00
2	WINDSCREEN	BROKEN	1	\$42.00	\$42.00
3	HEADLAMP	GRAZED	1	\$86.00	\$86.00
4	HEADLAMP STAY	WARPPED	1	\$64.00	\$64.00
5	HANDLEBAR	WARPPED	1	\$79.00	\$79.00
6	STEERING CONE – UPPER	NECESSARY	1	\$42.00	\$42.00
7	STEERING CONE – LOWER	NECESSARY	1	\$43.00	\$43.00
8	FORK OIL SEAL	NECESSARY	2	\$24.00	\$48.00
9	FORK DUST COVER	NECESSARY	2	\$26.00	\$52.00
10	FORK OIL (15WT)	NECESSARY	1	\$33.00	\$33.00
11	MIRROR – L/H	GRAZED	1	\$40.00	\$40.00
12	FRONT SIGNAL – L/H	GRAZED	1	\$42.00	\$42.00
13	CLUTCH LEVER	BROKEN	1	\$31.00	\$31.00
14	HANDGRIP – L/H	GRAZED	1	\$20.00	\$20.00
15	FRONT NUMBER PLATE	NECESSARY	1	\$15.00	\$15.00
16	FOOTREST RUBBER – L/H	GRAZED	1	\$20.00	\$20.00
17	FOOTSTEP BAR	WARPPED	1	\$72.00	\$72.00
18	REAR FOOTREST BRACKET – L/H	DENTED	1	\$60.00	\$60.00
19	REAR MUDGUARD	BROKEN	1	\$116.00	\$116.00
20	REAR NUMBER PLATE	NECESSARY	1	\$15.00	\$15.00
21	REAR SIGNAL – L/H	GRAZED	1	\$39.00	\$39.00
22	BRAKELIGHT COVER	GRAZED	1	\$49.00	\$49.00
23	REAR BOX	GRAZED	1	\$192.00	\$192.00
24	FORK ALIGNMENT	NECESSARY	1	\$120.00	\$120.00
25	FRAME ALIGNMENT	NECESSARY	1	\$260.00	\$260.00
26	RESPRAY FRONT COWLING	NECESSARY	1	\$60.00	\$60.00
27	RESPRAY FRONT FENDER	NECESSARY	1	\$60.00	\$60.00
28	PERFORM ELECTRICAL CHECK	NECESSARY	1	\$20.00	\$20.00
29	TOWING FROM ACCIDENT SCENE TO WORKSHOP	NECESSARY	1	\$35.00	\$35.00
30	LABOUR TO REPLACE PARTS DUE TO ACCIDENT	NECESSARY	1	\$260.00	\$260.00

Acknowledged by Repairer

Page 1

p. 715

643-50

14 ft. W

1190

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Dec 2017		15 Jan 2018 11:38 Edit Adj Rpt	S\$1,150.00 Edit Estimates	S\$1,150.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by Insurer]

Insured:	CYCLE & CARRIAGE INDUSTRIES PTE LTD, ID: S7807645C		
Main Claimant:	CERTIS CISCO SECURITY PTE LTD, Co. Reg. No.: 200900882K		
Vehicle Reg. No.:	FBF2615H	Date of Loss:	18/12/2017 09:00 - :59
Claim Type:	TP / 541833	Policy/Cover Note No.:	B28875680MCY (Comprehensive) Coverage: 01/01/2017 - 31/12/2017
Vehicle Reg. No. (Insured):	SKV1809G	Policy No. (Claimant):	
		Excess:	S\$1,000.00
Repairer:	Unique Motorsports Pte Ltd (Tannery Lane) 11 Tannery Lane, 347774 Macpherson - Tel: 62925578		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 14/02/2018]		
Driver/Custodian (Insured):	TAN CHEN LIANG (CHEN ZHENGLIANG) (), NRIC: S7807645C, Tel: +6594518806		
Adj Asg. Remarks:	request Marcus Chua for survey		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBF2615H (541833)**
[SKV1809G]
TP
CERTIS CISCO SECURITY PTE LTD
Dec 18 2017 9:00AM
[CYCLE & CARRIAGE INDUSTRIES PTE LTD]
Unique Motorsports Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#)

Assessment Reports				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	15/01/18 11:33	Accident Statement From: OD - Reg. No: SKV1809G, Claimant: CYCLE & CARRIAGE INDUSTRIES PTE LTD	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	18/01/18 15:16	Adjuster Immediate Advice	1	Load HTM	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	16/01/18 19:14	Chassis Number	1	Load JPG	☒
2	16/01/18 19:14	Odometer Reading	1	Load JPG	☒
3	16/01/18 19:14	General View	1	Load JPG	☒
4	16/01/18 19:14	General View	1	Load JPG	☒
5	16/01/18 19:14	General View	1	Load JPG	☒
6	16/01/18 19:14	General View	1	Load JPG	☒
7	16/01/18 19:14	General View	1	Load JPG	☒
8	16/01/18 19:14	General View	1	Load JPG	☒
9	16/01/18 19:14	General View	1	Load JPG	☒
10	16/01/18 19:14	General View	1	Load JPG	☒
11	16/01/18 19:14	General View	1	Load JPG	☒
12	16/01/18 19:14	General View	1	Load JPG	☒
13	16/01/18 19:14	General View	1	Load JPG	☒
14	16/01/18 19:14	General View	1	Load JPG	☒
15	16/01/18 19:14	General View	1	Load JPG	☒
16	16/01/18 19:14	General View	1	Load JPG	☒
17	16/01/18 19:14	General View	1	Load JPG	☒
18	16/01/18 19:14	General View	1	Load JPG	☒
19	16/01/18 19:14	General View	1	Load JPG	☒
20	16/01/18 19:14	General View	1	Load JPG	☒
21	16/01/18 19:14	General View	1	Load JPG	☒
22	16/01/18 19:14	General View	1	Load JPG	☒
23	16/01/18 19:14	General View	1	Load JPG	☒
24	16/01/18 19:14	General View	1	Load JPG	☒
25	16/01/18 19:14	General View	1	Load JPG	☒
26	16/01/18 19:14	General View	1	Load JPG	☒
27	16/01/18 19:14	General View	1	Load JPG	☒
28	16/01/18 19:14	General View	1	Load JPG	☒
29	16/01/18 19:14	General View	1	Load JPG	☒
30	16/01/18 19:14	General View	1	Load JPG	☒

					☒
31	16/01/18 19:14	General View	1	Load JPG	☒
32	16/01/18 19:14	General View	1	Load JPG	☒
33	16/01/18 19:14	General View	1	Load JPG	☒
34	16/01/18 19:14	General View	1	Load JPG	☒
35	16/01/18 19:14	General View	1	Load JPG	☒
36	16/01/18 19:14	General View	1	Load JPG	☒
37	16/01/18 19:14	General View	1	Load JPG	☒
38	16/01/18 19:14	General View	1	Load JPG	☒
39	16/01/18 19:14	General View	1	Load JPG	☒
40	16/01/18 19:14	General View	1	Load JPG	☒
41	16/01/18 19:14	General View	1	Load JPG	☒
42	16/01/18 19:14	General View	1	Load JPG	☒
43	16/01/18 19:14	General View	1	Load JPG	☒
44	16/01/18 19:15	General View	1	Load JPG	☒
45	16/01/18 19:15	General View	1	Load JPG	☒
46	16/01/18 19:15	General View	1	Load JPG	☒
47	16/01/18 19:15	General View	1	Load JPG	☒
48	16/01/18 19:15	General View	1	Load JPG	☒
49	16/01/18 19:15	General View	1	Load JPG	☒
50	16/01/18 19:15	General View	1	Load JPG	☒
51	16/01/18 19:15	General View	1	Load JPG	☒
52	16/01/18 19:15	General View	1	Load JPG	☒
53	16/01/18 19:15	General View	1	Load JPG	☒
54	16/01/18 19:15	General View	1	Load JPG	☒
55	16/01/18 19:15	General View	1	Load JPG	☒
56	16/01/18 19:15	General View	1	Load JPG	☒
57	16/01/18 19:15	General View	1	Load JPG	☒
58	16/01/18 19:15	General View	1	Load JPG	☒
59	16/01/18 19:15	General View	1	Load JPG	☒
60	16/01/18 19:15	General View	1	Load JPG	☒
61	16/01/18 19:15	General View	1	Load JPG	☒
62	16/01/18 19:15	General View	1	Load JPG	☒
63	16/01/18 19:15	General View	1	Load JPG	☒
64	16/01/18 19:15	General View	1	Load JPG	☒
65	16/01/18 19:15	General View	1	Load JPG	☒
66	16/01/18 19:15	General View	1	Load JPG	☒
67	16/01/18 19:15	General View	1	Load JPG	☒
68	16/01/18 19:15	General View	1	Load JPG	☒
69	16/01/18 19:15	General View	1	Load JPG	☒
70	16/01/18 19:15	General View	1	Load JPG	☒
71	16/01/18 19:15	General View	1	Load JPG	☒
72	16/01/18 19:15	General View	1	Load JPG	☒
73	16/01/18 19:15	General View	1	Load JPG	☒
74	16/01/18 19:15	General View	1	Load JPG	☒
75	16/01/18 19:15	General View	1	Load JPG	☒
76	16/01/18 19:15	General View	1	Load JPG	☒
77	16/01/18 19:15	General View	1	Load JPG	☒
78	16/01/18 19:15	General View	1	Load JPG	☒
79	16/01/18 19:15	General View	1	Load JPG	☒

80	16/01/18 19:15	General View	1	Load JPG	☒
81	16/01/18 19:15	General View	1	Load JPG	☒
82	09/02/18 09:33	Reinspection Photo	1	Load JPG	☒
83	09/02/18 09:33	Reinspection Photo	1	Load JPG	☒
84	09/02/18 09:33	Reinspection Photo	1	Load JPG	☒
85	09/02/18 09:33	Reinspection Photo	1	Load JPG	☒
Documentation					
				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	15/01/18 11:38	FBF2615H E-file & Police Report	1	Load PDF	
2	15/01/18 11:38	PRI from Unique Motorsports	1	Load PDF	
3	15/01/18 11:38	Survey Agree on SJE - LKK	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18000861/UVD3E2

Date: 13/02/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B28875680MCY

Claimant Vehicle No : FBF2615H

Insured Vehicle No : SKV1809G

Date of Loss: 18/12/2017

Nature of Claim: TP

Claim No: 541833

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBF2615H

Make & Model: YAMAHA T135, 135cc

Engine No: E3D6E004296

Reg. Date: 20/04/2011 (Man. Year: 2010)

Chassis No: LBPKE1281A0052715

Colour: Black

Odometer: 1831 km

Engine Capacity: 124 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 2.75-18

Rear Tyre Size: 3.00-18

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,399.00	843.50	555.50	39.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	695.00	645.00	50.00	7.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,094.00	1,488.50	605.50	28.92
Approved Total (Overridden) (S\$)		1,150.00		
(S\$)	2,094.00	1,150.00	944.00	45.08
+ GST 7.00/7.00% (S\$)	146.58	80.50	66.08	45.08
Nett Amount (S\$)	2,240.58	1,230.50	1,010.08	45.08

INSPECTION

Date of Assignment: 15/01/2018

Date Inspected: 16/01/2018 Inspected At:

Unique Motorsports Pte Ltd (Tannery Lane)
11 Tannery Lane
Singapore 347774

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 13 Feb 2018)
Parts: N/A YAMAHA T135 135cc (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for FBF2615H)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT COWLING	Cracked	79.00 F	*79.00 FL
2	1		*WINDSCREEN	Cracked	42.00 F	*42.00 FL
3	1		*HEADLAMP	Cracked	86.00 F	*86.00 FL
4	1		*HEADLAMP STAY	Not Necessary	64.00 F	*- FL
5	1		*HANDLE BAR	Bent	79.00 F	*79.00 FL
6	1		*STEERING CONE - UPPER	Not Necessary	42.00 F	*- FL
7	1		*STEERING CONE - LOWER	Not Necessary	43.00 F	*- FL
8	2		*FORK OIL SEAL	Not Necessary	48.00 F	*- FL
9	2		*FORK DUST COVER	Not Necessary	52.00 F	*- FL
10	1		*FORK OIL (15WT)	Not Necessary	33.00 F	*- FL
11	1		*MIRROR - L/H	Cut	40.00 F	*40.00 FL
12	1		*FRONT SIGNAL - L/H	Cracked	42.00 F	*42.00 FL
13	1		*CLUTCH LEVER	Cut	31.00 F	*31.00 FL
14	1		*HANDGRIP - L/H	Torn	20.00 F	*20.00 FL
15	1		*FRONT NUMBER PLATE	Necessary	15.00 FS	*10.00 FS
16	1		*FOOTREST RUBBER - L/H	Torn	20.00 F	*20.00 FL
17	1		*FOOTSTEP BAR	Bent	72.00 F	*72.00 FL
18	1		*REAR FOOTREST BRACKET - L/H	Serviceable	60.00 F	*- FL
19	1		*REAR MUDGUARD	Broken	116.00 F	*116.00 FL
20	1		*REAR NUMBER PLATE	Bent	15.00 FS	*10.00 FS
21	1		*REAR SIGNAL - L/H	Cracked	39.00 F	*39.00 FL
22	1		*BRAKELIGHT COVER	Cracked	49.00 F	*49.00 FL
23	1		*REAR BOX	Cracked	192.00 FS	*180.00 FS
24	1		*FORK ALIGNMENT	Not Necessary	120.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,399.00	915.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	71.50
Total Parts (S\$)	1,399.00	843.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	FRAME ALIGNMENT	New	260.00	240.00
2	RESPRAY FRONT COWLING	New	60.00	60.00
3	RESPRAY FRONT FENDER	New	60.00	60.00
4	PERFORM ELECTRICAL CHECK	New	20.00	0.00
5	TOWING FROM ACCIDENT SCENE TO WORKSHOP	New	35.00	35.00
6	LABOUR TO REPLACE PARTS DUE TO ACCIDENT	New	260.00	250.00
Gross Labour Cost (\$\$)			695.00	645.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >