



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6096Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR N/S WHEEL COVER (CONSISTENT)	TO REPAIR SEE LABOUR	116.00	-
	LESS 10% DISCOUNT		-11.60	-
			104.40	-
	<u>SPECIAL NETT ITEMS</u>			
1	REAR N/S FENDER STICKER (SN) (CONSISTENT)	NECESSARY	60.00	60.00
1	SET N/S DOOR STICKER (SN) (CONSISTENT)	NECESSARY	100.00	100.00
1	SUNDRY (SN) (CONSISTENT)	NECESSARY	50.00	20.00
			210.00	180.00
	<u>LABOUR</u>			
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET,ETC TO FACILITATE REPAIRS .	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF THE FRONT N/S DOOR ,REAR N/S DOOR ,REAR N/S FENDER ,REAR BUMPER .INCLUSIVE OF THE REPAIR OF REAR N/S WHEEL COVER .		650.00	400.00
	TO PUTTY AND SPRAY PAINTING ON THE FRONT N/S DOOR ,REAR N/S DOOR ,REAR N/S FENDER ,REAR BUMPER .		800.00	770.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	200.00	-
			1,910.00	1,170.00
	GRAND TOTAL		2,224.40	1,350.00
RECOMMENDED COST OF REPAIRS				1,350.00

Report Ref No. CC4/ASM18000863/K1ps3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.