

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

11-Jan-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6096 Z

1 pc	Rear n/s wheel cover	<i>X repair</i>	\$ 116.00
			\$ 116.00
		Less 10%	\$ 11.60
			\$ 104.40

### S/NETT

1 pc	Rear n/s fender sticker	<i>✓ nec</i>	\$ 60.00
1 set	n/s door sticker	<i>✓ nec</i>	\$ 100.00

Sundry

\$ ~~50.00~~ *20*

To check wheel alignment

\$ ~~80.00~~ *X*

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

\$ ~~180.00~~ *X*

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front n/s door, rear n/s door, rear n/s fender, rear bumper

\$ ~~650.00~~ *400*

To putty and spray painting on the front n/s door, rear n/s door, rear n/s fender, rear bumper

\$ ~~800.00~~ *770*

To apply rustproofing on the repaired and replaced panels.

\$ ~~200.00~~ *X*

\$ 2,224.40

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE  
ANY UNFORESEEN DAMAGES.

*Kalvin LKK*  
*16/1/18 136 hr.*  
*3 Pairs*  
*4/5*  
*After Repair photo*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: