

LKK:
IDAC

12/01/18

570118

Pre-assign / CCU / FTE



SPJ 9956

CHUA SENG CHYE

HP: 9851 0063

D.O.A: 11/04/13

(YES / NO)

Nature of Accident :

If **NO**, Driver Name / Age :

(V/L: ~~YES~~ / NO)

97236725154

: 17000335241

mitsubishi outlander - 2.4 CVT (A)

TANTONG RHU FLYOVER

TP YES / NO : TP GIA REPORT: YES / NO

%	Final ?	Yes / No
100		
90		
80		
70		
60		
50		
40		
30		
20		
10		
0		

SFJ 99556

SHC 4230R

SFZ 9155T

SGH 6264R



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP: SNPT (wood glue)

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS.

WSP:

Tel :

Liability:

RMKS

Date/ Time	STAGE	DATE / PIC
17/01/18 (Jes)	SHC 4230R - CS/FIT100/1777/R141 DOA 21/02/18 SET 99552 - X	
	Discussed with Mr Yew. Although there is video. Chain collision is still apply as the laps of time is <u>vs</u> 1 second only.	
17/01/18 @ 2:45	4 veh chain collision. Spoken Spoken with OI, confirmed the accident & since NCD will be penalise.	
6/3/18 @ 10:30	File pass to typist to prepare report.	
	RECEIVED 16 MAR 2018	
RECEIVED 10 MAY 2018		
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI: 2/17/18	Sent via email
	After call ltr to OI:	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA :	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	

PRELIMINARY ADVICE		Date/Time:	Sent By:	Post-Repair Photos:	☐	☐
				Others:	☐	☐
FINALIZATION		Date/Time:	Confirm with:	Confirm by:	Email ☐	Call ☐
Repair Cost:	\$S 7,350.00	10 days)	Reduction: %		Email ☐	Call ☐
FINAL SETTLEMENT		Date/Time: 30/4/18	Confirm with Lee 926		Email ☐	Call ☐
Final Liability:	% 100	(Agreed / Assessed)	BOLA S/N No. : 28		If NO or B 28, Ass. Lia : 100-1.	
Repair Cost:	\$S 7,350.00					
Loss of Rental (LOR):	\$S 1872.50	14 days)				
Loss of Use (LOU):	\$S (S x days)					
Loss of Income (LOI):	\$S (S x days)					
LOR only ☐	LOU only ☐	LOR + LOU ☐	LOR + LOU ☐	[Tick only one]		
GIA/LTA Search	\$S 7.00					
Medical:	\$S				1) Claim status: Normal/Reject/Private Settle	
Disbursement:	\$S	(e.g. Tow/ Independent)			2) Report Format: TP	
Legal Cost	\$S				3) Survey fee: 8320 + 820	
Total:	\$S 9229.50	Global Sum \$S:			Email ☐	Call ☐
FINAL PAYMENT		Date/Time:	Confirm with:		Email ☐	Call ☐
Payee 1:	\$S 9229.50	Name 1:	SMART TAXIS PTE LTD			
Payee 2: (Strike if N.A.)	\$S	Name 2:				
Payee 3: (Strike if N.A.)	\$S	Name 3:				

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s:

of

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

10 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHC4230R.

Yr Regn:

2013 Nov

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

o.c

1298

Colour:

Maroon

A/C:

Insured / Std / NI / NA

Sp.Reading:

—

T/Radio:

Insured / Std / NI / NA

Eng/No:

O/No:

STDKN364505704820

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

Insider / Jammed / Leaked / Burnt or

Brake:

Insider / Jammed / Leaked / Burnt or

Modi:

Nil / Slim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

—

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken.

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

11/1/18

D.O.I.

12/1/18

Survey held at

SMRT WL

Des. of Damages

FA / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Battery weak
	ALG TP SFJ9955 L.
	TAX / 01 / 18 / 2059.
	45 \$ 7,350.00
	= (10% \$ 8809.65 / 54.52%)

Date/Time File Pass to?

☐ : Preli. Report
 ☐ : Final Report

1)

Date/Time File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐ : Site Insp (\$)
 ☐ : Interview (\$)
 ☐ : Tech. Invs (\$)
 ☐ : Weekend (\$)

PHOTO

OTHERS

TOTAL




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18000865/T1ys3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 15-01-2018		
Code : AIG				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SFJ 9955L	Veh. Inspected	SHC 4230R	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	15/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	11/01/2018	Inspection Date	12/01/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



23-1-18 / 13:55

FAX Number : 63685592

24-1-18 / 08:55

Estimator Telephone Number : 68662623


Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

15-1-18 / 08:55

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4230R
 Ref. No : TAX/01/18/2059
 Reg. Date : 22/11/2013
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : CHIA CHAN KONG
 Type of Accident : CHAIN COLLISION
 Date / Time of Accident : 11/01/2018 07:25:00 AM
 Accident Reported Date / Time : 11/01/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Taufikh
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094040
 Special Instruction to ARC, if any :
 SFJ9955L - AIG - LKK
 Before paint photo and after paint photo, FOR CHECK ITEM and REPLACE ITEM. PLEASE CALL SURVEYOR
 TAUFIKH, HP 9749 5749/ EMAIL: taufikh@lkkauto.com
 lumpsum repair
 Prepared Date : 11/01/2018 09:57:19 AM



Recording Camera

☐ ☒

Radio Antenna

☐ ☒

1st witness

Date 15-1-18

2nd witness

Date

E 12 F
 KM 330888

Vehicle to Waive Date In: 15/1
 Time In: 1650
 Date Out: 01/02/18
 Time Out: 1050
 Received by (SIC):

25/1/18 12:00 Reject
 RR Bumper August Part Emblem crack
 14.21 P957

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U50-5704820


Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,859.00	1,400.00
Total Spray Painting Charges	: 2,430.00	1,250.00
Total Material Charges	: 7,787.82	4,245.01
Other Charges	: 1,430.00	460.00
TOTAL	: 13,506.82	7,355.01
Lum Sum Total	: 13,500.00	7,350.00
No. of Repair Days	: 11.00	10.00
Prepared / Adjusted By	:	TAUFIKH (LKK)
Arc / Surveyor Sign Off Date	: 11/01/2018 04:41:40 PM	12/01/2018 04:08:12 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 11/01/2018 04:35:54 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1801-075

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 1/11/2018 4:41:31 PM



Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	1,014.00	600.00
TO REPAIR REAR PORTION	845.00	800.00
Total Labour	1,859.00	1,400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	200.00
TO RESPRAY FRONT SUPPORT PANEL	180.00	150.00
TO RESPRAY FRONT FENDER LH	378.00	200.00
TO RESPRAY FRONT DOOR LH	378.00	200.00
TO REPSRAY REAR BUMPER	378.00	200.00
TO RESPRAY BUMPER BEAM	180.00	0.00
TO RESPRAY TAIL GATE	378.00	200.00
TO RESPRAY REAR PANEL	180.00	100.00
Total Spray Painting & Panel Beating	2,430.00	1,250.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	40.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	60.00
TO TOP UP A/C GAS	120.00	120.00
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	60.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00
TO REPLACE SUNDRY PARTS	100.00	30.00
TO WASH AND VACUUM	60.00	0.00
TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	250.00	120.00
Total Other Costs	1,430.00	460.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace	No ☒ de
52021-47023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace	Replace ☒ S	No ☒ bt
52611-47080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace	Check	No ☒ nn
57014-47030			ARM SUB-ASSY, FR BUMPER LH	1	250.40	25.00	187.80	Replace	Check	No ☒ nn
52114-47140			BRACKET, FR BUMPER	1	110.40	25.00	82.80	Replace	Replace ☒ S	No ☒ nn
			NUMBER PLATE	1	15.00	0.00	15.00	Replace	Replace	No ☒ dis
			NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace	No ☒ dis
53102-47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	25.00	233.32	Replace	Replace	No ☒ de
75310-47010		6505638	EMBLEM FRONT	1	86.50	25.00	64.87	Replace	Replace	No ☒ nec
53111-47040		6505573	GRILLE, RADIATOR	1	310.60	25.00	232.95	Replace	Replace	No ☒ nn
52161-16010			BUMPER CLIPS	10	1.61 ☒ 16.10	25.00	12.07	Replace	Replace	No ☒ nec
76851-47020		6505616	BUMPER LIP FRT	1	139.60	25.00	104.70	Replace	Check	No ☒ nn
52618-47050		6505540	BUMPER FRT ABSORBER LOWER	1	127.70	25.00	95.78	Replace	Check	No ☒ nn
52116-47040		6505516	BUMPER SUPPORT F/LH	1	76.40	25.00	57.30	Replace	Replace	No ☒ de
53201-47902			SUPPORT SUB-ASSY	1	1,460.40	25.00	1,095.30	Replace	Check	No ☒ nn
81170-47500		6505436	HEAD LAMP LH	1	945.20	10.00	850.68	Replace	Replace	No ☒ nn
16400-37230		6505302	RADIATOR ASSY	1	1,496.90	25.00	1,122.68	Replace	Check	No ☒ nn
G9010-47031			RADIATOR ASSY, UPPER	1	679.60	25.00	509.70	Replace	Replace ☒ S	No ☒ dis
57104-47020		6505507	RADIATOR LOWER SUPPORT	1	876.30	25.00	657.23	Replace	Check	No ☒ nn
G9225-47021			HOSE, INVERTER NO.1	1	80.00	25.00	60.00	Replace	Check	No ☒ nn
G9214-47060			BRACKET, INVERTER, NO.1	1	31.40	25.00	23.55	Replace	Check	No ☒ nn
16267-37030			RADIATOR HOSE, BYPASS NO.3	1	37.20	25.00	27.90	Replace	Check	No ☒ nn
16571-37140		6505303	RADIATOR TOP HOSE NO 1	1	42.40	25.00	31.80	Replace	Check	No ☒ nn
16523-21050			CUSHION, RADIATOR	2	11.30 ☒ 22.60	25.00	16.95	Replace	Check	No ☒ nn
16534-37010			SUPPORT, RADIATOR, LH	1	17.70	25.00	13.28	Replace	Check	No ☒ nn
16535-20030			SUPPORT, RADIATOR,	1	18.50	25.00	13.88	Replace	Check	No ☒ nn
16711-37040			FAN SHROUD	1	244.50	25.00	183.38	Replace	Check	No ☒ nn
16712-37030			FAN SHROUD TOP	1	99.60	25.00	74.70	Replace	Replace ☒ S	No ☒ nn
88460-47150			A/C CONDENSER	1	1,181.90	25.00	886.43	Replace	Replace ☒ S	No ☒ bt

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
53802-47050		6505558	FENDER FRT/LH	1	723.40	25.00	542.55 ✓	Replace	Replace	No ✓ <i>bt</i>
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92 ✓	Replace	Replace	No ✓ <i>nel</i>
53876-47030		6505554	FENDER LINER FRT/LH	1	171.70	25.00	128.78	Replace	Check	No <i>x un</i>
67002-47070		6505529	DOOR FRT/LH	1	894.40	100.00	0.00	Replace	Repair	No <i>R</i>
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00 ✓	Replace	Replace	No ✓ <i>nel</i>
	COMMON		COOLANT	4	12.32 <i>49.28</i>	0.00	49.28 ✓	Replace	Replace <i>S</i>	No ✓ <i>nel</i>
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95 ✓	Replace	Replace	No ✓ <i>del</i>
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.28	Replace	Check	No <i>x un</i>
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Check	No <i>x un</i>
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Check	No <i>x un</i>
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.68	Replace	Check	No <i>x un</i>
			SENSOR REVERSE	1	180.00	0.00	180.00 ✓	Replace	Replace	No ✓ <i>nel</i>
			PIXEL STICKER	2	60.00 <i>no</i>	0.00	120.00 ✓	Replace	Replace	No ✓ <i>nel</i>
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Check	No <i>x un</i>
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10 ✓	Replace	Replace	No ✓ <i>nel</i>
67005-47241			TAILGATE ASY	1	1,007.90	100.00	0.00	Replace	Repair	No <i>R</i>
75574-47020			TAIL GATE DOOR GLASS MOULDING, LH	0	29.40	25.00	0.00	Replace	Not given	No <i>x un</i>
75573-47080			TAIL GATE DOOR GLASS MOULDING, RH	0	29.40	25.00	0.00	Replace	Not given	No <i>x un</i>
64821-47030			TAILGATE LOWER WINDOW GLASS	0	721.30	25.00	0.00	Replace	Not given	No <i>x un</i>
	COMMON		SEALANT W/SCREEN	0	37.00	0.00	0.00	Replace	Not given	No <i>x un</i>
69350-47030			TAILGATE DOOR LOCK	0	444.10	25.00	0.00	Replace	Not given	No <i>x un</i>
69415-47020			TAILGATE LOCK, COVER	0	15.70	25.00	0.00	Replace	Not given	No <i>x un</i>
67881-47022			TAILGATE DOOR WEATHER STRIP	0	353.40	25.00	0.00	Replace	Not given	No <i>x un</i>
69431-47010			STRIKER, BACK DOOR	1	48.90	25.00	36.67 ✓	Replace	Replace	No ✓ <i>bt</i>
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.93 ✓	Replace	Replace <i>S</i>	No ✓ <i>nel</i>
81551-47180		6505462	TAIL LAMP RH	1	557.80	100.00	0.00	Replace	Repair	No <i>R</i>
58307-47060		6505522	END PANEL	0	602.10	25.00	0.00	Replace	Not given	No <i>x un</i>
	COMMON	4006314	SEALANT SIKAFLEX	0	37.00	0.00	0.00	Replace	Not given	No <i>x un</i>
53294-47030		6505561	DEFLECTOR, RADIATOR LH	1	77.00	25.00	57.75 ✓	Replace	Replace <i>S</i>	No ✓ <i>del</i>
TOTAL MATERIALS							9,734.81	5,306.26		

TOTAL MATERIALS(Discounted)

7,787.82 | 4,245.01

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
53294-17030		DEFLECTOR, RADIATOR LH	1	77.00	25.00	57.75	Replace	Replace	No <i>de</i>
TOTAL SUPPLEMENTARY MATERIALS						57.75			

$$\begin{array}{r}
 5206.26 \\
 - 2050 \\
 \hline
 4245.01 \\
 1400 \\
 + 1710 \\
 \hline
 7355.01
 \end{array}$$

23170.78

45- \$7,350

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4230R
 Ref. No : TAX/01/18/2059
 Reg. Date : 22/11/2013
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : CHIA CHAN KONG
 Type of Accident : CHAIN COLLISION
 Date / Time of Accident : 11/01/2018 07:25:00 AM
 Accident Reported Date / Time : 11/01/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094040
 Special Instruction to ARC, if any :
 SFJ9955L
 Prepared Date : 11/01/2018 09:57:19 AM



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval of Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 97495749

12/1/18 @ 1515

8 days

Lumpsum

Resurvey after repair

sur @ lkkauto.com

taufik @ lkkauto.com

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U50-5704820

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,859.00	0.00
Total Spray Painting Charges	: 2,430.00	0.00
Total Material Charges	: 10,690.63	10,690.63
Other Charges	: 1,180.00	0.00
TOTAL	: 16,159.63	0.00
Lum Sum Total	: 16,150.00	0.00
No. of Repair Days	: 9.00	0.00
Prepared / Adjusted By	:	
Arc / Surveyor Sing Off Date	: 11/01/2018 04:41:40 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 11/01/2018 04:35:54 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 1/11/2018 4:41:31 PM

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	1,014.00	0.00 600
TO REPAIR REAR PORTION	845.00	0.00 600
Total Labour	1,859.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00 150
TO RESPRAY FRONT FENDER LH	378.00	0.00 200
TO RESPRAY FRONT DOOR LH	378.00	0.00 200
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY BUMPER BEAM	180.00	0.00 100 ? photo
TO RESPRAY TAIL GATE	378.00	0.00 200
TO RESPRAY REAR PANEL	180.00	0.00 200 ? photo
Total Spray Painting & Panel Beating	2,430.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 40 40
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 60
TO TOP UP A/C GAS	120.00	0.00 100 ?
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 X
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0.00 X
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 60
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 40 ?
TO REPLACE SUNDRY PARTS	100.00	0.00 30
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	1,180.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace <i>de ✓</i>	No
52021-47023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace	Replace <i>de ✓</i>	No
52611-47080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace	Replace <i>de ✓</i>	No
57014-47030			ARM SUB-ASSY, FR BUMPER LH	1	250.40	25.00	187.80	Replace	Replace <i>de ✓</i>	No
52114-47140			BRACKET, FR BUMPER	1	110.40	25.00	82.80	Replace	Replace <i>de ✓</i>	No
			NUMBER PLATE	1	15.00	0.00	15.00	Replace	Replace <i>mis ✓</i>	No
			NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace <i>de ✓</i>	No
53102-47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	25.00	233.32	Replace	Replace <i>de ✓</i>	No
75310-47010		6505638	EMBLEM FRONT	1	86.50	25.00	64.87	Replace	Replace <i>de ✓</i>	No
53111-47040		6505573	GRILLE, RADIATOR	1	310.60	25.00	232.95	Replace	Replace <i>de ✓</i>	No
52161-16010			BUMPER CLIPS	10	1.61	25.00	12.07	Replace	Replace <i>de ✓</i>	No
76851-47020		6505616	BUMPER LIP FRT	1	139.60	25.00	104.70	Replace	Replace <i>de ✓</i>	No
52618-47050		6505540	BUMPER FRT ABSORBER LOWER	1	127.70	25.00	95.77	Replace	Replace <i>de ✓</i>	No
52116-47040		6505516	BUMPER SUPPORT F/LH	1	76.40	25.00	57.30	Replace	Replace <i>de ✓</i>	No
53201-47902			SUPPORT SUB-ASSY	1	1,460.40	25.00	1,095.30	Replace	Replace <i>de ✓</i>	No
81170-47500		6505436	HEAD LAMP LH	1	945.20	10.00	850.68	Replace	Replace <i>de ✓</i>	No
16400-37230		6505302	RADIATOR ASSY	1	1,496.90	25.00	1,122.67	Replace	Replace <i>de ✓</i>	No
G9010-47031			RADIATOR ASSY, UPPER	1	679.60	25.00	509.70	Replace	Replace <i>de ✓</i>	No
57104-47020		6505507	RADIATOR LOWER SUPPORT	1	876.30	25.00	657.22	Replace	Replace <i>de ✓</i>	No
G9225-47021			HOSE, INVERTER NO.1	1	80.00	25.00	60.00	Replace	Replace <i>de ✓</i>	No
G9214-47060			BRACKET, INVERTER, NO.1	1	31.40	25.00	23.55	Replace	Replace <i>de ✓</i>	No
16267-37030			RADIATOR HOSE, BYPASS NO.3	1	37.20	25.00	27.90	Replace	Replace <i>de ✓</i>	No
16571-37140		6505303	RADIATOR TOP HOSE NO 1	1	42.40	25.00	31.80	Replace	Replace <i>de ✓</i>	No
16523-21050			CUSHION, RADIATOR	2	11.30	25.00	16.95	Replace	Replace <i>de ✓</i>	No
16534-37010			SUPPORT, RADIATOR, LH	1	17.70	25.00	13.27	Replace	Replace <i>de ✓</i>	No
16535-20030			SUPPORT, RADIATOR,	1	18.50	25.00	13.87	Replace	Replace <i>de ✓</i>	No
16711-37040			FAN SHROUD	1	244.50	25.00	183.37	Replace	Replace <i>de ✓</i>	No
16712-37030			FAN SHROUD TOP	1	99.60	25.00	74.70	Replace	Replace <i>de ✓</i>	No
88460-47150			A/C CONDENSER	1	1,181.90	25.00	886.42	Replace	Replace <i>de ✓</i>	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
53802-47050		6505558	FENDER FRT/LH	1	723.40	25.00	542.55	Replace	bt Replace	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	nu Replace	No
53876-47030		6505554	FENDER LINER FRT/LH	1	171.70	25.00	128.77	Replace	Replace ?	No
67002-47070		6505529	DOOR FRT/LH	1	894.40	25.00	670.80	Replace	Ry Replace	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	nu Replace	No
	COMMO N		COOLANT	1	12.32	0.00	12.32	Replace	Replace ?	No
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	de Replace	No
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace ?	No
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace ?	No
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace ?	No
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace ?	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	mis Replace	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	nu Replace	No
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace ?	No
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	nu Replace	No
67005-47241			TAILGATE ASY	1	1,007.90	25.00	755.92	Replace	Ry Replace	No
75574-47020			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	25.00	22.05	Replace	X Replace	No
75573-47080			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	25.00	22.05	Replace	X Replace	No
64821-47030			TAILGATE LOWER WINDOW GLASS	1	721.30	25.00	540.97	Replace	X Replace	No
	COMMO N		SEALANT W/SCREEN	3	37.00	0.00	111.00	Replace	Y Replace	No
69350-47030			TAILGATE DOOR LOCK	1	444.10	25.00	333.07	Replace	X Replace	No
69415-47020			TAILGATE LOCK, COVER	1	15.70	25.00	11.77	Replace	X Replace	No
67881-47022			TAILGATE DOOR WEATHER STRIP	1	353.40	25.00	265.05	Replace	X Replace	No
69431-47010			STRIKER, BACK DOOR	1	48.90	25.00	36.67	Replace	X Replace	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	nu Replace	No
81551-47180		6505462	TAIL LAMP RH	1	557.80	10.00	502.02	Replace	3 Replace ?	No
58307-47060		6505522	END PANEL	1	602.10	25.00	451.57	Replace	X Repair Replace	No
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	X Replace	No
TOTAL MATERIALS								13,363.40	13,363.29	
TOTAL MATERIALS(Discounted)								10,690.63	10,690.63	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

Bevan Lim (LKK Auto)

From: Bevan Lim (LKK Auto)
Sent: Monday, 30 April 2018 5:23 PM
To: 'Tan Lee Gek (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims)'
Cc: Vic (LKKAuto); Admin A; Hsiao Tong (LKKAuto)
Subject: RE: Accident on 11/1/2018 involving SHC 4230R, SFJ 955L (AIG insured) Our Ref: TAX/01/18/2059/lg

WITHOUT PREJUDICE

Dear Lee Gek,

We propose settlement as follows:

Cost of Repair	\$7,350.00
Loss of Rental	\$1,872.5 (14days x \$133.75)
LTA Search Fee	\$7.00
Total	\$9,229.50

Kindly revert acceptance.

Thank you.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.


Best Regards,

Bevan Lim | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: BevanLim@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK
Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Tan Lee Gek (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims) <LeeGek@smrt.com.sg>

Sent: Tuesday, 13 March 2018 1:36 PM

To: CS A Team; Admin A

Subject: Re: Accident on 11/1/2018 involving SHC 4230R, SFJ 955L (AIG insured) Our Ref: TAX/01/18/2059/lg

Dear Sir / Madam,

We are claiming for our own losses as follows:-

Cost of Repair	\$7,350.00
Loss of Rental	\$1,939.38 (14.5 days x \$133.75)
LTA Search Fee	\$7.00
Total	\$9,296.38

We enclose the following documents:

- 1) Repair Invoice
- 2) Proof of Rental Rate
- 3) SAS report
- 4) Laid up report
- 5) LTA search

Please let us have your offer soon. Thanks.

Regards

Tan Lee Gek (DID: 6866 2647)

Claims Department

SMRT Automotive Services Pte Ltd



Bevan Lim (LKK Auto)

From: Bevan Lim (LKK Auto)
Sent: Wednesday, 25 April 2018 5:49 PM
To: Wui, Shawnkaijye
Cc: Vic (LKKAuto)
Subject: Your Ref: TP / 9723672551SG Our Ref: CC3/AIG18000865/T1mb3

Your Ref: **TP / 9723672551SG**
Our Ref: CC3/AIG18000865/T1mb3

WITHOUT PREJUDICE

Dear Sirs,

ACCIDENT INVOLVING SFJ 9955L (OI)/ SHC 4230R (TP) /OTHERS ON 10/10/2017

We refer to the above matter.

This is a 3 vehicle chain collision and insured was the last vehicle. Liability is down against our insured.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer to Third Party repairer, **SMRT AUTOMOTIVE SERVICES PTE LTD** is as follows: -

	Amount <u>Claimed</u>	Amount <u>Revised</u>
1. Cost of Repair	\$ 16,159.63	\$ 7,350.00
2. Loss of Rental (14.5days x \$133.75)	\$ 1,939.38	\$ 1,872.50 (14days x \$133.75)
3.LTA search	\$ 7.00	\$ 7.00
TOTAL	\$ 18,106.01	\$9,229.50

Total amount of claim (**Liability 100%**) **\$9,229.50**

***Recommended 10 repair days + 2 Sunday 1 pre-inspection day + 1 Date of accident =14 days

All the relevant documents had been uploaded in Merimen for your perusal.

For your approval in Merimen please.

Best Regards,

Bevan Lim | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: BevanLim@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

Jas Khine (LKKAUTO)

From: Shu Pei (LKKAUTO)
Sent: Tuesday, 13 March 2018 5:58 PM
To: LeeGek@smrt.com.sg
Cc: Admin A; CS A Team
Subject: RE: Accident on 11/1/2018 involving SHC 4230R, SFJ 955L (AIG insured) Our Ref: TAX/01/18/2059/lg
Attachments: 01 18 2059.pdf
Follow Up Flag: Follow up
Flag Status: Flagged

Dear Lee Gek,

Thank you for your email.

Please note that: -

LKK ref	Officer in charge
CC3/AIG18000865/T1ys3	Jas - 6841 2928

To check availability of the case handler , you may contact the undersigned.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan Lee Gek (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims) [mailto:LeeGek@smrt.com.sg]
Sent: Tuesday, 13 March 2018 1:36 PM
To: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: Re: Accident on 11/1/2018 involving SHC 4230R, SFJ 955L (AIG insured) Our Ref: TAX/01/18/2059/lg

Dear Sir / Madam,

We are claiming for our own losses as follows:-

Cost of Repair	\$7,350.00
Loss of Rental	\$1,939.38 (14.5 days x \$133.75)
LTA Search Fee	\$7.00
Total	\$9,296.38

We enclose the following documents:

- 1) Repair Invoice
- 2) Proof of Rental Rate
- 3) SAS report
- 4) Laid up report
- 5) LTA search

Please let us have your offer soon. Thanks.

Regards

Tan Lee Gek (DID: 6866 2647)

Claims Department

SMRT Automotive Services Pte Ltd



...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Jan 2018 Edit Reg		12 Jan 2018 00:00 Edit Adj Rpt	S\$7,350.00 Edit Estimates	S\$7,350.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by adjuster\]](#)

Insured:	Chua Seng Chye, ID: S1417921F, Tel: +6598510063		
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K		
Vehicle Reg. No.:	SHC4230R	Date of Loss:	11/01/2018 07:00 - :59 [49 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 9723672551SG	Policy/Cover Note No.:	1700033541 (Comprehensive) Coverage: 01/08/2017 - 31/07/2018
Vehicle Reg. No. (Insured):	SFJ9955L	Policy No. (Claimant):	D-17087562MFSH
		Excess:	
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ] Shawnkaijye.Wui@aig.com		
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 24/01/2018]		
Driver/Custodian (Insured):	Chua Seng Chye (), NRIC: S1417921F, Tel: +6598510063		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (30/04/2018): Alert - Adj Mandate Approved (S\$9229.50) - SHC4230R - Claim Handler: Wui, Shawn-...
- AIG_SG_EXPRESS (27/04/2018): Alert - Adj Mandate Maintained - SHC4230R - Claim Handler: Wui, Shawn-KJ

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

***SHC4230R (9723672551SG)
[SFJ9955L]**

TP

SMRT TAXIS PTE LTD

Jan 11 2018 7:00AM

[Chua Seng Chye]

SMRT Automotive Services Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View [View in Browser](#) ▼

Video			1 per page ▼	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	17/01/18 14:28	Video - Accident From: OD - Reg. No: SFJ9955L, Claimant: CHUA SENG CHYE	Load MP4	

Letters/Correspondences			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	Edit	

Assessment Reports			1 per page ▼	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	16/01/18 16:50	Accident Statement From: OD - Reg. No: SFJ9955L, Claimant: CHUA SENG CHYE	Load HTM	

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/04/18 13:57	General View	Load JPG	☒
2	27/04/18 13:57	General View	Load JPG	☒
3	27/04/18 13:57	General View	Load JPG	☒
4	27/04/18 13:57	General View	Load JPG	☒
5	27/04/18 13:57	General View	Load JPG	☒
6	27/04/18 13:57	General View	Load JPG	☒
7	27/04/18 13:57	General View	Load JPG	☒
8	27/04/18 13:57	General View	Load JPG	☒
9	27/04/18 13:57	General View	Load JPG	☒
10	27/04/18 13:57	General View	Load JPG	☒
11	27/04/18 13:57	General View	Load JPG	☒
12	27/04/18 13:57	General View	Load JPG	☒
13	27/04/18 13:57	General View	Load JPG	☒
14	27/04/18 13:57	General View	Load JPG	☒
15	27/04/18 13:57	General View	Load JPG	☒
16	27/04/18 13:57	General View	Load JPG	☒
17	27/04/18 13:57	General View	Load JPG	☒
18	27/04/18 13:57	General View	Load JPG	☒
19	27/04/18 13:57	General View	Load JPG	☒
20	27/04/18 13:57	General View	Load JPG	☒
21	27/04/18 13:57	General View	Load JPG	☒
22	27/04/18 13:57	General View	Load JPG	☒
23	27/04/18 13:57	General View	Load JPG	☒
24	27/04/18 13:57	General View	Load JPG	☒

Video			1 per page ▼	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
25	27/04/18 13:57	General View	 Load JPG	✓
26	27/04/18 13:57	General View	 Load JPG	✓
27	27/04/18 13:57	General View	 Load JPG	✓
28	27/04/18 13:57	General View	 Load JPG	✓
29	27/04/18 13:57	General View	 Load JPG	✓
30	27/04/18 13:57	General View	 Load JPG	✓
31	27/04/18 13:57	General View	 Load JPG	✓
32	27/04/18 13:57	General View	 Load JPG	✓
33	27/04/18 13:57	General View	 Load JPG	✓
34	27/04/18 13:57	General View	 Load JPG	✓
35	27/04/18 13:57	General View	 Load JPG	✓
36	27/04/18 13:57	General View	 Load JPG	✓
37	27/04/18 13:57	General View	 Load JPG	✓
38	27/04/18 13:57	General View	 Load JPG	✓
39	27/04/18 13:57	General View	 Load JPG	✓
40	27/04/18 13:57	General View	 Load JPG	✓
41	27/04/18 13:57	General View	 Load JPG	✓
42	27/04/18 13:57	General View	 Load JPG	✓
43	27/04/18 13:57	General View	 Load JPG	✓
44	27/04/18 13:57	General View	 Load JPG	✓
45	27/04/18 13:57	General View	 Load JPG	✓
46	27/04/18 13:57	General View	 Load JPG	✓
47	27/04/18 13:57	General View	 Load JPG	✓
48	27/04/18 13:57	General View	 Load JPG	✓
49	27/04/18 13:57	General View	 Load JPG	✓
50	27/04/18 13:57	General View	 Load JPG	✓
51	27/04/18 13:57	General View	 Load JPG	✓
52	27/04/18 13:57	General View	 Load JPG	✓
53	27/04/18 13:57	General View	 Load JPG	✓
54	27/04/18 13:57	General View	 Load JPG	✓
55	27/04/18 13:57	General View	 Load JPG	✓
56	27/04/18 13:57	General View	 Load JPG	✓
57	27/04/18 13:57	General View	 Load JPG	✓
58	27/04/18 13:57	General View	 Load JPG	✓
59	27/04/18 13:57	General View	 Load JPG	✓
60	27/04/18 13:57	General View	 Load JPG	✓
61	27/04/18 13:57	General View	 Load JPG	✓
62	27/04/18 13:57	General View	 Load JPG	✓
63	27/04/18 13:57	General View	 Load JPG	✓
64	27/04/18 13:57	General View	 Load JPG	✓
65	27/04/18 13:57	General View	 Load JPG	✓
66	27/04/18 13:57	General View	 Load JPG	✓
67	27/04/18 13:57	General View	 Load JPG	✓
68	27/04/18 13:57	General View	 Load JPG	✓
69	27/04/18 13:57	General View	 Load JPG	✓
70	27/04/18 13:57	General View	 Load JPG	✓
71	27/04/18 13:57	General View	 Load JPG	✓
72	27/04/18 13:57	General View	Load JPG	✓

Video			1 per page	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
73	27/04/18 13:57	General View	 Load JPG	☒
74	27/04/18 13:57	General View	 Load JPG	☒
75	27/04/18 13:57	General View	 Load JPG	☒
76	27/04/18 13:57	General View	 Load JPG	☒
77	27/04/18 13:57	General View	 Load JPG	☒
78	27/04/18 13:57	General View	 Load JPG	☒
79	27/04/18 13:57	General View	 Load JPG	☒
80	27/04/18 15:41	Reinspection Photo	 Load JPG	☒
81	27/04/18 15:41	Reinspection Photo	 Load JPG	☒
82	27/04/18 15:41	Reinspection Photo	 Load JPG	☒
83	27/04/18 15:41	Reinspection Photo	 Load JPG	☒
84	27/04/18 15:41	Reinspection Photo	 Load JPG	☒
85	27/04/18 15:41	Reinspection Photo	 Load JPG	☒
86	27/04/18 15:41	Reinspection Photo	 Load JPG	☒
87	27/04/18 15:41	Reinspection Photo	 Load JPG	☒
88	27/04/18 15:41	Reinspection Photo	 Load JPG	☒
89	27/04/18 15:41	Reinspection Photo	 Load JPG	☒
90	27/04/18 15:41	Reinspection Photo	 Load JPG	☒
91	27/04/18 15:41	Reinspection Photo	 Load JPG	☒
92	27/04/18 15:41	Reinspection Photo	 Load JPG	☒
93	27/04/18 15:41	Reinspection Photo	 Load JPG	☒
94	27/04/18 15:41	Reinspection Photo	 Load JPG	☒
95	27/04/18 15:41	Reinspection Photo	 Load JPG	☒
96	27/04/18 15:41	Reinspection Photo	 Load JPG	☒
97	27/04/18 15:41	Reinspection Photo	 Load JPG	☒
98	27/04/18 15:41	Reinspection Photo	 Load JPG	☒
99	27/04/18 15:41	Reinspection Photo	 Load JPG	☒
100	27/04/18 15:41	Reinspection Photo	 Load JPG	☒
101	27/04/18 15:41	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/01/18 18:58	TP GIA REPORT	 Load PDF	
2	15/01/18 18:58	TP ESTIMATE- MARKED	 Load PDF	
3	21/03/18 15:46	LETTER TO OI	 Load PDF	
4	21/03/18 15:46	LTA SEARCH	 Load PDF	
5	21/03/18 15:46	RENTAL RECEIPT	 Load PDF	
6	11/05/18 13:33	AUTHORISATION TO ACT	 Load PDF	
7	11/05/18 13:33	RELEASE VOUCHER	 Load PDF	
8	11/05/18 13:33	WORKSHOP INVOICE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SFJ9955L (Insd veh)	Model:	TOYOTA PRIUS TAXI 1.8 (A)
	SHC4230R (TP veh)		
Date of Accident:	11/01/2018		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	:	\$	23,170.78
Final Repair Cost	:	\$	7,350.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	14 days
LTA / GIA Search Fee	:	\$	7.00
Others:	:	\$	
	:	\$	
Final Settlement Sum	:	\$	9,229.50
Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ 100 _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown

1)	SMRT TAXIS PTE LTD	:	\$	9,229.50
2)		:	\$	
3)		:	\$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

11 May
2018

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18000865/T1MB3S2
Date: 11/05/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700033541
Claimant Vehicle No: SHC4230R Insured Vehicle No: SFJ9955L
Date of Loss: 11/01/2018 Nature of Claim: TP Claim No: 9723672551SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC4230R
Make & Model: TOYOTA PRIUS TAXI, 1.8 (A) Engine No: 2ZR5905381
Reg. Date: 22/11/2013 (Man. Year: 2013) Chassis No: JTDKN36U505704820
Colour: Maroon Odometer: 0 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,451.78	5,364.02	12,087.76	69.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,719.00	3,110.00	2,609.00	45.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	23,170.78	8,474.02	14,696.76	63.43
Approved Total (Overridden) (\$\$)		7,350.00		
Nett Amount (\$\$)	23,170.78	7,350.00	15,820.78	68.28
+ Car Rental (14.0 x S\$133.75/day) (\$\$)		1,872.50		
+ Doc/Search Fee (\$\$)		7.00		
Nett Liability (\$\$)		9,229.50		

INSPECTION

Date of Assignment: 12/01/2018
Date Inspected: 12/01/2018 Inspected At: SMRT Automotive Services Pte Ltd (Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705
Estimated Period of Repair: 10.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Lim Chin Siong Bevan

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER FRT (DISC 25%)	Deformed	482.00 F	*361.50 F
2	1		*BUMPER REINFORCEMENT FRT (DISC 25%)	Bent	498.40 F	*373.80 F
3	1		*BRACKET, FR BUMPER (DISC 25%)	Necessary	110.40 F	*82.80 F
4	1		*BUMPER GRILLE SUB-ASSY, LOWER (DISC 25%)	Deformed	311.10 F	*233.32 F
5	1		*EMBLEM FRONT (DISC 25%)	Necessary	86.50 F	*64.87 F
6	1		*GRILLE, RADIATOR (DISC 25%)	Cracked	310.60 F	*232.95 F
7	1		*BUMPER CLIPS (DISC 25%)	Necessary	16.10 F	*12.07 F
8	1		^{10pcs} *BUMPER SUPPORT F/LH (DISC 25%)	Deformed	76.40 F	*57.30 F
9	1		*RADIATOR ASSY, UPPER (DISC 25%)	Distorted	679.60 F	*509.70 F
10	1		*FAN SHROUD TOP (DISC 25%)	Cracked	99.60 F	*74.70 F
11	1		*A/C CONDENSER (DISC 25%)	Bent	1,181.90 F	*886.43 F
12	1		*FENDER FRT/LH (DISC 25%)	Bent	723.40 F	*542.55 F
13	1		*NAME PLATE (HYBRID) (DISC 25%)	Necessary	51.90 F	*38.92 F
14	1		*BUMPER REAR (DISC 25%)	Deformed	458.60 F	*343.95 F
15	1		*BUMPER SIDE RETAINER RR/RH (DISC 25%)	Necessary	94.80 F	*71.10 F
16	1		*STRIKER, BACK DOOR (DISC 25%)	Bent	48.90 F	*36.67 F
17	1		*NAME PLATE (HYBRID) (DISC 25%)	Necessary	51.90 F	*38.93 F
18	1		*DEFLECTOR RADIATOR LH (DISC 25%)	Deformed	77.00 F	*57.75 F
19	1		*DEFLECTOR, RADIATOR LH (DISC 25%)	Deformed	77.00 F	*57.75 F
20	1		*HEAD LAMP LH (DISC 10%)	Cracked	945.20 F	*850.68 F
21	1		*NUMBER PLATE (SN)	Distorted	15.00 F	*15.00 F
22	1		*NUMBER PLATE FRAME (SN)	Distorted	12.00 F	*12.00 F
23	1		*STICKER DECAL SMRT (DOOR) (SN)	Necessary	60.00 F	*60.00 F
24	4		*COOLANT (SN)	Necessary	49.28 F	*49.28 F
25	1		*SENSOR REVERSE (SN)	Not Working	180.00 F	*180.00 F
26	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
27	1		*BUMPER ENERGY ABSORBER FRT	Not Necessary	78.80 F	*- F
28	1		*ARM SUB-ASSY, FR BUMPER LH	Not Necessary	250.40 F	*- F
29	1		*BUMPER LIP FRT	Not Necessary	139.60 F	*- F
30	1		*BUMPER FRT ABSORBER LOWER	Not Necessary	127.70 F	*- F
31	1		*SUPPORT SUB-ASSY	Not Necessary	1,460.40 F	*- F
32	1		*RADIATOR ASSY	Not Necessary	1,496.90 F	*- F
33	1		*RADIATOR LOWER SUPPORT	Not Necessary	876.30 F	*- F
34	1		*HOSE, INVERTER NO.1	Not Necessary	80.00 F	*- F
35	1		*BRACKET, INVERTER, NO.1	Not Necessary	31.40 F	*- F
36	1		*RADIATOR HOSE, BYPASS NO.3	Not Necessary	37.20 F	*- F
37	1		*RADIATOR TOP HOSE NO 1	Not Necessary	42.40 F	*- F
38	2		*CUSHION, RADIATOR	Not Necessary	22.60 F	*- F
39	1		*SUPPORT, RADIATOR, LH	Not Necessary	17.70 F	*- F
40	1		*SUPPORT, RADIATOR	Not Necessary	18.50 F	*- F
41	1		*FAN SHROUD	Not Necessary	244.50 F	*- F
42	1		*FENDER LINER FRT/LH	Not Necessary	171.70 F	*- F
43	1		*BUMPER REINFORCEMENT REAR	Not Necessary	205.70 F	*- F
44	1		*ARM SUB-ASSY, RR BUMPER LH	Not Necessary	139.60 F	*- F
45	1		*ARM SUB-ASSY, RR BUMPER RH	Not Necessary	139.60 F	*- F
46	1		*BUMPER LIP REAR	Not Necessary	228.90 F	*- F
47	1		*BUMPER SIDE RETAINER RR/LH	Not Necessary	94.80 F	*- F
48	1		*TAILGATE DOOR GLASS MOULDING, LH	Not Necessary	29.40 F	*- F
49	1		*TAILGATE DOOR GLASS MOULDING, RH	Not Necessary	29.40 F	*- F
50	1		*TAILGATE LOWER WINDOW GLASS	Not Necessary	721.30 F	*- F
51	1		*SEALANT W/SCREEN	Not Necessary	37.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*TAILGATE DOOR LOCK	Not Necessary	444.10 F	*- F
53	1		*TAILGATE LOCK, COVER	Not Necessary	15.70 F	*- F
54	1		*TAILGATE DOOR WEATHER STRIP	Not Necessary	353.40 F	*- F
55	1		*END PANEL	Not Necessary	602.10 F	*- F
56	1		*SEALANT SIKAFLEX	Not Necessary	37.00 F	*- F
57	1		*DOOR FRT/LH	Repair	894.40 F	*- F
58	1		*TAILGATE ASY	Repair	1,007.90 F	*- F
59	1		*TAIL LAMP RH	Repair	557.80 F	*- F
Total Parts (\$\$)						17,451.78 5,364.02

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODYWORK.	New	1,859.00	1,400.00
2	SPRAY PAINT.	New	2,430.00	1,250.00
3	TO CHECK WIRING AND SYSTEM FUNCTION.	New	80.00	40.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA.	New	100.00	60.00
5	TO TOP UP A/C GAS.	New	120.00	120.00
6	TO TRANSFER REAR TAILGATE MECHANISM.	New	120.00	0.00
7	TO REMOVE AND REFIX REAR WINDSCREEN.	New	240.00	0.00
8	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	New	120.00	30.00
9	TO REMOVE AND REINSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	New	120.00	60.00
10	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.	New	120.00	0.00
11	TO REPLACE SUNDRY PARTS.	New	100.00	30.00
12	TO WASH AND VACUUM.	New	60.00	0.00
13	TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER.	New	250.00	120.00
Gross Labour Cost (S\$)			5,719.00	3,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >