



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2016 PEUGEOT 5008 1.6 BLUEHDI EAT6 S/R (SLM4657T)

Date of Loss

11 January 2018

Time of Loss

19.30

Loss Description

SLM4657T (INSD) HIT IN REAR BY SJE3747P

Comment

Workshop Details

Total Rebate Amount

57679

Nett Loss Amount

\$38,321.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

13/08/2018



Days of work completion *

210



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SLM4657T

Registration State

SINGAPORE

Mileage

17548

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2016

ASSESSMENT INFO...

2016

Purchase Date

dd/mm/yyyy



Registration Date *

31/03/2017



Age of Vehicle

0

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

NG YONG KWANG

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... PEUGEOT

ASSESSMENT INFO... PEUGEOT

CATEGORY Model

POLICY INFORMAT... 5008 1.6 BLUEHDI EAT6 S/R

ASSESSMENT INFO... 5008 1.6 BLUEHDI EAT6 S/R

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... VF30EBHZTGS234820

CATEGORY Date of Birth

FNOL INFORMATI... 28 August 1979

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 38

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO... VF30EBHZTGS234820

CATEGORY Engine No

POLICY INFORMAT... 10JBHX3016622

ASSESSMENT INFO... 10JBHX3016622

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 1560

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 96000

FNOL INFORMATI... 13

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI... 1 January 2005

POST SURVEY INF... dd/mm/yyyy

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY Address

FNOL INFORMATI... 468 SIGLAP RD # 01 - 27, 455943,
Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Personal Correspondence

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Male

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

S7925456H

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

16/01/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

400

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

215/50R17

Condition of Vehicle at time of survey

General condition

Good

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good

Tyre Condition

Spare wheel

Rear Tyre Size

215/50R17

Front left side

MICHELIN6mm

Front right side

MICHELIN6mm

Rear left side

MICHELIN6mm

Rear right side

MICHELIN6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

☒ Yes ☐ No

Part Supplied by AXA

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add

Approve

Deny

Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
☐		1	1			REAR BUMPER W/SENSOR MARKING HOLE			Deformed	702				702	Review
☐		2	1			REAR BUMPER BRACKET			Serviceable	0	0	0	0	0	Deny
☐		3	1			RR BUMPER CTR BRACKET			Serviceable	0	0	0	0	0	Deny
☐		4	1			SET RR BPR BRACKET			Serviceable	0	0	0	0	0	Deny
☐		5	1			LOW RR PAN FIX			Necessary	53.1				53.1	Review
☐		6	1			TAILGATE			Bent	1440				1440	Review
☐		7	1			TAILGATE GLASS			Necessary	432				432	Review
☐		8	1			BADGE ASSEMBLE			Necessary	54				54	Review
☐		9	1			TAILGATE FIX			Necessary	104.4				104.4	Review
☐		10	1			RR BUMPER REINFORCEMENT			Bent	297				297	Review
☐		11	1			RR OBSTACLE DETECTION SENSOR			Serviceable	0	0	0	0	0	Deny
☐		12	1			LHR BUMPER REVERSE/FOG LAMP			Cracked	126				126	Review

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	RI
		1		REPLACE / REPAIR REAR BUMPER, REAR BUMPER BEAM, TAILGATE, END PANEL	1200	0	0	Reviewing		1
		2		RESPRAY REAR BUMPER, END PANEL, TAILGATE	1200	0	0	Reviewing		1
		3		WIRING CONNECTION & CHECK	150	0	0	Reviewing		1
		4		REMOVE & REPLACE REVERSE SENSOR	150	0	0	Reviewing		1
		5		REMOVE & REPLACE REAR LIGHTING SYSTEM	150	0	0	Reviewing		1
		6		TRANSFER TAILGATE MECHANISM	400	0	0	Reviewing		1
		7		REMOVE & REPLACE REAR WINDSCREEN	600	0	0	Reviewing		1
		8		INNER SEAL FOR REAR WINDSCREEN	60	0	0	Reviewing		1
		9		SEALANT FOR REAR WINDSCREEN	50	0	0	Reviewing		1
		10		TUFF KOTE @ \$60 PER PANEL	60	0	0	Reviewing		1
		11		SELANT FOR REAR TAILGATE @ \$90 PER PANEL	90	0	0	Reviewing		1
		12		TO CONDUCT ECU COMPUTER DIAGNOSTIC INCLUDING CLEAR FAULT CODE	600	0	0	Reviewing		1

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		1	DAYS OF REPAIR : 5 DAYS	Reviewing			
☐		2	SUNDRIES	Reviewing	30	NECESSARY	
☐		3	REAR FOG LAMP RH	Deny	0	NOT NECESSARY (SUPPLEMENTARY)	
☐		4	VEHICLE TOWED TO VAL DUE TO ACCIDENT	Deny	0	NOT NECESSARY (SUPPLEMENTARY)	
☐		5	TO SUPPLY 1 UNIT REAR NUMBER PLATE	Reviewing	70	BENT (SUPPLEMENTARY)	
☐		6	TO SUPPLY & INSTALL REAR WINDSCREEN 3M SOLAR FILM	Reviewing	350	NECESSARY (SUPPLEMENTARY)	

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount \$7,968.50

Claim Amount \$7,968.50

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$4,710.00	\$4,710.00
Miscellaneous	\$450.00	\$450.00
Excess	-\$400.00	-\$400.00
Spare Parts	\$3,208.50	\$3,208.50

[Submit for Review](#)