

INSURANCE

INS. CASE OWNER

Shawn

CC 4 / AIG18000971

KWS3

LKK

IDAC

Surveyor:

KENNETH

DOI:

15/01/18

Date / Time:

15/01/18

Registered in Merimen:

15/01/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKN 568L

Name of Insured:

MOA AUTOMOTIVE PTE LTD

Insured Tel No.:

HP:

Excess Sec II : \$5

D.O.A : 15/01/18

Is driver the owner?

(YES ☒ NO)

Nature of Accident:

If NO. Driver Name / Age: JOHNSON S/O MURRAY

Driver Tel No.: 9238 8423

(V/L ☒ / NO)

Claim No.:

2100713479SG

Policy No.:

Make / Model:

Bmw 522i 2.5 AT ABS D/AB 2WD

Place of Accident:

4PR GAS/B
TRONG WEST ME 2

OI GIA REPORT ☒ / NO : TP GIA REPORT ☒ / NO

Insured Liability:

% Final ? Yes / No

SKN 568L

SL 2414U

SLK 9092A



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP: chng Hae Com
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting hr (1st):

Non-Reporting hr (2nd):

Non-Reporting hr (Final):

Notification hr (if non-pickup):

Call OI: 22/1/18 2 SH

After call hr to OI: vic oc 29/01/18

Documentation Check List: Handler Typist

Notification hr (if non-pickup)

After call hr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

Confirm by:

Confirm with:

Confirm by:

Confirm with:

Confirm by:

Confirm with:

Confirm by:

Confirm with:

Confirm by:

Confirm with:

Confirm by:

Confirm with:

Confirm by:

Confirm with:

Confirm by:

Confirm with:

Confirm by:

Confirm with:

Confirm by:

Confirm with:

Confirm by:

Confirm with:

Confirm by:

Confirm with:

Confirm by:

Confirm with:

Confirm by:

Confirm with:

Confirm by:

Confirm with:

Confirm by:

Confirm with:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

\$5

(days) Reduction:

%

FINAL SETTLEMENT

Date/Time:

Confirm with June

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

20

Repair Cost:

\$5 10700.00

Loss of Rental (LOR):

\$5 3250.00

(25 days) x 130.00

Loss of Use (LOU):

\$5 -

(5 x days)

Loss of Income (LOI):

\$5 -

(5 x days)

LOR only

☐

LOU only

☐

LOR + LOU

☐

LOR + LO

☐

[Tick only one]

GIA/LTA Search

\$5 2-00

Medical:

\$5 -

Disbursement:

\$5 -

(e.g. Tow/ Independent)

Legal Cost:

\$5 -

Total:

\$5 13958.00

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Payee 1:

\$5 13958.00

Name 1:

Cheng Hoe Motor Pte Ltd.

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

ASS. REC. BY:

REF:

1/6/1

meth

ASSIGNMENT

From:

Date:

Estimated Cost:

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Vsh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

20

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

STL 24140 Yr Regn: 11.08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Honda Stream cc 1789

Colour:

White A/C: Insured / Std / NI / NA

Sp. Reading:

122800 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

RNG 1068P74

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Maxxis 205/65R15

R: Yokohama

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal:

9 mm

R/Bal:

3 mm

L/Bal:

9 mm

L/Bal:

3 mm

D.O.A.

13/1/18

D.O.A.

15/1/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

16/1 File pass to Customer

11 Sep @ 10k Confirm Efile (20+5 x 120) Rental

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ - RS. \$

Phone:

Others:

TOTAL

Report Format :

Lump Sum / I.B.I. (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/AIG18000871/Kws3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 15-01-2018	
Code : AIG			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKN 5668L	Veh. Inspected	SJL 2414U
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	15/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	13/01/2018	Inspection Date	15/01/2018
Survey held at	CHENG HOE MOTOR PTE LTD 10 ANG MO KIO IND PARK 2A #01-04 ANG MO KIO AUTOPOINT, SINGAPORE 568047		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Attn: Kenneth

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST: 201001158E RCB NO: 201001158E

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES1890047/AMK

Date: 15 Jan 2018

Policy No: MPC17A00239101

Veh Reg No: SJL2414U

Make/Model: HONDA STREAM 1.8 X
AUTO

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 13/01/2018

TP Veh Reg No: SLK9092A

Chassis No: RN61068974

Engine No: R18A1776390

Reg. Date: 20/11/2008

Estimate Repair Cost to Vehicle No :SJL2414U

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 FRONT BUMPER	635.40	1 PC	By 635.40 ✓	
2 FRONT BUMPER REINFORCEMENT	218.40	1 PC	By 218.40 ✓	
3 FRONT BUMPER LOWER CENTRE GRILLE	85.60	1 PC	By 85.60 ✓	
4 FRONT BUMPER SIDE RETAINER	18.00	2 PC	By 36.00 ✓	
5 FRONT BUMPER CLIP	3.70	6 PC	By 22.20 ✓	
6 BONNET	638.50	1 PC	By 638.50 ✓	
7 BONNET INNER LOCK	85.60	1 PC	By 85.60 ✓	
8 BONNET HINGE	38.90	2 PC	R 77.80 ✓	
9 BONNET INNER TOP RUBBER	19.40	1 PC	By 19.40 ✓	
10 BONNET INNER LOCK OUTER COVER	20.30	1 PC	By 20.30 ✓	
11 FRONT GRILLE	202.60	1 PC	CM 202.60 ✓	
12 FRONT GRILLE MOULDING	210.50	1 PC	CM 210.50 ✓	
13 FRONT GRILLE LOGO	24.70	1 PC	By 24.70 ✓	
14 FRONT GRILLE CLIP	3.70	4 PC	By 14.80 ✓	
15 HEADLAMP	680.40	2 PC	CM 1,360.80 ✓	
16 HEADLAMP LOWER BRACKET	36.80	2 PC	CM 73.60 ✓	
17 HORN	40.10	2 PC	R 80.20 ✓	
18 FRONT LOWER ENGINE UNDER COVER	85.40	1 PC	CM 85.40 ✓	
19 AIR-CON CONDENSER	840.10	1 PC	By 840.10 ✓	
20 AIR-CON CONDENSER SUCTION HOSE	105.90	1 PC	By 105.90 ✓	
21 AIR-CON CONDENSER DISCHARGE HOSE	235.90	1 PC	By 235.90 ✓	
22 RADIATOR	1,507.30	1 PC	By 1,507.30 ✓	
23 FRONT AIRBAG SENSOR	189.80	1 PC	DM 189.80 ✓	
24 FRT SUPPORT PANEL	466.20	1 PC	By 466.20 ✓	
25 FRONT SUPPORT PANEL INNER TOP GARNISH	48.60	1 PC	By 48.60 ✓	
26 FRONT SUPPORT PANEL INNER TOP GARNISH CLIP	3.70	6 PC	By 22.20 ✓	
27 ENGINE RH MOUNTING	291.70	1 PC	CM 291.70 ✓	
28 GEARBOX MOUNTING	230.40	1 PC	CM 230.40 ✓	
29 FRONT FENDER	486.20	2 PC	R 972.40 ✓	
30 FRONT FENDER INNER SHIELD CLIP	3.70	12 PC	By 44.40 ✓	
31 REAR BUMPER	588.90	1 PC	By 588.90 ✓	
32 REAR BUMPER TOW HOOK COVER	14.30	1 PC	By 14.30 ✓	
33 REAR BUMPER SIDE RETAINER	21.90	2 PC	By 43.80 ✓	
34 REAR BUMPER CLIP	3.70	6 PC	By 22.20 ✓	
35 REAR TAILGATE	903.50	1 PC	By 903.50 ✓	
36 TAILGATE INNER LOCK	119.40	1 PC	By 119.40 ✓	
37 TAILGATE INNER RUBBER	121.60	1 PC	By 121.60 ✓	

501.20
60.80

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST 201001158E RCB NO 201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 13/01/2018

TP Veh Reg No: SLK9092A

Estimate No: ES1890047/AMK

Date: 15 Jan 2018

Policy No: MPC17A00239101

Veh Reg No: SJL2414U

Make/Model: HONDA STREAM 1.8 X
 AUTO

Chassis No: RN61068974

Engine No: R18A1776390

Reg. Date: 20/11/2008

Estimate Repair Cost to Vehicle No :SJL2414U

Description	U/Price	Quantity	List Price	Amount
			SS	SS
38 TAILGATE EMBLEM 'STREAM'	31.60	1 PC	31.60	—
39 TAILGATE NUMBER PLATE LAMP GARNISH	162.70	1 PC	162.70	—
40 TAILGATE NO PLATE LAMP	32.80	2 PC	65.60	X
41 TAILGATE WINDSCREEN GLASS MOULDING	65.00	1 PC	65.00	✓
42 TAILGATE INNER HANDLE	21.90	1 PC	21.90	—
43 TAILGATE INNER TRIM BOARD	141.90	1 PC	141.90	—
44 TAILGATE INNER SIDE TRIM	40.20	2 PC	80.40	X X
45 TAILLAMP	352.40	2 PC	704.80	—
46 RH TAILLAMP PANEL	145.30	1 PC	145.30	—
47 REAR END PANEL (INNER)	95.50	1 PC	95.50	—
48 REAR END PANEL (OUTER)	306.50	1 PC	306.50	—
49 REAR END PANEL INNER GARNISH (TOP & CENTRE)	116.70	1	116.70	—
50 REAR RH FENDER	858.30	1 PC	858.30	X
51 REAR RH FENDER QUARTER GLASS	229.70	1 PC	229.70	X
52 REAR RH FENDER QUARTER GLASS MOULDING	45.00	1 PC	45.00	X
53 REAR FENDER INNER TRIM	197.40	2 PC	394.80	—
54 SPARE TYRE HOLDER ASSY	148.70	1 PC	148.70	—
55 REAR EXHAUST MUFFLER	514.70	1 PC	514.70	—
56 REAR EXHAUST HEAT SHIELD	48.20	1 PC	48.20	—
57 REAR EXHAUST RUBBER MOUNTING	17.00	2 PC	34.00	—
58 EXHAUST MID PIPE	583.70	1 PC	583.70	—
59 REAR RH CHASSIS FRAME	584.30	1 PC	584.30	X
60 REAR LUGGAGE COMPARTMENT PANEL	1,062.20	1 PC	1,062.20	—
61 REAR LUGGAGE COMPARTMENT PANEL INNER CENTRE GARNISH	165.80	1 PC	165.80	—
62 REAR LUGGAGE COMPARTMENT SIDE TOP BOARD	130.40	2 PC	260.80	X✓
63 REAR LUGGAGE COMPARTMENT PANEL TOOL SPONGE	126.40	1 PC	126.40	X✓
64 FUEL TANK RH SIDE HEATSHIELD	141.50	1 PC	141.50	X X
			14636.20	17,796.40
			Less 20%	3,559.28
				Tg. 237.12
			2927.29	11708.96
Special Net				
65 FRONT NUMBER PLATE	35.00	1 PC	35.00	—
66 REAR NUMBER PLATE	35.00	1 PC	35.00	—
67 REVERSE SENSOR	200.00	1 SET	200.00	—
68 REVERSE CAMERA	350.00	1 UNIT	350.00	X✓
69 COOLANT	35.00	1 UNIT	35.00	—
70 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	—
71 REAR RH FENDER GLASS SEALANT	40.00	1 PC	40.00	X

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chenghoe@singnet.com.sg
 GST: 201001158E RCB NO: 201001158E

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before repair spray painting
- To resurvey damaged parts during survey
- Parts prices are subject to confirmation
- Any survey is on a "Without Prejudice" basis
- Major modification(s) is allowed
- Implementary item(s) must be resurveyed and
- Subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Estimate No: ES1890047/AMK

Date: 15 Jan 2018

Policy No: MPC17A00239101

Veh Reg No: SJL2414U

Make/Model: HONDA STREAM 1.8 X
 AUTO

Chassis No: RN61068974

Engine No: R18A1776390

Reg. Date: 20/11/2008

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 13/01/2018

TP Veh Reg No: SLK9092A

Estimate Repair Cost to Vehicle No :SJL2414U

Description	U/Price	Quantity	List Price	Amount
72 REAR LUGGAGE COMPARTMENT PANEL TOP COAT	100.00	1 PC	100.00	SS
73 REAR RH FENDER QUARTER GLASS TINTED FILM	100.00	1 PC	100.00	X
			935.00	935.00
Labour				760
74 TOWING	50.00	1 LA	50.00	✓
75 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
76 REMOVE & REFIX FRT BUMPER,BONNET & ATTACHMENTS,GRILLE,FRT FENDERS,HEADLAMPS;TO CUT,WELD & RENEW FRT SUPPORT PANEL;KNOCKING & REPAIR FRT CHASSIS & REALIGN THE SAME	900.00	1 LA	900.00	750
77 PUTTY & RESPRAY FRT BUMPER,BONNET,BOTH FENDERS,FRT SUPPORT PANEL & ALL AFFECTED AREAS	900.00	1 LA	900.00	800
78 REMOVE & REFIX REAR BUMPER,TAILGATE & ATTACHMENTS,TAILLAMPS;TO CUT,WELD & RENEW REAR END PANEL INNER & OUTER,REAR RH FENDER,REAR LUGGAGE PANEL,RH CHASSIS FRAME;KNOCKING & REPAIR REAR LH FENDER,REAR FLOORBOARD,REAR RH DOOR,JACK & REALIGN STRUCTURE THE SAME	2,600.00	1 LA	2,600.00	2000
79 PUTTY & RESPRAY REAR BUMPER,TAILGATE,BOTH REAR FENDERS,REAR END PANEL,REAR LUGGAGE PANEL,FLOORBOARD,REAR RH DOOR,REAR CHASSIS FRAMES & ALL AFFECTED AREAS	1,800.00	1 LA	1,800.00	1400
80 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
81 REMOVE & REFIX REAR RH FENDER QUARTER GLASS	60.00	1 LA	60.00	X
82 REMOVE & REFIX REVERSE CAMERA,RESET & REPOSITION	80.00	1 PC	80.00	✓
83 REMOVE & REFIX REAR MUFFLER,MID PIPE & REALIGN THE SAME	150.00	1 LA	150.00	100
84 REMOVE & REFIX BOTH ENGINE MOUNTINGS & REALIGN THE SAME	120.00	1 LA	120.00	80
85 REMOVE & REFIX REAR SEAT,CUSHION,CARPET TO FACILITATE REPAIR	120.00	1 LA	120.00	X
86 REMOVE & REFIX REAR UNDERCARRIAGE,AXLE & REALIGN THE SAME	300.00	1 LA	300.00	X
87 TO MOUNT ON CAR-O-LINER,JACK & STRAIGHTEN CHASSIS	250.00	1 LA	250.00	✓
88 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	X
89 TO CLEAR & RESET FAULT CODE	150.00	1 LA	150.00	100
90 RUSTPROOFING	240.00	1 LA	240.00	150
			8,000.00	8,000.00

6020

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6805A
Vehicle Details	
Vehicle No.:	SJL2414U
Vehicle to be Exported:	Yes
Intended De-registration Date:	13 Jan 2018
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8X A
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	R18A1776390
Chassis No.:	RN61068974
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$20,687.00
Original Registration Date:	20 Nov 2008
First Registration Date:	20 Nov 2008
Transfer Count:	1
Actual ARF Paid:	\$20,687.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Nov 2018
PARF Rebate Amount:	\$10,343.00
Intended COE Rebate Details	
COE Expiry Date:	19 Nov 2018
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$8,301.00
COE Rebate Amount:	\$705.00
Total Rebate Amount:	\$11,048.00

The information contained herein is correct as at 13 Jan 2018

OK

https://vrl.lta.gov.sg/lta/vrl/action/enquireRebateByPublicBeforeDeregInput?FUNCTION_ID... 13/01/2018

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE

How much is my car worth?



honda stream

Price Range

Depreciation

2008

Vehicle Type

Submit

Home » Used Cars » Dickson Automobile » Honda Stream 1.8A

Tools & Tips

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

Honda Stream 1.8A

Overview

Financial

Accessories

Similar

Research

Photos

Map



DICKSON AUTOMOBILE PTE LTD

A member of DICKSON AUTO GROUP

Established since 1986



Add to Shortlist

Add to Compare

Add a Note


Report Error

More Actions

Share

Car Details

Price	\$21,800	
Depreciation	\$10,800 /yr View models with similar depreciation	1
Reg Date	24-Dec-2008 (11mths 10days COE left)	
Manufactured	2007	1
Mileage	-	
Transmission	Auto	
Engine Cap	1,799 cc	
Road Tax	\$978 /yr	1
Power	103.0 kW (138 bhp) View specs of the Honda Stream (2007-2014)	
Curb Weight	1,350 kg	1
Features	1.8L I-VTEC Engine, 5 Speed Automatic Transmission, SRS Airbags, Auto Climatic Aircon Control, Knockdown Rear Seats.	
Accessories	Sport Rims, Sony Car Stereo System, Door Vipers, Solar Film, Electrical Retractable Side Mirrors With Indicator, Upholstery Leather Seats.	
Description	Interest Rate From 1.99% Only! Nice 3 Digit Number Plate! Low Mileage! Extended Warranty Available! Well Maintained MPV In Superb Condition, Drive And Feel It For Yourself! Buy It From Us With A Peace Of Mind, A Company Accredited With Outstanding Awards, Professional After Sales Service Assured. Drop By Our Air-con Showroom To Appreciate It In Pristine Condition Today!	
COE	\$2,658	1
OMV	\$23,245	1
ARF	\$23,245	1
Deery Value	\$11,873 as of today (change)	1
No. of Owners	2	1



Seller Information

Company	Dickson Automobile + dealer's proclat + 79 vehs sold 260 ve
Address	55 Ubi Avenue 3 #01-0 Search cars nearby this
Website	dicksonauto.com.sg
Office No	68447667
Contact Person(s)	Tank Ong Ricky Eng Eric Lee



Compare

Attn: Martin

1/3

HONDA STREAM

RN61068974

2008

GTL2414JA

PARTS	COST	LIST
1pc fit bumper Bu ✓		
1pc — w — reinforcement Bt —		
1pc — w — lower centre grille ?		
2pcs — w — side containers DIL		
6PCS — w — CHIPS M —		
1PC Bonnet Bu —		
1PC — w — innerlock DIL		
2PCS — w — hinges RX		
1PC — w — inner top rubber Sx1		
1PC — w — innerlock outer cover KPL		
1PC ABS Fit grille CM —		
1PC — w — moulding CM —		
1PC — w — logo M —		
4PCS — w — CHIPS M —		
2PCS HEADLAMPS CM —		
2PCS — w — lower brackets CM —		
2PCS Horns ?		
1pc fit lower engine under cover Sx		
1PC A/C CONDENSOR Bt/M ✓		
1PC — w — discharge hose ?		
1PC — w — discharge hose ?		
1PC RADIATOR ?		
1PC fit air bag sensor ?		

CHENG HOE MOTOR PTE LTD

10 ANG MO KIO IND PARK 2A

#01-04 AMK AUTOPOINT

SINGAPORE 568047

TEL: 6481 2001 FAX: 6482 1298

EMAIL: chmank@singnet.com.sg

2/3

CHENG HOE MOTOR PTE LTD
10 ANG MO KIO IND PARK 2A
#01-04 AMK AUTOPOINT
SINGAPORE 568047
TEL: 6481 2001 FAX: 6482 1296
EMAIL: chmamk@singnet.com.sg

SJ224148U

PARTS		COST	LIST
1PC Rear end panel (inner)	B1		
1PC — — — (outer)	B1		
1PC — — — inner top garnish	A1		
1PC — — — inner centre garnish	?		
1PC Rear RH fender	RX		
1PC — — — glass	WVX		
1PC — — — moulding	WVX		
2PCS Rear fender inner trim	B1		
1PC SPARE TYRE HOLDER ASSY	B1		
1PC Rear exhaust muffler	B1		
1PC — — — heat shield	?		
2PCS — — — rubber mountings	T1		
1PC Exhaust mid pipe	B1		
1PC Rear RH chassis frame	R7		
1PC Rear luggage compartment panel	?		
1PC — — — inner centre garnish (18)	Ch		
2PCS — — — side top boards	?		
1PC — — — tow sponge (12) (5, 18)	?		
2PCS THIRD ROW SEAT ASSY.	?		
1PC Fuel tank RH side heatshield	?		

CHENG HOE MOTOR PTE LTD
 10 ANG MO KIO IND PARK 2A
 #01-04 AMK AUTOPOINT
 SINGAPORE 568047
 TEL: 6481 2001 FAX: 6482 1298
 EMAIL: chmamk@singnet.com.sg

LABOURS	COST
Putty & Respray rear bumper, tailgate, both rear fenders, rear end panel, rear luggage panel, floorboard, rear RH Door, rear chassis frames & all affected areas.	2000 1800h 1600
R & R rear wls glass	120h ✓
R & R rear RH fender & glass	60h x
R & R reverse camera, reset & realign the same.	80h ✓
R & R rear muffler, mid pipe & realign the same.	150h 100
R & R both engine mountings & realign the same	120h ?
R & R rear seat, cushion, carpet to facilitate repair	120h 100
R & R rear w/carrriage, axle & realign the same	300h ?
To mount on car- o-liner.	250h ✓
To conduct ramp wheel alignment.	60h ✓
To clear & reset fault code	150h ?
Rustproofing	240h 150

<u>LABOURS</u>			<u>COST</u>
SN:	1pc FH no plate	B ₃	35 —
	1pc Rear no plate	B ₂	35 —
	1set Reverse Sensors	cm	200 —
	1 unit Reverse Camera		350 ?
	1 unit COOLANT	m	35 2asn
	1 unit Rear w/b glass sealant	m	40 —
	1 unit Rear RH fender glass sealant	m	40 x
	1 unit Rear luggage panel top coat		100 ?
	1 unit Rear RH fender A glass tinted-film	m	100 100 x
Towing			600 500
R & R A/c condensor, vacuum & refill gas			1000 —
R & R fit bumper, bonnet & attachments, grille, fit fenders, head lamps, cut, weld & r fit support panel, K & R for chassis & realign the same.			9000 6500
Putty & respray fit bumper, bonnet, both fenders, fit support panel & all affected areas.			9000 8000
R & R rear bumper tailgate & attachments, taillamps, cut, weld & r rear end panel inner & outer, rear RH fender, rear luggage panel, RH chassis frame, K & R rear LH fender, rear floorboard, jack & realign structure the same.			20000
rear RH door			26000

View Received Message

This mail is associated with :

***SJL2414U (2100713479SG)
[SKN5668L]**

TP
SHAFI MOHAMED SHAJAHAN
Jan 13 2018 11:00AM
[MOVA AUTOMOTIVE PTE LTD]
Cheng Hoe Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 03/12/2018 09:30 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$13958.00) - SJL2414U - Claim Handler: Wui, Shawn-KJ

Approved:13958.00.

DOCUMENTS SUMMARY

There are no documents.

PAYMENT ADVICE

Your Ref : AIG Vehicle no.	: SLK9092A
Claimant Vehicle No.	: SJL2414U
Date of Accident	: 13/01/2018
Traffic Accident involving vehicle/s No.	: JURONG WEST AVE 2

BREAKDOWN OF PAYMENT/S

<u>S/No.</u>	<u>Items</u>	<u>Amount</u>	<u>Remark</u>
1	Repair cost	\$ 10,700.00	
2	Loss of Rental	\$ 3,250.00	\$130 x 25 days
3	LTA Search	\$ 8.00	
TOTAL		\$ 13,958.00	

All payment should be made payable to Cheng Hoe Motor Pte Ltd.

Service Adviser : LKK
Contact No. : 6256 3561



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC4/AIG18000871/Kws3

23 JANUARY 2018

MOVA AUTOMOTIVE PTE LTD
BLK 408B FERNVALE LANE
#08-141
SINGAPORE 792404

Dear Sir/Madam,

ACCIDENT INVOLVING SKN 5668L / SLK 9092A / OTHERS ON 13.01.2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,

Siti Jaafar
Case Handler
DID: 6256 3561
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

AUTHORIZATION TO ACT
(AIG Asia Pacific - EXPRESS THIRD PARTY CLAIM)

I, Shafi Mohamed Shajahan (the third party claimant) of Blk 588D Ang Mo Kio St 52
#15-235 S564588 (address), owner of SJL2414U (vehicle no.)
hereby authorize CHENG HOE MOTOR PTE LTD ("the workshop") to act for me
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle
no. SJL2414U that was damaged pursuant to the accident which occurred on 13/01/2018
(date) along Jurong West Ave 2 (location) involving vehicle no/s
SLK9092A & SKN 5668 L ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 13 (day) of Jan (month) 2018 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

RELEASE VOUCHER

(AIG Asia Pacific - EXPRESS THIRD PARTY CLAIM)

"We/I, CHENG HOE MOTOR PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$10700.00 (Repair Cost), S\$3250.00 (Loss of Rental), S\$8.00 (Disbursement), for vehicle no SJL2414U that was damaged pursuant to the accident which occurred 13/01/2018 (date) along Jurong West Ave 2 (location) involving vehicle no/s SLK9092A. This is pursuant to the inspection conducted on 15/01/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Shafi Mohamed Shajahan ("the third party claimant") of vehicle no. SJL2414U make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage SJL2414U (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 3 (day) of 12 (month) 2018 (year)

LSC


Signed by appointed surveyor



Signed by "the workshop" (with chop)

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

TAX INVOICE

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

NO: CL8180911
Date: 21 Aug 2018
Policy No: MPC17A00239101
Veh Reg No: SJL2414U
Make/Model: HONDA STREAM 1.8 X
AUTO
Job No: JC1598105

WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 13/01/2018
TP Veh Reg No: SLK9092A

Description

To Supply all replaced parts, all necessary and agreed labour &
miscellaneous charges.
(As recommended by your appointed surveyor)

Quantity

1 PC

List Price

SS
SS 10,000.00

PAGE:1

Amount

SS
SS 10,000.00

Total SS 10,000.00
Add GST @ 7% 700.00
Total Amount payable SS 10,700.00

For Cheng Hoe Motor Pte Ltd



E. & O. E.

AUTHORISED SIGNATURE



專營運務必甲出租
汽車修理
汽車保險賠償服務
高貴多授權服務中心

國家汽車服務 NATIONAL AUTOMOBILE SERVICE

Block 5033, Ang Mo Kio Industrial Park 2, #01-279
(off Ang Mo Kio Avenue 3) Singapore 569536
TEL: 6482 5577 (3 Lines) FAX: 6482 5000
TOWING SERVICE: 9182 8211 (After 10.30pm)
Reg. No: 062389/00M



TRUCK RENTAL
MOTOR REPAIR
INSURANCE CLAIMS
AGENCY
AUTHORISED CASTROL
SERVICE CENTRE

車輛出租合同 VEHICLE RENTAL AGREEMENT

Date: 13/11/18
Owner: NATIONAL AUTOMOBILE SERVICE ("the owner")
Hirer: Shafi Mohamed Shajahan
Address: B1K 5880 Ang Mo Kio St 52 #15-235 S564588
NRIC / Co. Reg. No: S7276805A
Tel: Fax: H/P: 98206553

Owner and Hirer have agreed to enter into this Vehicle Rental Agreement for the motor vehicle described below and upon the terms and conditions contained on both sides of this document. Hirer acknowledges having read and understood all the terms and conditions and signifies acceptance upon signing.

Vehicle Reg. No: SJL 90X6 R		Agreement No.: 56387	
Driver's Particulars			
Name: as above		Odometer:	
Address:		Date & Time Out: 13/11/18 @ 1.40 PM	
		Date & Time In: 09/02/19 @ 6.35 PM	
IC No: S7276805A	Dr/Licence No: S7276805A	Hour @\$	
Date of Issue: 18/10/1997	Occupation: self employed	25 Days @\$ 1301	
Date of Birth: 31/10/1972	Tools: o/w	Wks @\$	
	Spare Tyre: one set	Mths @\$	

Third Party Claim

In respect of each third party insurance claim arising from the date of hire to date of return of the vehicle (both dates inclusive), Hirer unconditionally agrees to pay Owner \$5,000.00 comprising excess payable and compensation to Owner for impact of claim on future motor insurance premiums.

Own Vehicle Damage

Hirer is responsible for the first \$3,000.00 excess for collision/damage to first party, (i.e.) NATIONAL AUTOMOBILE SERVICE (including windscreen) plus loss of earnings while damaged vehicle is under repair.

Authorised Driver

Hirer shall pay additional excess of \$51500 if the Authorised Driver is below the age of 25 or is above 65 years old or has less than 2 years driving experience.

Driver Not Cover By Insurance

General Exception: Insurance policy does not cover against any driver aged below 22 and/or above 70 years old and/or with driving experience of 1 year and below.

Deposit (Refundable):

Sub-Total:

Balance To Pay: 32501

PETROL/DIESEL AT YOUR OWN EXPENSE
FOR LOCAL USE ONLY

NATIONAL AUTOMOBILE SERVICE

Authorised Signature

Hirer's Signature



國家汽車服務
NATIONAL AUTOMOBILE SERVICE

Block 5033, Ang Mo Kio Industrial Park 2 #01-279
Singapore 569536 Tel: 6482 5577 (3 Lines) Fax: 6482 5000

正式收據
OFFICIAL RECEIPT

DATE: 20/2/18

茲收到

RECEIVED FROM:

Shafi Mohamed Shajahan

銀額

AMOUNT:

Three Thousand Two Hundred & Fifty only

BEING PAYMENT OF: 係對還

(SUBJECT TO CHEQUE CLEARANCE)

rental of SUV 9076 R.

此收據必須候支票過賬之後始屬有效。

from 13/1/18 to 7/2/18

\$

CASH/CHEQUE

現銀 / 支票

3250/-

NATIONAL AUTOMOBILE SERVICE

✓

A.C. SYED & PARTNERS

ADVOCATES & SOLICITORS

COMMISSIONER FOR OATHS

101A UPPER CROSS STREET, #13-23 PEOPLE'S PARK CENTRE, SINGAPORE 058358

TEL : 6538 7411 & FAX : 6534 1011

TO : CHENG HOE MOTOR PTE LTD		BILL NO: B018 / 2018																																																																																																				
YOUR REF:																																																																																																						
OUR REF : ACS.CH.LTA.2018 (JAN 2018)		DATE : 5/2/18																																																																																																				
TO OUR PROFESSIONAL CHARGES for acting for you in the above matter including where necessary perusals, attendance preparation examination of documents relating thereto: correspondence, attendance, perusals, telephone calls, searches and all other incidental works not specifically mentioned herein to enable us to carry out the work entrusted to us inclusive of all advice.																																																																																																						
LTANET SEARCHES FOR THE MONTH JAN 2018 <table border="1"><thead><tr><th>S/NO</th><th>TP NO.</th><th>CHM</th><th>DOA</th></tr></thead><tbody><tr><td>1</td><td>2/1/2018</td><td>SJS7547A</td><td>GY5366Y 30/12/2017</td></tr><tr><td>2</td><td>2/1/2018</td><td>SKL4956Y</td><td>SJR4742C 29/12/2017</td></tr><tr><td>3</td><td>2/1/2018</td><td>SKQ6059Y</td><td>SKW7049M 1/1/2018</td></tr><tr><td>4</td><td>3/1/2018</td><td>SKE1673U</td><td>SJR2885L 3/1/2018</td></tr><tr><td>5</td><td>3/1/2018</td><td>YP6455B</td><td>SJU4191B 30/12/2017</td></tr><tr><td>6</td><td>3/1/2018</td><td>SGF3587P</td><td>SJG2424S 27/12/2017</td></tr><tr><td>7</td><td>3/1/2018</td><td>SKU8016L</td><td>SKS1610C 30/12/2017</td></tr><tr><td>8</td><td>5/1/2018</td><td>GBC1376U</td><td>SLP6769A 4/1/2018</td></tr><tr><td>9</td><td>8/1/2018</td><td>SKD5999J</td><td>SJJ4139L 6/1/2018</td></tr><tr><td>10</td><td>8/1/2018</td><td>GBF1775K</td><td>SLP3471C 5/1/2018</td></tr><tr><td>11</td><td>8/1/2018</td><td>SFM9595B</td><td>SJR592U 30/12/2017</td></tr><tr><td>12</td><td>8/1/2018</td><td>FBL3571L</td><td>SLH9325U 5/1/2018</td></tr><tr><td>13</td><td>11/1/2018</td><td>SFY4710E</td><td>SCZ1001T 10/1/2018</td></tr><tr><td>14</td><td>11/1/2018</td><td>GBB2710L</td><td>GBG5663T 11/1/2018</td></tr><tr><td>15</td><td>12/1/2018</td><td>SLJ4826M</td><td>SGY1911A 11/1/2018</td></tr><tr><td>16</td><td>12/1/2018</td><td>YL6367T</td><td>SKF9455A 9/1/2018</td></tr><tr><td>17</td><td>12/1/2018</td><td>GBC4242C</td><td>SJZ3236L 22/12/2017</td></tr><tr><td>18</td><td>13/1/2018</td><td>SKN5668L</td><td>SJL2414U 13/1/2018</td></tr><tr><td>19</td><td>14/1/2018</td><td>SJX1232X</td><td>SLF4986E 11/1/2018</td></tr><tr><td>20</td><td>14/1/2018</td><td>GU4511Y</td><td>SJX9477D 11/1/2018</td></tr><tr><td>21</td><td>14/1/2018</td><td>SLK1743H</td><td>SJF4726M 11/1/2018</td></tr><tr><td>22</td><td>14/1/2018</td><td>SJQ8960T</td><td>SJK2043L 11/1/2018</td></tr><tr><td>23</td><td>15/1/2018</td><td>SLG964P</td><td>GBG821L 10/1/2018</td></tr><tr><td>24</td><td>15/1/2018</td><td>SKP8802K</td><td>SJU8089M 13/1/2018</td></tr></tbody></table>			S/NO	TP NO.	CHM	DOA	1	2/1/2018	SJS7547A	GY5366Y 30/12/2017	2	2/1/2018	SKL4956Y	SJR4742C 29/12/2017	3	2/1/2018	SKQ6059Y	SKW7049M 1/1/2018	4	3/1/2018	SKE1673U	SJR2885L 3/1/2018	5	3/1/2018	YP6455B	SJU4191B 30/12/2017	6	3/1/2018	SGF3587P	SJG2424S 27/12/2017	7	3/1/2018	SKU8016L	SKS1610C 30/12/2017	8	5/1/2018	GBC1376U	SLP6769A 4/1/2018	9	8/1/2018	SKD5999J	SJJ4139L 6/1/2018	10	8/1/2018	GBF1775K	SLP3471C 5/1/2018	11	8/1/2018	SFM9595B	SJR592U 30/12/2017	12	8/1/2018	FBL3571L	SLH9325U 5/1/2018	13	11/1/2018	SFY4710E	SCZ1001T 10/1/2018	14	11/1/2018	GBB2710L	GBG5663T 11/1/2018	15	12/1/2018	SLJ4826M	SGY1911A 11/1/2018	16	12/1/2018	YL6367T	SKF9455A 9/1/2018	17	12/1/2018	GBC4242C	SJZ3236L 22/12/2017	18	13/1/2018	SKN5668L	SJL2414U 13/1/2018	19	14/1/2018	SJX1232X	SLF4986E 11/1/2018	20	14/1/2018	GU4511Y	SJX9477D 11/1/2018	21	14/1/2018	SLK1743H	SJF4726M 11/1/2018	22	14/1/2018	SJQ8960T	SJK2043L 11/1/2018	23	15/1/2018	SLG964P	GBG821L 10/1/2018	24	15/1/2018	SKP8802K	SJU8089M 13/1/2018
S/NO	TP NO.	CHM	DOA																																																																																																			
1	2/1/2018	SJS7547A	GY5366Y 30/12/2017																																																																																																			
2	2/1/2018	SKL4956Y	SJR4742C 29/12/2017																																																																																																			
3	2/1/2018	SKQ6059Y	SKW7049M 1/1/2018																																																																																																			
4	3/1/2018	SKE1673U	SJR2885L 3/1/2018																																																																																																			
5	3/1/2018	YP6455B	SJU4191B 30/12/2017																																																																																																			
6	3/1/2018	SGF3587P	SJG2424S 27/12/2017																																																																																																			
7	3/1/2018	SKU8016L	SKS1610C 30/12/2017																																																																																																			
8	5/1/2018	GBC1376U	SLP6769A 4/1/2018																																																																																																			
9	8/1/2018	SKD5999J	SJJ4139L 6/1/2018																																																																																																			
10	8/1/2018	GBF1775K	SLP3471C 5/1/2018																																																																																																			
11	8/1/2018	SFM9595B	SJR592U 30/12/2017																																																																																																			
12	8/1/2018	FBL3571L	SLH9325U 5/1/2018																																																																																																			
13	11/1/2018	SFY4710E	SCZ1001T 10/1/2018																																																																																																			
14	11/1/2018	GBB2710L	GBG5663T 11/1/2018																																																																																																			
15	12/1/2018	SLJ4826M	SGY1911A 11/1/2018																																																																																																			
16	12/1/2018	YL6367T	SKF9455A 9/1/2018																																																																																																			
17	12/1/2018	GBC4242C	SJZ3236L 22/12/2017																																																																																																			
18	13/1/2018	SKN5668L	SJL2414U 13/1/2018																																																																																																			
19	14/1/2018	SJX1232X	SLF4986E 11/1/2018																																																																																																			
20	14/1/2018	GU4511Y	SJX9477D 11/1/2018																																																																																																			
21	14/1/2018	SLK1743H	SJF4726M 11/1/2018																																																																																																			
22	14/1/2018	SJQ8960T	SJK2043L 11/1/2018																																																																																																			
23	15/1/2018	SLG964P	GBG821L 10/1/2018																																																																																																			
24	15/1/2018	SKP8802K	SJU8089M 13/1/2018																																																																																																			
sub-total c/f		S 192.00																																																																																																				
M/s. A C SYED & PARTNERS ADVOCATES & SOLICITORS SINGAPORE We reserved the right to forward a subsequent bill for any disbursements omitted herein. E. & O.E.																																																																																																						

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Jan 2018 Edit Reg		15 Jan 2018 00:00 Edit Adj Rpt	S\$10,000.00 Edit Estimates	S\$10,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: MOVA AUTOMOTIVE PTE LTD , Co. Reg. No.: 198904033G									
Main Claimant: SHAFI MOHAMED SHAJAHAN , ID: S7276805A									
Vehicle Reg. No.: SJL2414U		Date of Loss: 13/01/2018 11:00 - :59 [109 Months and 24 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 2100713479SG		Policy/Cover Note No.: 0999995097 (Comprehensive)							
Vehicle Reg. No. (Insured): SKN5668L		Policy No. (Claimant): MPC17A00239101							
		Excess:							
Repairer: Cheng Hoe Motor Pte Ltd (AMK) 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT, 568047 Ang Mo Kio - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ] Shawnkaijye.Wui@aig.com									
Claimant's Insurer: ECICS Limited (HQ) - Tel: 63374779 /6303 0178									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 24/01/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (03/12/2018): Alert - Adj Mandate Approved (S\$13958.00) - SJL2414U - Claim Handler: Wui, Shawn... - AIG_SG (16/01/2018): Request for TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJL2414U (2100713479SG)
[SKN5668L]
TP
SHAFI MOHAMED SHAJAHAN
Jan 13 2018 11:00AM
[MOVA AUTOMOTIVE PTE LTD]
Cheng Hoe Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		☐	☒		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	(Draft)	Third Party Express Settlement – Payment Breakdown													Edit					
Assessment Reports															1 per page		☐	☒		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print				
1	16/01/18 16:45	Accident Statement From:OD - Reg. No: SKN5668L, Claimant: MOVA AUTOMOTIVE PTE LTD													Load HTM					
Photos/Images															3 per page		☐	☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	13/08/18 14:55	General View													Load JPG	☒				
2	13/08/18 14:55	General View													Load JPG	☒				
3	13/08/18 14:55	General View													Load JPG	☒				
4	13/08/18 14:55	General View													Load JPG	☒				
5	13/08/18 14:55	General View													Load JPG	☒				
6	13/08/18 14:55	General View													Load JPG	☒				
7	13/08/18 14:55	General View													Load JPG	☒				
8	13/08/18 14:55	General View													Load JPG	☒				
9	13/08/18 14:55	General View													Load JPG	☒				
10	13/08/18 14:55	General View													Load JPG	☒				
11	13/08/18 14:55	General View													Load JPG	☒				
12	13/08/18 14:55	General View													Load JPG	☒				
13	13/08/18 14:55	General View													Load JPG	☒				
14	13/08/18 14:55	General View													Load JPG	☒				
15	13/08/18 14:55	General View													Load JPG	☒				
16	13/08/18 14:55	General View													Load JPG	☒				
17	13/08/18 14:55	General View													Load JPG	☒				
18	13/08/18 14:55	General View													Load JPG	☒				
19	13/08/18 14:55	General View													Load JPG	☒				
20	13/08/18 14:55	General View													Load JPG	☒				
21	13/08/18 14:55	General View													Load JPG	☒				
22	13/08/18 14:55	General View													Load JPG	☒				
23	13/08/18 14:55	General View													Load JPG	☒				
24	13/08/18 14:55	General View													Load JPG	☒				
25	13/08/18 14:55	General View													Load JPG	☒				
26	13/08/18 14:55	General View													Load JPG	☒				
27	13/08/18 14:55	General View													Load JPG	☒				
28	13/08/18 14:55	General View													Load JPG	☒				
29	13/08/18 14:55	General View													Load JPG	☒				
30	13/08/18 14:55	General View													Load JPG	☒				

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	13/08/18 14:55	General View		☒
32	13/08/18 14:55	General View		☒
33	13/08/18 14:55	General View		☒
34	13/08/18 14:55	General View		☒
35	13/08/18 14:55	General View		☒
36	13/08/18 14:55	General View		☒
37	13/08/18 14:55	General View		☒
38	13/08/18 14:55	General View		☒
39	13/08/18 14:55	General View		☒
40	13/08/18 14:55	General View		☒
41	13/08/18 14:55	Reinspection Photo		☒
42	13/08/18 14:55	Reinspection Photo		☒
43	13/08/18 14:55	Reinspection Photo		☒
44	13/08/18 14:55	Reinspection Photo		☒
45	13/08/18 14:55	Reinspection Photo		☒
46	13/08/18 14:55	Reinspection Photo		☒
47	13/08/18 14:55	Reinspection Photo		☒
48	13/08/18 14:55	Reinspection Photo		☒
49	13/08/18 14:55	Reinspection Photo		☒
50	13/08/18 14:55	Reinspection Photo		☒
51	13/08/18 14:55	Reinspection Photo		☒
52	13/08/18 14:55	Reinspection Photo		☒
53	13/08/18 14:55	Reinspection Photo		☒
54	13/08/18 14:55	Reinspection Photo		☒
55	13/08/18 14:55	Reinspection Photo		☒
56	13/08/18 14:55	Reinspection Photo		☒
57	13/08/18 14:55	Reinspection Photo		☒
58	13/08/18 14:55	Reinspection Photo		☒
59	13/08/18 14:55	Reinspection Photo		☒
60	13/08/18 14:55	Reinspection Photo		☒
61	13/08/18 14:55	Reinspection Photo		☒
62	13/08/18 14:55	Reinspection Photo		☒
63	13/08/18 14:55	Reinspection Photo		☒
64	13/08/18 14:55	Reinspection Photo		☒
65	13/08/18 14:55	Reinspection Photo		☒
66	13/08/18 14:55	Reinspection Photo		☒
67	13/08/18 14:55	Reinspection Photo		☒
68	13/08/18 14:55	Reinspection Photo		☒
69	13/08/18 14:55	Reinspection Photo		☒
70	13/08/18 14:55	Reinspection Photo		☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/01/18 17:21	EMAIL FROM WORKSHOP DD 15.01.2018		☐
2	15/01/18 17:21	ACKNOWLEDGEMENT EMAIL TO AIG DD 15.01.2018		☐
3	17/01/18 11:54	TP GIA REPORT		☐
4	17/01/18 11:54	TP ESTIMATE INCOMPLETE (PARTS ITEM)		☐
5	24/01/18 10:01	LETTER TO OI		☐
6	23/11/18 17:54	RENTAL RECEIPT		☐
7	23/11/18 17:54	LTA SEARCH		☐
8	27/11/18 17:18	Email to AIG to seek mandate SJL 2414U		☐
9	30/11/18 09:18	LTA REBATE		☐

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
10	06/12/18 08:57	WORKSHOP INVOICE	 Load PDF	
11	06/12/18 08:57	AUTHORISATION TO ACT FORM	 Load PDF	
12	06/12/18 08:57	Release Voucher	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SKN5668L (Insd veh)	Model:	HONDA STREAM 1.8 X (A)
	SJL2414U (TP veh)		
Date of Accident:	13/01/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	24,794.17
Final Repair Cost	:	\$	10,700.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	3,250.00 25 days
LTA / GIA Search Fee	:	\$	8.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	13,958.00

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No —BOLA Scenario No: _____
	_____28_____
BOLA Liability: _____100_____ (%)	Assessed Liability (*): _____100_____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____	

Payment Instruction: Payee's Breakdown			
1)	Cheng Hoe Motor Pte Ltd	:	\$ 13,958.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

06 Dec
2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18000871/KWA3Q2

Date: 06/12/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999995097
 Claimant Vehicle No: SJL2414U Insured Vehicle No: SKN5668L
 Date of Loss: 13/01/2018 Nature of Claim: TP Claim No: 2100713479SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJL2414U**
 Make & Model: HONDA STREAM, 1.8 X (A) Engine No: R18A1776390
 Reg. Date: 20/11/2008 (Man. Year: 2008) Chassis No: RN61068974
 Colour: White Odometer: 122800 km
 Engine Capacity: 1799 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R15 Rear Tyre Size: 205/65 R15
 Front Left Side: Maxxis 9 mm Rear Left Side: Yokohama 3 mm
 Front Right Side: Maxxis 9 mm Rear Right Side: Yokohama 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,172.12	11,821.36	3,350.76	22.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,000.00	5,980.00	2,020.00	25.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,172.12	17,801.36	5,370.76	23.18
Approved Total (Overridden) (S\$)		10,000.00		
(S\$)	23,172.12	10,000.00	13,172.12	56.84
+ GST 7.00/7.00% (S\$)	1,622.05	700.00	922.05	56.84
Nett Amount (S\$)	24,794.17	10,700.00	14,094.17	56.84
+ Car Rental (25.0 x S\$130.00/day) (S\$)		3,250.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		13,958.00		

INSPECTION

Date of Assignment: 15/01/2018
 Date Inspected: 15/01/2018 Inspected At:

Cheng Hoe Motor Pte Ltd (AMK)
 10 ANG MO KIO IND PARK 2A, #01-04

ANG MO KIO AUTOPOINT
Singapore 568047

Estimated Period of Repair: 20.0 days

Adjuster: KENNETH KONG

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	635.40 FL	*635.40 FL
2	1		*FRONT BUMPER REINFORCEMENT	Bent	218.40 FL	*218.40 FL
3	1		*FRONT BUMPER LOWER CENTRE GRILLE	Distorted	85.60 FL	*85.60 FL
4	2		*FRONT BUMPER SIDE RETAINER	Distorted	36.00 FL	*36.00 FL
5	6		*FRONT BUMPER CLIP	Necessary	22.20 FL	*22.20 FL
6	1		*BONNET	Buckled	638.50 FL	*638.50 FL
7	1		*BONNET INNER LOCK	Bent	85.60 FL	*85.60 FL
8	2		*BONNET HINGE	Repair	77.80 FL	*- FL
9	1		*BONNET INNER TOP RUBBER	Cut	19.40 FL	*19.40 FL
10	1		*BONNET INNER LOCK OUTER COVER	Dented	20.30 FL	*20.30 FL
11	1		*FRONT GRILLE	Cracked	202.60 FL	*202.60 FL
12	1		*FRONT GRILLE MOULDING	Cracked	210.50 FL	*210.50 FL
13	1		*BONNET GRILLE LOGO	Necessary	24.70 FL	*24.70 FL
14	4		*FRONT GRILLE CLIP	Necessary	14.80 FL	*14.80 FL
15	2		*HEADLAMP	Cracked	1,360.80 FL	*1,360.80 FL
16	2		*HEADLAMP LOWER BRACKET	Cracked	73.60 FL	*73.60 FL
17	2		*HORN	Dented	80.20 FL	*80.20 FL
18	1		*FRONT LOWER ENGINE UNDER COVER	Cracked	85.40 FL	*85.40 FL
19	1		*AIR-CON CONDENSER	Punctured	840.10 FL	*840.10 FL
20	1		*AIR-CON CONDENSER SUCTION HOSE	Bent	105.90 FL	*105.90 FL
21	1		*AIR-CON CONDENSER DISCHARGE HOSE	Bent	235.90 FL	*235.90 FL
22	1		*RADIATOR	Punctured	1,507.30 FL	*1,507.30 FL
23	1		*FRONT AIRBAG SENSOR	Damaged	189.80 FL	*189.80 FL
24	1		*FRT SUPPORT PANEL	Buckled	466.20 FL	*466.20 FL
25	1		*FRONT SUPPORT PANEL INNER TOP GARNISH	Distorted	48.60 FL	*48.60 FL
26	6		*FRONT SUPPORT PANEL INNER TOP GARNISH CLIP	Necessary	22.20 FL	*22.20 FL
27	1		*ENGINE RH MOUNTING	Cracked	291.70 FL	*291.70 FL
28	1		*GEARBOX MOUNTING	Cracked	230.40 FL	*230.40 FL
29	2		*FRONT FENDER	Repair	972.40 FL	*- FL
30	12		*FRONT FENDER INNER SHIELD CLIP	Not Necessary	44.40 FL	*- FL
31	1		*REAR BUMPER	Bent	588.90 FL	*588.90 FL
32	1		*REAR BUMPER TOW HOOK COVER	Dented	14.30 FL	*14.30 FL
33	2		*REAR BUMPER SIDE RETAINER	Distorted	43.80 FL	*43.80 FL
34	6		*REAR BUMPER CLIP	Necessary	22.20 FL	*22.20 FL
35	1		*REAR TAILGATE	Bent	903.50 FL	*903.50 FL
36	1		*TAILGATE INNER LOCK	Dented	119.40 FL	*119.40 FL
37	1		*TAILGATE INNER RUBBER (50%)	Cut	97.28 FS	*60.80 FS
38	1		*TAILGATE EMBLEM STERAM	Necessary	31.60 FL	*31.60 FL
39	1		*TAILGATE NUMBER PLATE LAMP GARNISH	Cracked	162.70 FL	*162.70 FL
40	2		*TAILGATE NO PLATE LAMP	Serviceable	65.60 FL	*- FL
41	1		*TAILGATE WINDSCREEN GLASS MOULDING	Necessary	65.00 FL	*65.00 FL
42	1		*TAILGATE INNER HANDLE	Missing	21.90 FL	*21.90 FL
43	1		*TAILGATE INNER TRIM BOARD	Buckled	141.90 FL	*141.90 FL
44	2		*TAILGATE INNER SIDE TRIM	Serviceable	80.40 FL	*- FL
45	2		*TAILLAMP	Cracked	704.80 FL	*704.80 FL
46	1		*RH TAILLAMP PANEL	Bent	145.30 FL	*145.30 FL
47	1		*REAR END PANEL (INNER)	Bent	95.50 FL	*95.50 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
48	1		*REAR END PANEL (OUTER)	Bent	306.50 FL	*306.50 FL
49	1		*REAR END PANEL INNER GARNISH (TOP & CENTRE)	Dented	116.70 FL	*116.70 FL
50	1		*REAR RH FENDER	Repair	858.30 FL	*- FL
51	1		*REAR RH FENDER QUARTER GLASS	Not Necessary	229.70 FL	*- FL
52	1		*REAR RH FENDER QUARTER GLASS MOULDING	Not Necessary	45.00 FL	*- FL
53	2		*REAR FENDER INNER TRIM	Deformed	394.80 FL	*394.80 FL
54	1		*SPARE TYRE HOLDER ASSY	Bent	148.70 FL	*148.70 FL
55	1		*REAR EXHAUST MUFFLER	Bent	514.70 FL	*514.70 FL
56	1		*REAR EXHAUST HEAT SHIELD	Dented	48.20 FL	*48.20 FL
57	2		*REAR EXHAUST RUBBER MOUNTING	Torn	34.00 FL	*34.00 FL
58	1		*EXHAUST MID PIPE	Bent	583.70 FL	*583.70 FL
59	1		*REAR RH CHASSIS FRAME	Repair	584.30 FL	*- FL
60	1		*REAR LUGGAGE COMPARTMENT PANEL	Bent / Buckled	1,062.20 FL	*1,062.20 FL
61	1		*REAR LUGGAGE COMPARTMENT PANEL INNER CENTRE GARNISH	Cracked	165.80 FL	*165.80 FL
62	2		*REAR LUGGAGE COMPARTMENT SIDE TOP BOARD	Serviceable	260.80 FL	*- FL
63	1		*REAR LUGGAGE COMPARTMENT PANEL TOOL SPONGE	Serviceable	126.40 FL	*- FL
64	1		*FUEL TANK RH SIDE HEATSHIELD	Repair	141.50 FL	*- FL
65	1		*FRONT NUMBER PLATE	Bent	35.00 FS	*35.00 FS
66	1		*REAR NUMBER PLATE	Cracked	35.00 FS	*35.00 FS
67	1		*SET REVERSE SENSOR	Cracked	200.00 FS	*200.00 FS
68	1		*UNIT REVERSE CAMERA	Serviceable	350.00 FS	*- FS
69	1		*UNIT COOLANT	Necessary	35.00 FS	*20.00 FS
70	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
71	1		*REAR RH FENDER GLASS SEALANT	Not Necessary	40.00 FS	*- FS
72	1		*REAR LUGGAGE COMPARTMENT PANEL TOP COAT	Necessary	100.00 FS	*80.00 FS
73	1		*REAR RH FENDER QUARTER GLASS TINTED FILM	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 18,707.08 14,659.00
 - List Item Discount on L Items 20.00/20.00% (\$\$) 3,534.96 2,837.64

Total Parts (\$\$) 15,172.12 11,821.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	50.00	50.00
2	REMOVE AND REFIX AIRCON ,CHECK ,VACUUM & REFILL GAS	New	100.00	100.00
3	REMOVE & REFIX FRT BUMPER ,BONNET & ATTACHMENTS ,GRILLE ,FRT FENDERS ,HEADLAMPS TO CUT ,WELD & RENEW FRT SUPPORT PANEL ,KNOCKING & REPAIR FRT CHASSIS & REALIGN THE SAME	New	900.00	750.00
4	PUTTY & RESPRAY FRT BUMPER ,BONNET ,BOTH FENDERS ,FRT SUPPORT PANEL & ALL AFFECTED AREAS	New	900.00	800.00
5	REMOVE & REFIX REAR BUMPER ,TAILGATE & ATTACHMENTS ,TAILLAMPS ,TO CUT ,WELD & RENEW REAR END PANEL INNER & OUTER ,REAR RH FENDER ,REAR LUGGAGE PANEL ,RH CHASSIS FRMAE,KNOCKING & REPAIR REAR LH FENDE ,REAR FLOOR BOARD ,REAR RH DOOR ,JACK & REALIGN STRUCTURE THE SAME	New	2,600.00	2,000.00
6	PUTTY & RESPRAY REAR BUMPER ,TAILGATE ,BOTH REAR FENDERS ,REAR END PANEL,REAR LUGGAGE PANEL ,FLOORBOARD ,REAR RH DOOR ,REAR CHASSIS FRAMES & ALL AFFECTED AREAS	New	1,800.00	1,400.00
7	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
8	REMOVE & REFIX REAR RH FENDER QUARTER GLASS	New	60.00	0.00
9	REMOVE & REFIX REVERSE CAMERA ,RESET & REPOSITION	New	80.00	80.00
10	REMOVE & REFIX REAR MUFFLER ,MID PIPE & REALIGN THE SAME	New	150.00	100.00
11	REMOVE & REFIX BOTH ENGINE MOUNTINGS & REALIGN THE SAME	New	120.00	80.00
12	REMOVE & REFIX REAR SEAT ,CUSHION ,CARPET TO FACILITATE REPAIR	New	120.00	0.00
13	REMOVE & REFIX REAR UNDERCARRIAGE ,AXLE & REALIGN THE SAME	New	300.00	0.00
14	TO MOUNT ON CAR-O-LINER ,JACK & STRAIGHTEN CHASSIS	New	250.00	250.00
15	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	60.00	0.00
16	TO CLEAR & RESET FAULT CODE	New	150.00	100.00
17	RUSTPROOFING	New	240.00	150.00
Gross Labour Cost (\$\$)			8,000.00	5,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >