



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
FULCO RENT-A-CAR PTE LTD 22 Ubi Rd 4 Singapore 408617	Cust No/Name /Fulco Rent-A-Car Pte Ltd
Contact No Work: 67436266	Reg No/Reg Date SJH5349B / 13/08/2008
	Date In/Mileage / 0
	Chassis No JMYSRCY2A8U007704
	Engine No 4A910087622
	Make/Model MIT/LANCER EX 1.5 A/T BASIC (NEW)
	Colour/Trim A03 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00001	Cash	12/01/2018/ 13:59	DS	323 / ChrisBulaclac	50505
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
S MIPNT88088	REAR NUMBER PLATE WITH CASING / BT				50.00
S MIPNT88088	TO REPLACE REAR END PNL, REAR REINFORMENT, REAR BUMPER ETC STRAIGHTEN, (600) PERFORM, ALIGN ON REPAIR ACCIDENT AFFECTED AREAS				2400.00
S MIPNT88088	REVERSE SENSOR / DM				280.00
S MIPNT88088	TO CHEK LIGHTING & WIRING ON REAR ACCIDENT AFFECTED AREAS				80.00
S MIPNT88088	TO REMOVE AND RE-INSTALL REAR CARPETS & UPHOLSTERY FOR GIVE AWAY TO REPAIR ON REAR ACCIDENT AFFECTED AREAS				600.00
S MIPNT88088	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS				2520.00
M SUNDRY	C & C LOGO				35.00
M SUNDRY	MIVEC EMBLEM				40.00
S MIPNT88088	TO APPLY SEALANT ON REAR ACCIDENT AFFECTED AREAS				200.00
M SUNDRY	JJMR200300 CLIP BUMPER				20.00
M JJ6410B172WA	FACE KIT, REAR BUMPER	1.00	710.00	10.00	639.00
M JJ6410A436HA	COVER, RR BUMPER	1.00	19.00	10.00	17.10
M JJ6410C543	BRKT, R/BMPR FACE SUP	1.00	16.00	10.00	14.40
M JJ6410C544	BRKT, R/BMPR FACE SUP	1.00	16.00	10.00	14.40
M JJ6410B929	REINFORCEMENT, RR BUM	1.00	220.00	10.00	198.00
M JJ6410B028	REINFORCEMENT, RR BUM	1.00	85.00	10.00	76.50
M JJ7415A111	MARK, THREE-DIA	1.00	49.00	10.00	44.10
P JJ7415A226	MARK - EX	1.00	40.00	10.00	36.00
M JJ7415A112	MARK, LANCER	1.00	54.00	10.00	48.60
P JJMR971764	CLIP, SPLASH SHIELD	1.00	3.00	10.00	2.70
M JJMU488006	CLIP, COVER	10.00	2.00	10.00	18.00

Confirm & accepted by

893.7

4238.7

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info	
FULCO RENT-A-CAR PTE LTD 22 Ubi Rd 4 Singapore 408617 Contact No Work: 67436266	Cust No/Name	/Fulco Rent-A-Car Pte Ltd
	Reg No/Reg Date	SJH5349B / 13/08/2008
	Date In/Mileage	/ 0
	Chassis No	JMYSRCY2A8U007704
	Engine No	4A910087622
	Make/Model	MIT/LANCER EX 1.5 A/T BASIC (NEW)
	Colour/Trim	A03 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00001	Cash	12/01/2018/ 13:59	DS	323 / ChrisBulaciac	50505

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z NOTES ACCIDENT ON 12/01/2018 ALONG BKE WOODLANDS 0.19KM OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT TP # SLE5859M TP INSURER : AXA INSURANCE				
<h1>Estimate</h1>				
4 Days. refae paint photos. Give Q&P. - 82880282 26/2/18.				
<div style="border: 1px solid black; padding: 5px;"> <p><u>LKK Auto Consultants</u> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: _____ Date: _____</p> </div>				

Confirm & accepted by

Parts	1,108.80
Labour	0.00
Standard Menu	0.00
Specialist Job	6,130.00
Others (Lub, etc)	0.00
Sundry	95.00
Total (w/o GST)	7,333.80

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.