

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKA934U
Accident Date : 06-Jan-2018

NA Witham

No. : 05703

11 Sep 87

Date : 10-Jan-2018

Our Ref : 218008 (AXA) / CHAN

Bunny Ate Rain

PAGE : 1

PRIMA FOOD PTE LTD
201 KEPPEL ROAD LEVEL 2
ANNEXE BLOCK
Singapore 099419

ESTIMATED COST OF REPAIR FOR TOYOTA HIACE GBA1847M

1 pc Bonnet	<i>Bn</i> 856.62	✓
1 pc Bonnet logo	<i>m</i> 66.15	✓
2 pcs Headlamp	@ S\$589.76 1,179.52	✓
1 pc Radiator grille	<i>m</i> 458.84	✓
1 pc Front bumper fascia	<i>Bn</i> 488.20	✓
1 pc Front bumper tow cover	<i>m's</i> 17.20	✓
2 pcs Front bumper side retainer	@ S\$156.73 <i>dsp</i> 313.46	✓
1 pc Front bumper reinforcement	304.42	✓
1 pc Rh engine mounting	144.10	✓
1 pc Lh engine mounting	164.11	✓
1 pc Rear o/s fender	<i>Bn</i> 1,193.90	✓
1 pc Rear o/s fender sliding track	466.64	✓
1 pc O/s fender sliding track cover	<i>Sen</i> 32.83	X
1 pc Rear o/s fender wheel housing	350.50	✓
1 pc Rear o/s fender corner panel	<i>Bn</i> 496.22	✓
1 pc CORner panel inner panel	<i>Bn</i> 260.90	✓
1 pc Tail gate	<i>Bn</i> 1,872.72	✓
1 pc Tail gate rubber	<i>Red let</i> 289.20	<i>50%</i>
1 pc Tail gate inner trim board	<i>CM</i> 193.24	✓
1 pc Tail gate outer handle	<i>Sen</i> 89.12	X
2 pcs Taillamp	<i>cls Bn</i> @ S\$286.90 573.80	✓
1 pc O/s taillamp lower garnish	<i>Bn</i> 147.10	✓
1 pc Rear end panel inner	<i>Bn</i> 1,043.20	✓
1 pc Rear end panel outer	<i>m</i> 309.15	✓
1 pc Floor panel	1,992.20	✓
1 pc Rear end panel top track	<i>m</i> 138.70	✓
1 pc Rear bumper fascia	<i>CM</i> 443.02	✓
1 pc Rear o/s air duct	<i>Red</i> 64.45	✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKA934U

Page : 2

2 4 pcs	Rear o/s bumper side bracket	@ S\$ 23.30	<i>cls m</i> 93.20 <i>✓</i>
1 pc	Rear exhaust pipe		<i>B</i> 931.60 <i>✓</i>
2 pcs	Exhaust pipe mounting	@ S\$ 50.30	<i>Tn</i> 100.60 <i>✓</i>
1 pc	Rear o/s coil spring assy (set)		952.30 <i>?</i>

			16,027.21
Less 25% :			4,006.80

- 1 pc Front no.plate
- 1 pc Tail gate 70km/h sticker
- 1 pc Tail gate glass sealant
- 1 pc Rear bumper reverse sensor

12,020.41 20sn
no 30.00 *sn*
no 15.00 *sn* *✓*
no 40sn 60.00 *sn* *✓*
mit 200sn 300.00 *sn*

To towing

80.00 *501*

To rewire damaged parts and refocus headlamp beam.

20.00 *✓*

To remove & refix rear windscreen glass and conduct water leak test.

150.00 *1201*

To remove roof lining, front and rear seats, trim board and carpet

100.00 *801*

To apply undersealing

80.00 *✓*

To remove and renew exhaust silencer box

80.00 *601*

To putty and spray replaced parts

2,200.00 *1801*

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

22001
2,400.00

To dismantle and lower rear undercarriage

200.00 *?*

Con't Page 3

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKA934U

Page : 3

To check and adjust wheel alignment

65.00 *60*

To remove & renew engine mounting

80.00 *?*

Total : S\$17,880.41
=====

Singapore Dollars Seventeen Thousand Eight Hundred
and Eighty and Cents Forty One Only