

S. CASE OWNER

CC 6 / AIG1800

LKK:
IDAC

Surveyor

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of insured:

Insured Tel No.:

HP:

Excess Sec II :\$5

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OE:

After call ltr to OE:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OE:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with: Jason.

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

28

Repair Cost:

S\$

26215.00

Loss of Rental (LOR):

S\$

1000.00

(

10

days)

x

100

Loss of Use (LOU):

S\$

-

(

5

x

days)

Loss of Income (LOI):

S\$

-

(

5

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

S\$

7.43

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost:

S\$

-

Total:

S\$

27222.45

Global Sum S\$:

27200.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

27200.00

Name 1:

Kim Chwee Auto Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

mercury

REF:

A16/
ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: **SJT36587**
at Workshop no: **K. m. chuee**
of: _____
Insured: **SLR 9414**
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☒	☐

Bal. or Market Value: **79k**
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / FR. Seen: _____ Consistent? : Yes or No
Est. Repairs: **12** days Res: Yes or No
Lump Sum: **10** % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle IN / OUT

Veh No: **SJT36587** Regn: **6 15**
Type: **C** M.Cer / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or **(RT)**
Make: **Volkswagen Jetta** C.O. **1390**
Colour: **Gold** A/C: Insured / Std / NI / NA
Sp. Reading: **49239** T.Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: **WVWZZZ16TFM030070**
Gen. Cond: **Good** / Fair / Poor / Burnt
Steering: **Good** / Jammed / Leaked / Burnt or
Brake: **Good** / Jammed / Leaked / Burnt or
Mod: **Nil** / S/Rim / STD A/Rim or
Tyre Size: F: **205/55R18**
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Zh. l. l. n. n.

Front: _____ Rear: _____
R/Bal: **7** mm R/Bal: **7** mm
L/Bal: **7** mm L/Bal: **7** mm
D.O.A. **12/1/18** D.O.I. **15/1/18**

Survey held at: _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & R/L.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction **LTA54497** Tyres 4x1. " **new 6.1.18 only.**
Rep 10,000 next 24503
Note: **new parts replacement. ashy 2/2**

2/2/18 Repairs sum \$24,500 confirmed with client.

(Ref. #46846.71
66%)

Date/Time: File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: **5**

Survey Fee

Transportation

Phone

Date/Time: File Return to?

Report Format :

Lump Sum / I.B. /

Add Fee: ☐ : Site Insp. \$

☐ : Interp. \$

☐ : Tech. Insp. \$

☐ : Weekend \$





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/LCR18000881/Uwb3		
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120		Date : 15-01-2018		
		Code : LCR		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLR 941Y	Veh. Inspected	SJT 3658J	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	15/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/01/2018	Inspection Date	15/01/2018	
Survey held at	KIM CHWEE AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

KIM CHWEE AUTO PTE LTD

VEHICLE NO: SIT3658J

No. Authorized
NCH
Repair sum
\$24,500/-
12 days

Qty Particular Amount S\$

List Item:

1 PCS	BOOTLID	20/3uc	1411-01	\$	1,668.80	✓
2 PCS	BOOTLID HINGES @\$102.33	n		\$	204.66	X
1 PCS	BOOTLID WEATHERSTRIP	twi		\$	26.25	/
1 PCS	BOOTLID INNER LOCK	twi		\$	194.45	/
1 PCS	BOOTLID LOCK CATCH	11		\$	37.53	X
1 PCS	BOOTLID INNER TRIM	11		\$	181.17	X
1 PCS	BOOTLID REAR LOGO	neu		\$	89.37	/
1 PCS	BOOTLID 'JETTA' EMBLEM	neu		\$	76.11	/
1 PCS	BOOTLID 'TSI' EMBLEM	neu		\$	57.33	/
2 PCS	BOOTLID REFLECTORS @\$245.50	neu		\$	491.00	/
2 PCS	TAILLAMPS @\$385.50	neu		\$	771.00	/
1 PCS	REAR BUMPER	dis	1411-01	\$	1,459.25	✓
1 PCS	REAR BUMPER LOWER SPOILER (Black)	Yorn		\$	531.90	✓
2 PCS	REAR BUMPER REFLECTORS @\$55.35	11		\$	110.70	X
1 PCS	REAR BUMPER CENTRE HOLDER	bu/cou		\$	129.05	/
1 PCS	REAR BUMPER REINFORCEMENT	dis		\$	514.20	/
2 PCS	REAR BUMPER HOLD @FS: @\$75.60	bu		\$	151.20	/
2 PCS	REAR BUMPER SIDE RETAINERS @\$61.02	bu		\$	122.04	/
1 PCS	REAR EXHAUST BOX	n		\$	926.10	X
3 PCS	REAR EXHAUST MOUNTINGS @\$58.05	11		\$	174.15	X
1 PCS	REAR END PANEL ASSY	2.500		\$	938.25	/
1 PCS	REAR END PANEL TOP GARNISH	twi		\$	118.80	/
1 PCS	REAR FLOOR PANEL TOP BOARD	11		\$	378.10	X
1 PCS	REAR FLOOR PANEL	n		\$	1,445.00	X
1 PCS	REAR FLOOR PANEL TOOL FOAM	11		\$	163.88	X
2 PCS	REAR FENDER INNER TRIMS @\$343.81	bu/rou		\$	687.62	/
8PCS	REAR FENDER INNER TRIM CLIPS @\$55	neu		\$	40.00	/
2 PCS	REAR FENDERS @\$1105	n		\$	2,210.00	X
1 PCS	BONNET	bu		\$	1,245.30	/
2 PCS	BONNET HINGES @\$101.79	bu		\$	203.58	/
1 PCS	BONNET RUBBER @\$24.03	neu		\$	48.00	/
1 PCS	BONNET INSULATOR	dis		\$	219.24	/
1 SET	BONNET INSULATOR CLIPS	neu		\$	50.00	/
1 PCS	BONNET LOCK	twi		\$	201.42	/
1 PCS	BONNET LOCK CATCH	11		\$	46.68	X
2 PCS	HEADLAMPS @\$5098.50	neu	766.68x2= 1533.36	\$	10,197.00	/
2 PCS	HEADLAMP TOP PANELS @\$89.39	bu		\$	178.78	/
1 PCS	FRONT GRILLE	510	300x6	\$	708.75	/
1 PCS	FRONT GRILLE LOGO	neu		\$	116.37	/
1 PCS	FRONT GRILLE FRAME	neu		\$	228.42	/
1 PCS	FRONT BUMPER	dis	852	\$	1,445.32	/
1 PCS	FRONT BUMPER NUMBER PLATE GARNISH	dis		\$	112.32	/
1 PCS	FRONT BUMPER TOW COVER	Yorn		\$	30.78	/
1 PCS	FRONT BUMPER LOWER CENTRE GRILLE	twi	576	\$	227.07	/

(340x5)

1 PCS	FRONT BUMPER LOWER LID	11	\$	531.90	X
2 PCS	FRONT BUMPER FOG LAMP COVERS @ \$113	11	\$	226.00	X
1 PCS	FRONT BUMPER INNER FRAME	11	\$	160.11	✓
1 PCS	FRONT BUMPER SPONGE	11	\$	120.52	✓
1 PCS	FRONT BUMPER REINFORCEMENT	11	\$	579.20	✓
2 PCS	FRONT BUMPER SIDE RETAINERS @ \$35.91	11	\$	71.82	✓
1 SET	FRONT BUMPER CLIPS	11	\$	50.00	✓
1 PCS	FRONT SUPPORT PANEL	11	\$	901.80	✓
2 PCS	FRONT SUPPORT PANEL SIDE GARNISH @ \$51.33	11	\$	102.60	✓
1 PCS	AIRCON CONDENSER	11	\$	884.25	✓
1 PCS	AIRCON LIQUID PIPE	11	\$	696.60	X
1 PCS	AIRCON DISCHARGE PIPE	11	\$	529.20	X
1 PCS	AIRCON SUCTION PIPE	11	\$	588.30	X
1 PCS	TURBO AIR COOLER	11	\$	857.45	✓
1 PCS	RADIATOR	11	\$	9,909.47	✓
1 PCS	RADIATOR FAN ASSY	11	\$	865.92	✓
1 PCS	FRONT FENDERS @ \$641.20	11	\$	1,282.40	✓
1 PCS	FRONT FENDER INNER SHIELDS @ \$166.50	11	\$	333.00	17c
1 PCS	ALTERNATOR	11	\$	1,880.00	✓
1 PCS	TURBO CHARGER	11	\$	4,800.00	✓
1 PCS	FRONT FENDER INNER PANEL N/S	11	\$	965.20	X
1 PCS	AIR CLEANER BOX	11	\$	485.30	✓
1 PCS	AIR DUCT	11	\$	115.20	✓
1 PCS	AIRCON COMPRESSOR	11	\$	1,387.83	X
1 PCS	EXHAUST CATERLIC	11	\$	2,445.00	X
1 PCS	TURBO HEAT SHIELD	11	\$	195.20	X
2 PCS	FRONT DOORS @ \$1005	11	\$	2,010.00	X
List Item Total:			\$	62,131.21	

Special Nett Item:

1 SET	REAR BUMPER REVERSE SENSOR	11	\$	280.00	200
1 PCS	REAR END PANEL SEALANT	11	\$	50.00	✓
1 PCS	REAR LICENCE PLATE W/HOLDER	11	\$	50.00	40
1 PCS	REAR FLOOR PANEL INSULATOR	11	\$	300.00	150
1 PCS	FRONT LICENCE PLATE W/HOLDER	11	\$	50.00	40
1 BOL	RADIATOR COOLANT	11	\$	50.00	✓
1 PCS	BATTERY	11	\$	200.00	X
Special Nett Total:			\$	980.00	

Labour Charge:

TOWING CHARGE	\$	65.00	60
TO CHECK WIRING	\$	100.00	30
TO DISMANTLE & REPLACE REVERSE SENSOR	\$	100.00	50
TO TRANSFER BOOTLID MECHANISM	\$	100.00	80
TO DISMANTLE & REPLACE REAR EXHAUST	\$	100.00	X
TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY	\$	120.00	80
TO SPRAY RUST PROOFING	\$	150.00	✓
TO REFILL AIRCON GAS	\$	150.00	100
TO DISMANTLE & REPLACE TURBO CHARGE	\$	150.00	60
LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACE PARTS	\$	4,000.00	1800
TO PUTTY & SPRAY PAINTING	\$	3,200.00	1800
Labour Charge Total:	\$	8,235.00	

4740
27331.15

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$ 71,346.21

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6823D
Vehicle Details	
Vehicle No.:	SJT3658J
Vehicle to be Exported:	No
Intended De-registration Date:	15 Jan 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	JETTA GP 1.4 TSI 90 A/T TL 1632G5
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	CAXF55579
Chassis No.:	WVWZZZ16ZFM030070
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$17,557.00
Original Registration Date:	09 Jun 2015
First Registration Date:	09 Jun 2015
Transfer Count:	0
Actual ARF Paid:	\$7,557.00 3778
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Jun 2025
PARF Rebate Amount:	\$5,667.00
Intended COE Rebate Details	
COE Expiry Date:	08 Jun 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$66,000.00
COE Rebate Amount:	\$48,830.00
Total Rebate Amount:	\$54,497.00

The information contained herein is correct as at 15 Jan 2018

OK

SGCARMART.COM

New Cars

Used Cars

Sell My Car

Directory

Products

Articles

Forum

Tools & Tips

Login

Sign up

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?

Post an Advertisement

Sell it yourself! Advertise it at just \$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

BMW 316i M-Sport

Buy A BMW 316i M-Sport At The Price Of A Normal 316i...
Direct Owner StarAd

AutoInn

As Inspiration For Car Buyers

click here to view our PRISTINE USED CARS at GREAT PRICES

Browse by Category

23 vehicles

Jetta

Advanced Search

Submit

Sort by Date Posted

20 results/page

Back (1 2) Next

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Jetta		Any	Any	2015	Any	Any	Any	Available
	Volkswagen	Jetta 1.4A TSI	\$78,800	\$8,820 /yr	17-Dec-2015	1,390 cc	21,000 km	Sedan	Available
Selling Cheap,agent Maintained And Warranty, Low Mileage Done 21,000km, Very Well Maintained, View To Appreciate.									
Posted: 12-Jan-2018 Tags: 2015 Volkswagen Jetta, Volkswagen Jetta, Volkswagen, Jetta, Used Volkswagen									
	Volkswagen	Jetta 1.4A TSI	\$69,800	\$9,360 /yr	02-Jan-2015	1,390 cc	57,000 km	Sedan	Available
Graded B by									
Fully Agent Maintained. Well Maintained. Excellent Condition, Still Under Agent Warranty. Spacious, Powerful And Fuel Economical Mid Sized Continental Family Sedan. Fuel Consumption 14 To 15km/L. Hur...									
Posted: 13-Jan-2018 Tags: 2015 Volkswagen Jetta, Volkswagen Jetta, Volkswagen, Jetta, Used Volkswagen									
	Volkswagen	Jetta 1.4A TSI Trendline	\$75,800	\$9,860 /yr	30-Apr-2015	1,390 cc	45,000 km	Sedan	Available
Low Price Tag Need No Compare As Car Is In Superb Condition, Very Fuel Economy Yet Powerful 7 Speed Drive, Low Depreciation Than Japanese Car And Very Low Maintenance. Flexible Loan, Trade In Welcome...									
AL Autocar Pte Ltd									
Posted: 12-Jan-2018 Tags: 2015 Volkswagen Jetta, Volkswagen Jetta, Volkswagen, Jetta, Used Volkswagen									
	Volkswagen	Jetta 1.4A TSI Highline	\$86,800	\$11,040 /yr	24-Jun-2015	1,390 cc	37,250 km	Sedan	Available
Powerful Sedan That Surpasses Expectations. Excellent Combinations Of Comfort And Safety Without Compromising On Power And Space. 100% Accident Free. 1 Owner, Tip Top Brand New Condition, Price Negoti...									
Posted: 13-Jan-2018 Tags: 2015 Volkswagen Jetta, Volkswagen Jetta, Volkswagen, Jetta, Used Volkswagen									
Car Buying Car Selling Car Aftermarket Car Ownership On The Move Lifestyle									
	Volkswagen	Jetta 1.4A TSI Highline	\$72,500	\$9,530 /yr	28-Feb-2015	1,390 cc	38,150 km	Sedan	Available
1 Owner With Agent Maintain, Genuine Mileage, Low Fuel Consumption, Excellent Engine Performance, Huge Leg Room And Boot Space, Price And Downpayment Negotiable, Trade In Welcome									
Posted: 12-Jan-2018 Tags: 2015 Volkswagen Jetta, Volkswagen Jetta, Volkswagen, Jetta, Used Volkswagen									
	Volkswagen	Jetta 1.4A TSI	\$78,988	\$10,520 /yr	09-Feb-2015	1,390 cc	48,439 km	Sedan	Available
Singapore's Only Certified Volkswagen Preowned Centre, The Only Place To Find Volkswagen Management Units! 115 Points Check By Volkswagen, Certified Vehicle History And Mileage, No Chassis/Structural ...									
Das WeltAuto									
Posted: 12-Jan-2018 Tags: 2015 Volkswagen Jetta, Volkswagen Jetta, Volkswagen, Jetta, Used Volkswagen									
Compare									

View Received Message

This mail is associated with :

***SJT3658J (7994283259SG)
[SLR941Y]**

TP
KHOO AH HOCK
Jan 12 2018 12:00AM
[LCRF PTE LTD]
Kim Chwee Auto Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 18/04/2018 16:04 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$27222.45) - SJT3658J - Claim Handler: Gan, Angie-GL

Approved:27222.45,

DOCUMENTS SUMMARY

There are no documents.

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-50 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379R

Date : 20.02.2018

AIG Asia Pacific Insurance Pte Ltd

Chartis Building

78 Shenton Way #07-16

Singapore 079120

Attn: Motor Claim Department

ACCIDENT INVOLVING VEHICLE: SJT3658J AND SLR941Y ON 12.01.2018

We are the authorized repair workshop for the owner of motor vehicle no: **SJT3658J**, which was involved in the captioned accident with your insured vehicle no: **SLR941Y**. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

1) Cost of Repair (inclusive of GST)	\$ 26,215.00
2) Loss Of Use Rental	\$ 1,800.00
3) GIA Search Fee	\$ 7.45
	\$ 28,022.45

We enclosed herewith the following documents to support the claims:

- | | |
|------------------------------------|----------------------------------|
| a) Final Repair Invoice | b) Vehicle Registration Log Card |
| c) Rental Agreement/Invoice | d) I/C & Driving Licence |
| e) Insurance Certificate | f) GIA Search Result/GIA Report |
| g) Letter of Authorisation, etc... | |

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you.

Yours faithfully,

Jason Tang (jason@fastechauto.com.sg)

For Kim Chwee Auto Pte Ltd

Vivian Lau (LKKAUTO)

From: Vivian Lau (LKKAUTO)
Sent: Wednesday, 17 January, 2018 3:23 PM
To: 'eyap@lioncityrentals.com.sg'
Cc: Zayyer (LKKAUTO); Hsiao Tong (LKKAUTO)
Subject: ACCIDENT INVOLVING SLR 941Y & SJT 3658J ON 12/01/2018

Our Ref: CC6/LCR18000881/Uwb3

17 January 2018

LION CITY RENTALS PTE LTD

Dear Sir/Madam,

ACCIDENT INVOLVING SLR 941Y & SJT 3658J ON 12/01/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please call us if you have further queries.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)


AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Khoo Ah Hock ("the third party claimant")
of Blk 232 Jurong East St 21 #05-428 S260232 (address),
owner of SJT 3658J (vehicle no.) hereby authorize
Kim Chwee Auto Pte Ltd
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SJT 3658J that was
damaged pursuant to the accident which occurred on 12/01/18 (date) along
PIE > Changi (location)
involving vehicle no/s SLR 941J ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment fortherto settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 15 day of 1 (month) 20 18 (year)


Signed by "the third party claimant"


Signed by "the workshop"

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, KIM CHWEE AUTO PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for \$ 27,200.00 (Global Sum) for vehicle no. SJT 3658J that was damaged pursuant to the accident which occurred on 12/01/2018 (date) along PIE (location) involving vehicle no/s SLR 941Y.

This is pursuant to the inspection conducted on 15/01/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner KHOO AH HOCK ("the third party claimant") of vehicle no. SJT 3658J make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJT 3658J (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 19 (day) of 4 (month) 2018 (year)

Cks

Signed by appointed surveyor



Signed by "the workshop" (with chop)

*** This Discharge Voucher applies only to the claimant's claim for his property damage and will not affect his personal injuries claim and/or uninsured losses claim in a later date. Further, the settlement terms herein should not be used as an evidence to prejudice in the claimant's personal injuries claim and/or other uninsured losses claim arising of the subject matter in this action.

TAX INVOICE

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-50 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379R

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claim Department

Tax Invoice : 20094

Date: 20.02.2018

Vehicle No: SJT3658J

Make/Model: V/JETTA

Chassis/Eng# :

Accident Date: 12.01.2018

Claim No : 0118-20094

:

	Amount
To proceed on repair sum	S\$ 24,500.00

E. & O. E.

Total : S\$ 24,500.00

GST @ 7% : S\$ 1,715.00

Amount Due : **S\$ 26,215.00**



for KIM CHWEE AUTO PTE LTD

All Invoices are subjected to GST

DYNAMIC CAR RENTAL

1 Kaki Bukit Ave 6 #01-46 Autobay

Singapore 417883

Tel No: 6741 7244 / 6746 5405 Fax No: 6745 8520 / 6746 5786

Co. Reg No: 52928467K

To: KHOO AH HOCK

Invoice : DCR-2018-01-31

Date 22.01.2018

Agreement No : 19890

Payment Term: LOD

DESCRIPTION

AMOUNT

Rental charges for vehicle : SKG3439G (0118-20094) \$ 1,800.00

Rental Period from 12.01.2018 to 22.01.2018 .

E. & O. E.

Total \$ 1,800.00

NANCY LAM

for Dynamic Car Rental

Dynamic Car Rental

DCR-2018-01-31

1 KAKI BUKIT AVENUE 6, #01-46/48/50 AUTOBAY, SINGAPORE 417883.

TEL: (+65) 6741 7244, 6746 5405 FAX: (+65) 6745 8520, 6746 5786

Co. Reg. No. 52928467K

RENTAL TERMS AND CONDITIONS

No. 19890

Name Khoo Ah Hock			REG. No. SG5439G		MAKE MODEL:	
ADDRESS			DIESEL		PETROL	E 1/4 1/2 3/4 F
			KM IN		DATE & TIME IN 22/08/18 @ 3.47pm	
			KM OUT		DATE & TIME OUT 12/08/18 @ 4.30pm	
			KM DRIVEN		TIME USED	
NAMED DRIVER						
DRIVING LICENCE NO	DATE OF EXPIRY	PLACE OF ISSUE	HOURS		@S\$	
PASSPORT NO	DATE OF ISSUE	PLACE OF ISSUE	10 DAYS		@S\$ 180	1800
ADD NAMED DRIVER			WEEKS		@S\$	
DRIVING LICENCE NO	DATE OF EXPIRY	PLACE OF ISSUE	MONTHS		@S\$	
PASSPORT NO	DATE OF ISSUE	PLACE OF ISSUE	BY INITIALLING, RENTER AGREES TO PAY ADD FEE FOR COLLISION DAMAGES WAIVER (C.D.W.)		SUB-TOTAL	1800
IMPORTANT NOTES:					TOTAL RENTAL	
This vehicle is licenced to carry 04 passengers only. No refund will be given for vehicle returns early. No refund will be given for period left in vehicle. Hirer is liable to pay first \$2000 under section I & II in any accident plus loss of earnings while damaged vehicle is under repair. Hirer is liable to pay all parking fee and traffic summonses.					DELIVERY FEE	
Vehicle return during office hour only. No Service on Public Holiday and Sunday.					COLLECTION FEE	
ADDITIONAL CONDITIONS:			X		PER DAY	PER WEEK
* Geographical areas: Singapore & West Malaysia.					\$	\$
* Driver must be:						
a) 18 years old and above;						
b) holding a valid relevant class of driving license.						
* Additional Own Damage Excess of S\$1,000 is applicable for any named/unnamed drivers who:						
a) age 22 to 23 years old;						
b) age 66 to 70 years old;						
c) with driving experience of 1 year to less than 2 years in Singapore on the relevant classes of driving license.						
* Additional All Claims excess of S\$2,000 is applicable for any named/unnamed drivers who:						
a) is 18 years old to 21 years old and/or						
b) is 71 years old and above and/or						
c) with driving experience of less than 1 year on the relevant classes of driving license.						
* Upon returning the replacement vehicle, you must ensure that all expensive and important items to be removed away from this replacement vehicle. We'll not be responsible for any reporting of such losses.						
* Hirer is liable to pay first \$2000 under section I & II in any accident plus loss of earning while damage vehicle is under repair.						
Hirer is responsible for Additional \$2,000.00 Excess to the THIRD PARTY DAMAGE / INJURY claims.						
			BY INITIALLING, RENTER AGREES TO PAY ADD FEE FOR PERSONAL ACCIDENT INSURANCE (P.A.I.)			
			X		PER DAY	PER WEEK
					\$	\$
			PREPAYMENT		TOTAL CHARGE	
			CHECK		DEPOSIT	
			CASH			
			RECEIPT NO.		NETT CHARGE	
			AMOUNT DUE / REFUND			

I HAVE READ THE TERMS AND CONDITIONS ON BOTH SIDES OF THIS RENTAL AGREEMENT AND AGREE THEREOF.

SIGNED BY THE PARTIES HERETO ON THE

DAY OF

X 
DYNAMIC CAR RENTAL

X 
RENTER'S/DRIVER'S SIGNATURE



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 12 Jan 2018 / 16:05:53

Receipt Date/Time : 12 Jan 2018 / 16:05:53

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180112-001598

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLR941Y				
As at 12 Jan 2018/15:20:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SLR941Y Enquiry Fee 20180112160441577155	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	20180112160447978	Direct Debit: eNETS Debit (Internet Banking)		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt OK Save as PDF

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Jan 2018 Edit Reg		15 Jan 2018 00:00 Edit Adj Rpt	\$24,500.00 Edit Estimates	\$24,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: LCRF PTE LTD , Co. Reg. No.: -									
Main Claimant: KHOO AH HOCK , ID: S2196823D									
Vehicle Reg. No.: SJT3658J		Date of Loss: 12/01/2018 00:00 - :59 [31 Months and 3 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 7994283259SG		Policy/Cover Note No.: 0999994988 (Comprehensive)							
Vehicle Reg. No. (Insured): SLR941Y		Policy No. (Claimant): A28748015							
		Excess:							
Repairer: Kim Chwee Auto Pte Ltd (HQ) 1 Kaki Bukit Avenue 6 #01-48, AutoBay@Kaki Bukit, 417883 Eunos - Tel: 67465405/67417244									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Gan, Angie-GL] Angiegeokling.Gan@aig.com									
Claimant's Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 24/01/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (18/04/2018): Alert - Adj Mandate Approved (\$27222.45) - SJT3658J - Claim Handler: Gan, Angie... - AIG_SG (16/01/2018): Request for TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJT3658J (7994283259SG)
[SLR941Y]
TP
KHOO AH HOCK
Jan 12 2018 12:00AM
[LCRF PTE LTD]
Kim Chwee Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser					
Letters/Correspondences															1 per page			☐					
No.	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print					
1	(Draft)		Third Party Express Settlement – Payment Breakdown												1			Edit					
Assessment Reports															1 per page			☐					
No.	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail			Print					
1	16/01/18 13:23		Accident Statement From: SC - Reg. No: SLR941Y, Claimant: LCRF PTE LTD												1			Load HTM					
Photos/Images															3 per page			☐					
No.	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print					
1	15/01/18 19:17		Odometer Reading												1			Load JPG			☒		
2	15/01/18 19:18		General View												1			Load JPG			☒		
3	15/01/18 19:18		Chassis Number												1			Load JPG			☒		
4	15/01/18 19:18		General View												1			Load JPG			☒		
5	15/01/18 19:18		General View												1			Load JPG			☒		
6	15/01/18 19:18		General View												1			Load JPG			☒		
7	15/01/18 19:18		General View												1			Load JPG			☒		
8	15/01/18 19:18		General View												1			Load JPG			☒		
9	15/01/18 19:18		General View												1			Load JPG			☒		
10	15/01/18 19:18		General View												1			Load JPG			☒		
11	15/01/18 19:18		General View												1			Load JPG			☒		
12	15/01/18 19:18		General View												1			Load JPG			☒		
13	15/01/18 19:18		General View												1			Load JPG			☒		
14	15/01/18 19:18		General View												1			Load JPG			☒		
15	15/01/18 19:18		General View												1			Load JPG			☒		
16	15/01/18 19:18		General View												1			Load JPG			☒		
17	15/01/18 19:18		General View												1			Load JPG			☒		
18	15/01/18 19:18		General View												1			Load JPG			☒		
19	15/01/18 19:18		General View												1			Load JPG			☒		
20	15/01/18 19:18		General View												1			Load JPG			☒		
21	15/01/18 19:18		General View												1			Load JPG			☒		
22	15/01/18 19:18		General View												1			Load JPG			☒		
23	15/01/18 19:18		General View												1			Load JPG			☒		
24	15/01/18 19:18		General View												1			Load JPG			☒		
25	15/01/18 19:18		General View												1			Load JPG			☒		
26	15/01/18 19:18		General View												1			Load JPG			☒		
27	15/01/18 19:18		General View												1			Load JPG			☒		
28	15/01/18 19:18		General View												1			Load JPG			☒		
29	15/01/18 19:18		General View												1			Load JPG			☒		
30	15/01/18 19:18		General View												1			Load JPG			☒		

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	15/01/18 19:18	General View		☒
32	15/01/18 19:18	General View		☒
33	15/01/18 19:18	General View		☒
34	15/01/18 19:18	General View		☒
35	15/01/18 19:18	General View		☒
36	15/01/18 19:18	General View		☒
37	15/01/18 19:18	General View		☒
38	15/01/18 19:18	General View		☒
39	15/01/18 19:18	General View		☒
40	15/01/18 19:18	General View		☒
41	15/01/18 19:18	General View		☒
42	15/01/18 19:18	General View		☒
43	15/01/18 19:18	General View		☒
44	15/01/18 19:18	General View		☒
45	15/01/18 19:18	General View		☒
46	15/01/18 19:18	General View		☒
47	15/01/18 19:18	General View		☒
48	15/01/18 19:18	General View		☒
49	15/01/18 19:18	General View		☒
50	15/01/18 19:18	General View		☒
51	15/01/18 19:18	General View		☒
52	15/01/18 19:18	General View		☒
53	15/01/18 19:18	General View		☒
54	15/01/18 19:18	General View		☒
55	15/01/18 19:18	General View		☒
56	15/01/18 19:18	General View		☒
57	15/01/18 19:18	General View		☒
58	15/01/18 19:18	General View		☒
59	15/01/18 19:18	General View		☒
60	15/01/18 19:18	General View		☒
61	15/01/18 19:18	General View		☒
62	15/01/18 19:18	General View		☒
63	15/01/18 19:18	General View		☒
64	15/01/18 19:18	General View		☒
65	15/01/18 19:18	General View		☒
66	15/01/18 19:18	General View		☒
67	15/01/18 19:18	General View		☒
68	15/01/18 19:18	General View		☒
69	15/01/18 19:18	General View		☒
70	15/01/18 19:18	General View		☒
71	15/01/18 19:18	General View		☒
72	15/01/18 19:18	General View		☒
73	15/01/18 19:18	General View		☒
74	15/01/18 19:18	General View		☒
75	15/01/18 19:18	General View		☒
76	15/01/18 19:18	General View		☒
77	15/01/18 19:18	General View		☒
78	15/01/18 19:18	General View		☒
79	15/01/18 19:18	General View		☒
80	15/01/18 19:18	General View		☒

Letters/Correspondences			1 per page		☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
81	15/01/18 19:18	General View		Load JPG	☒
82	15/01/18 19:18	General View		Load JPG	☒
83	15/01/18 19:18	General View		Load JPG	☒
84	15/01/18 19:18	General View		Load JPG	☒
85	15/01/18 19:18	General View		Load JPG	☒
86	15/01/18 19:18	General View		Load JPG	☒
87	15/01/18 19:18	General View		Load JPG	☒
88	15/01/18 19:18	General View		Load JPG	☒
89	15/01/18 19:18	General View		Load JPG	☒
90	15/01/18 19:19	General View		Load JPG	☒
91	15/01/18 19:19	General View		Load JPG	☒
92	15/01/18 19:19	General View		Load JPG	☒
93	15/01/18 19:19	General View		Load JPG	☒
94	15/01/18 19:19	General View		Load JPG	☒
95	15/01/18 19:19	General View		Load JPG	☒
96	15/01/18 19:19	General View		Load JPG	☒
97	15/01/18 19:19	General View		Load JPG	☒
98	15/01/18 19:19	General View		Load JPG	☒
99	15/01/18 19:19	General View		Load JPG	☒
100	15/01/18 19:19	General View		Load JPG	☒
101	15/01/18 19:19	General View		Load JPG	☒
102	15/01/18 19:19	General View		Load JPG	☒
103	15/01/18 19:19	General View		Load JPG	☒
104	15/01/18 19:19	General View		Load JPG	☒
105	15/01/18 19:19	General View		Load JPG	☒
106	15/01/18 19:19	General View		Load JPG	☒
107	15/01/18 19:19	General View		Load JPG	☒
108	15/01/18 19:19	General View		Load JPG	☒
109	15/01/18 19:19	General View		Load JPG	☒
110	15/01/18 19:19	General View		Load JPG	☒
111	15/01/18 19:19	General View		Load JPG	☒
112	15/01/18 19:19	General View		Load JPG	☒
113	15/01/18 19:19	General View		Load JPG	☒
114	15/01/18 19:19	General View		Load JPG	☒
115	15/01/18 19:19	General View		Load JPG	☒
116	15/01/18 19:19	General View		Load JPG	☒
117	15/01/18 19:19	General View		Load JPG	☒
118	15/01/18 19:19	General View		Load JPG	☒
119	15/01/18 19:19	General View		Load JPG	☒
120	15/01/18 19:19	General View		Load JPG	☒
121	15/01/18 19:19	General View		Load JPG	☒
122	15/01/18 19:19	General View		Load JPG	☒
123	15/01/18 19:19	Reinspection Photo		Load JPG	☒
124	15/01/18 19:19	Reinspection Photo		Load JPG	☒
125	15/01/18 19:19	Reinspection Photo		Load JPG	☒
126	15/01/18 19:19	Reinspection Photo		Load JPG	☒
127	15/01/18 19:19	Reinspection Photo		Load JPG	☒
128	15/01/18 19:19	Reinspection Photo		Load JPG	☒
129	15/01/18 19:19	Reinspection Photo		Load JPG	☒
130	15/01/18 19:19	Reinspection Photo		Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
131	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
132	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
133	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
134	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
135	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
136	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
137	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
138	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
139	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
140	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
141	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
142	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
143	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
144	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
145	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
146	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
147	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
148	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
149	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
150	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
151	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
152	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
153	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
154	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
155	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
156	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
157	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
158	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
159	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
160	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
161	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
162	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
163	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
164	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
165	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
166	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
167	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
168	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
169	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
170	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
171	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
172	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
173	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
174	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
175	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
176	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
177	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
178	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
179	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
180	15/01/18 19:19	Reinspection Photo	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
181	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
182	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
183	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
184	15/01/18 19:19	Reinspection Photo	 Load JPG	☒
185	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
186	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
187	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
188	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
189	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
190	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
191	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
192	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
193	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
194	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
195	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
196	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
197	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
198	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
199	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
200	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
201	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
202	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
203	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
204	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
205	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
206	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
207	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
208	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
209	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
210	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
211	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
212	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
213	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
214	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
215	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
216	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
217	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
218	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
219	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
220	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
221	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
222	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
223	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
224	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
225	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
226	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
227	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
228	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
229	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
230	15/01/18 19:20	Reinspection Photo	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
231	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
232	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
233	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
234	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
235	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
236	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
237	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
238	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
239	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
240	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
241	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
242	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
243	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
244	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
245	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
246	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
247	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
248	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
249	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
250	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
251	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
252	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
253	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
254	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
255	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
256	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
257	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
258	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
259	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
260	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
261	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
262	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
263	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
264	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
265	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
266	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
267	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
268	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
269	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
270	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
271	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
272	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
273	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
274	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
275	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
276	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
277	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
278	15/01/18 19:20	Reinspection Photo	 Load JPG	☒
279	16/04/18 16:43	Photo After Spray	 Load JPG	☒
280	16/04/18 16:43	Photo After Spray	 Load JPG	☒

Letters/Correspondences			1 per page	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
281	16/04/18 16:43	Photo After Spray		☒
282	16/04/18 16:43	Photo After Spray		☒
283	16/04/18 16:43	Photo After Spray		☒
284	16/04/18 16:43	Photo After Spray		☒
285	16/04/18 16:43	Photo After Spray		☒
286	16/04/18 16:43	Photo After Spray		☒
287	16/04/18 16:43	Photo After Spray		☒
288	16/04/18 16:43	Photo After Spray		☒
289	16/04/18 16:43	Photo After Spray		☒
290	16/04/18 16:43	Photo After Spray		☒
291	16/04/18 16:43	Photo After Spray		☒
292	16/04/18 16:43	Photo After Spray		☒
293	16/04/18 16:43	Photo After Spray		☒
294	16/04/18 16:43	Photo After Spray		☒
295	16/04/18 16:43	Photo After Spray		☒
296	16/04/18 16:43	Photo After Spray		☒
297	16/04/18 16:43	Photo After Spray		☒
298	16/04/18 16:43	Photo After Spray		☒
299	16/04/18 16:43	Photo After Spray		☒
300	16/04/18 16:43	Photo After Spray		☒
301	16/04/18 16:43	Photo After Spray		☒
302	16/04/18 16:43	Photo After Spray		☒
303	16/04/18 16:43	Photo After Spray		☒
304	16/04/18 16:43	Photo After Spray		☒
305	16/04/18 16:43	Photo After Spray		☒
306	16/04/18 16:43	Photo After Spray		☒
307	16/04/18 16:43	Photo After Spray		☒
308	16/04/18 16:43	Photo After Spray		☒
309	16/04/18 16:43	Photo After Spray		☒
310	16/04/18 16:43	Photo After Spray		☒
311	16/04/18 16:43	Photo After Spray		☒
312	16/04/18 16:43	Photo After Spray		☒
Documentation			1 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/01/18 18:19	TP GIA REPORT		
2	17/01/18 15:24	Email letter to OI ACCIDENT INVOLVING SLR 941Y & SJT 3658J ON 12.01.2018		
3	16/04/18 14:05	RENTAL RECEIPT		
4	16/04/18 14:05	LTA SEARCH		
5	16/04/18 16:40	Email to AIG to seek mandate SJT 3658J		
6	24/04/18 14:20	WORKSHOP INVOICE		
7	24/04/18 14:20	AUTHORISATION TO ACT FORM		
8	24/04/18 14:20	Release Voucher		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLR941Y (Insd veh)	Model:	VOLKSWAGEN JETTA GP
	SJT3658J (TP veh)		1.4 TSI 90 A/T (A)
Date of Accident:	12/01/2018		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	76,340.44
Final Repair Cost	:	\$	27,200.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	10 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	27,200.00
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability ____100____(%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____(%)		Assessed Liability (*): ____100____(%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Kim Chwee Auto Pte Ltd	:	\$ 27,200.00
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

24 Apr
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR18000881/UWB3Q2

Date: 24/04/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994988
Claimant Vehicle No : SJT3658J **Insured Vehicle No :** SLR941Y
 Date of Loss: 12/01/2018 Nature of Claim: TP Claim No: 7994283259SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJT3658J**
 Make & Model: VOLKSWAGEN JETTA GP, 1.4 TSI 90 A/T (A) Engine No: CAXF55579
 Reg. Date: 09/06/2015 (Man. Year: 2015) Chassis No: WVVZZZ16ZFM030070
 Colour: Gold Odometer: 49239 km
 Engine Capacity: 1390 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Falken 7 mm Rear Left Side: Falken 7 mm
 Front Right Side: Falken 7 mm Rear Right Side: Falken 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	63,111.21	23,121.15	39,990.06	63.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,235.00	4,210.00	4,025.00	48.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	71,346.21	27,331.15	44,015.06	61.69
Approved Total (Overridden) (S\$)		24,500.00		
(S\$)	71,346.21	24,500.00	46,846.21	65.66
+ GST 7.00/7.00% (S\$)	4,994.23	1,715.00	3,279.23	65.66
Nett Amount (S\$)	76,340.44	26,215.00	50,125.44	65.66
+ Car Rental (10.0 x S\$100.00/day) (S\$)		1,000.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		27,222.45		
Global Sum Settlement (S\$)		27,200.00		

INSPECTION

Date of Assignment: 15/01/2018
 Date Inspected: 15/01/2018 Inspected At:

Kim Chwee Auto Pte Ltd (HQ)
1 Kaki Bukit Avenue 6 #01-48,
AutoBay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 12.0 days

Adjuster: MARCUS CHUA

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Buckled	1,668.80 F	*1,411.01 FL
2	1		*BOOTLID HINGES	Repair	204.66 F	*- FL
3	1		*BOOTLID WEATHERSTRIP	Twisted	26.25 F	*26.25 FL
4	1		*BOOTLID INNER LOCK	Twisted	194.45 F	*194.45 FL
5	1		*BOOTLID LOCK CATCH	Not Necessary	37.53 F	*- FL
6	1		*BOOTLID INNER TRIM	Not Necessary	181.17 F	*- FL
7	1		*BOOTLID REAR LOGO	Necessary	89.37 F	*89.37 FL
8	1		*BOOTLID JETTA EMBLEM	Necessary	76.11 F	*76.11 FL
9	1		*BOOTLID TSI EMBLEM	Necessary	57.33 F	*57.33 FL
10	2		*BOOTLID REFLECTORS	Cracked	491.00 F	*491.00 FL
11	2		*TAILLAMPS	Cracked	771.00 F	*771.00 FL
12	1		*REAR BUMPER	Distorted	1,459.25 F	*1,459.25 FL
13	1		*REAR BUMPER LOWER SPOILER (BLACK)	Torn	531.90 F	*531.90 FL
14	2		*REAR BUMPER REFLECTORS	Not Necessary	110.70 F	*- FL
15	1		*REAR BUMPER CENTRE HOLDER	Bent / Cracked	129.05 F	*129.05 FL
16	1		*REAR BUMPER REINFORCEMENT	Dented	514.20 F	*514.20 FL
17	2		*REAR BUMPER HOLDERS	Bent	151.20 F	*151.20 FL
18	2		*REAR BUMPER SIDE RETAINERS	Bent	122.04 F	*122.04 FL
19	1		*REAR EXHAUST BOX	Repair	926.10 F	*- FL
20	3		*REAR EXHAUST MOUNTINGS	Not Necessary	174.15 F	*- FL
21	1		*REAR END PANEL ASSY	Badly Dented	938.25 F	*938.25 FL
22	1		*REAR END PANEL TOP GARNISH	Twisted	118.80 F	*118.80 FL
23	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	378.10 F	*- FL
24	1		*REAR FLOOR PANEL	Repair	1,445.00 F	*- FL
25	1		*REAR FLOOR PANEL TOOL FOAM	Not Necessary	163.88 F	*- FL
26	2		*REAR FENDER INNER TRIMS	Deformed / Torn	687.62 F	*687.62 FL
27	8		*REAR FENDER INNER TRIM CLIPS	Necessary	40.00 F	*40.00 FL
28	2		*REAR FENDERS	Repair	2,210.00 F	*- FL
29	1		*BONNET	Buckled	1,245.30 F	*1,245.30 FL
30	2		*BONNET HINGES	Bent	203.58 F	*203.58 FL
31	2		*BONNET RUBBER	Necessary	48.00 F	*48.00 FL
32	1		*BONNET INSULATOR	Distorted	219.24 F	*219.24 FL
33	1		*SET BONNET INSULATOR CLIPS	Necessary	50.00 F	*50.00 FL
34	1		*BONNET LOCK	Twisted	201.42 F	*201.42 FL
35	1		*BONNET LOCK CATCH	Not Necessary	46.68 F	*- FL
36	2		*HEADLAMPS	Cracked	10,197.00 F	*1,533.36 FL
37	2		*HEADLAMP TOP PANELS	Buckled	178.78 F	*178.78 FL
38	1		*FRONT GRILLE	Broken	708.75 F	*350.46 FL
39	1		*FRONT GRILLE LOGO	Cracked	116.37 F	*116.37 FL
40	1		*FRONT GRILLE FRAME	Cracked	228.42 F	*228.42 FL
41	1		*FRONT BUMPER	Distorted	1,445.32 F	*852.00 FL
42	1		*FRONT BUMPER NUMBER PLATE GARNISH	Distorted	112.32 F	*112.32 FL
43	1		*FRONT BUMPER TOW COVER	Torn	30.78 F	*30.78 FL
44	1		*FRONT BUMPER BLOWER CENTRE GRILLE	Twisted	227.07 F	*227.07 FL
45	1		*FRONT BUMPER LOWER LID	Not Necessary	531.90 F	*- FL
46	2		*FRONT BUMPER FOG LAMP COVERS	Not Necessary	226.00 F	*- FL
47	1		*FRONT BUMPER INNER FRAME	Distorted	160.11 F	*160.11 FL
48	1		*FRONT BUMPER SPONGE	Torn	120.52 F	*120.52 FL
49	1		*FRONT BUMPER REINFORCEMENT	Distorted	579.20 F	*573.69 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	2		*FRONT BUMPER SIDE RETAINERS	Bent	71.82 F	*71.82 FL
51	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
52	1		*FRONT SUPPORT PANEL	Bent / Buckled	901.80 F	*901.80 FL
53	2		*FRONT SUPPORT PANEL SIDE GARNISH	Torn	102.60 F	*102.60 FL
54	1		*AIRCON CONDENSER	Bent / Punctured	884.25 F	*884.25 FL
55	1		*AIRCON LIQUID PIPE	Not Necessary	696.60 F	*- FL
56	1		*AIRCON DISCHARGE PIPE	Not Necessary	529.20 F	*- FL
57	1		*AIRCON SUCTION PIPE	Not Necessary	588.30 F	*- FL
58	1		*TURBO AIR COOLER	Bent / Punctured	857.45 F	*857.45 FL
59	1		*RADIATOR	Bent / Punctured	9,909.47 F	*909.47 FL
60	1		*RADIATOR FAN ASSY	Shorted / Jammed	865.92 F	*865.92 FL
61	2		*FRONT FENDERS	Buckled / Bent	1,282.40 F	*1,282.40 FL
62	1		*FRONT FENDER INNER SHIELDS	N/S Deformed / Torn	333.00 F	*166.50 FL
63	1		*ALTERNATOR	Cracked	1,880.00 F	*1,880.00 FL
64	1		*TURBO CHARGER (HOUSING ONLY)	Cracked	4,800.00 F	*752.00 FL
65	1		*FRONT FENDER INNER PANEL N/S	Repair	965.20 F	*- FL
66	1		*AIR CLEANER BOX	Cracked	485.30 F	*485.30 FL
67	1		*AIR DUCT	Twisted	115.20 F	*115.20 FL
68	1		*AIRCON COMPRESSOR	Not Necessary	1,387.83 F	*- FL
69	1		*EXHAUST CATERLIC	Not Necessary	2,445.00 F	*- FL
70	1		*TURBO HEAT SHIELD	Dented	195.20 F	*195.20 FL
71	2		*FRONT DOORS	Repair	2,010.00 F	*- FL
72	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
73	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
74	1		*REAR LICENCE PLATE W/HOLDER	Bent	50.00 FS	*40.00 FS
75	1		*REAR FLOOR PANEL INSULATOR	Necessary	300.00 FS	*150.00 FS
76	1		*FRONT LICENCE PLATE W/HOLDER	Bent	50.00 FS	*40.00 FS
77	1		*BOL RADIATOR COOLANT	Necessary	50.00 FS	*50.00 FS
78	1		*BATTERY	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	63,111.21	24,310.16
- List Item Discount on L Items 0.00/5.00% (S\$)	0.00	1,189.01

Total Parts (S\$)	63,111.21	23,121.15
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGE	New	65.00	60.00
2	TO CHECK WIRING	New	100.00	30.00
3	TO DISMANTLE & REPLACE REVERSE SENSOR	New	100.00	50.00
4	TO TRANSFER BOOTLID MECHANISM	New	100.00	80.00
5	TO DISMANTLE & REPLACE REAR EXHAUST	New	100.00	0.00
6	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY	New	120.00	80.00
7	TO SPRAY RUST PROOFING	New	150.00	150.00
8	TO REFILL AIRCON GAS	New	150.00	100.00
9	TO DISMANTLE & REPLACE TURBO CHARGE	New	150.00	60.00
10	LABOUR FOR PANEL BEATING ,CUT,WELD ,STRAIGHTEN & REPLACE PARTS	New	4,000.00	1,800.00
11	TO PUTTY & SPRAY PAINTING	New	3,200.00	1,800.00
Gross Labour Cost (S\$)			8,235.00	4,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >