

HWA SENG SPRAY PAINTING CO

160 Sin Ming Drive, #05-11,

Sin Ming Autocity

SINGAPORE 575722

(COMPANY REGISTRATION NO. 09574400B)

TEL: 64533100

FAX: 62669932

Not Authored
11/10/18
Penny After Pain

Accident Date: 10/01/2018

Your Insured

Vehicle No: SKQ 8197 T

Estimate repair cost to HYUNDAI GETZ reg no :SGJ 4479 R

1pc o/s/f door	S\$	B ₁ 1200.80	✓
1pc o/s/f door rubber		96.50	?
1pc o/s/f door protector		M ₁ 44.30	✓
2pcs o/s/f door hinges	(S\$36.10/pc)	B ₁ 72.20	✓
1pc o/s/f door power window motor		195.20	?
1pc o/s/f door power window regulator		260.40	?
1pc o/s/f door check		D ₁ 52.20	✓
1pc o/s 'A' pillar		1496.40	?
1pc o/s/f fender		B ₁ 348.30	✓
1pc o/s/f fender inner shield		CM 78.00	✓
1pc o/s/f fender mudflag		D ₁ /R 37.60	✓
1pc o/s headlamp		CM 288.40	✓
1pc bonnet		R 981.20	X
1pc front bumper		CM 333.90	✓
1pc front bumper o/s retainer		D ₁ 10.20	✓
1pc support panel		718.00	?
1pc bonnet o/s hinges		R 23.80	X
1pc wiper washer container assy		36.20	?
1pc wiper washer motor		81.90	?
1pc steering rack and pinion		1661.70	?
1pc cross member		943.90	?
1pc o/s/f stabilizer bar		227.20	?
1pc o/s/f lower arm		B ₁ 250.00	✓
1pc o/s/f driveshaft		940.00	?
1pc o/s/f knuckle		B ₁ 247.80	✓
1pc o/s/f bearing		B ₁ 108.30	✓
1pc o/s/f bearing hub		B ₁ 150.40	✓
1pc o/s/f front tie rod		91.30	?
1pc o/s/f stabilizer link		62.60	?
1pc o/s/f absorber		B ₁ 191.70	✓
1pc front bumper reinforcement		R 178.20	X
1pc front windscreen moulding		105.00	?
		11513.60	
		1151.36	

Less 10%

20%

LKK Auto Consultants hence 10362.24

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

HWA SENG SPRAY PAINTING CO

2 of 2

160 Sin Ming Drive, #05-11,

Sin Ming Autocity

SINGAPORE 575722

(COMPANY REGISTRATION NO. 09574400B)

TEL: 64533100

FAX: 62669932

Estimate repair cost to HYUNDAI GETZ reg no :SGJ 4479 R

c/f.....

10362.24

Labour & misc charges

Towing

1pc o/s sport rim

1pc o/s tyre

Labour to remove front windscreen

Sealant and clip

Inner seal

Labour to remove and install dashboard

Labour to remove and install air con system

Labour to remove and install door trim

Labour to remove and install under carriage

Computer wheel alignment

Wire checking

Panel knocking

Spray painting

Tuff kot

	100.00	501
B ₁	400.00	2501
P ₁	200.00	3081
	160.00	7
	80.00	7
	60.00	7
	200.00	7
	160.00	7
	120.00	601
	450.00	3201
	120.00	601
	50.00	201
	1200.00	11001
	1400.00	10001
	180.00	901

15242.24

HWA SENG SPRAY PAINTING COMPANY

