

来發 (明记) 嘛哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0018245
Lok Kok Lung

Page 2 of 2
Your ref. TP-SGM 4102L AXA
Job No. 69128
Our ref. 18.01.08
Payment
Date 8/1/2018

Attn

Vehicle No SKA 351B
Vehicle Model : Toyota Altis
Accident on ... 6/1/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Labour & Misc:					
1.00		To transfer reversing camera + cable	60.00		60.00
1.00		To transfer rear parking sensor	60.00		60.00
1.00		To apply anti rust chemical	80.00		80.00 60.
1.00		To straighten rear body including cutting and welding, to knock dents on rear tail lamp panel RH and renew of parts	700.00		700.00 600
1.00		To spray paint	700.00		700.00 600.

Not Authorised
P/P Repair
Before paint job
LKK Auto
5w 1day
FIVE
10/1/2018

Sub-Total
GST 7.00%
Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

3,552.97
248.71
3,801.68

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0018245
Lok Kok Lung

Page 1 of 2
Your ref. TP-SGM 4102L AXA
Job No. 69128
Our ref. 18.01.08
Payment
Date 8/1/2018

Attn

Vehicle No SKA 351B
Vehicle Model : Toyota Altis
Accident on ... 6/1/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Rear bumper	482.00	25.00	361.50 ✓
1.00	Pc	Rear bumper sponge	123.50	25.00	92.63 ✓
1.00	Pc	Rear bumper bracket RH	82.81	25.00	62.11 ✓
1.00	Pc	Rear end panel	552.22	25.00	414.17 ✓
1.00	Pc	Rear tail lamp gasket RH	25.10	25.00	18.83 ✓
1.00	Pc	Rear boot lid	789.10	25.00	591.83 ✓
1.00	Pc	Rear boot lid lock mechanism	96.53	25.00	72.40 ✓
1.00	Pc	Rear boot lid Corolla emblem	54.32	25.00	40.74 ✓
1.00	Pc	Rear boot lid Altis emblem	42.35	25.00	31.76 ✓
1.00	Pc	Rear boot lid Toyota logo emblem	52.15	25.00	39.11 ✓
1.00	Pc	Rear boot lid 1.6 emblem	32.13	25.00	24.10 ✓
1.00	Pc	Rear boot lid VVTi emblem	38.43	25.00	28.82 ✓
1.00	Pc	Rear end panel trim garnish	185.29	25.00	138.97 ✓
Nett item:					
1.00	Pc	Rear boot lid Dual emblem	40.00	10.00	36.00 ✓

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."