



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 7828D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	LEFT FRONT FENDER GARNISH	SCRATCHED	160.00	160.00
1	LEFT REAR FENDER GARNISH	SCRATCHED	160.00	160.00
	LESS 20% DISCOUNT		-64.00	-64.00
			256.00	256.00
	<u>LABOUR</u>			
	TO TUFF KOTE.		50.00	30.00
	TO REMOVE & REPLACE LEFT FRONT FENDER GARNISH & LEFT REAR FENDER GARNISH.TO REPAIR FRONT BUMPER & KNOCK LEFT REAR DOOR.		450.00	350.00
	TO PUTTY RESPRAY PAINTING FRONT BUMPER,LEFT FRONT FENDER & LEFT REAR DOOR.TO POLISH.		450.00	400.00
			950.00	780.00
	GRAND TOTAL		1,206.00	1,036.00
RECOMMENDED COST OF REPAIRS				1,036.00

Report Ref No. CS/FCI18000911/R1vd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.