

12/03/2012

ASS. REC. BY:

REF: CS/FCI18000915/Aqd3⁰²

Special Instruction:

Surveyor

Adrian

ASSIGNMENT (Office)

From (Person):

Teo Swee Keong

of

FCI

Date/Time:

15/01/2018 @ 7:27pm

Estimated Cost:

Bill to:

OD (TP/WS/TP RES/OD RES/EVA/INV/MV/CS)

To Inspect Vehicle No:

SKM1053 S

Insured:

SHD 6939 L

at Workshop m/s

New Hack Teck Motor

Tel:

6747 9241

of

1 Kaki Bkt Ave 6 # 81KC # 0743 Autobay

Policy No:

Claim No:

b18000550MPH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15/01/2018

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

9:09am @ 16/1/18

Person Contacted:

sukyi

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKM1053S - x
	SHD 6939L - x
12/1/18 @ 5:37pm	Informed Serene, we are pending estimate from repairer.
12/3/18 @ 11:36am	Revised to Serene by email.
	by \$11800, 8 days (Red \$11708.00, 49%)

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s: _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKM10535 Yr Regt: 2014 Jan.Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz B200 c.c. 1991Colour: Black A/C: Insured / Std / NI / NASp. Reading: 323528 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD2120342A893078Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 245/45R17R: 245/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kumho

Front: _____ Rear: _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.L. 15/01/18Survey held at NHTDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 1st Cap.

RECEIVED 12 MAR 2018

Date/Time, File Pass to? ☐ : Preli. Report1) 12/3 Insured ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 8Resurvey No. of Trip: 1

Survey Fee

Transportation

S - RS SIPhotos 057Others 13/4/18

TOTAL

Add Fee: ☐ Site Insp. (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

13x15=195

170 + 195

50

50

102

567

Report Format: TPLump Sum / I.B.A. (\$) 11800



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18000915/Aqd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 16-01-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 6939L	Veh. Inspected	SKM 1053S
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	TEO SWEE KEONG	Assign Date	16/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	15/01/2018	Inspection Date	16/01/2018
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Reference No. : C2/Fe11800w/15/AgA3
Policy Type: OD / TP / TP RES / TL / EVA

SPCM 10535

Typist

Admin (Nirphen): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

Y-Date	N-Date
✓	
✓	
✓	
✓	
✓	
✓	
✓	
✓	
✓	
✓	
✓	

Surveyor (Adrian): Case handler to make sure the surveyor completed all required information.

1) Assignment Form		
C	Vehicle No	
C	Regn Month/Year	
N	Vehicle Type	
N	Make & Model	
C	Engine Capacity. (C.C)	
N	Colour	
C	Odometer. (Sp.Reading)	
C	Chassis No	
N	General Condition	
N	Steering	
N	Brake	
N	Modification (Modi)	
C	Tyre Size	
N	Tyre Make	
C	Tyre Balance	
C	Date of Inspection	
N	Survey held	
N	Des.of Damages	

C	Damaged Vehicle Photographs Uploaded	☒	☐	☐	☐
---	--------------------------------------	-------------------------------------	--------------------------	--------------------------	--------------------------

N	ALL Parts condition			
C	Market Value for OD cases			
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)			
C	Days of repair			
C	Finalised Amount			
C	Re-inspection Cases to Finalize within 5 Days			

C	Resurvey photo Uploaded	☒	☐	☐
---	-------------------------	-------------------------------------	--------------------------	--------------------------

	10/3/18
---	---------

Date _____

[†]C: Critical *N: Non-Critical

21/05/2014

Nivitha (LKK Auto)

From: Teo Swee Keong <TeoSweeKeong@msfirstcapital.com.sg>
Sent: Monday, 15 January 2018 7:27 PM
To: 'assignments@lkkauto.com'
Cc: Serene Ler
Subject: NEW SURVEY ASSIGNMENT - OUR REF: SHD6939L DOA 15.01.18
Attachments: FW: SKM1053S CLAIMING AGAINST SHD6939L DOA 15.01.18 (716 KB); MOTOR SURVEY ASSIGNMENT.pdf

Dear Sirs

New survey request for your handling.

Thanks and Regards,

SK Teo
Motor Claims Dept

MS First Capital Insurance Ltd | 36 Robinson Road #16-01 City House Singapore 068877 | DID : 6507 3848 | Fax No. : 6507 3849 |

A member of **MS&AD** INSURANCE GROUP

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data.

Please refer to www.msfirstcapital.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Admin nht [mailto:admin@nhtmotor.com]
Sent: Monday, January 15, 2018 3:29 PM
To: Teo Swee Keong <TeoSweeKeong@msfirstcapital.com.sg>
Cc: Serene Ler <SereneLer@msfirstcapital.com.sg>; reena@nhtmotor.com
Subject: Re: YR REF: SKM1053S YR REF: SHD6939L DOA 15.01.18

Hi Swee Keong

Please arrange for LKK Auto Consultants Pte Ltd



On Mon, Jan 15, 2018 at 3:18 PM, Teo Swee Keong <TeoSweeKeong@msfirstcapital.com.sg> wrote:

Dear Sirs,

We refer to your survey request dated 15/01/2018.

Please find below our list of surveyors for your reference. Kindly select from our list below and inform us of your choice within the next 2 days.

1. LKK Auto Consultants Pte Ltd
2. Vicom Ltd

Once you inform us of your choice, the surveyor will be appointed within 2 working days of your email.

If you do not agree to any of the surveyors above, you may proceed to appoint your own surveyor. In this instance, we will also appoint a surveyor from our list above to conduct the PRI. Upon completion of repairs, please contact our appointed surveyor to conduct a physical re-inspection of the vehicle.

Thank you.

Thanks and Regards,

SK Teo

Motor Claims Dept

MS First Capital Insurance Ltd | 36 Robinson Road #16-01 City House Singapore 068877 | DID : 6507 3848 | Fax No. : 6507 3849 |

A member of **MS&AD** INSURANCE GROUP

Personal Data Protection Act 2012 ("PDPA");

Under the PDPA, there are various requirements that regulate the processing of your personal data.

Please refer to www.msfirstcapital.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Caroline Cabrera

Sent: Monday, January 15, 2018 11:12 AM

To: Teo Swee Keong <TeoSweeKeong@msfirstcapital.com.sg>

Subject: FW: SKM1053S CLAIMING AGAINST SHD6939L DOA 15.01.18

Dear SK,

For survey

Thanks & Regards

Caroline Cabrera

Motor Claims

First Capital Insurance Ltd

A member of **MS&AD** INSURANCE GROUP

36 Robinson Road #16-01 City House | Singapore 068877 | Reg. No. 195000106C

D: 6507 3848 | F: 6507 3849

email: www.first-insurance.com.sg

Personal Data Protection Act 2012 ("PDPA");

Under the PDPA, there are various requirements that regulate the processing of your personal data.

Please refer to www.first-insurance.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

*If you have received this message in error, please delete the message and all copies from your system
and notify the sender immediately by return e-mail.*

From: Admin nht [<mailto:admin@nhtmotor.com>]
Sent: Monday, January 15, 2018 10:59 AM
To: Motor_Claims <Motor_Claims@msfirstcapital.com.sg>
Cc: Reena <reena@nhtmotor.com>
Subject: SKM1053S CLAIMING AGAINST SHD6939L DOA 15.01.18

Hi Motor Claim Dept

Please send us your surveyor list, thanks.

Please take note this claim is under New Hock Teck Motor Pte Ltd

--

MOTOR SURVEY ASSIGNMENT

Date 15/1/18
Accident Date 15/1/18
Insured Vehicle SHD6939L
Our Ref No. SHD6939L
Claim Type 3rd Party
Third Party Vehicle SKM10535
Survey Location New Hock Teck Motor Pte Ltd
Contact Person Sukyi
1 Kaki Bukit Ave 6 Blk C #01-43
Contact No. AutoBay Kaki Bukit S'pore 417883
6747 9241
Fax No. 6741 7276
Survey Type Without Prejudice (Liability clear / No est. provided)
Appointed Surveyor LKK
Contact Person
Contact Number 6256 3561
Fax No. 6841 6315

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

Encl. Accident Reports & est

Cc : Workshop

Officer In charge

New Hock Teck Motor Pte Ltd

Attention

Serene Ler

Sukyi

IMPORTANT NOTE

Kindly submit the survey report by email only to surveyor@first-insurance.com.sg within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 12 March 2018 11:36 AM
To: 'Teo Swee Keong'; assignments
Cc: 'Serene Ler'; SUR
Subject: RE: NEW SURVEY ASSIGNMENT - OUR REF: SHD6939L DOA 15.01.18
Attachments: CSFC18000915Aqd3.pdf

Dear Serene,

Enclosed herewith preliminary advice of SKM 1053S.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 17 January 2018 5:37 PM
To: 'Teo Swee Keong' <TeoSweeKeong@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: NEW SURVEY ASSIGNMENT - OUR REF: SHD6939L DOA 15.01.18

Dear Serene,

Please be informed that we have inspected the vehicle SKM 1053S on 15/01/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 16 January 2018 9:13 AM
To: 'Teo Swee Keong' <TeoSweeKeong@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: NEW SURVEY ASSIGNMENT - OUR REF: SHD6939L DOA 15.01.18

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: SHD6939L

Date: 12 March 2018

Our Ref: CS/FCI18000915/Aqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKM 1053S

Please be informed that we had conducted the inspection of the abovementioned vehicle on 15/01/2018 at the premises of M/s NEW HOCK TECK, and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 23,008.20</u>
Revised Estimate Amount	: <u>S\$ 11,800.00 (Lump Sum)</u>
"Check" Items Amount	: <u>S\$ -</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$ -</u>
Nett Value	: <u>S\$ -</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 17 January 2018 5:37 PM
To: 'Teo Swee Keong'; assignments
Cc: 'Serene Ler'; SUR
Subject: RE: NEW SURVEY ASSIGNMENT - OUR REF: SHD6939L DOA 15.01.18

Dear Serene,

Please be informed that we have inspected the vehicle SKM 1053S on 15/01/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 16 January 2018 9:13 AM
To: 'Teo Swee Keong' <TeoSweeKeong@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: NEW SURVEY ASSIGNMENT - OUR REF: SHD6939L DOA 15.01.18

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo Swee Keong [<mailto:TeoSweeKeong@msfirstcapital.com.sg>]
Sent: Monday, 15 January 2018 7:27 PM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: Serene Ler <Sereneler@msfirstcapital.com.sg>
Subject: NEW SURVEY ASSIGNMENT - OUR REF: SHD6939L DOA 15.01.18

Dear Sirs

New survey request for your handling.

Thanks and Regards,

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 3851C

Vehicle Details

Vehicle No.: SKM1053S

Vehicle to be Exported: Yes

Intended De-registration Date: 15 Jan 2018

Vehicle Make: MERCEDES BENZ

Vehicle Model: E200 SEDAN (R17)

Primary Colour: Black

Manufacturing Year: 2013

Engine No.: 27492030107322

Chassis No.: WDD2120342A893078

Maximum Power Output: 135.0 kW (181 bhp)

Open Market Value: \$43,296.00

Original Registration Date: 23 Jan 2014

First Registration Date: 23 Jan 2014

Transfer Count: 0

Actual ARF Paid: \$47,615.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 22 Jan 2024

PARF Rebate Amount: \$35,711.00

Intended COE Rebate Details

COE Expiry Date:	22 Jan 2024
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$78,700.00
COE Rebate Amount:	\$47,368.00
Total Rebate Amount:	\$83,079.00

The information contained herein is correct as at 15 Jan 2018

OK



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

IMPERIAL CHAUFFEUR SERVICES PTE LTD

15/01/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP 1st Car?

Xiao Chan

WDD2120342A893078

Accident date: 15/01/2018

Estimated repair cost for vehicle no: SKM1053S MERCEDES E200 2.0 '14

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid Buckled		\$2,859.00
2	2	Rear Boot Lid Hinge Not New		\$143.00
3	1	Rear Boot Lid Emblem Logo		\$48.00
4	1	Rear Boot Lid E200 Logo		\$75.00
5	1	Rear Boot Lid 7g-Tronic Logo		\$62.00
6	1	Rear Boot Lid Cnc Logo		\$55.00
7	1	Rear Boot Lid Inner Lock Damaged		\$870.00
8	1	Rear Boot Lid Inner Rubber		\$165.00
9	1	Rear Boot Lid Inner Trim Board		\$220.00
10	1	Rear Boot Lid Centre Chrome Moulding		\$128.00
11	2	Rear Boot Lid Side Retainer Reflector	\$451.00	\$902.00
12	2	Rear Tail Lamp cracked	\$737.00	\$1,474.00
13	2	Rear Tail Lamp Inner Side Cover	\$38.00	\$76.00
14	8	Rear Tail Lamp Inner Side Cover Clip	\$6.50	\$52.00
15	1	Rear Bumper Deformed		\$1,765.00
16	1	Rear Bumper Lower Deformed		\$338.00
17	8	Rear Bumper Clip	\$6.50	\$52.00
18	2	Rear Bumper Side Retainer	\$48.00	\$96.00
19	1	Rear Bumper Reinforcement Best		\$762.00
20	1	Rear Bumper Centre Top Beam Deformed		\$145.00
21	1	Rear Bumper Towing Cover Deformed		\$67.00
22	4	Rear Bumper Reverse Sensor Damaged	\$202.00	\$808.00
23	4	Rear Bumper Reverse Sensor Holder Bracket	\$68.00	\$272.00
24	1	Rear End Panel Dented		\$1,296.00
25	1	Rear End Panel Inner Repair		\$345.00
26	1	Rear End Panel Top Garnish cracked		\$170.00
27	1	Rear End Panel Lock Sensor Damaged		\$370.00
28	2	Rear Fender Inner Trim Board	\$295.00	\$590.00

29	1	Rear Spare Tyre Panel <i>Repairs</i>		\$276.00	x
30	1	Rear Spare Tyre Panel Top Cover <i>deformed</i>		\$365.00	✓
31	1	Rear Spare Tyre Panel & End Panel Sealant <i>He m</i>		\$450.00	x
32	1	Rear Exhaust <i>Bent</i>		\$1,875.00	✓
33	1	Rear Centre Exhaust <i>2 m</i>		\$1,363.00	✓
34	2	Rear Exhaust Mounting <i>m</i>	\$29.60	\$59.20	+
35	1	Rear Exhaust Aluminium Cover		\$105.00	x

Subtotal :- \$18,698.20

13757
12381.30

Labour charges

To remove & refit cushion	\$280.00	60
To remove & refit reverse sensor	\$100.00	60
To remove & refit rear & centre exhaust	\$380.00	100
To check wiring	\$100.00	30
Tuff kote	\$150.00	x 80
Towing fee	2450	\$100.00 x
Panel beating	\$1,600.00	1100
Spray painting	\$1,600.00	800

To perform diagnostic test
to transfer *boothid* fittings.

200 120
200 100

Subtotal :- \$4,310.00

Total :- \$23,008.20

total 14811.30

h/s 11.8K

08 days

11.8K
08 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18000915/Aqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 15-03-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6939L	Veh. Inspected	SKM 1053S	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18000550MFSH	Excess (\$)	0.00	
Assign From	TEO SWEE KEONG	Assign Date	15/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ E200	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WDD2120342A893078	Colour	BLACK	
Odometer	323528	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/45 R17	KUMHO	6 mm	
L/H Front Tyre	245/45 R17	KUMHO	6 mm	
R/H Rear Tyre	245/45 R17	KUMHO	6 mm	
L/H Rear Tyre	245/45 R17	KUMHO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/01/2018	Inspection Date	15/01/2018	
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKM 1053S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID	BUCKLED	2,859.00	2,570.00
2	REAR BOOT LID HINGE	NOT NECESSARY	143.00	-
1	REAR BOOT LID EMBLEM LOGO	NECESSARY	48.00	48.00
1	REAR BOOT LID E200 LOGO	NECESSARY	75.00	75.00
1	REAR BOOT LID 7G-TRONIC LOGO	NECESSARY	62.00	62.00
1	REAR BOOT LID CNC LOGO	NECESSARY	55.00	55.00
1	REAR BOOT LID INNER LOCK	DAMAGED	870.00	347.00
1	REAR BOOT LID INNER RUBBER	CUT	165.00	165.00
1	REAR BOOT LID INNER TRIM BOARD	NOT NECESSARY	220.00	-
1	REAR BOOT LID CENTRE CHROME MOULDING	NOT NECESSARY	128.00	-
2	REAR BOOT LID SIDE REFLECTOR @\$451.00	CUT	902.00	902.00
2	REAR TAIL LAMP @\$737.00	CRACKED	1,474.00	1,474.00
2	REAR TAIL LAMP INNER SIDE COVER @\$38.00	CUT	76.00	76.00
8	REAR TAIL LAMP INNER SIDE COVER CLIP @\$6.50	NECESSARY	52.00	20.00
1	REAR BUMPER	DEFORMED	1,765.00	1,661.00
1	REAR BUMPER LOWER	DEFORMED	338.00	338.00
8	REAR BUMPER CLIP @\$6.50	NECESSARY	52.00	52.00
2	REAR BUMPER SIDE RETAINER @\$48.00	NECESSARY	96.00	96.00
1	REAR BUMPER REINFORCEMENT	BENT	762.00	762.00
1	REAR BUMPER CENTRE TOP BEAM	DEFORMED	145.00	145.00
1	REAR BUMPER TOWING COVER	DEFORMED	67.00	67.00
4	REAR BUMPER REVERSE SENSOR @\$202.00	DAMAGED	808.00	808.00
4	REAR BUMPER REVERSE SENSOR HOLDER BRACKET @\$68.00	DAMAGED (2 PCS ONLY)	272.00	136.00
1	REAR END PANEL	DENTED	1,296.00	1,018.00
1	REAR END PANEL INNER	TO REPAIR SEE LABOUR	345.00	-
1	REAR END PANEL TOP GARNISH	CRACKED	170.00	170.00
1	REAR END PANEL LOCK SENSOR	DAMAGED	370.00	370.00
2	REAR FENDER INNER TRIM BOARD @\$295.00	NOT NECESSARY	590.00	-
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	276.00	-

Report Ref No. CS/FCI18000915/Aqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR SPARE TYRE PANEL TOP COVER	DEFORMED	365.00	365.00
1	REAR SPARE TYRE PANEL & END PANEL SEALANT	NOT NECESSARY	450.00	-
1	REAR EXHAUST	BENT	1,875.00	1,875.00
1	REAR CENTRE EXHAUST	NOT NECESSARY	1,363.00	-
2	REAR EXHAUST MOUNTING @\$29.60	NOT NECESSARY	59.20	-
1	REAR EXHAUST ALUMINIUM COVER	NOT NECESSARY	105.00	-
	LESS 10% DISCOUNT		-	-1,365.70
			18,698.20	12,291.30
	LABOUR			
	TO REMOVE & REFIT CUSHION.		280.00	60.00
	TO REMOVE & REFIT REVERSE SENSOR.		100.00	60.00
	TO REMOVE & REFIT REAR & CENTRE EXHAUST.		380.00	100.00
	TO CHECK WIRING.		100.00	30.00
	TUFF KOTE.		150.00	80.00
	TOWING FEE.	NOT NECESSARY	100.00	-
	PANEL BEATING INCLUSIVE OF THE REPAIR OF REAR END PANEL INNER AND REAR SPARE TYRE PANEL.		1,600.00	1,100.00
	SPRAY PAINTING.		1,600.00	800.00
	TO PERFORM DIAGNOSTIC TEST.		200.00	120.00
	TO TRANSFER BOOTLID FITTINGS.		200.00	100.00
			4,710.00	2,450.00
	GRAND TOTAL		23,408.20	14,741.30
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			11,800.00

Report Ref No. CS/FCI18000915/Aqd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.