

ASS. REC. BY:

REF:

CS/GM18000522/Urbn2

Special Instruction:

Surveyor:

MARCUS

ASSIGNMENT (Office)

From (Person):

Rachel Tan

of

AHL

Date/Time:

16/01/2018 10:33am

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBF 338X

Insured:

GBC 8181T

at Workshop m/s

Fastech Auto

Tel:

6746 5405

of

Blk 1 Kerk Bukit Ave 6 #01-45

Policy No:

Claim No:

CLMOMVC000002338

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A.

13/01/2018

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time:

16/01/2018 10:52am

Person Contacted:

Nancy

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GBF 338X - X

GBC 8181T - NA/GA18000811/r3

DOA: 12/01/2018

17/1/18

Email Rachel informed pending est from repairer

5/2/18

Email preli revised to Rachel

08/11/18 waf

AS3. REC. BY: Marcus

REF:

GAI/
ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s:

of:

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR. Seen:

Consistent? : Yes or No

Est. Repairs:

10

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Date / Time

Action / Instruction

2/2/18

4/5 @ 11000 confirmed with Alan.

7/2/18

Confirmed with CI

DOA: 13/1/18

Veh No:

G13F338X

Yr Regn:

5 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Topto Dyne

o.c.

2882

Colour:

S.hue

A/C:

Insured / Std / NI / NA

Sp. Reading

74760

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195-R15

R:

155-R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

6

mm

R/Bal:

6/6

mm

L/Bal:

6

mm

L/Bal:

6/6

mm

D.O.A:

13/1/18

D.O.A:

16/1/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & H.

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 07 FEB 2018

Date/Time: File Pass to?



Preli. Report

1)



Final Report

Date/Time: File Return to?

2)

7/2 - typist

Report Format:

TP

Lump Sum / I.B.I. (\$

11,000)

Days Of Repair:

10

Resurvey No. of Trip:

2

Survey Fee

Transportation

Add Fee:



Site Insp (\$

) S - RS S



Interview (\$

) Photos



Tech. Invs (\$

) Others



Weekend (\$

)

TOTAL

450



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI18000922/Uvb

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 16-01-2018



Code : GAI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 8181T	Veh. Inspected	GBF 338X
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	RACHEL TAN	Assign Date	16/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	13/01/2018	Inspection Date	16/01/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

Company Registration No. 19960711

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564

Your Ref: PLEASE ADVISED
Our Ref: CS/GAI18000922/Uvb

Date: 5/2/2018

The Motor Claims Department
M/s: GREAT AMERICAN INSURANCE COMPANY

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. GBF 338X


We thank you for your instruction on 16/1/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 16/1/2018 at the premises of M/s FASTECH AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$37,921.95
Revised Estimate Amount	: S\$11,000.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear and front portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

Survey Department Check List (Case Handler)

Reference No.: CS/ GAI/8000922/UVB
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 5/2/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 7 February 2018 11:05 AM
To: 'Tan, Rachel'
Cc: SUR
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF338X (GBC8181T - GA)
Attachments: photo.pdf

Dear Rachel,

According to surveyor, the vehicle sustained damage at its rear portion and front portion. The rear tailgate, rear end panel were affected by the collision, cutting and welding works were required as part of the repair.

Similarly the front portion would require cutting and welding as the front panel was affected. Labour, repair and spray paint total 10 days,

We attached survey photos for your review.

We have checked and confirmed DOA is 13/1/2018.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [<mailto:Rachel.Tan@sg.gaig.com>]
Sent: Monday, 5 February 2018 11:39 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF338X (GBC8181T - GA)

Hi Veron

Please confirm repair cost \$11K and 10 days for repair.
Any damage photos?
From GIA report doesn't seem like need 10 days for repair.

Regards
Rachel Tan
Executive, Motor Claims, Great American Insurance Company
Tel: 6804 7846

From: Tan, Rachel
Sent: Monday, February 5, 2018 11:36 AM
To: 'Veron Chen (LKKAUTO)' <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF338X (GBC8181T - GA)

Hi Veron

CLMOMVC000002338 GBC8181T (OI) with GBF338X (LIB) and SLM1998D

Please confirm if DOA is 12 Jan 2018 or 13 Jan.
Our records shows 12 Jan

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company
Tel: 6804 7846

From: Veron Chen (LKKAUTO) [<mailto:veronchen@lkkauto.com>]

Sent: Monday, February 5, 2018 11:34 AM

To: Tan, Rachel <Rachel.Tan@sg.gaig.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF338X (GBC8181T - GA)

Dear Rachel,

Enclosed preliminary revised of vehicle GBF 338X
Date of survey: 16/1/2018
Number of days:10 days

Kindly provides us the claim number.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)

Sent: Wednesday, 17 January 2018 3:11 PM

To: 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF338X (GBC8181T - GA)

Dear Rachel,

Please be informed that we have inspected the vehicle GBF 338X on 16/1/2018.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Tuesday, 16 January 2018 10:42 AM

To: 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>

Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF338X (GBC8181T - GA)

Dear Rachel,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [<mailto:Rachel.Tan@sg.gaig.com>]

Sent: Tuesday, 16 January 2018 10:18 AM

To: Nancy Lam <nancy.lam@fastechauto.com.sg>

Cc: SUR <sur@lkkauto.com>

Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF338X (GBC8181T - GA)

Without Prejudice

Dear Nancy

Noted on your request, please provide estimates too.

Dear LKK

Please accept assignment to conduct PRS. Attached is TP GIA report.

Thank you,



Regards,

Rachel Tan, Executive | P. +65 6804 7846 | Rachel.tan@sg.gaig.com



Claims | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190

This email transmission, including any attachments, is intended solely for the addressee named above, and may contain confidential or privileged information. If you are not the intended recipient, be aware that any disclosure, copying, distribution or use of the contents of this e-mail is prohibited. If you have received this e-mail in error, please notify the sender immediately by reply email and destroy the message and its attachments.



For more information on our financial ratings, visit GAIG.com/FinancialStrength.

From: Nancy Lam [mailto:nancy.lam@fastechauto.com.sg]
Sent: Tuesday, January 16, 2018 10:15 AM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF338X (GBC8181T - GA)

Without Prejudice

Dear Rachel

Please arrange LKK Auto Consultants to survey the car.

Regards,
Nancy Lam
Fastech Auto Pte Ltd
Tel: 6746 5405
Fax: 6745 8520

From: Nancy Lam [mailto:nancy.lam@fastechauto.com.sg]
Sent: Monday, January 15, 2018 1:34 PM
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Subject: FW: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF338X

Hi Kelvyna

Attached our insured GIA report for your reference.

Regards,
Nancy Lam
Fastech Auto Pte Ltd
Tel: 6746 5405
Fax: 6745 8520

From: Nancy Lam [mailto:nancy.lam@fastechauto.com.sg]
Sent: Saturday, January 13, 2018 12:01 PM
To: 'kelvyna.ngian@sg.gaig.com' <kelvyna.ngian@sg.gaig.com>
Subject: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF338X

Hi Sir

My client claiming your insured GBC 8181T.

Please kindly arrange PRS for GBF 338X .

Date of accident 13.01.2018

In accordance to APPENDIX C Pre-action Protocol for Non-Injury Motor Accident Cases of PRACTICE DIRECTIONS AMENDMENT NO. 1 OF 2016 paragraph 2.3, you are require to provide a list of at least 10 motor surveyors within 2 days of the notice.

Regards,
Nancy Lam
Fastech Auto Pte Ltd
Tel: 6746 5405
Fax: 6745 8520

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Veron Chen (LKKAUTO)

To: Tan, Rachel
Cc: SUR
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF338X (GBC8181T - GA)
Attachments: photo.pdf

Don

Dear Rachel,

Enclosed herewith damage photos.

*The vehicle sustained damage at its
rear & portion and front portion.*

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

*The rear & tailgate, rear end panel were
affected by the collision. Cutting
and welding works were required as*

From: Tan, Rachel [mailto:Rachel.Tan@sg.gaig.com]

Sent: Monday, 5 February 2018 11:39 AM

To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF338X (GBC8181T - GA)

Part of the repair:

Similarly, the front portion

Hi Veron

*it would require a cutting and welding
as the front panel was affected.*

Please confirm repair cost \$11K and 10 days for repair.

Any damage photos?

From GIA report doesn't seem like need 10 days for repair.

We estimate Labour, repair and

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

*spray painting total 10
days.*

From: Tan, Rachel

Sent: Monday, February 5, 2018 11:36 AM

To: 'Veron Chen (LKKAUTO)' <veronchen@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF338X (GBC8181T - GA)

*We attached spray photos for
your review.*

Hi Veron

CLMOMVC000002338 GBC8181T (OI) with GBF338X (LIB) and SLM1998D

Please confirm if DOA is 12 Jan 2018 or 13 Jan.

Our records shows 12 Jan

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 5 February 2018 11:34 AM
To: 'Tan, Rachel'
Cc: SUR
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF338X (GBC8181T - GA)
Attachments: GBF 338X PRELI REVISED.pdf

Dear Rachel,

Enclosed preliminary revised of vehicle GBF 338X
Date of survey: 16/1/2018
Number of days:10 days

Kindly provides us the claim number.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 17 January 2018 3:11 PM
To: 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF338X (GBC8181T - GA)

Dear Rachel,

Please be informed that we have inspected the vehicle GBF 338X on 16/1/2018.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 16 January 2018 10:42 AM
To: 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF338X (GBC8181T - GA)

Dear Rachel,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [<mailto:Rachel.Tan@sg.gaig.com>]

Sent: Tuesday, 16 January 2018 10:18 AM

To: Nancy Lam <nancy.lam@fastechauto.com.sg>

Cc: SUR <sur@lkkauto.com>

Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF338X (GBC8181T - GA)

Without Prejudice

Dear Nancy

Noted on your request, please provide estimates too.

Dear LKK

Please accept assignment to conduct PRS. Attached is TP GIA report.

Thank you,

Regards,

Rachel Tan, Executive | P. +65 6804 7846 | Rachel.tan@sg.gaig.com



Claims | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190

This email transmission, including any attachments, is intended solely for the addressee named above, and may contain confidential or privileged information. If you are not the intended recipient, be aware that any disclosure, copying, distribution or use of the contents of this e-mail is prohibited. If you have received this e-mail in error, please notify the sender immediately by reply email and destroy the message and its attachments.



Moody's
A1 (Good)
Affirmed June 13, 2018

Standard & Poor's
A+ (Strong)
Affirmed March 2, 2018

For more information on our financial ratings, visit GAIG.com/FinancialStrength.

From: Nancy Lam [<mailto:nancy.lam@fastechauto.com.sg>]

Sent: Tuesday, January 16, 2018 10:15 AM

To: Tan, Rachel <Rachel.Tan@sg.gaig.com>

Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF338X (GBC8181T - GA)

Without Prejudice

Dear Rachel

Please arrange LKK Auto Consultants to survey the car.

Regards,
Nancy Lam
Fastech Auto Pte Ltd
Tel: 6746 5405
Fax: 6745 8520

From: Nancy Lam [mailto:nancy.lam@fastechauto.com.sg]
Sent: Monday, January 15, 2018 1:34 PM
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Subject: FW: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF338X

Hi Kelvyna

Attached our insured GIA report for your reference.

Regards,
Nancy Lam
Fastech Auto Pte Ltd
Tel: 6746 5405
Fax: 6745 8520

From: Nancy Lam [mailto:nancy.lam@fastechauto.com.sg]
Sent: Saturday, January 13, 2018 12:01 PM
To: 'kelvyna.ngian@sg.gaig.com' <kelvyna.ngian@sg.gaig.com>
Subject: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF338X

Hi Sir

My client claiming your insured GBC 8181T.

Please kindly arrange PRS for GBF 338X .

Date of accident 13.01.2018

In accordance to APPENDIX C Pre-action Protocol for Non-Injury Motor Accident Cases of PRACTICE DIRECTIONS AMENDMENT NO. 1 OF 2016 paragraph 2.3, you are require to provide a list of at least 10 motor surveyors within 2 days of the notice.

Regards,
Nancy Lam
Fastech Auto Pte Ltd
Tel: 6746 5405
Fax: 6745 8520

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 17 January 2018 3:11 PM
To: 'Tan, Rachel'
Cc: SUR
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF338X (GBC8181T - GA)

Dear Rachel,

Please be informed that we have inspected the vehicle GBF 338X on 16/1/2018.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 16 January 2018 10:42 AM
To: 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF338X (GBC8181T - GA)

Dear Rachel,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [<mailto:Rachel.Tan@sg.gaig.com>]
Sent: Tuesday, 16 January 2018 10:18 AM
To: Nancy Lam <nancy.lam@fastechauto.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF338X (GBC8181T - GA)

Without Prejudice

Dear Nancy

Noted on your request, please provide estimates too.

Dear LKK

Please accept assignment to conduct PRS. Attached is TP GIA report.

Thank you,
Regards,

Rachel Tan, Executive | P. +65 6804 7846 | Rachel.tan@sg.gaig.com



Claims | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190

This email transmission, including any attachments, is intended solely for the addressee named above, and may contain confidential or privileged information. If you are not the intended recipient, be aware that any disclosure, copying, distribution or use of the contents of this e-mail is prohibited. If you have received this e-mail in error, please notify the sender immediately by reply email and destroy the message and its attachments.



Moody's
A1 (Good)
Affirmed June 15, 2015

Standard & Poor's
A+ (Strong)
Affirmed March 2, 2016

For more information on our financial ratings, visit GAIG.com/FinancialStrength.

From: Nancy Lam [<mailto:nancy.lam@fastechauto.com.sg>]
Sent: Tuesday, January 16, 2018 10:15 AM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF338X (GBC8181T - GA)

Without Prejudice

Dear Rachel

Please arrange LKK Auto Consultants to survey the car.

Regards,
Nancy Lam
Fastech Auto Pte Ltd
Tel: 6746 5405
Fax: 6745 8520

From: Nancy Lam [<mailto:nancy.lam@fastechauto.com.sg>]
Sent: Monday, January 15, 2018 1:34 PM
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Subject: FW: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF338X

Hi Kelvyna

Attached our insured GIA report for your reference.

Regards,
Nancy Lam
Fastech Auto Pte Ltd
Tel: 6746 5405

Fax: 6745 8520

From: Nancy Lam [mailto:nancy.lam@fastechauto.com.sg]
Sent: Saturday, January 13, 2018 12:01 PM
To: 'kelvyna.ngian@sg.gaig.com' <kelvyna.ngian@sg.gaig.com>
Subject: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF338X

Hi Sir

My client claiming your insured GBC 8181T.

Please kindly arrange PRS for GBF 338X .

Date of accident 13.01.2018

In accordance to APPENDIX C Pre-action Protocol for Non-Injury Motor Accident Cases of PRACTICE DIRECTIONS AMENDMENT NO. 1 OF 2016 paragraph 2.3, you are require to provide a list of at least 10 motor surveyors within 2 days of the notice.

Regards,
Nancy Lam
Fastech Auto Pte Ltd
Tel: 6746 5405
Fax: 6745 8520

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Catherine Chong (LKK Auto)

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Tuesday, 16 January, 2018 10:33 AM
To: assignments
Subject: FW: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF338X (GBC8181T - GA)
Attachments: GBF338X GIA Report.PDF

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [mailto:Rachel.Tan@sg.gaig.com]
Sent: Tuesday, 16 January 2018 10:18 AM
To: Nancy Lam <nancy.lam@fastechauto.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF338X (GBC8181T - GA)

Without Prejudice

Dear Nancy

Noted on your request, please provide estimates too.

Dear LKK

Please accept assignment to conduct PRS. Attached is TP GIA report.

Thank you,

Regards,

Rachel Tan, Executive | P. +65 6804 7846 | Rachel.tan@sg.gaig.com



Claims | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190

This email transmission, including any attachments, is intended solely for the addressee named above, and may contain confidential or privileged information. If you are not the intended recipient, be aware that any disclosure, copying, distribution or use of the contents of this e-mail is prohibited. If you have received this e-mail in error, please notify the sender immediately by reply email and destroy the message and its attachments.



Moody's
A1 (Good)
Attained June 15, 2015

Standard & Poor's
A+ (Strong)
Attained March 2, 2016

For more information on our financial ratings, visit GAIG.com/FinancialStrength.

From: Nancy Lam [<mailto:nancy.lam@fastechauto.com.sg>]
Sent: Tuesday, January 16, 2018 10:15 AM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Subject: RE: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF338X (GBC8181T - GA)

Without Prejudice

Dear Rachel

Please arrange LKK Auto Consultants to survey the car.

Regards,
Nancy Lam
Fastech Auto Pte Ltd
Tel: 6746 5405
Fax: 6745 8520

From: Nancy Lam [<mailto:nancy.lam@fastechauto.com.sg>]
Sent: Monday, January 15, 2018 1:34 PM
To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>
Subject: FW: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF338X

Hi Kelvyna

Attached our insured GIA report for your reference.

Regards,
Nancy Lam
Fastech Auto Pte Ltd
Tel: 6746 5405
Fax: 6745 8520

From: Nancy Lam [<mailto:nancy.lam@fastechauto.com.sg>]
Sent: Saturday, January 13, 2018 12:01 PM
To: 'kelvyna.ngian@sg.gaig.com' <kelvyna.ngian@sg.gaig.com>
Subject: REQUEST FOR PRE-REPAIR INSPECTION OUR REF:GBF338X

Hi Sir

My client claiming your insured GBC 8181T.

Please kindly arrange PRS for GBF 338X .

Date of accident 13.01.2018

In accordance to APPENDIX C Pre-action Protocol for Non-Injury Motor Accident Cases of PRACTICE DIRECTIONS AMENDMENT NO. 1 OF 2016 paragraph 2.3, you are require to provide a list of at least 10 motor surveyors within 2 days of the notice.

Regards,
Nancy Lam
Fastech Auto Pte Ltd
Tel: 6746 5405
Fax: 6745 8520

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	4530K

Vehicle Details

Vehicle No.:	GBF338X
Vehicle to be Exported:	No
Intended De-registration Date:	16 Jan 2018
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA DYNA 150 MANUAL
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	1KD2607440
Chassis No.:	JTFAT35Y20K206377
Maximum Power Output:	-
Open Market Value:	\$24,944.00
Original Registration Date:	25 May 2016
First Registration Date:	25 May 2016
Transfer Count:	0
Actual ARF Paid:	\$1,248.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	24 May 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$21,722.00
COE Rebate Amount:	\$18,148.00
Total Rebate Amount:	\$18,148.00

The information contained herein is correct as at 16 Jan 2018

OK

New Cars

Used Cars

Sell My Car

Directory

Products

Articles

Forum

Tools & Tips

DISCOVER MEDAN AND PADANG
Daily Flights

39
NEW Destinations

Book now
Travel from 7 May 2018 till 31 Jan 2019
*Terms and conditions apply.

AirAsia

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Toyota Harrier Elegance 2.0



Almost New Toyota Harrier.
Direct Owner Sales.
Direct Owner StarAd

Think One Automobile

NEW & USED COMMERCIAL VEHICLES

Browse by Category

Sort by Date Posted

20 results/page

15 vehicles

toyota dyna

Advanced Search Submit

Search Selection

Make

toyota dyna

Model

Any

Price

Any

Depreciation

Any

Reg Date

2016

Eng Cap

Any

Mileage

Any

Veh Type

Any

Status

Available

Toyota Dyna 150

\$63,800

\$7,820 /yr

15-Mar-2016

2,982 cc

-

Truck

Available

Fuel Type:

Diesel

1 Ownership Only, Maintain By Borneo Motor. Comes With Full Length Canopy & Fully Covered Checkered Plate. Saving Of Almost 2K. SUPERB Condition, View To Appreciate. Financing Available And Competitive I...

Posted: 15-Jan-2018

Tags: 2016 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota

Toyota Dyna 150

\$67,888

\$8,270 /yr

01-Apr-2016

2,982 cc

-

Truck

Available

Fuel Type:

Diesel

1 Owner, Best Selling Toyota Dyna 10 Feet Lorry. Like New, Showroom Condition. 100% Loan Available, \$0 Drive Away. High Trade In. Act Fast, Don't Miss It, Call Now For More Details.

Posted: 15-Jan-2018

Tags: 2016 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota

Toyota Dyna 150

\$79,800

\$9,010 /yr

22-Nov-2016

2,982 cc

-

Truck

Available

Fuel Type:

Diesel

Cabin Height Thermoking Freezer Worth \$16,000. Goes Up To -30 Degrees, Suitable For Ice Cream And Many Frozen Products. Almost New Condition, Come Down And View Before This Rare Beauty Disappears.

Posted: 13-Jan-2018

Tags: 2016 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota

Toyota Dyna 150

\$70,800

\$8,230 /yr

24-Aug-2016

2,982 cc

-

Truck

Available

Fuel Type:

Diesel

A Super Excellent Condition Dyna, Low Mileage, Only Drive For 2 Years, Look Like New, Hope To Find A True Lover To Take Over The Vehicle, With A Smooth And Buttery Drive To Carry You With Your Daily L...

Posted: 12-Jan-2018

Tags: 2016 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota

Toyota Dyna 150

\$69,800

\$8,180 /yr

29-Jul-2016

2,982 cc

-

Truck

Available

Fuel Type:

Diesel

1 Owner, Owner Going To Oversea To Work So Ask Me To Help Him To Sell, He Hope The Dyna Can Entrust To Someone Can Cherish It, Come And View The Smooth And Buttery Drive That Can Carry You With Your D...

Posted: 12-Jan-2018

Tags: 2016 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota

Toyota Dyna 150

\$67,888

\$8,050 /yr

21-Jun-2016

2,982 cc

-

Truck

Available

Fuel Type:

Diesel

1 Owner Only And Low Mileage! Like Brand New Condition, No Repairs Needed! Nice Number Plate! 100% Loan, \$0 Down Payment Required. Easy In House Loan Available. Don't Miss It. Call Now!

Posted: 10-Jan-2018

Tags: 2016 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota

Car Buying

Car Ownership

Car Selling

On The Move

Car Aftermarket

Lifestyle

Buying a pre-owned car, but Unsure of its Condition?

Get, STA Car Evaluation

Compare

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/01/2018 09:46
Date Of Accident	13/01/2018 09:20
Exact Location Of Accident	ALONG CTE >TWRDS AYE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF338X
Insured/Policyholder	
Name Of Registered Owner	AT CARPENTRY PTE LTD
Co Reg No	20104530K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90000000
Vehicle Particulars	
Manufacturer	TOYOTA
Model	TOYOTA DYNA 150 MANUAL
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD17V05935/VCV/R00
Cover Note Number	
Driver	
Name of Driver	MURUGIAH ARUNACHALAM
Passport No/FIN	G7899482M
Date Of Birth	04/05/1983
Occupation	OUTDOOR
Date Of Driving Pass	28/06/2011
Driving Experience	6 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83954435
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 8 BURN ROAD #01-08 TRIVEX
Postcode 369977
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions RAINING
Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 4
Passenger 1 NAME: : QIAN CHUAN
GENDER: : MALE
Passenger 2 NAME: : KHAN MD ABBAS ALI
GENDER: : MALE
Passenger 3 NAME: : MENG XIANG FEI
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN:

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBC8181T
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver
NRIC/Passport Number
Contact Number

Address

Postcode

Insurance Company Name

GREAT AMERICAN INSURANCE COMPANY

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SLM1998D

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

MURUGIAH ARUNACHALAM

Approximate Age

Injuries Sustain

Injured person in which vehicle?

GBF338X

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

Address

8 BURN ROAD #01-08 TRIVEX

Postcode

369977

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT(VAC)
23 KAKI BUKIT AVE 4
Reporting Centre Personnel's Signature
Singapore 415933
Name: Tel: 67416697
NRIC/FIN No.: Fax: 67492305
Email: vackb@singnet.com.sg

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 13/01/18 at 9.20am, I was driving my vehicle (A) along CTE towards Ayer. In front vehicle (C) stop. I fell on suit. suddenly vehicle (B) hit on my rear portion and cause my car to push forward and hit on vehicle (C). There 3 cars involved in an accident.

vehicle (A) - 3 passengers

- ① Qian Chuan (M) 056796959
- ② Khan Md Abbas Ali (M) 063045098
- ③ Meng Xiang Fei (M) 07 6042462

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Amey

IDAC KAKI BUKIT (VAC)
23 KAKI BUKIT AVE 4

Reporting Centre
Name: *Singnet*
Tel: 67416097
NRIC/FIN No.: *41933*
Fax: 67492305
Email: vackb@singnet.com.sg

FASTECH AUTO PTE LTD

VEHICLE NO: GBF338X

Qty Particular

Amount S\$

List Item:

1 PCS	TAILGATE	Body 20	\$ 1,645.10	✓
1 PCS	TAILGATE 'TOYOTA' STICKER	neu	\$ 121.10	✓
1 PCS	TAILGATE DYNA STICKER	neu	\$ 45.50	✓
1 PCS	TAILGATE LOWER MEMBER	20/200	\$ 545.10	✓
1 PCS	TAILGATE LOCK LATCH N/S	neu	\$ 119.30	✓
1 PCS	TAILGATE LOWER 'L' PANEL N/S	neu	\$ 82.50	✓
1 PCS	TAILGATE LOWER 'L' PANEL RUBBER N/S	neu	\$ 62.30	✓
2 PCS	TAILLAMPS @\$285.30	Misc	\$ 570.60	1 pc
2 PCS	TAILLAMP BRACKETS @\$119.30	neu	\$ 238.60	X
1 PCS	DROP SIDEGATE N/S	neu	\$ 2,101.10	X
1 PCS	DROP SIDEGATE LOWER MEMBER N/S	neu	\$ 688.50	X
1 PCS	REAR EXHAUST PIPE	11	\$ 585.20	X
1 PCS	REAR SPARE TYRE CHAIN & BRACKET	neu	\$ 392.50	✓
1 PCS	FRONT BUMPER	20/200 698.90	\$ 1,698.90	✓
2 PCS	FRONT BUMPER BRACKETS @\$112	neu	\$ 224.00	✓
1 PCS	FRONT CENTRE CROSS MEMBER	20/200 862.30	\$ 1,662.30	✓
2 PCS	HEADLAMPS @\$673.31	neu	\$ 1,346.62	✓
2 PCS	FRONT CABIN MOUNTINGS @\$279.60	11	\$ 559.20	X
1 PCS	FRONT GRILLE	neu	\$ 807.92	✓
1 PCS	FRONT GRILLE LOGO	neu	\$ 56.90	✓
1 SET	FRONT GRILLE CLIPS	neu	\$ 20.00	✓
1 PCS	FRONT GRILLE RUBBER	neu	\$ 43.70	✓
1 PCS	FRONT PANEL	20/200 959.10	\$ 1,959.10	✓
1 PCS	FRONT PANEL DYNA EMBLEM	neu	\$ 48.50	✓
1 PCS	FRONT PANEL TOP CENTRE GARNISH (BLACK)	neu	\$ 288.31	✓
2 PCS	FRONT CORNER GARNISH (BLACK) @\$178.60	Misc	\$ 357.20	1 pc
2 PCS	FRONT CORNER PANELS @\$195.27	neu	\$ 390.54	X
1 PCS	FRONT WIPER PANEL CENTRE	11	\$ 279.88	X
2 PCS	FRONT WIPER ARMS @\$192.91	11	\$ 385.82	X
1 PCS	FRONT WIPER LINK	11	\$ 276.82	X
1 PCS	FRONT WIPER MOTOR	11	\$ 927.96	X
1 PCS	FRONT DASHBOARD	20/200 124.8	\$ 928.86	✓
1 PCS	AIRCON BLOWER HOUSING	neu	\$ 998.90	✓
1 PCS	AIRCON COIL HOUSING	11	\$ 1,098.70	X
1 PCS	HEATER HOUSING ASSY	neu	\$ 1,484.92	✓
1 PCS	FRONT BRAKE BOOSTER	11	\$ 1,053.31	X
1 PCS	FRONT BRAKE CYLINDER MASTER PUMP	11	\$ 587.90	X
2 PCS	FRONT DOORS @\$1927.80	neu	\$ 3,855.60	X
1 PCS	FRONT WINDSCREEN RUBBER	neu	\$ 247.69	✓
4 PCS	FRONT BRAKE PIPES @\$215	11	\$ 860.00	X
List Item Total:			\$ 29,646.95	

Special Nett Item:

1 PCS	TAILGATE 70KM/HR STICKER	neu	\$ 20.00	105.2
-------	--------------------------	-----	----------	-------

not allowed
d/s \$11,000
10 day.
166.118

25%

12493.52
9370.44

1 PCS 13PAX STICKER
 1 SET REAR REVERSE SENSOR
 1 PCS REAR STEP BAR
 1 PCS REAR LICENCE PLATE
 1 PCS REAR LICENCE PLATE BRACKET
 1 PCS FRONT LICENCE PLATE
 2 PCS FRONT DOOR ROC STICKERS @\$30
 Special Nett Total:

rec \$ 20.00 10
 shold \$ 280.00 200
 bar \$ 380.00 300
 bar \$ 20.00 15
 n \$ 85.00 X
 bar \$ 20.00 15
 m \$ 60.00 ✓
 \$ 885.00

Labour Charge:

TO CHECK WIRING
 TO DISMANTLE & REPLACE REVERSE SENSOR
 TO DISMANTLE & REFIX REAR EXHAUST
 TO DISMANTLE & REFIX FRONT WINDSCREEN
 TO DISMANTLE & REPLACE FRONT DASHBOARD
 TO REFILL AIRCON GAS
 TO DISMANTLE & REPLACE HEATER, COOLING HOUSING
 TO SPRAY RUST PROOFING
 TO TRANSFER BOTH DOOR MECHANISM
 LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS
 TO PUTTY & SPRAY PAINTING
 Labour Charge Total:

\$ 80.00 30
 \$ 80.00 50
 n \$ 80.00 X
 \$ 150.00 60
 \$ 380.00 200
 \$ 150.00 100
 \$ 150.00 80
 \$ 200.00 100
 n \$ 120.00 X
 \$ 3,000.00 1600
 \$ 3,000.00 1600
 \$ 7,390.00
 13450.44

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$ 37,921.95

LKK Auto Consultants hence notify
 the Insurer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
GREAT AMERICAN INSURANCE COMPANY		Ref : CS/GAI18000922/Uvbn2	
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Date : 12-02-2018	
		Code : GAI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBC 8181T	Veh. Inspected	GBF 338X
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVC000002338	Excess (\$)	0.00
Assign From	RACHEL TAN	Assign Date	16/01/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA DYNA (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTFAT35Y20K206377	Colour	SILVER
Odometer	74760	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15	YOKOHAMA	6 mm
L/H Front Tyre	195 R15	YOKOHAMA	6 mm
R/H Rear Tyre	155 R12 (D)	YOKOHAMA	6/6 mm
L/H Rear Tyre	155 R12 (D)	YOKOHAMA	6/6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	13/01/2018	Inspection Date	16/01/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 338X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE	BADLY DENTED	1,645.10	1,645.10
1	TAILGATE "TOYOTA" STICKER	NECESSARY	121.10	121.10
1	TAILGATE DYNA STICKER	NECESSARY	45.50	45.50
1	TAILGATE LOWER MEMBER	DENTED / BENT	545.10	545.10
1	TAILGATE LOCK LATCH N/S	BENT	119.30	119.30
1	TAILGATE LOWER "L" PANEL N/S	BENT	82.50	82.50
1	TAILGATE LOWER "L" PANEL RUBBER N/S	CUT	62.30	62.30
2	TAILLAMPS @\$285.30	N/S CRACKED	570.60	285.30
2	TAILLAMP BRACKETS @\$119.30	TO REPAIR SEE LABOUR	238.60	-
1	DROP SIDEGATE N/S	TO REPAIR SEE LABOUR	2,101.10	-
1	DROP SIDEGATE LOWER MEMBER N/S	TO REPAIR SEE LABOUR	688.50	-
1	REAR EXHAUST PIPE	NOT NECESSARY	585.20	-
1	REAR SPARE TYRE CHAIN & BRACKET	JAMMED	392.50	392.50
1	FRONT BUMPER	DENTED / BENT	1,698.90	698.90
2	FRONT BUMPER BRACKETS @\$112.00	BENT	224.00	224.00
1	FRONT CENTRE CROSS MEMBER	DENTED / BENT	1,662.30	862.30
2	HEADLAMPS @\$673.31	CRACKED	1,346.62	1,346.62
2	FRONT CABIN MOUNTINGS @\$279.60	NOT NECESSARY	559.20	-
1	FRONT GRILLE	CRACKED	807.92	807.92
1	FRONT GRILLE LOGO	NECESSARY	56.90	56.90
1	SET FRONT GRILLE CLIPS	NECESSARY	20.00	20.00
1	FRONT GRILLE RUBBER	NECESSARY	43.70	43.70
1	FRONT PANEL	DENTED / BENT	1,959.10	959.10
1	FRONT PANEL DYNA EMBLEM	NECESSARY	48.50	48.50
1	FRONT PANEL TOP CENTRE GARNISH (BLACK)	CUT	288.31	288.31
2	FRONT CORNER GARNISH (BLACK) @\$178.60	N/S CUT	357.20	178.60
2	FRONT CORNER PANELS @\$195.27	TO REPAIR SEE LABOUR	390.54	-
1	FRONT WIPER PANEL CENTRE	NOT NECESSARY	279.88	-
2	FRONT WIPER ARMS @\$192.91	NOT NECESSARY	385.82	-
1	FRONT WIPER LINK	NOT NECESSARY	276.82	-
1	FRONT WIPER MOTOR	NOT NECESSARY	927.96	-

Report Ref No. CS/GAI18000922/Uvbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT DASHBOARD	DEFORMED / TORN	928.86	928.86
1	AIRCON BLOWER HOUSING	CRACKED	998.90	998.90
1	AIRCON COIL HOUSING	NOT NECESSARY	1,098.70	-
1	HEATER HOUSING ASSY	CRACKED	1,484.92	1,484.92
1	FRONT BRAKE BOOSTER	NOT NECESSARY	1,053.31	-
1	FRONT BRAKE CYLINDER MASTER PUMP	NOT NECESSARY	587.90	-
2	FRONT DOORS @\$1927.80	TO REPAIR SEE LABOUR	3,855.60	-
1	FRONT WINDSCREEN RUBBER	NECESSARY	247.69	247.69
4	FRONT BRAKE PIPES @\$215.00	NOT NECESSARY	860.00	-
	LESS 25% DISCOUNT		-	-3,123.48
			29,646.95	9,370.44
	<u>SPECIAL NETT ITEMS</u>			
1	TAILGATE 70KM/HR STICKER (SN)	NECESSARY	20.00	10.00
1	13 PAX STICKER (SN)	NECESSARY	20.00	10.00
1	SET REAR REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR STEP BAR (SN)	BENT	380.00	300.00
1	REAR LICENCE PLATE (SN)	BENT	20.00	15.00
1	REAR LICENCE PLATE BRACKET (SN)	TO REPAIR SEE LABOUR	85.00	-
1	FRONT LICENCE PLATE (SN)	BENT	20.00	15.00
2	FRONT DOOR ROC STICKERS @\$30.00 (SN)	NECESSARY	60.00	60.00
			885.00	610.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACE REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX REAR EXHAUST.	NOT NECESSARY	80.00	-
	TO DISMANTLE & REFIX FRONT WINDSCREEN.		150.00	60.00
	TO DISMANTLE & REPLACE FRONT DASHBOARD.		380.00	200.00
	TO REFILL AIRCON GAS.		150.00	100.00
	TO DISMANTLE & REPLACE HEATER,COOLING HOUSING.		150.00	80.00
	TO SPRAY RUST PROOFING.		200.00	100.00
	TO TRANSFER BOTH DOOR MECHANISM.	NOT NECESSARY	120.00	-

Report Ref No. CS/GAI18000922/Uvbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF TAILLAMP BRACKETS,DROP SIDEGATE N/S,DROP SIDEGATE LOWER MEMBER N/S,FRONT CORNER PANELS,FRONT DOORS AND REAR LICENCE PLATE BRACKET. TO PUTTY & SPRAY PAINTING.		3,000.00	1,600.00
			3,000.00	1,600.00
			7,390.00	3,820.00
GRAND TOTAL			37,921.95	13,800.44
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				11,000.00

Report Ref No. CS/GAI18000922/Uvbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.