

卓亚水喷漆公司 TOH AH SWEE SPRAY PAINTING CO.

BLK 2, KRANJI LOOP #01-02 (OFF KRANJI ROAD), SINGAPORE 739538.

TEL: 6366 0115 (WORKSHOP), 6366 0286 (OFFICE) FAX: 6368 5943

EMAIL: enquiry@toahswee.com.sg

BUSINESS REG. NO: 09935300L

GST REG. NO: 09-935300-L

15/01/2018

AXA INSURANCE SINGAPORE PTE LTD

143 CECIL STREET

#01-01 GB BUILDING

SINGAPORE 069524

ATTN : MOTOR CLAIMS DEPT.

ESTIMATED REPAIR BILL

TYPE OF CLAIM : OWN DAMAGE CLAIM
NAME : HUA YANG ENTERPRISE PTE LTD
VEHICLE NO. : SKL6688H
MAKE/MODEL : MERC E250
POLICY NO/ CN NO. : P1308836
ACCIDENT DATE : 08/01/2018

MATERIAL COST

IPC FRONT BUMPER
IPC FRONT BUMPER BRACKET RH
IPC FRONT FENDER RH
IPC FRONT FENDER INNER SHIELD RH
IPC HEAD LAMP RH

casul
hp 90010068
4 days
P/P
17/01/18 @ 0830

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$	DE	1,672.00
\$	RM	72.00
\$	R	1,200.00
\$	CR	434.00
\$	CR	3,960.00
SUB-TOTAL :		\$ 7,338.00
EXCESS: 1500 LESS DISCOUNT 10% :		\$ 733.80
		\$ 6,604.20

MATERIAL COST - SPECIAL NETT

1SET SENSOR - mcs

Authorized
Resurvey by paint

LABOUR CHARGE

TO USE RESET COMPUTER SYSTEM

TO REMOVE DAMAGED PARTS, TO KNOCK OUT DENTS, TO STRAIGHTEN, ADJUST, CHECK, RESHAPE INCLUDING CUTTING AND WELDING WHERE NECESSARY, TO REMOVE AND REINSTALL NECESSARY FITTINGS TO FACILITATE REPAIRS, TO REPLACE AND ALIGN THE ABOVE PARTS.

PUTTY AND SPRAY PAINTING ON ABOVE NEW AND REPAIRED PARTS INCLUDING SUPPLY OF PAINT MATERIALS

\$	400	1,000.00
\$	500	1,200.00
\$	9844.20	8,924.20
ADD GST 7% :		\$ 624.69
TOTAL :		\$ 9,548.89

SINGAPORE DOLLARS : NINE THOUSAND FIVE HUNDRED FOURTY EIGHT AND CENTS EIGHTY NINE ONLY

OH AH SWEE SPRAY PAINTING CO.

weekem