

22/03/2002

ASS. REC. BY:

REF:

CS/MS618000927/T1 Hbz

Special Instruction:

Surveyor:

Taufik

ASSIGNMENT (Office)

From (Person):

Melman

Onstina Wong

of

MS6

Date/Time:

16-01-2018 10:45am

Estimated Cost:

Bill to:

OD / ~~TD~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHB 4561R

Insured:

SLD 6773

at Workshop m/s

Ding Automotiv

Tel:

8303 9588

of

31 Corporation Road

Policy No:

MSD / VPCP / 17-001233-00

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12012018

CA / REV / REP. / REV 24 HRS Wpk

H.O.D. Endorsement:

Date/Time:

16012018 11:37 am

Person Contacted:

Alex

Vehicle ~~IN~~ OUT

Date/Time	Action/Instruction (✓) Estimate	
	SHB 4561R - MS / TCT / 110871.5 / Ktbm2	DA: 01/02/17
	SLD 6773 - NA / TDA / 16020555 / 64	DA: 06/11/2016
03/04/18	To close at 4k	
	Lump Sum 4k	
	(Red: 11032-71 : 73%)	

Taylor

MS16

From _____ Date _____
 Estimated Cost _____
 OD ☒ TP ☒ WS ☒ TP RES ☒ OD RES ☒ EVA ☒ INV ☒ MW ☒
 To inspect vehicle No _____
 at Workshop No _____
 of _____
 insured _____
 Policy No _____
 Claims No _____
 Sum Insured _____ Excess _____
 (Offender's Record) _____
 Make of Vehicle _____

NS	OS

(Policy Condition) _____
 Remarks: The veh had commenced its repair at the time of inspection.
 Ball or Market Value _____
 IDAO Accident Report: _____ Consistent? : Yes or No
 CIA / PP Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res: Yes or No
 LHM Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS _____
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT _____

SHB 456/R Page 200 July
 Type: M Car / M Cycle / Bus / Van / Lorry / Cab / Prime Mover
 Truck / Trailer or _____
 Make: Hyundai Sonata 1991
 Colour: yellow
 So Reading: 430966
 Engine No _____
 Ch No: KM HET 41UMAA786 459
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / STD / AIR / or
 Tyre Size: R: 2.5 / 60R16
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM
 TOYO / YOKO or Twinkle.
 Front: R. Bal. 6 mm L. Bal. 6 mm D.O.A. 16/1/18
 Surveyed at: Ding Anfo
 Des. of Damages: Fr. ☒ Rear ☒ OS ☒ NS ☒ UO ☒ Roof top or
 The UO Chassis frame / Body Structure affected due to collision

Date Time Action Instruction
 Inform the workshop to pass book value

RECEIVED 19 JUL 2018

Date Time File Pass to: ☐ Preli. Report ☒ Final Report

Days Of Repair: 7
 Resurvey No. of Trial: 1

Date Time File Returned:

Add Fee: ☐ Site Insp \$ ☐ Test 4 \$ ☐ Test 10 \$ ☐ Add A \$

Report Format: TP
 4000f

Survey Fee	300
Transport	10
1-Hour Fee	
2-Hour Fee	
3-Hour Fee	
4-Hour Fee	
5-Hour Fee	
6-Hour Fee	
7-Hour Fee	
8-Hour Fee	
9-Hour Fee	
10-Hour Fee	
11-Hour Fee	
12-Hour Fee	
13-Hour Fee	
14-Hour Fee	
15-Hour Fee	
16-Hour Fee	
17-Hour Fee	
18-Hour Fee	
19-Hour Fee	
20-Hour Fee	
21-Hour Fee	
22-Hour Fee	
23-Hour Fee	
24-Hour Fee	
25-Hour Fee	
26-Hour Fee	
27-Hour Fee	
28-Hour Fee	
29-Hour Fee	
30-Hour Fee	




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18000927/T1tb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 16-01-2018	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLD 677J	Veh. Inspected	SHB 4561R
Policy No.	MSD/VPCP/17-001233-00	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	16/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	12/01/2018	Inspection Date	16/01/2018
Survey held at	31 CORPORATION RD		
Repairer	DING AUTO PTE LTD		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Jan 2018		16 Jan 2018 10:48 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: 199400399N		
Main Claimant:	CITYCAB PTE LTD, Co. Reg. No.: 199502839G		
Vehicle Reg. No.:	SHB4561R	Date of Loss:	12/01/2018 00:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	MSD/VPCP/17-001233-00 Coverage: 01/06/2017 - 31/05/2018
Vehicle Reg. No. (Insured):	SLD677J	Policy No. (Claimant):	
		Excess:	
Repairer:	Ding Automotive Pte Ltd (HQ) 31 CORPORATION ROAD, 649825 Boon Lay - Tel: 96992878		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 17/01/2018]		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

There are no mail for this case.

☐ **ALL ASSOCIATED TASKS** View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAUTO)

From: Kenneth Ding <kenneth.ding@dingauto.sg>
Sent: Tuesday, 3 April 2018 1:27 PM
To: Denise Tay (LKKAUTO); 'Accounts Ding Auto'
Cc: 'DAMtaxi'; 'Kelly Ding'
Subject: RE: SHB4561R - Finalize Amount & After Repair Photo.

Dear Denise,

We cannot accept your offer of \$2.8k with 7 repair days.

Can you breakdown your offer as this vehicle can still be rented out at estimated \$100.00 per day.

Therefore, if the vehicle is left with 2 months, the minimum offer based on the rental rate will be at least \$6k.

Finalize Amount

Total Repair - 7 Days

Labour - \$2160
Special Nets - \$400
Parts - \$3913.09
Parts after 20% discount = \$3130.47
Total L+S+P = \$5690.47 - 20% LUMP SUM
Final Amount = \$4552.37

*Our computation is base on the
balance life span of the taxi
and the book value using depreciation
method.*

Please re-consider finalize amount and get back to us.

Thank you.

Best Regards,
Kenneth Ding
HP: 92313123
Fax: 6452 0614

*For an amicable settlement,
can we resolve this cost of
repair at \$3.5k.*

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Tuesday, April 3, 2018 1:22 PM
To: Kenneth Ding; 'Accounts Ding Auto'
Cc: 'DAMtaxi'; 'Kelly Ding'
Subject: RE: SHB4561R - Finalize Amount & After Repair Photo.

Dear Kenneth,

Offer lump sum \$2800, 7days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Denise Tay (LKKAuto)

From: Kenneth Ding <kenneth.ding@dingauto.sg>
Sent: Thursday, 29 March 2018 5:15 PM
To: Denise Tay (LKKAuto); 'Accounts Ding Auto'
Cc: 'DAMtaxi'
Subject: RE: SHB4561R - Finalize Amount & After Repair Photo.
Attachments: SHB 4561R BOOK VALUE.TIF

Dear Denise,

This data is from Citycab, the amount should be the same.

There is another calculation, based on vehicle balance months to multiple by the rental rate per day.

Anyway, there is enough amount for the repair to be repair.

Thank you and please finalize the repair cost with us.

Thank you.

Best Regards,
Kenneth Ding
HP: 92313123
Fax: 6452 0614

To ask for again repair photo

From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]
Sent: Thursday, March 29, 2018 4:54 PM
To: Accounts Ding Auto
Cc: Kenneth Ding; DAMtaxi
Subject: RE: SHB4561R - Finalize Amount & After Repair Photo.

Dear All,

Please check on my last email

Need to clarify on the amount Nett book value for without or with coe.

Same amount? 9961.00?

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 14 March 2018 3:47 PM
To: 'Accounts Ding Auto' <accounts@dingauto.sg>

65934.91
(cost of taxi. = ~~6594~~

ARF 6570 = 10790.00

Repairment = 65934.91 - 10790.00

96

= 574.42 / mtn

Book value = (574.42 x 6)

+ 10790.00

= 14236.52

Nett value = 14236.52 - 11423.00

= 2813.52

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 2839G

Vehicle Details

Vehicle No.: SHB4561R

Vehicle to be Exported: Yes

Intended De-registration Date: 17 Jan 2018

Vehicle Make: HYUNDAI

Vehicle Model: SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO

Primary Colour: Yellow

Manufacturing Year: 2010

Engine No.: D4EAA930492

Chassis No.: KMHET41VMAA786459

Maximum Power Output: 110.0 kW (147 bhp)

Open Market Value: \$16,600.00

Original Registration Date: 15 Jul 2010

First Registration Date: 15 Jul 2010

Transfer Count: 0

Actual ARF Paid: \$16,600.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 14 Jul 2018

PARF Rebate Amount: \$9,960.00

Intended COE Rebate Details

COE Expiry Date: 14 Jul 2018

COE Category: A - Car (1600cc & below)

1/17/2018

PARF/COE Rebate Enquiry

COE Period(Years):	8
PQP Paid:	\$23,875.00
COE Rebate Amount:	\$1,463.00
Total Rebate Amount:	\$11,423.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 17 Jan 2018

OK

Report ID : SHICFPL32
Date : 17.01.2018
Time : 13:43:58

CityCab Pte Ltd
Vehicle Mgt for Fleet Safety Division
AS AT 31.12.2017

USER ID : CITNEX03
PAGE : 1

Co.Code : CMB
Licence Pl.No : SHB4561R
Old Asset No : 10007541-0
Veh.Model : Hyundai Sonata
Reg.Date : 15.07.2010
Cap.Date : 15.07.2010
Accident.Date : 12.01.2018
Veh.Age : 090

Asset No	SA.No	Bal.Dep.Mths	Per. Bch. Dep	Bal. Dep. Value	Asset Description 1	Cost	Op. Acc. Dep	Cur. Year Dep	Accum. Dep	Net Book Value	Scrap value/Estimated PARF Refund
			\$	\$		\$	\$	\$	\$	\$	\$
10007541	0	000	244.43	0.00	SHB4561R HSN 15.07.2010 BASIC COST	22,000.00	19,065.80-	2,933.20-	21,999.00-	1.00	1.00
10007541	1	000	36.89	0.00	SHB4561R HSN 15.07.2010 IMPORT DUTY	3,319.91	2,877.26-	442.65-	3,319.91-	0.00	0.00
10007541	2	000	73.78	0.00	SHB4561R HSN 15.07.2010 AFR 1000KMS16600	16,600.00	5,754.67-	885.33-	6,640.00-	9,960.00	9,960.00
10007541	3	000	265.28	0.00	SHB4561R HSN 15.07.2010 COE 80%	23,875.00	20,691.67-	3,183.33-	23,875.00-	0.00	0.00
10007541	4	000	0.00	0.00	SHB4561R HSN 15.07.2010 COE TOP UP	0.00	0.00	0.00	0.00	0.00	0.00
10007541	5	000	0.00	0.00	SHB4561R HSN 15.07.2010 AIR CONDITIONER	0.00	0.00	0.00	0.00	0.00	0.00
10007541	6	000	0.00	0.00	SHB4561R HSN 15.07.2010 PRINTER DIGITAX THERMAL	0.00	0.00	0.00	0.00	0.00	0.00
10007541	7	000	0.00	0.00	SHB4561R HSN 15.07.2010 TAXIMETER DIGITAX FI	0.00	0.00	0.00	0.00	0.00	0.00
10007541	8	000	1.56	0.00	SHB4561R HSN 15.07.2010 VEH REG FEE	140.00	171.34-	18.66-	140.00-	0.00	0.00
			1.94	0.00		14.51	46.10.74-	7.13.17-	55,973.91-	9,961.00	
	COE		265.28	0.00	Vehicle : Without T/A & COE	42,059.91	27,819.07-	4,279.84-	32,098.91-	9,961.00	
	Vehicle		356.66	0.00	Vehicle : Without T/A, With COE	65,934.91	48,510.74-	7,463.17-	55,973.91-	9,961.00	
			621.94	0.00	Taximeter	0.00	0.00	0.00	0.00	0.00	

CC18010377

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/01/2018 13:46
Date Of Accident	12/01/2018 22:15
Exact Location Of Accident	ALONG PIE TOWARD CHANGI AIRPORT NEAR EUNOS EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB4561R
Insured/Policyholder	
Name Of Registered Owner	CITYCAB PTE LTD
Co Reg No	199502839G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-93830648

Vehicle Particulars

Manufacturer	HYUNDAI
Model	SONATA-2.0 CRDI (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

Insurance Company

Name of Insurance Company	FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-15072702MFSH
Cover Note Number	

Driver

Name of Driver	LIM HIANG BOON
NRIC No	S1623560A
Date Of Birth	27/09/1963
Occupation	OUTDOOR
Date Of Driving Pass	19/07/1983
Driving Experience	34 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93830648
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address 862 JURONG WEST STREET 81 #15-618 S640862
Postcode
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions RAINING
Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1
NAME: : UNKNOWN
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name JURONG NEIGHBOURHOOD POLICE POST
Police Station Address ROAD: BLK 158 YUNG LOH ROAD , POSTCODE: 610158 , COUNTRY: SINGAPORE
Police Station Contact TEL NO: 1800-2659999 - FAX NO: 62664987
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED POLICE REPORT

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: FILE NOT SUITABLE
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLD677J
Vehicle Make/Model/Colour TOYOTA ALTIS
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver FELIX CHOONG CHEE KIAT
NRIC/Passport Number
Contact Number 93666120
Address



Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

A handwritten signature in black ink, consisting of a stylized 'S' followed by a series of loops and a final horizontal stroke.

Accident Sketch Plan Pg. 1

SKETCH PLAN

Handwritten notes on the sketch plan grid:

- Top right: A: SHB4561R, B: SLD677J
- Left side: toward, change support (Falcon Enues)
- Grid content: A diagram showing two vehicles, A and B, with an arrow indicating movement from B towards A.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Handwritten text in the first line: refer to police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

GIARMC SketchPlanForm_v3

Driver's Signature
(If driver is not the policyholder)
Date & Time:

13/01/18
1315

Reporting Centre Personnel's Signature
Name: Kenneth Okey
NRIC/FIN No.:

58414393P2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20180113/2056

Police Station Of Origin:
Jurong East N.P.C
92 Boon Lay Way SINGAPORE 609962
Tel No: 1800-8999999

1 of 3

Report No. T/20180113/2056

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/01/2018 12:38	Vide Report No.:	Station Diary No.: 44
--	------------------	--------------------------

Informant's Particulars

Name of Informant: LIM HIANG BOON			Address: APT BLK 862 JURONG WEST STREET 81 #15-618 SINGAPORE 640862		
ID Type / ID No.: NRIC NO / S1623560A			Contact No.: Home/Office: Mobile: 93830648		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 54	Date of Birth: 27/09/1963	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 2B,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 12/01/2018 20:15	Type of Location: Expressway
Location: Along Road 1. PAN ISLAND EXPRESSWAY near to Jalan Eunus exit				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit: 90 Km/h
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicles Involved

Vehicle No.	Type of Vehicle	Make	Model	Colour	Condition	No of Passengers
SHB4561R	Car	HYUNDAI	Sonata	Yellow	Seriously Damaged	1
SLD677J	Car	TOYOTA		Silver	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



Police Station Of Origin:
Jurong East N.P.C
92 Boon Lay Way SINGAPORE 609962
Tel No: 1800-8999999

2 of 3

Report No. T/20180113/2056

CONTINUATION OF REPORT

Driver				
Name	LIM HIANG BOON		ID No.	S1623560A
Related Vehicle	SHB4561R (Car)		Contact No.	93830648
Hospital/Clinic	A LIFE CLINIC PTE LTD		Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	13/01/2018	Date Discharge	NIL	
No. of Days granted Medical Leave	05	Degree of Injury	Slight	
Driver				
Name	FELIX CHOONG CHEE KIAT		ID No.	S8141611Q
Related Vehicle	NIL		Contact No.	93666120
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

Brief Details.

On 12/01/2018 at about 2015hrs, I was driving my 'Citycab' taxi (SHB4561R) with a passenger along the Pan Island Expressway (PIE) towards Changi Airport. I was driving on the first lane of the expressway near to Jalan Eunos exit when the car in front of my vehicle came to a stop due to the heavy traffic. Suddenly, a silver Toyota (SLD677J) came from the back of my car and knocked into the rear portion of my taxi. I made a check with my passenger and he was alright.

I then alighted from my taxi and exchanged particulars with the driver. No one was injured. The rear of my taxi was dented and the front portion of the silver Toyota was also dented. We then agreed on insurance claim. There is in-car camera installed in my taxi. On 12/01/2018 in the evening, I felt dizzy and experienced discomfort while sleeping. I then visited the doctor on 13/01/2018 and was given 5 days of medical leave from 13/01/2018 to 17/01/2018.



**SINGAPORE
POLICE FORCE**



T/20180113/2056

Police Station Of Origin:
Jurong East N.P.C
92 Boon Lay Way SINGAPORE 609962
Tel No: 1800-8999999

3 of 3

Report No. T/20180113/2056

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

D /
Sgt 2 LEONG HIN CHI

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIA /
Staff Sgt TANG SIEW PING
Contact No: 65476430

Signature Of Informant:

Date/Time:

13/01/2018 12:38

Classification Of Case:

Authentication Stamp
NP168

SINGAPORE
POLICE FORCE

SN 34

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 2839G

Vehicle Details

Vehicle No.: SHB4561R

Vehicle to be Exported: No

Intended De-registration Date: 17 Jan 2018

Vehicle Make: HYUNDAI

Vehicle Model: SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO

Primary Colour: Yellow

Manufacturing Year: 2010

Engine No.: D4EAA930492

Chassis No.: KMHET41VMAA786459

Maximum Power Output: 110.0 kW (147 bhp)

Open Market Value: \$16,600.00

Original Registration Date: 15 Jul 2010

First Registration Date: 15 Jul 2010

Transfer Count: 0

Actual ARF Paid: \$16,600.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 14 Jul 2018

PARF Rebate Amount: \$9,960.00

Intended COE Rebate Details

COE Expiry Date: 14 Jul 2018

COE Category: A - Car (1600cc & below)

COE Period(Years): 8

PQP Paid:	\$23,875.00
COE Rebate Amount:	\$1,463.00
Total Rebate Amount:	\$11,423.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 17 Jan 2018

OK

Ding Automotive Pte Ltd

Blk 10 Sin Ming Industrial Est. Sector C, #01-20, Singapore 575645

Tel:6452 1208, Fax:6452 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

15/01/2018 8:38

JOB-NO: 50110451

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHB4561R

TRANS: AUTO

CHASSIS: KMHET41VMAA786459

MAKE / MODEL: HYUNDAI / Sonata 2.0 CRDi

ENGINE: D4EAA930492

OWNER'S INSURER: FIRST CAPITAL INSURANCE LIMITED

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	MARK UP	MARKUP PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 PANEL BEAT & STRAIGHTEN CHASSIS	1.00	1,500.00	0.00	1,500.00	Y		1000
2 MOUNT WORK BENCH	1.00	300.00	0.00	300.00	Y		X
3 RUST PROOFING	1.00	80.00	0.00	80.00	Y		40
4 R & R SPARE TYRES/BOARD/CARPET/TRIM	1.00	120.00	0.00	120.00	Y		60
5 R & R REAR WINDSCREEN	1.00	120.00	0.00	120.00	Y		X
6 CONDUCT WHEEL ALIGNMENT	1.00	60.00	0.00	60.00	Y		X
7 TOWING CHARGES	1.00	150.00	0.00	150.00	Y		60
8 SUNDIRES	1.00	50.00	0.00	50.00	Y		30
9 ADJUST TAILLAMP AND CHECK WIRING	1.00	60.00	0.00	60.00	Y		30
10 R & R BOOTLID COMPOENENT	1.00	80.00	0.00	80.00	Y		40
11 SPRAY PAINT ACCIDENT AREA - BOOTLID,END PANEL,SPARE TYRES PANEL,FENDER RRHS, FENDER RLHS, BUMPER	1.00	1,600.00	0.00	1,600.00	Y		900
TOTAL:		4,120.00	0.00	4,120.00			

MATERIALS

1 REAR BUMPER	1.00	523.93	0.00	523.93	Y		de
2 REAR BUMPER REINFORMENT	1.00	462.30	0.00	462.30	Y		dis
3 REAR BUMEP R RETAINER RHS	1.00	42.68	0.00	42.68	Y		nr
4 REAR BUMEP R RETAINER LHS	1.00	42.68	0.00	42.68	Y		nr
5 REAR BUMPER BRACKET RHS	1.00	79.75	0.00	79.75	Y		nr
6 REAR BUMPER BRACKET LHS	1.00	79.75	0.00	79.75	Y		nr
7 REAR BUMPER SPONGE	1.00	113.52	0.00	113.52	Y		de
8 REAR BUMPER PROTECTOR RHS	1.00	102.96	0.00	102.96	Y		Rp
9 REAR BUMPER PROTECTOR LHS	1.00	102.96	0.00	102.96	Y		nr
10 REAR BUMPER LWR EXT	1.00	40.70	0.00	40.70	Y		Con
11 REAR REVERSE SENSOR	1.00	250.00	0.00	250.00	Y		200.00
12 BOOTLID	1.00	1,139.00	0.00	1,139.00	Y		bt
13 BOOTLID EMBLEM LOGO	1.00	21.45	0.00	21.45	Y		nr
14 BOOTLID EMBLEM HYUNDAI	1.00	20.13	0.00	20.13	Y		nr
15 BOOTLID EMBLEM SONATA	1.00	40.92	0.00	40.92	Y		nr
16 BOOTLID EMBLEM CRDI	1.00	18.70	0.00	18.70	Y		nr
17 BOOTLID LAMP RHS	1.00	203.50	0.00	203.50	Y		3x m
18 BOOTLID LAMP LHS	1.00	203.50	0.00	203.50	Y		3x m
19 BOOTLID PLATE LAMP	1.00	49.50	0.00	49.50	Y		X m
20 BOOTLID HINGE RHS	1.00	140.80	0.00	140.80	Y		Rp
21 BOOTLID HINGE LHS	1.00	140.80	0.00	140.80	Y		Rp

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	MARK UP	MARKUP PRICE	IND	SUR.DISP	REV PRICE
22 BOOTLID LOCK CATCH	1.00	109.48	0.00	109.48		Y	del
23 BOOTLID LOCK CATCH	1.00	108.90	0.00	108.90		Y	X nn
24 BOOTLID INSULATOR	1.00	155.10	0.00	155.10		Y	del
25 BOOTLID RUBBER BEADING	1.00	91.30	0.00	91.30		Y	del
26 BOOTLID DAMPER RRHS	1.00	104.50	0.00	104.50		Y	X nn
27 BOOTLID DAMPER RLHS	1.00	104.50	0.00	104.50		Y	X nn
28 BOOTLID KEY LOCK	1.00	109.01	0.00	109.01		Y	del
29 BOOTLID STICKER CAB BOOKING - 65521111	1.00	40.00	0.00	40.00		Y	del
30 BOOTLID STICKER CITYCAB	1.00	40.00	0.00	40.00		Y	del
31 BOOTLID INSULATOR CLIP	1.00	35.00	0.00	35.00		Y	del
32 REAR NUMBER PLATE	1.00	35.00	0.00	35.00		Y	del
33 REAR END PANEL	1.00	323.29	0.00	323.29		Y	del
34 REAR END PANEL TOP GARNISH	1.00	42.02	0.00	42.02		Y	del
35 REAR END PANEL SEALANT	1.00	50.00	0.00	50.00		Y	del
36 TAILLAMP RHS	1.00	323.40	0.00	323.40		Y	X nn
37 TAILLAMP LHS	1.00	323.40	0.00	323.40		Y	del
38 TAILLAMP INNER PANEL RHS	1.00	267.30	0.00	267.30		Y	del
39 TAILLAMP INNER PANEL LHS	1.00	267.30	0.00	267.30		Y	del
40 SPARE TYRES PANEL	1.00	812.90	0.00	812.90		Y	del
41 SPARE TYRES BOARD	1.00	162.14	0.00	162.14		Y	X nn
42 SPARE TYRES INSUALTOR PAD	1.00	280.00	0.00	280.00		Y	X nn
43 SPARE TYRES SEALANT	1.00	50.00	0.00	50.00		Y	X nn
44 REAR FENDER RHS	1.00	1,598.30	0.00	1,598.30		Y	X nn
45 REAR FENDER LHS	1.00	1,598.30	0.00	1,598.30		Y	del
46 REAR FENDER INNER SHIELD RHS	1.00	31.02	0.00	31.02		Y	X nn
47 REAR FENDER INNER SHIELD LHS	1.00	31.02	0.00	31.02		Y	del
TOTAL:		10,912.71	0.00	10,912.71			

TOTAL PARTS & LABOUR : 15,032.71 0.00 15,032.71

EXCESS/LOADING: S\$ 0.00

No. Of Day: 67

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: S\$

DATE OF SURVEY: 16/1/18

SURVEYED BY: Tanyan

CONTACT NO: 97443749 FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL: FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey on "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

G-STAR-WI-ET-001-02-Rev00

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Jan 2018		16 Jan 2018 10:48 Edit Adj Rpt	S\$4,000.00 Edit Estimates	S\$4,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	HITACHI CAPITAL ASIA PACIFIC PTE LTD , Co. Reg. No.: 199400399N								
Main Claimant:	CITYCAB PTE LTD , Co. Reg. No.: 199502839G								
Vehicle Reg. No.:	SHB4561R	Date of Loss:	12/01/2018 22:00 - :59 [89 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/18-000087	Policy/Cover Note No.:	MSD/VPCP/17-001233-00 (Comprehensive) Coverage: 01/06/2017 - 31/05/2018						
Vehicle Reg. No. (Insured):	SLD677J	Policy No. (Claimant):							
		Excess:	S\$1,500.00						
Repairer:	Ding Automotive Pte Ltd (HQ) 31 CORPORATION ROAD, 649825 Boon Lay - Tel: 96992878								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Imm.Advice due 17/01/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHB4561R (MSC/V/18-000087)

[SLD677J]




































TP






































CITYCAB PTE LTD

Jan 12 2018 10:00PM

[HITACHI CAPITAL ASIA PACIFIC PTE LTD]

Ding Automotive Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
2	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
3	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
4	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
5	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
6	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
7	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
8	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
9	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
10	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
11	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
12	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
13	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
14	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
15	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
16	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
17	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
18	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
19	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
20	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
21	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
22	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
23	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
24	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
25	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
26	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
27	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
28	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
29	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
30	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
31	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
32	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
33	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
34	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
35	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
36	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	
37	03/04/18 14:04	General View						Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	03/04/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
39	03/04/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
40	03/04/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
41	03/04/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
42	03/04/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
43	03/04/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
44	03/04/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
45	03/04/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
46	03/04/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
47	03/04/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
48	03/04/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
49	03/04/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
50	03/04/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
51	03/04/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
52	03/04/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
53	03/04/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
54	03/04/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
55	03/04/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
56	03/04/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
57	03/04/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
58	03/04/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
59	03/04/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
60	03/04/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
61	03/04/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
62	03/04/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
63	03/04/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
64	03/04/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
65	03/04/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
66	03/04/18 14:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	03/04/18 14:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	03/04/18 14:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	03/04/18 14:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	03/04/18 14:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	03/04/18 14:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/01/18 10:49	SLD677J GIA Rpt	 Load PDF	
2	16/01/18 10:49	SHB4561R GIA Rpt	 Load PDF	
3	16/01/18 10:58	Email frm TP - PRI	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18000927/T1TBE2

Date: 05/04/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VPCP/17-001233-00
Claimant Vehicle No :	SHB4561R	Insured Vehicle No :	SLD677J
Date of Loss:	12/01/2018	Nature of Claim:	TP
		Claim No:	MSC/V/18-000087

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB4561R		
Make & Model:	HYUNDAI SONATA NF, 2.0 CRDI AT ABS 2WD 4DR TURBO (A)	Engine No:	D4EAA930492
Reg. Date:	15/07/2010 (Man. Year: 2010)	Chassis No:	KMHET41VMAA786459
Colour:	Yellow	Odometer:	430966 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Triangle 6 mm	Rear Left Side:	Triangle 6 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,962.71	3,520.47	7,442.24	67.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,070.00	2,130.00	1,940.00	47.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,032.71	5,650.47	9,382.24	62.41
Approved Total (Overridden) (\$\$)		4,000.00		
(\$\$)	15,032.71	4,000.00	11,032.71	73.39
+ GST 7.00/7.00% (\$\$)	1,052.29	280.00	772.29	73.39
Nett Amount (\$\$)	16,085.00	4,280.00	11,805.00	73.39

INSPECTION

Date of Assignment:	16/01/2018	
Date Inspected:	16/01/2018	Inspected At: Ding Automotive Pte Ltd (HQ) 31 CORPORATION ROAD Singapore 649825

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Apr 2018)

Parts: 143 HYUNDAI SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHB4561R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*30.00 FS
2	1		*REAR BUMPER	Deformed	523.93 F	*523.93 FL
3	1		*REAR BUMPER REINFORCEMENT	Distorted	462.30 F	*462.30 FL
4	1		*REAR BUMPER RETAINER RHS	Necessary	42.68 F	*42.68 FL
5	1		*REAR BUMPER RETAINER LHS	Necessary	42.68 F	*42.68 FL
6	1		*REAR BUMPER BRACKET RHS	Necessary	79.75 F	*79.75 FL
7	1		*REAR BUMPER BRACKET LHS	Necessary	79.75 F	*79.75 FL
8	1		*REAR BUMPER SPONGE	Deformed	113.52 F	*113.52 FL
9	1		*REAR BUMPER PROTECTOR RHS	Repair	102.96 F	*- FL
10	1		*REAR BUMPER PROTECTOR LHS	Cut	102.96 F	*102.96 FL
11	1		*REAR BUMPER LWR EXT	Cracked	40.70 F	*40.70 FL
12	1		*REAR REVERSE SENSOR	Not Working	250.00 FS	*200.00 FS
13	1		*BOOTLID	Bent	1,139.00 F	*1,139.00 FL
14	1		*BOOTLID EMBLEM LOGO	Necessary	21.45 F	*21.45 FL
15	1		*BOOTLID EMBLEM HYUNDAI	Necessary	20.13 F	*20.13 FL
16	1		*BOOTLID EMBLEM SONATA	Necessary	40.92 F	*40.92 FL
17	1		*BOOTLID EMBLEM CRDI	Necessary	18.70 F	*18.70 FL
18	1		*BOOTLID LAMP RHS	Not Necessary	203.50 F	*- FL
19	1		*BOOTLID LAMP LHS	Not Necessary	203.50 F	*- FL
20	1		*BOOTLID PLATE LAMP	Not Necessary	49.50 F	*- FL
21	1		*BOOTLID HINGE RHS	Repair	140.80 F	*- FL
22	1		*BOOTLID HINGE LHS	Repair	140.80 F	*- FL
23	1		*BOOTLID LOCK CATCH	Distorted	109.48 F	*109.48 FL
24	1		*BOOTLID LOCK CATCH	Not Necessary	108.90 F	*- FL
25	1		*BOOTLID INSULATOR	Deformed	155.10 F	*155.10 FL
26	1		*BOOTLID RUBBER BEADING	Twisted	91.30 F	*91.30 FL
27	1		*BOOTLID DAMPER RRHS	Not Necessary	104.50 F	*- FL
28	1		*BOOTLID DAMPER RLHS	Not Necessary	104.50 F	*- FL
29	1		*BOOTLID KEY LOCK	Distorted	109.01 F	*109.01 FL
30	1		*BOOTLID STICKER CAB BOOKING - 65521111	Necessary	40.00 F	*40.00 FL
31	1		*BOOTLID STICKER CITYCAB	Necessary	40.00 F	*40.00 FL
32	1		*BOOTLID INSULATOR CLIP	Necessary	35.00 F	*35.00 FL
33	1		*REAR NUMBER PLATE	Cracked	35.00 F	*35.00 FL
34	1		*REAR END PANEL	Bent	323.29 F	*323.29 FL
35	1		*REAR END PANEL TOP GARNISH	Deformed	42.02 F	*42.02 FL
36	1		*REAR END PANEL SEALANT	Necessary	50.00 F	*50.00 FL
37	1		*TAILLAMP RHS	Not Necessary	323.40 F	*- FL
38	1		*TAILLAMP LHS	Cracked	323.40 F	*323.40 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*TAILLAMP INNER PANEL RHS	Repair	267.30 F	*- FL
40	1		*TAILLAMP INNER PANEL LHS	Repair	267.30 F	*- FL
41	1		*SPARE TYRES PANEL	Repair	812.90 F	*- FL
42	1		*SPARE TYRES BOARD	Not Necessary	162.14 F	*- FL
43	1		*SPARE TYRES INSULATOR PAD	Not Necessary	280.00 F	*- FL
44	1		*SPARE TYRES SEALANT	Not Necessary	50.00 F	*- FL
45	1		*REAR FENDER RHS	Not Necessary	1,598.30 F	*- FL
46	1		*REAR FENDER LHS	Repair	1,598.30 F	*- FL
47	1		*REAR FENDER INNER SHIELD RHS	Not Necessary	31.02 F	*- FL
48	1		*REAR FENDER INNER SHIELD LHS	Torn	31.02 F	*31.02 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,962.71	4,343.09
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	822.62
Total Parts (\$\$)	10,962.71	3,520.47

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEAT & STRAIGHTEN CHASSIS	New	1,500.00	1,000.00
2	MOUNT WORK BENCH	New	300.00	0.00
3	RUST PROOFING	New	80.00	40.00
4	R & R SPARE TYRES / BOARD / CARPET / TRIM	New	120.00	60.00
5	R & R REAR WINDSCREEN	New	120.00	0.00
6	CONDUCT WHEEL ALIGNMENT	New	60.00	0.00
7	TOWING CHARGES	New	150.00	60.00
8	ADJUST TAILLAMP AND CHECK WIRING	New	60.00	30.00
9	R & R BOOTLID COMPONENT	New	80.00	40.00
10	SPRAY PAINT ACCIDENT AREA - BOOTLID, END PANEL, SPARE TYRES PANEL, FENDER RRHS, FENDER RLHS, BUMPER	New	1,600.00	900.00
Gross Labour Cost (S\$)			4,070.00	2,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >