

INS. CASE OWNER:

CL

CC 4/ASM1800 0938

Kwa39

LKK:
IDAC:SW91
2082

Surveyor:

Kenneth

DOI:

12/1/18

Date / Time:

12/1/18

Registered in Merimen:

Pre-assign / CCU / FTE

SPY 4710E



Insured Vehicle No.:

Claim No.:

S8m007IN

Name of Insured:

Lu Yuan

Policy No.:

6A1518431

Insured Tel No.:

HP:

81985922

Make / Model:

T. Camry

Excess Sec II :\$5

D.O.A.:

10-1-18

Place of Accident:

SUP ROAD OF RT. BAYE AVE 27
RT. BAYE PC

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L-YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

S81001T



INSRS:

WSP:

Tel:

Liability:

RMKS:

Cheng Hoe
Kee

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: 22/1/18 5H

After call ltr to OI: 24/1/18 - use on

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

22/1/18 15:03 hr: spoke to OI, Mr Lu Yuan/81985922 agreed to settled on TP's claim, aware of NOB issue. will sent our letter.

24/1/18 - send letter to OI.

13/6/18 File pass to typist typ report

1/1/18 seek mandate via SWAAT
RECEIVED 13 JUN 2018

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

24

Repair Cost:

\$5 3531.00

Loss of Rental (LOR):

\$5

(

days)

Loss of Use (LOU):

\$5 700.00

(\$ 100 x 7

days)

Loss of Income (LOI):

\$5

(\$ x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

\$5 8.00

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost

\$5

Total:

\$5 4239.00

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5 4239.00

Name 1:

Cheng Hoe Motor Pte Ltd

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

ASS. REC. BY:

REF:

A/G/

AXA ?

Kennerth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SCZ 10017 Yr Regn: 09, 10Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy Vios c.c. 1897Colour: M. Maroon A/C: Insured / Std / Nil / NASp. Reading: 177762 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: MRO 53449305191930Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / 8/Rim / STD A/Rim or

Tyre Size: F: 195/35R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Neuton

Front _____ Rear _____

R/Bal. 8 mm R/Bal. 8 mmL/Bal. 8 mm L/Bal. 8 mmD.O.A. 10/1/18 D.O.I. 12/1/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

16/1 File pass to Coroner11/2 Q3300 Confirmed E SideTuition Co(6+1X100)(ed-1171.49)26/1

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation

\$ - RS - \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18000938/Kwa3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Date : 16-01-2018	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SFY 4710E	Veh. Inspected	SCZ 1001T	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M0071N	Excess (\$)	0.00	
Assign From		Assign Date	16/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	10/01/2018	Inspection Date	12/01/2018	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST 201001158E RCB NO 201001158E

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 10/01/2018

TP Veh Reg No: SFY4710E

Estimate No: ES1890049/AMK

Date: 12 Jan 2018

Policy No: 5045874150-07

Veh Reg No: SCZ1001T

Make/Model: TOYOTA VIOS 1.5 G A

Chassis No: MR053HY9305191930

Engine No: 1NZY181791

Reg. Date: 20/09/2010

Estimate Repair Cost to Vehicle No :SCZ1001T

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 REAR BUMPER	407.50	1 PC	407.50	✓
2 REAR BUMPER RH REFLECTOR	82.81	1 PC	82.81	✓
3 REAR BUMPER RH RETAINER (LONG)	92.33	1 PC	92.33	✓
4 REAR BUMPER RH RETAINER (SHORT)	31.22	1 PC	31.22	✓
5 REAR BUMPER CLIP	3.50	6 PC	21.00	✓
6 REAR BUMPER RH REINFORCEMENT BRACKET	63.77	1 PC	63.77	✓
7 REAR BOOT	510.85	1 PC	510.85	✓
8 REAR BOOT INNER LOCK	100.30	1 PC	100.30	✓
9 REAR BOOT INNER RUBBER	175.35	1 PC	175.35	50% ✓
10 REAR BOOT LOGO	50.25	1 PC	50.25	✓
11 REAR BOOT EMBLEM 'VIOS'	44.30	1 PC	44.30	✓
12 REAR BOOT EMBLEM 'G'	37.31	1 PC	37.31	✓
13 RH TAILLAMP	250.80	1 PC	250.80	✓
14 RH TAILLAMP INNER SEAL	26.42	1 PC	26.42	✓
15 REAR END PANEL	571.84	1 PC	571.84	✓
16 REAR END PANEL INNER TOP GARNISH	200.56	1 PC	200.56	✓
17 REAR END PANEL INNER TOP GARNISH CLIP	3.50	2 PC	7.00	✓
18 REAR SPARE TYRE TOP BOARD	114.38	1 PC	114.38	✓
19 REAR SPARE TYRE RH SIDE SPONGE	214.00	1 PC	214.00	✓
			3,001.99	
	Less 25%		750.50	2,251.49
Special Net				
20 REVERSE SENSOR	200.00	1 SET	200.00	✓
			200.00	200.00
Labour				
21 REMOVE & REFIX REAR BUMPER, REAR BOOT & ATTACHMENTS, TAILLAMPS, TO CUT, WELD & RENEW REAR END PANEL, KNOCKING & REPAIR REAR RH FENDER, SPARE TYRE PANEL & REALIGN THE SAME	900.00	1 LA	900.00	✓
22 PUTTY & RESPRAY REAR BUMPER, REAR BOOT, REAR FENDER, REAR END PANEL, REAR SPARE TYRE PANEL & ALL AFFECTED AREAS	900.00	1 LA	900.00	✓
23 REMOVE & REFIX REVERSE CAMERA, RESET & REPOSITION	80.00	1 PC	80.00	✓
24 RUSTPROOFING	90.00	1 LA	90.00	✓
			1,970.00	1,970.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO.201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department
WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 10/01/2018
TP Veh Reg No: SFY4710E

Estimate No: ES1890049/AMK
Date: 12 Jan 2018
Policy No: 5045874150-07
Veh Reg No: SCZ1001T
Make/Model: TOYOTA VIOS 1.5 G A
Chassis No: MR053HY9305191930
Engine No: 1NZY181791
Reg. Date: 20/09/2010

Estimate Repair Cost to Vehicle No :SCZ1001T

Description	U/Price	Quantity	List Price	Amount
			SS	SS
			Total	SS 4,421.49
			Add GST @ 7%	309.50
			Total Amount Payable	SS 4,730.99

VEHICLE LYING AT :
NO.10 ANG MO KIO INDUSTRIAL PARK 2A
#01-04 AMK AUTOPOINT
SINGAPORE 568047
TEL : 64812001

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SC210017

LABOURS		COST
SA: 1 set Reverse Sensors	1/1	200 ✓
R & R rear bumper, bootlid & attachments, taillamps, cut, weld & r rear end panel, k & r rear RH fender, s/tyre panel & realign the same.		900/2 ⁷⁵⁰
Putty & respray rear bumper, bootlid, rear fender rear end panel, rear s/tyre panel & all affected areas.		900/2 ⁸⁰⁰
R & R reverse camera, reset & realign the same.		80/2 ✓
Rustproofing		90/2 600

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SCZ1001T		
Vehicle Type :	L10 - For Instruction Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	TOYOTA		
Vehicle Model :	VIOS G AUTO		
Chassis No. :	MR053HY9305191930		
Propellant :	Petrol		
Engine No. :	1NZY181791		
Engine Capacity :	1497 cc		
Maximum Power Output :	80.0 kW (107 bhp)		
Maximum Laden Weight :	1520 kg		
Unladen Weight :	1110 kg		
Year Of Manufacture :	2010		
Original Registration Date :	20 Sep 2010		
Lifespan Expiry Date :	-		
COE Category :	A - Car (1600cc & below)		
Quota Premium :	\$29,000.00		
COE Expiry Date :	19 Sep 2020		
Road Tax Expiry Date :	19 Sep 2018		
PARF Eligibility Expiry Date :	19 Sep 2020		
Inspection Due Date :	19 Sep 2018		
Intended Transfer Date :	11 Jan 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK Print



Re:S8M0071N- Mandate approval

Type

🔔 Question

Message

Pls proceed

Reply



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

Date: 11 JUN 2018

AXA Insurance (S) Pte Ltd
C/O LKK Auto Consultants

Attn : THE MOTOR CLAIMS DEPT

Dear Sir / Madam

**ACCIDENT INVOLVING VEHICLE NO. SCZ1001T & SFY4710E ON 10/01/2018
SLIP RD (BT BATOK WEST AVE 2 TO BT BATOK RD).**

We are authorized by SCZ1001T for their above matter.

Record reveals that you are the insurer of SFY4710E. We therefore wish to seek compensation from you as below:-

1. Cost of Repairs	S\$ 3531.00
2. Loss of Income (6+1 x \$100/Day) 1st/1m CAR	S\$ 700.00
3. Hire of Vehicle	S\$ 0.00
4. LTA Search Fee/GIA Reports	S\$ 8.00
TOTAL	S\$ 4239.00

Please let us have your reply soonest possible.

Thank you.

Yours faithfully

CHENG HOE MOTOR PTE LTD



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

23 JANUARY 2018

LU YUAN
BLK 323 BUKIT BATOK ST 33
#07-112
SINGAPORE 650323

Dear Sir/Madam,

OUR REF : CC4/ASM18000938/Kwa3
YOUR REF : SFY 4710E
**ACCIDENT INVOLVING SFY 4710E AND SCZ 1001T ALONG SLIP ROAD OF BT
BATOK AVE 2 TWDS BT BATOK ROAD ON 10.01.2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from **CHENG HOE MOTOR PL**, acting on behalf of the owner of SCZ 1001T against your motor insurance policy.

Based on the accident report, accident scenario, it was reported that your vehicle had rear-ended the Third Party vehicle SCZ 1001T. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 7 days from the date of this letter **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Siti Jaafar
Case Handler
DID: 6256 3561
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AXA Insurance Pte Ltd (AXA)
(Motor Claims Dept)

AUTHORIZATION TO ACT

I, Ong Chin Hong ("the third party claimant")
of 221 Pavilion Circle S 658236 (address),

owner of SCZ1001T (vehicle no.) hereby authorize

CHENG HOE MOTOR PTE LTD

("The workshop") to act for me with respect to my claim for
repair costs and/or rental and/or loss of use ("claim") for my
Vehicle No. SCZ1001T that was damaged pursuant to the
accident which occurred on 10/1/2018 (date) along Slip Road (BT
Batok West Ave 2 to BT Batok Rd) (location)

involving Vehicle No/s SFY4710E

("The accident").

I further authorize the workshop to settle my above mentioned
claim in a manner that they deem fit and the workshop is further
authorized to receive payment further to settlement of my claim
with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach
on my behalf is on a without prejudice and without admission of
liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 11 day of January (month) 20 18 (year)


Signed by "the third party claimant"


Signed by "the workshop"



redefining / insurance

This Discharge Voucher applies strictly for Claimant's claim for property damages only does not constitute a full discharge for any other claims or further claims whatsoever present or future that may manifest arising directly or indirectly from this accident.

This settlement terms herein is without an admission of liability on the part of the claimant and the settlement terms should not be used as evidence in any related suits or claims arising from this accident.

CLAIM REF : [S8M0071N]
INSURED : [LU Yuan]

DISCHARGE VOUCHER

We/I [Ong Chin Hong], NRIC NO. S1257029E)
hereby agree to accept the sum of dollars [Four thousand two hundred thirty-nine only] (\$\$4,239.00) paid to
us/me by AXA INSURANCE PTE LTD as full and final settlement of all claims of whatever kind
including damages for personal injuries and damages to property that we/I may have against the
said AXA INSURANCE PTE LTD or their insured or the driver of motor vehicle no. [SFY4710E]
as a result of an accident along [Slip Rd of BT Batok Ave 2] on [10/1/2018] of
which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no.
[SCZ1001T].

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be
liable for any further claim(s) whatsoever and whosoever present or future that we/I may have
against the said insurer, owner and/or driver of vehicle no. [SFY4710E] in
connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and
hereby undertake to indemnify AXA INSURANCE PTE LTD against any claim made or to be made in
respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever
on the part of the said insurer, owner and/or driver of vehicle no. [SFY4710E].

* Payment To Be Made Payable To CHENG HOE MOTOR PTE LTD *

Dated this 20 day of December 2018

Claimant's Signature : [Signature]

NRIC no./ Company Stamp : X S1257027E

Occupation/ Business : Outdoor
Blk 1019 Yishun Ind Park A

Address c/o : #01-374 S 768761

Telephone No. : 67556142

Witness's Name : Wendy Ng

Witness's Signature : [Signature]

Witness's NRIC No. : S7017853B

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

TAX INVOICE

M/S : AXA INSURANCE (S) PTE LTD
8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP/AXA/AMK

Claim Type: Third Party

Accident Date: 10/01/2018

TP Veh Reg No: SFY4710E

NO: **CL8180541**

Date: 05 Jun 2018

Policy No: 5045874150-07

Veh Reg No: **SCZ1001T**

Make/Model: TOYOTA VIOS 1.5 G A

Job No: JC1597549

Description

| Quantity |

List Price

PAGE:1

Amount

To Supply all replaced parts, all necessary and agreed labour & miscellaneous charges.

1 PC

SS
SS 3,300.00

SS
SS 3,300.00

(As recommended by your appointed surveyor)

Total

SS 3,300.00

Add GST @ 7%

231.00

Total Amount payable

SS 3,531.00

For Cheng Hoe Motor Pte Ltd

E. & O. E.

AUTHORISED SIGNATURE



A.C. SYED & PARTNERS

ADVOCATES & SOLICITORS

COMMISSIONER FOR OATHS

101A UPPER CROSS STREET, #13-23 PEOPLE'S PARK CENTRE, SINGAPORE 058358

TEL : 6538 7411 & FAX : 6534 1011

TO : CHENG HOE MOTOR PTE LTD		BILL NO: B018 / 2018																																																																																																					
YOUR REF:																																																																																																							
OUR REF : ACS.CH.LTA.2018 (JAN 2018)		DATE : 5/2/18																																																																																																					
TO OUR PROFESSIONAL CHARGES for acting for you in the above matter including where necessary perusals, attendance preparation examination of documents relating thereto; correspondence, attendance, perusals, telephone calls, searches and all other incidental works not specifically mentioned herein to enable us to carry out the work entrusted to us inclusive of all advice.																																																																																																							
LTANET SEARCHES FOR THE MONTH JAN 2018 <table border="1"><thead><tr><th>S/NO</th><th>TP NO.</th><th>CHM</th><th>DOA</th></tr></thead><tbody><tr><td>1</td><td>2/1/2018</td><td>SJS7547A</td><td>GY5366Y 30/12/2017</td></tr><tr><td>2</td><td>2/1/2018</td><td>SKL4956Y</td><td>SJR4742C 29/12/2017</td></tr><tr><td>3</td><td>2/1/2018</td><td>SKQ6059Y</td><td>SKW7049M 1/1/2018</td></tr><tr><td>4</td><td>3/1/2018</td><td>SKE1673U</td><td>SJR2885L 3/1/2018</td></tr><tr><td>5</td><td>3/1/2018</td><td>YP6455B</td><td>SJU4191B 30/12/2017</td></tr><tr><td>6</td><td>3/1/2018</td><td>SGF3587P</td><td>SJG2424S 27/12/2017</td></tr><tr><td>7</td><td>3/1/2018</td><td>SKU8016L</td><td>SKS1610C 30/12/2017</td></tr><tr><td>8</td><td>5/1/2018</td><td>GBC1376U</td><td>SLP6769A 4/1/2018</td></tr><tr><td>9</td><td>8/1/2018</td><td>SKD5999J</td><td>SJJ4139L 6/1/2018</td></tr><tr><td>10</td><td>8/1/2018</td><td>GBF1775K</td><td>SLP3471C 5/1/2018</td></tr><tr><td>11</td><td>8/1/2018</td><td>SFM9595B</td><td>SJR592U 30/12/2017</td></tr><tr><td>12</td><td>8/1/2018</td><td>FBL3571L</td><td>SLH9325U 5/1/2018</td></tr><tr><td>13</td><td>11/1/2018</td><td>SFY4710E</td><td>SCZ1001T 10/1/2018</td></tr><tr><td>14</td><td>11/1/2018</td><td>GBB2710L</td><td>GBG5663T 11/1/2018</td></tr><tr><td>15</td><td>12/1/2018</td><td>SLJ4826M</td><td>SGY1911A 11/1/2018</td></tr><tr><td>16</td><td>12/1/2018</td><td>YL6367T</td><td>SKF9455A 9/1/2018</td></tr><tr><td>17</td><td>12/1/2018</td><td>GBC4242C</td><td>SJZ3236L 22/12/2017</td></tr><tr><td>18</td><td>13/1/2018</td><td>SKN5668L</td><td>SJL2414U 13/1/2018</td></tr><tr><td>19</td><td>14/1/2018</td><td>SJX1232X</td><td>SLF4986E 11/1/2018</td></tr><tr><td>20</td><td>14/1/2018</td><td>GU4511Y</td><td>SJX9477D 11/1/2018</td></tr><tr><td>21</td><td>14/1/2018</td><td>SLK1743H</td><td>SJF4726M 11/1/2018</td></tr><tr><td>22</td><td>14/1/2018</td><td>SJQ8960T</td><td>SJK2043L 11/1/2018</td></tr><tr><td>23</td><td>15/1/2018</td><td>SLG964P</td><td>GBG821L 10/1/2018</td></tr><tr><td>24</td><td>15/1/2018</td><td>SKP8802K</td><td>SJU8089M 13/1/2018</td></tr></tbody></table>				S/NO	TP NO.	CHM	DOA	1	2/1/2018	SJS7547A	GY5366Y 30/12/2017	2	2/1/2018	SKL4956Y	SJR4742C 29/12/2017	3	2/1/2018	SKQ6059Y	SKW7049M 1/1/2018	4	3/1/2018	SKE1673U	SJR2885L 3/1/2018	5	3/1/2018	YP6455B	SJU4191B 30/12/2017	6	3/1/2018	SGF3587P	SJG2424S 27/12/2017	7	3/1/2018	SKU8016L	SKS1610C 30/12/2017	8	5/1/2018	GBC1376U	SLP6769A 4/1/2018	9	8/1/2018	SKD5999J	SJJ4139L 6/1/2018	10	8/1/2018	GBF1775K	SLP3471C 5/1/2018	11	8/1/2018	SFM9595B	SJR592U 30/12/2017	12	8/1/2018	FBL3571L	SLH9325U 5/1/2018	13	11/1/2018	SFY4710E	SCZ1001T 10/1/2018	14	11/1/2018	GBB2710L	GBG5663T 11/1/2018	15	12/1/2018	SLJ4826M	SGY1911A 11/1/2018	16	12/1/2018	YL6367T	SKF9455A 9/1/2018	17	12/1/2018	GBC4242C	SJZ3236L 22/12/2017	18	13/1/2018	SKN5668L	SJL2414U 13/1/2018	19	14/1/2018	SJX1232X	SLF4986E 11/1/2018	20	14/1/2018	GU4511Y	SJX9477D 11/1/2018	21	14/1/2018	SLK1743H	SJF4726M 11/1/2018	22	14/1/2018	SJQ8960T	SJK2043L 11/1/2018	23	15/1/2018	SLG964P	GBG821L 10/1/2018	24	15/1/2018	SKP8802K	SJU8089M 13/1/2018
S/NO	TP NO.	CHM	DOA																																																																																																				
1	2/1/2018	SJS7547A	GY5366Y 30/12/2017																																																																																																				
2	2/1/2018	SKL4956Y	SJR4742C 29/12/2017																																																																																																				
3	2/1/2018	SKQ6059Y	SKW7049M 1/1/2018																																																																																																				
4	3/1/2018	SKE1673U	SJR2885L 3/1/2018																																																																																																				
5	3/1/2018	YP6455B	SJU4191B 30/12/2017																																																																																																				
6	3/1/2018	SGF3587P	SJG2424S 27/12/2017																																																																																																				
7	3/1/2018	SKU8016L	SKS1610C 30/12/2017																																																																																																				
8	5/1/2018	GBC1376U	SLP6769A 4/1/2018																																																																																																				
9	8/1/2018	SKD5999J	SJJ4139L 6/1/2018																																																																																																				
10	8/1/2018	GBF1775K	SLP3471C 5/1/2018																																																																																																				
11	8/1/2018	SFM9595B	SJR592U 30/12/2017																																																																																																				
12	8/1/2018	FBL3571L	SLH9325U 5/1/2018																																																																																																				
13	11/1/2018	SFY4710E	SCZ1001T 10/1/2018																																																																																																				
14	11/1/2018	GBB2710L	GBG5663T 11/1/2018																																																																																																				
15	12/1/2018	SLJ4826M	SGY1911A 11/1/2018																																																																																																				
16	12/1/2018	YL6367T	SKF9455A 9/1/2018																																																																																																				
17	12/1/2018	GBC4242C	SJZ3236L 22/12/2017																																																																																																				
18	13/1/2018	SKN5668L	SJL2414U 13/1/2018																																																																																																				
19	14/1/2018	SJX1232X	SLF4986E 11/1/2018																																																																																																				
20	14/1/2018	GU4511Y	SJX9477D 11/1/2018																																																																																																				
21	14/1/2018	SLK1743H	SJF4726M 11/1/2018																																																																																																				
22	14/1/2018	SJQ8960T	SJK2043L 11/1/2018																																																																																																				
23	15/1/2018	SLG964P	GBG821L 10/1/2018																																																																																																				
24	15/1/2018	SKP8802K	SJU8089M 13/1/2018																																																																																																				
		sub-total c/f	S 192.00																																																																																																				
 M/s. A C SYED & PARTNERS ADVOCATES & SOLICITORS SINGAPORE We reserved the right to forward a subsequent bill for any disbursements omitted herein. E. & O.E.																																																																																																							

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SFY 4710E (Insd veh)	Model:	TOYOTA VIOS
	SCZ 1001T (TP veh)		
Date of Accident:	10/01/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	: \$		4,730.99
Final Repair Cost	: \$		3,531.00
Loss of Use	: \$		700.00
			7days at \$100.00 per day
Rental (if any)	: \$		days
LTA / GIA Search Fee	: \$		8.00

Others:	: \$	0.00
---------	------	------

	: \$	
Final Settlement Sum	: \$	4,239.00

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No- BOLA Scenario No:

_____27_____

BOLA Liability: _____100_____(%) Assessed Liability (*): _____(%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks

Payment Instruction: Payee's Breakdown

1)	CHENG HOE MOTOR PTE LTD	: \$	4,239.00
----	-------------------------	------	----------

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

01/02/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

Service Request Details

Claim#
SAM0071N

Reference
CCA/ASM18000928/Wwa3a2

Loss Date
10 January 2018

Request Date
12 January 2018

Dist Date

Vendor Name
LUK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss
Third Party Vehicle Damage

Services
Direct settlement

Vehicle Information

Incident Vehicle Registration #
SCZ1001T

Make
Mitsubishi

Model
TOYOTA VIOS

Service Address
BLK 323 #07-112...650323

Primary Contact/Insured
LU YUAN
BLK 323 #07-112, 650323, Singapore 81985922

Claim Handler
LOH Cynthia
6568804843
cynthia.loh@axa.com.sg

Actions

Next Step
Wait for Approve Invoice

Third Party

(1) TP-Ching Hwe Motor : ARC (2) ID-H2B

Additional Instructions

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
Document Type			Document SubType			
Upload Documents						
NAME	TYPE	SUB-TYPE	AUTHOR	DATE	UPLOADED	
LUKInvoice1.pdf	Invoice	Surveyor/ Assessor expense	LUK AUTO CONSULTANTS PTE LTD (TP)	1 February 2019		

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 payment breakdown SCZ 1001T.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 February 2019
 LOO.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 February 2019
 DISCHARGE VOUCHER.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	3 February 2019
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	PGA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	3 February 2019
 WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	3 February 2019
 LKK Reinspection Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 November 2018
 LKK Inspection Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 November 2018
 Immediate Advice- SCZ 1001T.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 November 2018
 LIA SEARCH.pdf	Letters and Correspondence	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 July 2018
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	17 July 2018
 TP ESTIMATE - MARKED.pdf	Forms / Claim Documents	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	17 January 2018
 TP GIA IPT.PDF	Reports & Statement	GIA Report	LOH Cynthia	12 January 2018
 INSD GIA.PDF	Reports & Statement	GIA Report	LOH Cynthia	12 January 2018
 EMAIL TO WORKSHOP.pdf	Other	Other	DHIWAR Namrata	11 January 2018
 EMAIL RECEIVED FROM WORKSHOP.pdf	Other	Other	DHIWAR Namrata	11 January 2018

Assessment Details

General & Workshop Details				Vehicle Condition		Taxes & Ratio		Parts & Labour		Miscellaneous		Summary		Parts			
Add		Approve		Deny		Submit All											
EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC QUANTY	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE		
		1	1		REAR BUMPER			Bent	407.5		25		305.63	Approve			
		2	1		REAR BUMPER RH REFLECTOR			Cracked	82.81		25		62.11	Approve			
		3	1		REAR BUMPER RH RETAINER (LONG)			Damaged	92.33		25		69.25	Approve			
		4	1		REAR BUMPER RH RETAINER (SHORT)			Damaged	31.22		25		23.42	Approve			
		5	6		REAR BUMPER CLIP			Necessary	3.5		25		15.75	Approve			
		6	1		REAR BUMPER RH REINFORCEMENT BRACKET			Bent	63.77		25		47.63	Approve			
		7	1		REAR BOOT			Buckled	510.85		25		383.14	Approve			
		8	1		REAR BOOT INNER LOCK			Defiled	100.3		25		75.23	Approve			
		9	1		REAR BOOT LOGO			Necessary	50.25		25		37.69	Approve			
		10	1		REAR BOOT EMBLEM VIOS			Necessary	44.3		25		33.23	Approve			
		11	1		REAR BOOT EMBLEM G			Necessary	37.31		25		27.98	Approve			
		12	1		RH TAILLAMP			Cracked	250.8		25		188.1	Approve			
		13	1		RH TAILLAMP INNER SEAL			Necessary	26.42		25		19.82	Approve			
		14	1		REAR END PANEL			Bent	571.84		25		429.88	Approve			

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTYRS	DISC QUNTY	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	15	1			REAR END PANEL INNER TOP GARNISH			Damaged	200.56		25		150.42	Approve	
	16	2			REAR END PANEL INNER TOP GARNISH CLIP			Necessary	3.5		25		5.25	Approve	
	17	1			REAR SPARE TYRE TOP BOARD			Dentist	114.38		25		85.79	Approve	
	18	1			REAR SPARE TYRE RH SIDE SPONGE			Cracked	214		25		160.5	Approve	

Labour

Add

Remove

Empty

Subtract All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR H&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	1		REMOVE & REFIX REAR BUMPER ,REAR BOOT & ATTACHMENTS ,TAIL LAMPS,TO CUT ,WELD & RENEW REAR END PANEL ,KNOCKING & REPAIR REAR RH FENDER ,SPARE TYRE PANEL & REALIGN THE SAME	600	0	0	Approve		
	2		PUTTY & RESPRAY REAR BUMPER ,REAR BOOT,REAR FENDER ,REAR END PANEL ,REAR SPARE TYRE PANEL & ALL AFFECTED AREAS	800	0	0	Approve		
	3		REMOVE & REFIX REVERSE CAMERA,RESET& REPOSITION	80	0	0	Approve		
	4		RUSTPROOFING	60	0	0	Approve		

Assessment Details

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	REAR BOOT INNER RUBBER (50%)	Approve	87.88	CUT	
	2	SET REVERSE SENSOR	Approve	200	SHORTED	
	3	DAYS OF REPAIR & DAYS	Approve			

Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition		Taxes & Rollo		Parts & Labour		Miscellaneous		Summary		Claim Amount	
Claim Amount		\$4,147.70													
CATEGORY		ESTIMATE		REVISED AMOUNT											
Spares Parts		\$2,120.02		\$2,120.02											
Labour		\$1,740.00		\$1,740.00											
Miscellaneous		\$287.68		\$287.68											

Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary	Claim Amount
Claim Amount		\$3,300.00						\$3,300.00
CATEGORY		ESTIMATE	REVISED AMOUNT					
Miscellaneous		\$3,300.00	\$3,300.00					