

MR053H49305191930

T110105

8CZ10017

PARTS	COST	LIST
1pc Rear bumper B1 -		
1pc - v RH Reflector CR1 -		
1pc - v RH Retainer (Long) DIN		
1pc - v - (short) DIN		
6pus - v clips M -		
1pc - v - RH reinforcement bracket M -		
1pc Bootlid BUL -		
1pc - v inner lock M -		
1pc - v inner rubber distal 50mm		
1pc - v logo M -		
1pc - v Emblem (Vios) M -		
1pc - v - (G) M -		
1pc RH taillamp CR1 -		
1pc - v inner seal M -		
1pc Rear end panel B1 -		
1pc - v inner top garnish M -		
2pus - v clips M -		
1pc Rear of tyre panel top board M -		
1pc - v RH side sponge CR1 -		
CHENG HOE MOTOR PTE LTD		
10 ANG MO KIO IND PARK 2A		
#01-04 AMK AUTOPOINT		
SINGAPORE 568047		
TEL: 6481 2001 FAX: 6482 1296		
EMAIL: chmamk@singnet.com.sg		

SC210017

LABOURS		COST
SA : 1set Reverse Sensors	1/1	200 ✓
R & R rear bumper, bootlid & attachments, taillamps, cut, weld & r rear end panel, ker rear RH fender, s/tyre panel & realign the same.		900/z ⁷⁵⁰
Putty & respray rear bumper, bootlid, rear fender rear end panel, rear s/tyre panel & all affected areas.		900/z ⁸⁰⁰
R & R reverse camera, reset & realign the same		80/z ✓
Rustproofing		90/z 600