

SERVICE ESTIMATE

92672 - C00001 SL: SERVICE SALES - PC
 Mr Shanker s/o Neela Segaran
 32 Pavilion Green

Singapore 658317

Closed by : Paul Ong Qing Yong
 Svc Consultant :
 Remarks : Mr Shanker s/o Neela

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 1
 Inv.date. : 16/01/2018
 WIP No. . : 40121 *46671*
 Veh.In/Out:
 *Tel.No. . : Mobile: 81255433
 Reg.No. . : SLQ9377Y
 Reg.date . : 27/07/2017
 Mileage .. : 0
 Chassis No: SAJAB4AGXHA954473

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE REAR BUMPER, REAR VALANCE, ETC	0	1700.00	0	1,700.00	S	<i>900</i>
800	TO PUTTY SPRAYPAINT ON REAR BUMPER, BOOTLID, ETC	0	1500.00	0	1,500.00	S	<i>800</i>
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	486.00	0	486.00	S	<i>✓</i>
	BUMPER COVER	1.0 EA	847.10		847.10	S	<i>de-</i>
	PANEL-VALANCE	1.0 EA	520.30		520.30	S	<i>ant</i>

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
 is subject to final approval from Insurance Company

Acknowledged by Repairer	
Signature: _____	3,686.00
Date: _____	1,367.40
Labour Total	
Parts Total	
Package Total	0.00

Gross Total. 5,053.40
 Net..... 5,053.40
 GST @ 7.0% 353.74
 Total..... 5,407.15
 Paid..... 0.00
 Please Pay.. 5,407.15

GST: S=StdRated; O=OutOfScope; Z=ZeroRated