

**COMFORTDELGRO ENGINEERING PTE LTD**  
**REPAIR ESTIMATE\***

*Angkia - CP/P*

IS

VEHICLE NO : SHA 2622S

DATE 15/1/2018

MAKE :

*LKK - Kalvin*

MODEL : HYUNDAI IONIQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			
	Rear Bumper Reinforcement ?			
	Rear Bumper Clip ✓			
	Rear Bumper Sponge ?			
	Rear Bumper Under Cover ✓			
	Rear Bumper Protector (LH/RH) X			
	<b>SUB TOTAL</b>			\$ -
	<b>LESS 20%</b>			\$ -
	<b>DISCOUNTED TOTAL</b>			\$ -
	Rear Bumper Reverse Sensor X			\$ 135.70
	Rear No. Plate ✓			\$ 25.00
				<b>\$ 160.70</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ <del>350.00</del> <sup>200</sup>
	Spray Painting Charge			\$ <del>200.00</del> <sup>180</sup>
	Wiring Charge			\$ <del>50.00</del> <sup>X</sup>
	Remove/Refix Reverse Sensor			\$ <del>120.00</del> <sup>20</sup>
	<b>TOTAL LABOUR</b>			<b>\$ 720.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 880.70</b>
	<p><i>Kalvin LKK</i>  <i>15/1/18 1235 hrs.</i>  <i>2 Days.</i>  <i>PIP</i>  <i>Before Paint photo</i></p>			
	<p><b>LKK Auto Consultants hence notify the Repairer of the following:</b></p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification is allowed</li> <li>• Supplementary to the resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer  Signature:  Date:</p>			
	<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>			