

REPAIR ESTIMATE*

VEHICLE NO : SHC 3044T

DATE 12/1/2018 16:55

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover XXXXXX ✓			\$ 538.80
	Front Bumper Sponge ?			\$ 136.30
	Front Bumper Reinforcement ?			\$ 504.10
	Front Bumper Grille (LH) X			\$ 17.60
	Front Bumper Bracket Top (LH) ?			\$ 22.40
	Front Bumper Protector (LH) X <i>reg.</i>			\$ 29.20
	Headlamp Support Panel Assy X			\$ 1,023.00
	Headlamp (LH) X			\$ 797.90
	Front Fender (LH) ✓			\$ 593.00
	Front Fender Shield (LH) ?			\$ 86.00
	Front Fender Retainer ✓			\$ 9.20
	Front Wheel Hub Cap (LH) ✓			\$ 145.00
	SUB TOTAL			\$ 3,902.50
	LESS 20%			\$ 780.50
	DISCOUNTED TOTAL			\$ 3,122.00
	Labour Charge			300
	Panel Beating			\$ 560.00
	Spray Painting Charge			\$ 360.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 20.00
	Frt Wheel Alignment			\$ 80.00
	TOTAL LABOUR			\$ 1,140.00
	ESTIMATE TOTAL			\$ 4,262.00
	<i>Ka/lin 16/11/14</i>			
	<i>15/1/18 1050hr</i>			
	<i>2071</i>			
	<i>45</i>			
	<i>After Repair</i>			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be relayed and is subject to final approval from Ins. Co. Company

Acknowledged by Repairer
Signature: _____
Date: _____

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.