

# AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721  
 TEL: 6452 8211 FAX: 6451 7420

## ESTIMATE

**THAMAINDRAN**  
 c/o 46 Lentor Plain  
 Singapore 786548

*Not authorized  
 11 May @ 7  
 Repair After Paint  
 5 days*

Date: 16/01/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
<b>RE : TOYOTA COROLLA ALTIS / SLL3030M</b>		
1 pc	rear bumper	<i>Bu</i> 564.10 <i>—</i>
1 pc	rear bumper reinforcement	<i>Bu</i> 365.40 <i>—</i>
2 pcs	rear bumper reflector @ 173.20	<i>su</i> 346.40 <i>X</i>
2 pcs	rear bumper side retainer @ 63.40	<i>n/s?</i> 126.80 <i>+</i>
2 pcs	rear bumper reinforcement bracket @ 147.10	294.20 <i>?</i>
2 pcs	rear bumper corner retainer @ 61.40	122.80 <i>?</i>
1 pc	rear boot lid	<i>Bu</i> 765.20 <i>—</i>
1 pc	rear boot lock	<i>n</i> 164.40 <i>X</i>
1 pc	rear boot lock catch	<i>n</i> 73.20 <i>X</i>
2 pcs	rear boot lamp <i>n/s?</i> @ 357.10	714.20 <i>+</i>
1 pc	rear boot weathership	<i>su</i> 279.60 <i>?</i>
1 pc	rear boot emblem	<i>su</i> 74.10 <i>—</i>
1 pc	rear boot emblem "COROLLA"	<i>su</i> 64.30 <i>—</i>
1 pc	rear boot emblem "ALTIS"	<i>su</i> 65.70 <i>—</i>
1 pc	rear end panel	571.40 <i>?</i>
1 pc	rear end panel garnish	331.90 <i>?</i>
2 pcs	reverse sensor @ 346.40	692.80 <i>?</i>
1 pc	rear lock sensor receiver	275.00 <i>?</i>
2 pcs	rear tail lamp <i>n/s?</i> @ 564.70	<i>clsu x</i> 1,129.40
1 pc	rear spare tyre panel top board	<i>su</i> 356.10 <i>X</i>
1 pc	rear exhaust silencer	<i>n</i> 974.80 <i>X</i>
	sub-total	8,351.80
	less 25%	2,087.95
	sub-total	6,263.85

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

balance brought forward.	6,263.85
To remove and replace the parts mentioned above, above, panel beat and realign the necessary affected areas.	1,000.00 ?
To check wiring system.	<i>200</i> 50.00
To apply putty and spray painting on affected areas.	<i>600</i> 750.00
To install reverse sensor & reverse camera.	<i>600</i> 120.00
To apply rust proofing on affected areas.	200.00 ?
To apply water proof sealant on affected areas.	200.00 ?
To carry out exhaust works.	<i>na</i> 120.00 X
<b>Total</b>	<b>8,703.85</b>