

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100

FAX: 62247743

ATTN: Motor Claim Department

Estimate No: ES1890095/AMK

Date: 29 Jan 2018

Policy No: A28929261QMX

Veh Reg No: SGQ94G

Make/Model: HONDA ODYSSEY 2.4L A

WS Ref: TP/INDIA/AMK

Claim Type: Third Party

Accident Date: 12/01/2018

TP Veh Reg No: SHA6971H

Chassis No: JHMRC1890GC203121

Engine No: K24W72011421

Reg. Date: 07/04/2016

Not Authorise

Resurvey & Repair

4 days

Estimate Repair Cost to Vehicle No :SGQ94G

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT RH DOOR	897.80	1 PC	897.80	✓
2 FRONT RH DOOR WINDOW GLASS	542.80	1 PC	542.80	✓
3 FRONT RH DOOR SIDE MIRROR ASSY	1,304.00	1 PC	1,304.00	✓
4 FRONT RH DOOR SIDE MIRROR OUTER COVER	74.70	1 PC	74.70	✓
5 FRONT RH DOOR OUTER MOULDING	82.30	1 PC	82.30	✓
6 FRONT RH DOOR POWER WINDOW MOTOR WITH REGULATOR	392.60	1 PC	392.60	✓
7 FRONT RH DOOR FRAME STICKER	35.60	1 PC	35.60	✓
			3,329.80	
		Less 20%	665.96	2,663.84
Special Net				
8 FRONT RH DOOR WINDOW GLASS TINTED FILM	100.00	1 PC	100.00	✓
			100.00	100.00
Labour				
9 REMOVE & REFIX FRT RH DOOR & ATTACHMENTS; KNOCKING & REPAIR FRT RH FENDER & REALIGN THE SAME	500.00	1 LA	500.00	✓
10 PUTTY & RESPRAY FRT RH FENDER, FRT RH DOOR & SIDE MIRROR & ALL AFFECTED AREAS	500.00	1 LA	500.00	✓
11 REMOVE & REFIX FRT RH DOOR WINDOW GLASS & RESET CENTRAL LOCKING	60.00	1 LA	60.00	✓
12 RUSTPROOFING	60.00	1 LA	60.00	✓
			1,120.00	1,120.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100 FAX: 62247743

ATTN: Motor Claim Department

WS Ref: TP/INDIA/AMK

Claim Type: Third Party

Accident Date: 12/01/2018

TP Veh Reg No: SHA6971H

Estimate No: ES1890095/AMK

Date: 29 Jan 2018

Policy No: A28929261QMX

Veh Reg No: SGQ94G

Make/Model: HONDA ODYSSEY 2.4L
A

Chassis No: JHMRC1890GC203121

Engine No: K24W72011421

Reg. Date: 07/04/2016

Estimate Repair Cost to Vehicle No :SGQ94G

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 3,883.84
			Add GST @ 7%	271.87
			Total Amount Payable	<u>S\$ 4,155.71</u>

VEHICLE LYING AT :
NO.10 ANG MO KIO INDUSTRIAL PARK 2A
#01-04 AMK AUTOPOINT
SINGAPORE 568047
TEL : 64812001

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE