

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SHD4765J
Accident Date : 09-Jan-2018

No. : 05707

Date : 12-Jan-2018

Our Ref : 218012 (III) / CHAN

PAGE : 1

RON SITU YONG JUN
7 SIN MING WALK
#16-15
Singapore 575577

Not Authored

Resurvey B4 pricing

Today

ESTIMATED COST OF REPAIR FOR LEXUS IS200T 2.0 SKG1177A

1 pc Front o/s fender
1 pc Front o/s bumper side retainer
1 pc Front bumper fascia

B1 1,063.70 —
D1 109.50 —
Bulkin 950.40 —

2,123.60

Less 10% : 212.36

1,911.24

To putty and spray replaced parts

650.00 *500*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

350
400.00

Total : S\$ 2,961.24

Singapore Dollars Two Thousand Nine Hundred and
Sixty One and Cents Twenty Four Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s), must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date