



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18000969/R1vd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 12-03-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 4776T	Veh. Inspected	SFA 3588A
Policy No.		Coverage (\$)	0.00
Claim No.	SHA4776T (DOA: 13/1/2018)	Excess (\$)	0.00
Assign From	TEO SWEE KEONG	Assign Date	16/01/2018

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ E250 SEDAN	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WDD2120362B081338	Colour	GREY
Odometer	89880	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/40 R18	BRIDGESTONE	6 mm
L/H Front Tyre	245/40 R18	BRIDGESTONE	6 mm
R/H Rear Tyre	245/40 R18	BRIDGESTONE	6 mm
L/H Rear Tyre	245/40 R18	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	13/01/2018	Inspection Date	24/01/2018
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------