



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
Mr Lim Siew Khoon	Cust No/Name KCV05333/Mdm Lim Siew Khoon
23 Namly Place	Reg No/Reg Date SKX8238Y / 21/12/201
Hamrock Park	Date In/Mileage / 0
Singapore 267170	Chassis No JMFXTGA2WFZC08677
Contact No 97895783	Engine No 4B11QT1823
	Make/Model MIT/ASX 2.0 CVT 2WD (N04)
	Colour/Trim A03 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KCV05333	CRDVCH	13/01/2018/ 09:45		465 / Tay Jian Ye	19691			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								550. 1650.00
TO RENEW REAR BUMPER AND REPAIR END PANEL								X 300.00
A 28610501								100 ? 200.00
TO RENEW REAR EXHAUST MUFFLER								
E PNT88000								420 1260.00
TO REMOVE AND REFIT REAR BOOT TRIMS TO FACILITATE REPAIR								
E PNT98000								20 50.00
PAINT WORK SPRAY REAR BUMPER AND END PANEL								
A 54900099								✓ 200.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								
A 10028901								X 80.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								my 220.00
M SUNDRY								
TO APPLY ANTI CORROSION ON AFFECTED PORTION								20 50.00
M SUNDRY								? 220.00
TO SUPPLY PARKING SENSOR								? 25.00
M SUNDRY								mis 15.00
SUNDRIES								de 877.00
M REINFORCEMENT,RR BUMPER					1.00	220.00	00.00	my 2.00
M BRKT,R/BMPR FACE SUPT,LH					1.00	25.00	00.00	X 479.00
M BRKT,R/BMPR FACE SUPT,RH					1.00	25.00	00.00	X 46.00
M COVER,RR BUMPER					1.00	15.00	00.00	
M FACE,RR BUMPER					1.00	877.00	00.00	
M CLIP,ENG ROOM COVER					1.00	2.00	00.00	
M MUFFLER,EXHAUST MAIN					1.00	479.00	00.00	
M HANGER,EXHAUST MUFFLER					2.00	23.00	00.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: Tay Jian 97495749

Date: 22/1/18

SURVEYOR NAME: Tay Jian

SURVEYOR SIGNATURE: 22/1/18

DATE: 22/1/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME:

SURVEYOR SIGNATURE:

DATE:

Confirm & accepted by

REMARKS:

Nett

5,699.00

7% GST on

5699.00

398.93

Total Payable

6,097.93

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.