

ASS. REC. BY:

REF:

CS / MSG18000975 / Tigb

Special Instruction:

Survivor
Maimen

Tang

ASSIGNMENT (Office)

From (Person):

Lionel Tan

of

MSTH

Date/Time:

16/01/2018 359 pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLT 3153A

Insured:

G8G 2531K

at Workshop m/s

Barneo motor

Tel:

9221 3150

of

2 Pandan Crescent

Policy No:

29069179 MKF

Claim No:

546588

Sum Insured:

Excess:

Make of Veh:

D.O.A.

13/01/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wpr

17.01.2018 @ 2pm owner waiting

H.O.D. Endorsement:

Date/Time:

16/01/2018 11:00pm

Person Contacted:

Raymond

Vehicle-IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLT 3153A - x
	G8G 2531K - x
18/1/18 @ 5:48pm	revised to Lionel Tan via Maimen.
26/4/18 @ 10:34am	confirmed with Raymond final Ag \$11627.69, 1 days.
	(Per \$8367.45, 42%)

26/4.

Tang M

MSIG

MSIG

Date 17/01/2018

SLT 3153A

2017 Oct

Insurance Code

CP WS/TP RES/CO RES/EVA/INV/MV

Thrust vehicle No SLT 3153A

Engine No Borneo Motor

2 pandan Crescent

Insured

Policy No

Claim No

Sum Insured Excess

Diagnosis Report 2pm Owner waiting

Make of van

Policy Condition

Remark: The van had commenced its repair at the time of inspection.



Set of Vehicle

ICAO Accident Room Consistent? Yes or No

Q4 PR Seen Consistent? Yes or No

Set Repair 6 days Pass: Yes or No

Set Buy 4 Give: Yes or No

Q4 PR / REP / 24 HRS up

Date Person Contacted

Vehicle IN OUT

Date Time Action Instruction

Truck Trailer

Make Toyota Harbin

Color Silver

Engine 5147

Engine

Owner STEZ B36H 80 Joon 297

Gen Cond Good / Fair / Poor / Burnt

Steering Inspected / Jammed / Leaked / Burnt

Brake Inspected / Jammed / Leaked / Burnt

Mod Nil / S Rim / STD A Rim

Tyre Size 235/55R18

Set IDUN/EXNOVA/GY/PS/LIZA/MIC/GHTSU/PR/SUM

TOYO/YOKO or

Front 6 Rear 6

FRS 6 RRS 6

LBS 6 RBS 6

DOA DO

Survey note Borneo Pandan

Set of Damages FR Rear OS NS UC Roof/Roof

Rear n/s

The UIC / Chassis frame / Body Structure affected due to collision

RECEIVED 27 APR 2018

Creating a Report

28/4 11/18

Set of Report

Set of Report

Report Received

11627.64

Days Of Repair 6

Resurvey No. of Trip 1

Add Fee

Set of Fee

Set of Fee

Set of Fee





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18000972/T1qb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 16-01-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBG 2531K	Veh. Inspected	SLT 3153A
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (LIONEL TAN)	Assign Date	16/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	13/01/2018	Inspection Date
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Jan 2018		16 Jan 2018 15:59 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	GARDENIA FOODS (S) PTE LTD, Co. Reg. No.: 197801714R								
Main Claimant:	HO TECK SOON ALBERT, ID: S1162853B								
Vehicle Reg. No.:	SLT3153A	Date of Loss:	13/01/2018 10:00 - :59						
Claim Type:	TP	Policy/Cover Note No.:	C/NO:121681 (Comprehensive) Coverage: 01/01/2018 - 31/12/2018						
Vehicle Reg. No. (Insured):	GBG2531K	Policy No. (Claimant):							
		Excess:							
Repairer:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 17/01/2018]								
Driver/Custodian (Insured):	ONG POH LEE (47 / Male), NRIC: S7029960G, Tel: +6598574068								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 26 April 2018 10:34 AM
To: Raymond.Seah@borneomotors.com.sg
Cc: SUR
Subject: RE: PHOTOS OF SLT3153A

Dear Raymond,

Confirm final fig \$11,627.69 before GST and 6 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 22 February 2018 11:23 AM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: FW: PHOTOS OF SLT3153A

CS/MSG18000972/T1qb

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Raymond Seah PTCBC [<mailto:Raymond.Seah@borneomotors.com.sg>]
Sent: Thursday, 22 February 2018 11:13 AM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Cc: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: PHOTOS OF SLT3153A

fyi

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

1/18/2018

Adjuster Immediate Advice

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan Tian Pei

Date: 18 Jan 2018

Preliminary Advice

Insured Vehicle No	: GBG2531K	Accident Date	: 13/01/2018
TP Vehicle No	: SLT3153A	Assignment Date	: 16/01/2018
Make	: TOYOTA HARRIER	Est. Duration of Repair	: 6
Date of Inspection	: 17/01/2018		
Inspection At	: BORNEO MOTORS		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,995.14
Revised Amount	:S\$	10,135.67
Check Items (Estimated)	:S\$	1,203.14
Total	:S\$	11,338.81

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/01/2018 10:37
Date Of Accident	13/01/2018 10:40
Exact Location Of Accident	ALONG SLIP ROAD WEST COAST RD TOWARDS CLEMENTI AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT3153A
Insured/Policyholder	
Name Of Registered Owner	HO TECK SOON ALBERT
NRIC No	S1162853B
Email Address	ALBERT.HO@CITYSTATE.TRAVEL
Mobile Phone No	(LOCAL) +65-97354849
Alternative Phone No	OTHERS-97354849

Vehicle Particulars

Manufacturer	TOYOTA
Model	HARRIER-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USAGE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPPHQ17-005665
Cover Note Number	

Driver

Name of Driver	HE XIUWEN,JOANNE
NRIC No	S8818268E
Date Of Birth	27/05/1988
Occupation	INDOOR
Date Of Driving Pass	24/10/2008
Driving Experience	9 YEARS AND 2 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-94783738
Fax Number	
Contact Number	
Email Address	JOANNEHXW@GMAIL.COM

Address	71 JURONG EAST STREET 13 #16-10 SINGAPORE
Postcode	609650
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG2531K
Vehicle Make/Model/Colour	MITSUBISHI / CANTER / RED
Details Of Properties	FRONT RIGHT PORTION
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ONG POH LEE
NRIC/Passport Number	S7029960G
Contact Number	98574068
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:



- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 15/01/2018
10:25 am

Driver's Signature

(If driver is not the policyholder)


Date & Time: 15/01/2018
10:25 am
 CONFIDENTIAL ESTABLISHING PTE LTD
 EXTERNAL BUSINESS DIV, PASIR LIAH BRANCH
 NAME & SIGNATURE: 
 DESIGNATION:  DATE: 

Reporting Centre Personnel's Signature

Name: WONG CHEE WEI

NRIC/FIN No: 672180994

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along West Coast Road and turned left into the Filter lane to enter Clementi Avenue 2 (Flyover). When I was on the filter lane and waiting for the opportunity to turn left into Clementi Ave 2, I heard and felt a knock at the left back of my car. I then stopped the vehicle and noted that ~~the~~ the left back lights broken and dislodged from the car and the car was scratched. The vehicle that knocked my car was a Gardenia truck (GBG 2531K) and driver was Ong Poh Lee.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature

Date & Time: 15/01/2018
10:25 am


Driver's Signature
(If driver is not the policyholder)

Date & Time: 15/01/2018
10:25 am

CONFIDENTIAL - POLICE USE ONLY
EXTERNAL BUSIN. ONLY, FALLEN BRANCH
Name & Signature
Reporting Centre Personnel's Signature
Name: WONG CHEE WEI
NRIC/FIN No: 672180994



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1162853B



HO TECK SOON, ALBERT

何德順

RACE

CHINESE

Date of Birth

12-11-1955

Country of Birth

SINGAPORE

COMPOTROL GROUP HOLDING PTE LTD
EXTERNAL BUSINESS DIV, PASIRAN BRANCH
NAME & SIGNATURE: _____
DESIGNATION: _____ DATE: _____



1887812



NRIC No. S1162853B

COMPOTROL GROUP HOLDING PTE LTD
EXTERNAL BUSINESS DIV, PASIRAN BRANCH
NAME & SIGNATURE: _____
DESIGNATION: _____ DATE: _____

Board of Directors - Director

Q+

20-04-1994

71 JURONG EAST STREET 13 #10-10

SINGAPORE 608650

NRIC No. S1162853B

Date: 22-10-1999 (R/W: 213699)

REPUBLIC OF SINGAPORE **DRIVING LICENCE**

Licence Number: **S1162853B**

HO TECK SOON, ALBERT

Birth Date: **12 Nov 1955**
Issue Date: **06 Apr 2003**

000359369D

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	PASS DATE
Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	16 Apr 1984

NP 426A



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 068116
tel 65 6223 9433 | fax 65 6224 2802 | www.eqinsurance.com.sg
reg no. 1978-00480-N



CERTIFICATE OF INSURANCE

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

**PRIVATE CAR
Comprehensive**

Certificate No.: DMPPHQ17-005665

Form: PK2

Excess:

Insured/Named Driver SGD0.00

Unnamed Drivers SGD300.00

VEID Additional SGD1,200.00

1. Index Mark and Registration Number of Vehicles

SLT3153A

2. Name of Policyholder

NO Teck Soon Albert

3. Effective Date of the Commencement of Insurance for the purpose of the Act

25/10/2017

4. Date of Expiry of Insurance

24/10/2018

5. Person or Classes of Persons entitled to drive*

(a) The Policyholder

(b) Any other person who is driving on the Policyholder's order or with his permission.

*Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act has not been cancelled at the time of accident loss or damage.

6. Limitations as to use*

Use for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover:

(a) use for hire or reward

(b) use for racing, pace-making, reliability trials or speed testing

(c) use for the carriage of goods (other than samples) in connection with any trade or business

(d) use for any purpose in connection with the Motor Trade

*Limitations rendered inoperative by Section 8 of the Motor vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or and Amendment, Act or Acts passed in substitution thereof.

UHNBF/HO/DM0001/DIRECT MARKETING



A Member of Citystate

Authorised Signatory
EQ Insurance Company Limited



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 129462
Tel no.: 6631-1188

Account Detail		Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		S1000004 / ICCU1	Mr Ho Teck Soon Albert 71 Jurong East Street 13 #16-10 Singapore 609650 Mobile: 97354849
		Document No	
		Document Date	
		0	
		17/01/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	ANTMT	E1	25/10/2017	SLT3153A	0	29213	9DS/SLT3153A-130111
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTEZB3GH80J000297	8ARZ091098	60	Raymond Seah L M	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP/DS CLAIM TP VEH:GBG2531K ACC DATE:13/01/2018 TP INS:MSIG NO OF REPAIR DAYS: DATE-IN: DATE SURVEY:17/01/2018 BY:LKK-TAUFLIK AUTHORIZED ON:				30, 50.00
2	B	BP-ECU TO RESET ECU AND REPROGRAMME				✓ 508.50
3	Z	BP-SLANT SUPPLY SEALANT (NETT) FOR REAR TAILGATE				✓ 60.00
4	B	BP-LAB TO CHECK WIRING & LIGHTING. TO WATER TEST FOR LEAK.				✓ 115.26
5	B	BP-LAB TO DRILL HOLES & INSTALL REVERSE SENSOR ON NEW BUMPER.				✓ 169.50
6	B	BP-WS R/I REAR WINDSCREEN TO FACILIATE REPAIRS.				✓ 436.00
7	S	BP-SUBLET TO SUPPLY & INSTALL REAR WINDSCREEN 3M SOLAR FILM.				✓ 480.00
8	B	BP-LAB R/I REAR CARPET, TRIMMING, COMPONENT AND OTHER ATTACHMENT TO FACILIATE REPAIRS.				✓ 339.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	
			Less
			Amount Due

UXK Auto Consultants hence notify the Repairer of the following:

- To survey before spray painting
- To display damaged parts during survey
- Parts prices are subject to customer's
- Third party survey is on a "Without prejudice" basis
- No illegal modifications is allowed
- Supplementary items must always be used
- Is subject to final approval from Insurance Company

DATE 17/01/2018
TIME 14:14
Acknowledged by: [Signature]
Signature:
Date:

3543866

3543866

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SLT3153A

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	Mr Ho Teck Soon Albert 71 Jurong East Street 13 #16-10 Singapore 609650 Mobile: 97354849
	Document No	
	Document Date	
	0	
	17/01/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	ANTMT	E1	ASU60R	25/10/2017	SLT3153A	0	29213 -9DS/SLT3153A-13011:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTEZB3GH80J000297	8ARZ091098	60	Raymond Seah L M	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
9	B	BP-LAB TO REPLACE REAR ACCIDENT DAMAGE PARTS. <i>678</i>				<i>2034</i> 4068.00
		STRAIGHTEN/REALIGN ALL OTEHR AFFECTED AREAS.				
10	B	BP-RES TO SPRAY PAINT ON REAR ACCIDENT <i>556</i>				<i>1668</i> <i>442</i> 3336.00
		AFFECTED AREAS.				
11	B	BP-LAB R/I REAR TOP SPOILER TO FACILIATE <i>✓</i>				169.50
		REPAIRS.				
12	1	T81551-48430 LENS & BODY, RR RH	1.00	815.10	15.00	<i>Xm</i> 692.83
13	2	T81561-48420 LENS & BODY, RR LH	1.00	815.10	15.00	<i>689</i> 692.83
14	3	T52562-48010 RETAINER, RR BUMPER,	1.00	121.10	15.00	<i>Rm</i> 102.93
15	4	T52563-48010 RETAINER, RR BUMPER,	1.00	121.10	15.00	<i>rel</i> 102.93
16	5	T81581-48250 LENS & BODY, RR RH	1.00	608.60	15.00	<i>Mx</i> 517.31
17	6	T81591-48260 LENS & BODY, RR LH	1.00	608.60	15.00	<i>cm</i> 517.31
18	7	T89348-58070 BO RETAINER, ULTRASONIC	2.00	21.30	15.00	<i>Zm</i> 36.20
19	8	T89341-58060 BO SENSOR, ULTRASONIC,	2.00	481.90	15.00	<i>Rm</i> 819.22
20	9	T81910-48012 R/R BUMPER REFLECTOR,	1.00	58.20	15.00	<i>m</i> 49.47
21	0	T81920-48012 L/REAR BPR REFLECTOR	1.00	58.20	15.00	<i>m</i> 49.47
22	1	T52159-48933 COVER, RR BUMPER	1.00	904.00	15.00	<i>de</i> 768.40
23	2	T75392-42030 RETAINER, OUTSIDE	2.00	9.40	15.00	<i>NE</i> 15.98
24	3	T52155-48050 SUPPORT, RR BUMPER	1.00	82.70	15.00	<i>m</i> 70.29

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 8 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3543867

TO SECURITY GUARD

3543867

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 17/01/2018
TIME 14:14

VEHICLE NO SLT3153A

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors

Co Reg No : 196700086Z
GST Reg No: MR-8500000-9**ESTIMATE**Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail	Account No.	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	Mr Ho Teck Soon Albert 71 Jurong East Street 13 #16-10 Singapore 609650 Mobile: 97354849
	Document No.	
	Document Date	
	0	
	17/01/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	ANTMT	E1	ASU60R	25/10/2017	SLT3153A	0	29213 .9DS/SLT3153A-130111
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTEZB3GH80J000297	8AR2091098	60	Raymond Seah L M	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
25	4	T52156-48050	SUPPORT, RR BUMPER	1.00	82.70	15.00	70.29
26	5	T52169-48100	COVER, RR BUMPER,	1.00	466.00	15.00	396.10
27	6	S52161-OK040	PIECE, RR BUMPER	10.00	3.90	15.00	33.10
28	7	T52615-48230	ABSORBER, RR BUMPER	1.00	122.60	15.00	104.21
29	8	T58307-48120	PANEL SUB-ASSY, BODY	1.00	1006.40	15.00	855.44
30	9	T68105-48905	GLASS SUB-ASSY, BACK	1.00	1084.60	15.00	921.91
31	0	T75575-48040	MOULDING, BACK	1.00	51.90	15.00	44.11
32	1	T08826-08609	SUPER FAST URETHANE BLACK	1.00	90.08	15.00	76.57
33	2	T08826-08682	SINGLE STEP PRIMER	1.00	173.44	15.00	147.42
34	3	T67005-48340	PANEL SUB-ASSY, BACK	1.00	2126.40	15.00	1807.44
35	4	T67881-48070	WEATHERSTRIP, BACK	1.00	441.30	15.00	375.10
36	5	T69350-48081	LOCK ASSY, BACK DOOR	1.00	565.20	15.00	480.42
37	6	T69430-48030	STRIKER ASSY, BACK	1.00	39.70	15.00	33.74
38	7	T75442-48140	PLATE, BACK DOOR	1.00	73.70	15.00	62.64
39	8	T90975-02071	REAR BOOT LID EMBLEM,	1.00	55.50	15.00	47.17
40	9	T64716-48020 C0	COVER, DECK TRIM, RR	1.00	438.30	15.00	372.55

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	19,995.14
		Labour	10,263.38
		Materials	9,251.76
		Lubrication/Fluid	480.00
		Others	0.00
		0.00	
		Amount Due	21,394.80

PLEASE TEAR ALONG PERFORATED LINE

3543868

TO SECURITY GUARD

3543868

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 17/01/2018
TIME 14:14


VEHICLE NO SLT3153A

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors

Model Name HARRIER
 Model ASU60R-ANTMT
 VIN/VDS (Frame No) --JTEZB3GH80J000297
 (1705-)
 Catalog Code (521340)
 (ASU60R-ANTMT)
 (ASU60 -J000297)
 Prod. Date (YYYYMM) 201707
 Fig-No. 52-02





Model Name HARRIER
 Model ASU60R-ANTMT
 VIN/VDS (Frame No) --JTEZB3GH80J000297
 (1705-)


Catalog Code (521340)
 (ASU60R-ANTMT
 (ASU60 -J000297)

Prod. Date (YYYYMM) 201707

Fig-No. 81-11



※1 LED is included as a component



Model Name HARRIER
 Model-----ASU60R-ANTMT
 VIN/VDS (Frame No)--JTEZB3GH80J000297
 (1705-)



Catalog Code (521340)
 (ASU60R-ANTMT)
 (ASU60 -J000297)

2018/01/17 14:42

Prod. Date (YYYYMM) 201707
 Fig-No. 67-08

DOOR PANEL

68131



プラグホールはFIG57-01に掲載してあります。
 Regarding PLUG HOLE, it is indicated in FIG57-01
 (REFER TO FIG 57-01)

678120B



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

ESTIMATE

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1 Document No 0 Document Date 03/02/2018	Mr Ho Teck Soon Albert 71 Jurong East Street 13 #16-10 Singapore 609650 Mobile: 97354849

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	ANTMT	E1	ASU60R	25/10/2017	SLT3153A	5489	29213 :9DS/SLT3153A-13011:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTEZB3GH80J000297	8AR2091098	60	Raymond Seah L M	01/02/2018 16.55	03/02/2018 18.00		

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP/DS CLAIM TP VEH:GBG2531K ACC DATE:13/01/2018 TP INS:MSIG NO OF REPAIR DAYS:06 DATE-IN:01/02/2018 DATE SURVEY:17/01/2018 BY:LKK-TAUFLIK AUTHORISED ON:31/01/2018				30.00,
2	B	BP-ECU TO RESET ECU AND REPROGRAMME				508.50/
3	Z	BP-SLANT SUPPLY SEALANT (NETT) FOR REAR TAILGATE				60.00,
4	B	BP-LAB TO CHECK WIRING & LIGHTING. TO WATER TEST FOR LEAK.	36			115.26,
5	B	BP-LAB TO DRILL HOLES & INSTALL REVERSE SENSOR ON NEW BUMPER.	36			169.50,
6	B	BP-WS R/I REAR WINDSCREEN TO FACILIATE REPAIRS.	36			436.00,
7	S	BP-SUBLET TO SUPPLY & INSTALL REAR WINDSCREEN 3M SOLAR FILM.	M30			480.00,
8	B	BP-LAB R/I REAR CARPET, TRIMMING, COMPONENT AND OTHER ATTACHMENT TO FACILIATE REPAIRS.	36			339.00,

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3619796

TO SECURITY GUARD

3619796

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 03/02/2018
TIME 09:55

VEHICLE NO SLT3153A

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel: 6631 1188

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1 Document No 0 Document Date 03/02/2018	Mr Ho Teck Soon Albert 71 Jurong East Street 13 #16-10 Singapore 609650 Mobile: 97354849

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	ANTMT	E1	ASU60R	25/10/2017	SLT3153A	5489	29213 :9DS/SLT3153A-13011:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTEZB3GH80J000297	8ARZ091098	60	Raymond Seah L M	01/02/2018 16.55	03/02/2018 18.00		

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
9	B	BP-LAB TO REPLACE REAR ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIGN ALL OTEHR AFFECTED AREAS.	36			2034.00
10	B	BP-RES TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS.	*		+ 1 fee	1668.00
11	B	BP-LAB R/I REAR TOP SPOILER TO FACILITATE REPAIRS.	36			169.50
12	1	T81561-48420 LENS & BODY, RR LH	1.00	815.10	15.00	692.83
13	2	T52563-48010 RETAINER, RR BUMPER,	1.00	121.10	15.00	102.93
14	3	T81591-48260 LENS & BODY, RR LH	1.00	608.60	15.00	517.31
15	4	T52159-48933 COVER, RR BUMPER	1.00	904.00	15.00	768.40
16	5	T52169-48100 COVER, RR BUMPER,	1.00	466.00	15.00	396.10
17	6	S52161-OK040 PIECE, RR BUMPER	10.00	3.90	15.00	33.10
18	7	T68105-48905 GLASS SUB-ASSY, BACK	1.00	1084.60	15.00	921.91
19	8	T75575-48040 MOULDING, BACK	1.00	51.90	15.00	44.11
20	9	T08826-08609 SUPER FAST URETHANE BLACK	1.00	90.08	15.00	76.57
21	0	T08826-08682 SINGLE STEP PRIMER	1.00	173.44	15.00	147.42
22	1	T67005-48340 PANEL SUB-ASSY, BACK M SERIES	1.00	2126.40	15.00	1807.44
23	2	T75442-48140 PLATE, BACK DOOR	1.00	73.70	15.00	62.64
24	3	T90975-02071 EMBLEM, SYMBOL	1.00	55.50	15.00	47.17

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	11,627.69
	Please acknowledge receipt of vehicle	Parts	5,617.93	
		Labour	5,529.76	
		Materials	480.00	
		Lubrication/Fluid	0.00	
		Others	0.00	
			GST 7.00%	813.94
			Less	0.00
			Amount Due	12,441.63

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SLT3153A

CUSTOMER

DATE 03/02/2018
TIME 09:55

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

3619797

3619797

Vehicle Diagnostic Report

005923 km

JTEZB3GH80J000297

TOYOTA BODY CARE

Printed By: Default User(1)

06/02/2018 9:18:56 AM

Health Check Results All Systems(1 of 1)

Enhanced

Vehicle Information						VIN		Vehicle ID	
[REDACTED]						[REDACTED]		[REDACTED]	
ABS/VSC/TRC	Yes	C1425			X			F152648570	
LKA/LDA	Yes	C1A47			X			892214857001	
Main Body	No	B1244			X				
Entry&Start	No	U0142			X			899074805001	
AHS	Yes	B2414			X			8934F482002	
IPA/ICS/Clearance Sonar	No	C1AED			X				
Power Source Control	No	U0140			X				
Radar Cruise2								8926348050	
Stop and Start								896634815000	
Engine								896654846000	
Transmission									
Radar Cruise1								8965B48191	
EMPS								895DF48021	
Electric Parking Brake									
LKA/LDA (Sub)								8646F4804100	
Front Recognition Camera								8646G3302101	
								8665048B4001	
Air Conditioner								8380048X4008	
Combination Meter								8380048Z1002	
D-Door Motor									
P-Door Motor									
RR-Door Motor									
RL-Door Motor									
Master Switch									
Tilt&Telescopic								8917F48171	
SRS Airbag								881514805101	
Pre-Collision 2								8821F4702101	
Front Radar Sensor									
Starting Control								8911F470300	
Central Gateway									

Vehicle Diagnostic Report

005923 km

JTEZB3GH80J000297

TOYOTA BODY CARE

Printed By: Default User(1)

05/02/2018 9:20:21 AM

Health Check Results
All Systems(1 of 1)

Enhanced

[REDACTED]									
Radar Cruise2									8926348050
Stop and Start									8906348T5000
Engine									890654846000
Transmission									
Radar Cruise1									F152648570
ABS/VSC/TRC									8905B48191
EMPS									895DF48021
Electric Parking Brake									
LKA/LDA (Sub)									
LKA/LDA									8646F4804100
Front Recognition Camera									8646G3302101
									8865048B4001
Air Conditioner									8380048X4005
Combination Meter									8380048Z1002
									892214857001
Main Body									
O-Door Motor									
Entry&Start									
P-Door Motor									
RR-Door Motor									
RL-Door Motor									
Master Switch									
Tilt&Telescopic									899074805001
AHS									8934F482002
IPA/ICS/Clearance Sonar									8917F48171
SRS Airbag									881514805100
Pre-Collision 2									8821F4702100
Front Radar Sensor									
Starting Control									
Power Source Control									8911F470300
Central Gateway									

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Jan 2018		16 Jan 2018 15:59 Edit Adj Rpt	S\$11,627.69 Edit Estimates	S\$11,627.69 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS [Created by insurer] Insured: GARDENIA FOODS (S) PTE LTD, Co. Reg. No.: 197801714R Main Claimant: HO TECK SOON ALBERT, ID: S11628538 Vehicle Reg. No.: SLT3153A Date of Loss: 13/01/2018 10:00 - :59 [2 Months and 19 Days From LTA Reg Date (Man Yr)] Claim Type: TP / 546588 Policy/Cover Note No.: 29069129MKF (Comprehensive) Coverage: 01/01/2018 - 31/12/2018 Vehicle Reg. No. (Insured): GBG2531K Policy No. (Claimant): Excess: Repairer: Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857 Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pel - 6643 1307] Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 15/02/2018] Driver/Custodian (Insured): ONG POH LEE (47 / Male), NRIC: 57029960G, Tel: +6598574068				

Claim Documents

*SLT3153A (546588)
[GBG2531K]
TP
HO TECK SOON ALBERT
Jan 13 2018 10:00AM
[GARDENIA FOODS (S) PTE LTD]
Borneo Motors (S) Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	18/01/18 17:48	Adjuster Immediate Advice						Load HTM		
Photos/Images							3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	25/04/18 16:58	General View						Load JPG	☒	
2	25/04/18 16:58	General View						Load JPG	☒	
3	25/04/18 16:58	General View						Load JPG	☒	
4	25/04/18 16:58	General View						Load JPG	☒	
5	25/04/18 16:58	General View						Load JPG	☒	
6	25/04/18 16:58	General View						Load JPG	☒	
7	25/04/18 16:58	General View						Load JPG	☒	
8	25/04/18 16:58	General View						Load JPG	☒	
9	25/04/18 16:58	General View						Load JPG	☒	
10	25/04/18 16:58	General View						Load JPG	☒	
11	25/04/18 16:58	General View						Load JPG	☒	
12	25/04/18 16:58	General View						Load JPG	☒	
13	25/04/18 16:58	General View						Load JPG	☒	
14	25/04/18 16:58	General View						Load JPG	☒	
15	25/04/18 16:58	General View						Load JPG	☒	
16	25/04/18 16:58	General View						Load JPG	☒	
17	25/04/18 16:58	General View						Load JPG	☒	
18	25/04/18 16:58	General View						Load JPG	☒	
19	25/04/18 16:58	General View						Load JPG	☒	
20	25/04/18 16:58	General View						Load JPG	☒	
21	25/04/18 16:58	General View						Load JPG	☒	
22	25/04/18 16:58	General View						Load JPG	☒	
23	25/04/18 16:58	General View						Load JPG	☒	
24	25/04/18 16:58	General View						Load JPG	☒	
25	25/04/18 16:58	General View						Load JPG	☒	
26	25/04/18 16:58	General View						Load JPG	☒	
27	25/04/18 16:58	General View						Load JPG	☒	
28	25/04/18 16:59	Reinspection Photo						Load JPG	☒	
29	25/04/18 16:59	Reinspection Photo						Load JPG	☒	
30	25/04/18 16:59	Reinspection Photo						Load JPG	☒	
31	25/04/18 16:59	Reinspection Photo						Load JPG	☒	
32	25/04/18 16:59	Reinspection Photo						Load JPG	☒	
33	25/04/18 16:59	Reinspection Photo						Load JPG	☒	
34	25/04/18 16:59	Reinspection Photo						Load JPG	☒	

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
35	25/04/18 16:59	Reinspection Photo	 Load JPG	☒
36	25/04/18 16:59	Replacement Part Photo	 Load JPG	☒
37	25/04/18 16:59	Replacement Part Photo	 Load JPG	☒
38	25/04/18 16:59	Replacement Part Photo	 Load JPG	☒
39	25/04/18 16:59	Replacement Part Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/01/18 14:52	TPD SLT3153A GIA REPORT	 Load PDF	
2	16/01/18 14:52	OI GBG2531K GIA REPORT	 Load PDF	
3	16/01/18 14:52	Pre-Repair Survey	 Load PDF	
4	16/01/18 14:52	TPD SLT3153A - ESTIMATE REPAIR	 Load PDF	
5	16/01/18 14:52	TPD SLT3153A - COLOUR PHOTO	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer. Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18000972/T1QBQ2

Date: 27/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29069129MKF

Claimant Vehicle No: SLT3153A

Insured Vehicle No: GBG2531K

Date of Loss: 13/01/2018

Nature of Claim: TP

Claim No: 546588

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLT3153A

Make & Model: TOYOTA HARRIER, 2.0 (A)

Engine No: 8ARZ091098

Reg. Date: 25/10/2017 (Man. Year: 2017)

Chassis No: JTEZB3GH80J000297

Colour: Silver

Odometer: 5147 km

Engine Capacity: 1999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18

Rear Tyre Size: 235/55 R18

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,313.38	5,647.93	4,665.45	45.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,681.76	5,979.76	3,702.00	38.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,995.14	11,627.69	8,367.45	41.85
+ GST 7.00/7.00% (S\$)	1,399.66	813.94	585.72	41.85
Nett Amount (S\$)	21,394.80	12,441.63	8,953.17	41.85

INSPECTION

Date of Assignment: 16/01/2018

Date Inspected: 17/01/2018 Inspected At:

Borneo Motors (S) Pte Ltd (Pandan)
2 Pandan Crescent
Singapore 128462

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Apr 2018)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT3153A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	50.00 FS	*30.00 FS
2	1		*LENS & BODY ,RR RH	Not Necessary	692.83 FS	*- FS
3	1		*LENS & BODY ,RR LH	Cracked	692.83 FS	*692.83 FS
4	1		*RETAINER ,RR BUMPER,	Not Necessary	102.93 FS	*- FS
5	1		*RETAINER ,RR BUMPER,	Necessary	102.93 FS	*102.93 FS
6	1		*LENS & BODY ,RR RH	Not Necessary	517.31 FS	*- FS
7	1		*LENS & BODY ,RR LH	Cracked	517.31 FS	*517.31 FS
8	2		*RETAINER ,ULTRASONIC	Not Necessary	36.20 FS	*- FS
9	2		*SENSOR ,ULTRASONIC,	Not Necessary	819.22 FS	*- FS
10	1		*R/R BUMPER REFLECTOR,	Not Necessary	49.47 FS	*- FS
11	1		*R/R BUMPER REFLECTOR	Not Necessary	49.47 FS	*- FS
12	1		*COVER,RR BUMPER	Deformed	768.40 FS	*768.40 FS
13	2		*RETAINER ,OUTSIDE	Not Necessary	15.98 FS	*- FS
14	1		*SUPPORT ,RR BUMPER	Not Necessary	70.29 FS	*- FS
15	1		*SUPPORT ,RR BUMPER	Not Necessary	70.29 FS	*- FS
16	1		*COVER,RR BUMPER ,	Cut	396.10 FS	*396.10 FS
17	10		*PIECE ,RR BUMPER	Necessary	33.10 FS	*33.10 FS
18	1		*ABSORBER ,RR BUMPER	Not Necessary	104.21 FS	*- FS
19	1		*PANEL SUB-ASSY ,BODY	Not Necessary	855.44 FS	*- FS
20	1		*GLASS SUB-ASSY ,BACK	Necessary	921.91 FS	*921.91 FS
21	1		*MOULDING ,BACK	Necessary	44.11 FS	*44.11 FS
22	1		*SUPER FAST URETHANE BLACK	Necessary	76.57 FS	*76.57 FS
23	1		*SINGLE STEP PRIMER	Necessary	147.42 FS	*147.42 FS
24	1		*PANEL SUB-ASSY ,BACK	Bent	1,807.44 FS	*1,807.44 FS
25	1		*WEATHERSTRIP ,BACK	Not Necessary	375.10 FS	*- FS
26	1		*LOCK ASSY ,BACK DOOR	Not Necessary	480.42 FS	*- FS
27	1		*STRIKER ASSY ,BACK	Not Necessary	33.74 FS	*- FS
28	1		*PLATE,BACK DOOR	Necessary	62.64 FS	*62.64 FS
29	1		*REAR BOOT LID EMBLEM ,	Necessary	47.17 FS	*47.17 FS
30	1		*COVER,DECK TRIM ,RR	Not Necessary	372.55 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	10,313.38	5,647.93
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RESET ECU AND REPROGRAMME	New	508.50	508.50
2	SUPPLY SEALANT FOR REAR TAILGATE	New	60.00	60.00
3	TO CHECK WIRING & LIGHTING TO WATER TEST FOR LEAK	New	115.26	115.26
4	TO DRILL HOLES & INSTALL REVERSE SENSOR ON NEW BUMPER	New	169.50	169.50
5	R/I REAR WINDSCREEN TO FACILITATE REPAIRS	New	436.00	436.00
6	TO SUPPLY & INSTALL REAR WINDSCREEN 3M SOLAR FILM	New	480.00	480.00
7	R/I REAR CARPET ,TRIMMING ,COMPONENT AND OTHER ATTACHMENT TO FACILITATE REPAIRS	New	339.00	339.00
8	TO REPLACE REAR ACCIDENT DAMAGE PARTS ,STRAIGHTEN /REALIGN ALL OTHER AFFECTED AREAS	New	4,068.00	2,034.00
9	TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS	New	3,336.00	1,668.00
10	R/I REAR TOP SPOILER TO FACILITATE REPAIRS	New	169.50	169.50
Gross Labour Cost (S\$)			9,681.76	5,979.76

Report was unsubmitted during this print-out.

< END OF ESTIMATES >