

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

AIG Asia Pacific Insurance Pte. Ltd
AIG Building
78 Shenton Way #08-16
Singapore (079120)
ATTN: MOTOR CLAIM DEPARTMENT
Tel : 6419 3000 Fax : 6835 7416

DEAR SIR / MADAM :

ACCIDENT REPAIR ON: SJU5874H
MODEL : CHEVROLET CRUZE
POLICY NO : GA156878
CHASSIS NO : KL1JA6961AK587124
ENGINE NO : F16D35169091

Date: 18/01/2018
Page : 1 of 2

DATE / TIME OF ACCIDENT: 10/01/2018 Time: 1830Hrs ALONG UPPER PAYA LEBAR ROAD
THIRD PARTY VEHICLE NO: SLH3787J

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
		S\$		S\$
1 Front Fender LH	1	✓ 759.00	da	759.00
2 Front Fender Shield LH	1	✓ 99.00	dis	99.00
3 Front Fender Signal Lamp LH	1	X 35.00	mc	35.00
4 Front Bumper	1	✓ 914.00	dis	914.00
5 Front Bumper Side Retainer LH	1	✓ 20.00	dis	20.00
6 Front Bumper Side Retainer RH	1	X 20.00	mc	20.00
7 Fog Lamp LH	1	X 249.00	mc	249.00
8 Fog Lamp Cover LH	1	✓ 30.00	mis	30.00
9 Headlamp LH	1	mc		-
10 Headlamp Bracket LH	1	mc		-
11 Bonnet	1	X 1344.00	mc	1,344.00
12 Front Door Assy LH	1	X 1283.00	mc	1,283.00
13 Front Door Upper Hinge LH	1	X 41.00	mc	41.00
14 Front Door Lower Hinge LH	1	X 41.00	mc	41.00
15 Wheel Rim LH	1	-	da 280 AN.	-
16 Absorber LH	1	X 302.00	mc	302.00
17 Absorber Mounting LH	1	X 80.00	mc	80.00
18 Absorber Stopper LH	1	X 35.00	mc	35.00
19 Knuckle Arm LH	1	X 365.00	mc	365.00
20 Knuckle Bearing LH	1	X 539.00	mc	539.00
21 Lower Arm LH	1	X 593.00	mc	593.00
22 Stabilizer Link LH	1	X 85.00	mc	85.00
23 Tie Rod LH	1	X	mc	-
24 Tie Rod End LH	1	X	mc	-
Sub-Total:				6,834.00
Parts Discount 10%				683.40
Total Parts:				6,150.60

Special Nett Items

1 Anti-rust coating	1	80.00	20	80.00
2 Front Fender Shield Clips	10	3.00	42	30.00
3 Front Bumper Clips	10	3.00	42	30.00

Total Parts: 140.00

Labour Charges For Front Side Portion

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.	SOV	1,200.00
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	SOV	1,200.00
3	Provide skill labour to disconnect and check electrical wiring	se	60.00
4	Provide skill labour to check and re-adjust wheel alignment		80.00
5	Provide skill labour to replace/refit and rebalance tyre and rim	20	80.00
6	Provide skill labour to dismantle and transfer door fittings and mechanism to facilitate repair		100.00
7	Provide skill labour to remove and refit window glass		80.00

Total Labour:

Total Parts & Labour: 2,800.00
GST 7% 636.34
Grand Total: 9,726.94

Estimate Repair Duration 9 days

ACCIDENT VEHICLE OF : SJU5874H

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: ANTHONY

Survey attended by:

Name :
Company :
Date :
Time :
Contact No :
Email :

Auto Consultants hence notify
Repairer of the following:

- resurvey before/after spray painting
- display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: