From (Parent)	Manus.		FCI (Office)	D	16/01/18@ 247pm
Estimated Cost:	ED SWEE PEUT	y _ □ —	Bill to:	Deterim	10/01/16/02/1
A -	RES / OD RES /	EVA/INV/			
To Inspect Vehicle		L 6992			1C8759G
at Workshop m/s_		^	Engineering	68	S8 1846
of	51 Deful	cine 10			
Policy No:			Claim No:	01800046	5MFSH
Sum Insured:			Excess:		
Make of Veh:				D.O.A.	805/10/50
(Client's Record)		1.002	29.01.2018		
	EP. / REV 24 HRS		A 1		Endorsement:
Date/lime: 51	tom@16/1/18	Person Cont	acted: _ Alvin	Vehicle D	TUDLA
Date/Time A	ction/Instruction (~\\ F\$	finlate		
	SLL 69928-				
			00692/Alvhin2		D. O.A : 29/10/2016
			ereve lev by		B C // ///0/5010
11.00	110 - 1017	ce 1")	ever les no	V 1,1	

29/1/18 confirmed 2/5 \$ 1750 N.h Sharon.

RECEIVED 3 1 JAN 2010

31/1 Mist = -2 = 200 = 2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Ref: CS/FCI180009 Date: 16-01-2018 Code: FCI2 ars:-THIRD PARTY CLA Veh. Inspected Coverage (\$) Excess (\$) Assign Date articulars & Condition c.c Year of Reg. Colour Steering Modification ditions of Tyres Make					
Code: FCI2 ars:-THIRD PARTY CLA Veh. Inspected Coverage (\$) Excess (\$) Assign Date articulars & Condition c.c Year of Reg. Colour Steering Modification ditions of Tyres	SLL 6992S 0.00 0.00 16/01/2018				
Veh. Inspected Coverage (\$) Excess (\$) Assign Date articulars & Condition c.c Year of Reg. Colour Steering Modification ditions of Tyres	SLL 6992S 0.00 0.00 16/01/2018				
Coverage (\$) Excess (\$) Assign Date articulars & Condition c.c Year of Reg. Colour Steering Modification ditions of Tyres	0.00 0.00 16/01/2018				
Excess (\$) Assign Date articulars & Condition c.c Year of Reg. Colour Steering Modification ditions of Tyres	0.00 16/01/2018				
Assign Date articulars & Condition c.c Year of Reg. Colour Steering Modification ditions of Tyres	0				
c.c Year of Reg. Colour Steering Modification ditions of Tyres	0				
c.c Year of Reg. Colour Steering Modification ditions of Tyres					
Year of Reg. Colour Steering Modification ditions of Tyres					
Colour Steering Modification ditions of Tyres	Balance				
Steering Modification ditions of Tyres	Balance				
Modification ditions of Tyres	Balance				
ditions of Tyres	Balance				
manufacture of the state of the	Balance				
manufacture of the state of the	Balance				
Make	Balance				
A CONTRACTOR OF THE CONTRACTOR	mm				
	mm				
	mm				
	mm				
ption of Damages					
General Information					
Inspection Date					
G & TRADING PTE LTD					
Remarks					
	Inspection Date				



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: SHC 8759G

Date: 30 January 2018

Our Ref: CS/FCI18000985/Uqd3

The Motor Claims Department First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLL 6992S .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 29/01/2018 at the premises of M/s <u>PEGASUS ENGINEERING</u>, and have the following to report:-

Workshop Estimate Amount	: S\$	2,951.52	
Revised Estimate Amount	: S\$	2,200.40	
"Check" Items Amount	: <u>S\$</u>	-	
Market Value	: <u>S\$</u>	-	
LTA Reimbursement Value	: <u>S\$</u>	-	
Nett Value	: <u>S\$</u>		

Description of Damage:

<u>The vehicle sustained damages</u>
at the rear portion.



Yours faithfully

CHUA KANG SENG Licensed Appraiser

SU 69925 Reference No.: (5 FC/1800985 VGd3
Policy Type: OD /(TP) TP RES / TL / EVA Case Handler Typist Nivitha): Case handler to make sure all Information created by the assignment team are ACCURATE. Admin (Y-Date N-Date Y-Date N-Date (1) Office Assign Form C Reference No. Customer Code C N Assign From Assign Date C Veh No (Inspected) C Veh No (Insured) C C D.O.A Policy No C C Claim No Insurance Authorisation (CA /REV/REP) C Report Type Weekend Charges Survey held at/Repairer Excess C Marca): Case handler to make sure the surveryor completed all required information. Surveyor ((1) Assignment Form C Vehicle No C Regn Month/Year Vehicle Type Make & Model Engine Capacity. (C.C) C N Odometer. (Sp.Reading) C C Chassis No. General Condition N Steering Brake N N Modification (Modi) Tyre Size C Tyre Make N C Tyre Balance C Date of Inspection N Survey held Des.of Damages (2) System - (Views/Merimen) Damaged Vehicle Photographs Uploaded (3) Workshop Estimate/Assignment Form ALL Parts condition Market Value for OD cases Estimate Repair Cost for PRI (RSI, TMI, MSIG) C Days of repair C Finalised Amount Re-inspection Cases to Finalize within 5 Days (4) System - (Views/Merimen) Resurvey photo Uploaded Check By:

Survey Department Check List (Case Handler)

	RVEY ASSIGNMENT	72
Date 16/1/18	Our Ref No.	SHC87596
Accident Date 7/1/18	Claim Type	3rd Party
Insured Vehicle SH(8159()	Third Party Vehicle	SU 69925
Survey Location Pegasus Engineering 2 51 Desu Lane 10 Sipore 539216	Trading Contact Person Pte Ut	Alvinton
Contact No. Tel: 6858 1846	Fax No.	6481 6070

Appointed Surveyor Lhh

Contact Person

Contact Number 6256 356

Fax No. 6858 0877

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

Encl. Accident Reports & est

cc: Workshop Regusus Engineering 2 Trading Pte Ltd Attention

Officer In charge Serine Ler

IMPORTANT NOTE

Kindly submit the survey report by email only to surveyor@first-insurance.com.sg within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Nivitha (LKK Auto)

From:

Teo Swee Keong <TeoSweeKeong@msfirstcapital.com.sg>

Sent:

Tuesday, 16 January 2018 2:47 PM

To:

'assignments@lkkauto.com'

Cc:

Serene Ler; 'claims@pegasusengrg.com.sg'

Subject:

NEW SURVEY ASSIGNMENT - OUR REF: SHC8759G DOA: 07.01.2018

Attachments:

FW: Third party survey SLL6992S Your insured SHC8759G on 07.01.2018 (1.47 MB);

MOTOR SURVEY ASSIGNMENT.pdf

Dear Sirs

New survey request for your handling.

Thanks and Regards,

SK Teo

Motor Claims Dept

MS First Capital Insurance Ltd | 36 Robinson Road #16-01 City House Singapore 068877 | DID: 6507 3848 | Fax No.: 6507 3849 |

A Member of MS&AD INSURANCE GROUP

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to www.msfirstcapital.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Pegasus Engineering [mailto:claims@pegasusengrg.com.sg]

Sent: Tuesday, January 16, 2018 12:13 PM

To: Teo Swee Keong <TeoSweeKeong@msfirstcapital.com.sg>

Subject: Re: YR REF: SLL6992S OUR REF: SHC8759G DOA: 07.01.2018

Dear Sir,

We select LKK. Please arrange.

Thanks & Regards,

Sharon ow

Pegasus Engineering & Trading Pte Ltd 51 Defu Lane 10 Singapore 539216

Tel

: 6858 1846

Fax

: 6487 6070

Email

: claims@pegasusengrg.com.sg

On Mon, Jan 15, 2018 at 2:52 PM, Teo Swee Keong < Teo Swee Keong @msfirstcapital.com.sg > wrote:

Dear Sirs,
We refer to your survey request dated 15/01/2018.
Please find below our list of surveyors for your reference. Kindly select from our list below and inform us of your choice within the next 2 days.
LKK Auto Consultants Pte Ltd Vicom Ltd
Once you inform us of your choice, the surveyor will be appointed within 2 working days of your email.
If you do not agree to any of the surveyors above, you may proceed to appoint your own surveyor. In this instance, we will also appoint a surveyor from our list above to conduct the PRI. Upon completion of repairs, please contact our appointed surveyor to conduct a physical re-inspection of the vehicle.
Thank you.
Thanks and Regards,
SK Teo
Motor Claims Dept
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 DID : 6507 3848 Fax No. : 6507 3849
A member of MS&AD INSURANCE GROUP
Personal Data Protection Act 2012 ("PDPA"):
Under the PDPA, there are various requirements that regulate the processing of your personal data.

Please refer to www.msfirstcapital.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Caroline Cabrera

Sent: Monday, January 15, 2018 11:05 AM

To: Teo Swee Keong < TeoSweeKeong@msfirstcapital.com.sg >

Subject: FW: Third party survey SLL6992S Your insured SHC8759G on 07.01.2018

Dear SK.

For survey

Thanks & Regards

Caroline Cabrera

Motor Claims

First Capital Insurance Ltd

A member of MS&AD INSURANCE GROUP

36 Robinson Road #16-01 City House | Singapore 068877 | Reg. No. 195000106C

D: 6507 3848 | F: 6507 3849

email: www.first-insurance.com.sg

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data.

Please refer to www.first-insurance.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Pegasus Engineering [mailto:claims@pegasusengrg.com.sg]

Sent: Saturday, January 13, 2018 5:09 PM

To: Motor Claims MotorClaims@msfirstcapital.com.sg
Subject: Third party survey SLL6992S Your insured SHC8759G on 07.01.2018

Your Ref: SHC8759G

Our Ref:

SLL6992S

DOA: 07.01.2018

Without Prejudice

Dear All,

We refer to the above matter.

We enclose the following documents for your attention:-

- a. Copy of our client's SAS report and damaged photos;
- b. Copy of the estimated cost of repair.

Please arrange for a Pre-Repair Inspection under the NIMA Protocol and confirm in writing whether you are agreeable to direct settle with us at 100% liability for this case.

We await for your favourable reply.

Vehicle Not in our premises.

Thanks & Regards,

Alvin Low

-CO

Pegasus Engineering & Trading Pte Ltd 51 Defu Lane 10 Singapore 539216

Tel

: 6858 1846

Fax

: 6487 6070

Email : claims@pegasusengrg.com.sg

Shiau Chan (LKKAuto)

From:

Serene Ler <Sereneler@msfirstcapital.com.sg>

Sent:

Tuesday, 30 January 2018 4:53 PM

To:

Shiau Chan (LKKAuto); Teo Swee Keong; assignments

Cc:

Subject:

RE: NEW SURVEY ASSIGNMENT - OUR REF: D18000465MFSH / SHC8759G DOA:

07.01.2018

Attachments:

CSFCI18000985Uqd3.pdf

Dear Shiau Chan,

Thank you for the attached. Kindly note our case reference D18000465MFSH.

Regards, Serene Ler

Motor Claims

MS First Capital Insurance Limited

A Member of MS&AD Insurance Group

36 Robinson Road, City House, #16-01 | Singapore 068877 | Tel: 6507 3848 | Fax: 6507 3849 |Reg. No. 195000106C Motor Claims: motor_claims@msfirstcapital.com.sq | Website: www.msfirstcapital.com.sq

*With effect from 15 January 2018, we will be known as MS First Capital Insurance Limited. Our new website will be www.msfirstcapital.com.sg.

With immediate effect, my email address will change to Sereneler@msfirstcapital.com.sg.

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to www.first-insurance.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged. If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it. If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]

Sent: Tuesday, January 30, 2018 4:38 PM

To: Teo Swee Keong <TeoSweeKeong@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: Serene Ler <Sereneler@msfirstcapital.com.sg>; SUR <sur@lkkauto.com> Subject: RE: NEW SURVEY ASSIGNMENT - OUR REF: SHC8759G DOA: 07.01.2018

Dear Serene.

Enclosed herewith preliminary advice of SLL 6992S.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Tuesday, 30 January 2018 4:38 PM

To:

'Teo Swee Keong'; assignments

Cc:

'Serene Ler'; SUR

Subject:

RE: NEW SURVEY ASSIGNMENT - OUR REF: SHC8759G DOA: 07.01.2018

Attachments:

CSFCI18000985Uqd3.pdf

Dear Serene,

Enclosed herewith preliminary advice of SLL 6992S.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Tuesday, 16 January 2018 5:02 PM

To: 'Teo Swee Keong' <TeoSweeKeong@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: NEW SURVEY ASSIGNMENT - OUR REF: SHC8759G DOA: 07.01.2018

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: <u>assignments@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo Swee Keong [mailto:TeoSweeKeong@msfirstcapital.com.sg]

Sent: Tuesday, 16 January 2018 2:47 PM

To: 'assignments@lkkauto.com' <assignments@lkkauto.com>

Cc: Serene Ler < Sereneler@msfirstcapital.com.sg>; 'claims@pegasusengrg.com.sg' < claims@pegasusengrg.com.sg>

Subject: NEW SURVEY ASSIGNMENT - OUR REF: SHC8759G DOA: 07.01.2018

Dear Sirs

New survey request for your handling.

Thanks and Regards,

Enquire PARF/COE Rebate for Registered Vehicle

ehicle Owner Particulars	
wner ID Type:	Company
Owner ID:	7200G
ehicle Details	
/ehicle No.:	SLL6992S
/ehicle to be Exported:	Yes
ntended De-registration Date:	13 Jan 2018
/ehicle Make:	MAZDA
/ehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	P520432190
Chassis No.:	JM6BN22A8H0144842
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$14,688.00
Original Registration Date:	07 Mar 2017
First Registration Date:	07 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$9,688.00
ntended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Mar 2027
PARF Rebate Amount:	\$7,266.00
Intended COE Rebate Details	
COE Expiry Date:	06 Mar 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
	t 10 101 00

\$48,401.00

QP Paid:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Company	
Owner ID:	7200G	
Vehicle Details		
Vehicle No.:	SLL6992S	
Vehicle to be Exported:	No	
Intended De-registration Date:	29 Jan 2018	
Vehicle Make:	MAZDA	
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT	
Primary Colour:	Blue	
Manufacturing Year:	2017	
Engine No.:	P520432190	
Chassis No.:	JM6BN22A8H0144842	
Maximum Power Output:	88.0 kW (118 bhp)	
Open Market Value:	\$14,688.00	
Original Registration Date:	07 Mar 2017	
First Registration Date:	07 Mar 2017	
Transfer Count:	0	
Actual ARF Paid:	\$9,688.00	
Intended PARF Rebate Deta	ils	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	06 Mar 2027	
PARF Rebate Amount:	\$7,266.00	
Intended COE Rebate Deta	ls	
COE Expiry Date:	06 Mar 2027	
COE Category:	A - Car up to 1600cc & 97kW (130bhp)	
COE Period(Years):	10	
QP Paid:	\$48,401.00	
COE Rebate Amount:	\$44,042.00	
Total Rebate Amount:	\$51,308.00	

The information contained herein is correct as at 29 Jan 2018

13.01. My G 1300



call on 2601 2019 61142

First Capital

Insured's Veh No:

SHC8759G

Date of accident : 07.01.2018

Estimate To Repair Mazda 3 4-Door Sedan 1.5L Wehicle No: SU60026

13.01.2018

Vehicle No:

Chassis No:

JM6BN22A8H0144842

Pages:

1 of 1

S/No	Quantity	Description	1 0	Amount
		LIST ITEMS		
1	1 pc	rear bumper D/De	\$	1,075.00
2	1 pc	rear bumper reinforcement	\$	558.00
3	2 ps	rear bumper side retainer @ \$37.00 1 1	\$	74.00
4	2 ps	rear bumper side holder @ \$74.00 17	\$	148.00
5	4 ps	rear bumper side holder rivets @ \$9.10	\$	36.40
6	1 pc	n/s rear bumper tow cover SUC	\$	18.00
7	6 ps	rear bumper clip @ \$5.00 Nec		30.00
549		Personal Control (1998 DV F February Control (1998)	\$	1,939.40
		Less 20%	\$	387.88
	(=		\$	1,551.52
		SPECIAL NETT ITEM	,	
8	1 set	rear bumper parking sensor should 2005.	4\$	280.00
- 1		997 total (964) Antal (92 SAS) A 4550 (96 BB) 575-AAU(90) (12 CH) (14 CH) (14 CH) (14 CH) (15	\$	280.00
1 2 4		LABOUR & MISC. CHARGES To reinstall of rear bumper parking sensor. To check electrical lighting concerned. To rust-proofing of the affected areas. Panel beating, knocking and straighten the necessary portion, remove	\$ \$	120.00 20.00 20.00
		and renewal of parts, adjust and realign the same.	\$	500.00
5		Putty and spray painting of the affected portion.	\$	400.00
ы		ruccy and spray painting of the directed portion.	\$	1,120.00
			1	-,
		Grand Total	\$	2,951.52
		The state Cone and sharpe notify The state of the state		

Please conduct the survey at

Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Intern	ationale Des Experts En Autom	nobile
IRS	T CAPITAL INSU	RANCE LTD	Ref : CS/FCI1800098	85/Uqd3n2
	OBINSON ROAD 11 CITY HOUSES	INGAPORE 068877	Date: 01-02-2018 Code: FCI2	
		Policy Particula	rs :- THIRD PARTY CLAI	M
	Insured Veh.	SHC 8759G	Veh. Inspected	SLL 6992S
	Policy No.		Coverage (\$)	0.00
	Claim No.	D18000465MFSH	Excess (\$)	0.00
	Assign From	TEO SWEE KEONG	Assign Date	16/01/2018
2.	and constitution	Vehicle Pa	rticulars & Condition	
	Make & Model	MAZDA 3 (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JM6BN22A8H0144842	Colour	BLUE
	Odometer	55978	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3.		Con	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	TRIANGLE	7 mm
	L/H Front Tyre	205/60 R16	TRIANGLE	7 mm
	R/H Rear Tyre	205/60 R16	TRIANGLE	7 mm
	L/H Rear Tyre	205/60 R16	TRIANGLE	7 mm
1.			ption of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE ETAILS.	REAR PORTION.	
5.			eral Information	
	Accident Date	07/01/2018	Inspection Date	29/01/2018
	Survey held at	PEGASUS ENGINEERING 8	TRADING PTE LTD	
		51 DEFU LANE 10 SINGAPORE 539216		
5a.			Remarks	
	B)THE INSPECTION	NSISTENT TO ACCIDENT REP ON WAS CONDUCTED ON A" CE TO YOUR INSTRUCTIONS	WITHOUT PREJUDICE" BAS	SIS. SED REPAIRS.
5b.		Estima	ate Days of Repair	TO THE REAL PROPERTY.
-	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days			



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 6992S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DENTED / DEFORMED	1,075.00	1,075.00
1	REAR BUMPER REINFORCEMENT	DENTED	558.00	558.00
2	REAR BUMPER SIDE RETAINER @\$37.00	NOT NECESSARY	74.00	9-
2	REAR BUMPER SIDE HOLDER @\$74.00	NOT NECESSARY	148.00	15
4	REAR BUMPER SIDE HOLDER RIVETS @\$9.10	NOT NECESSARY	36.40	(C
1	N/S REAR BUMPER TOW COVER	SERVICEABLE	18.00	-
6	REAR BUMPER CLIP @\$5.00	NECESSARY	30.00	30.00
	LESS 20% DISCOUNT		-387.88	-332.60
			1,551.52	1,330.40
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER PARKING SENSOR (SN)	SHORTED	280.00	200.00
			280.00	200.00
	LABOUR			
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.		120.00	50.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		20.00	20.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	80.00	
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.		500.00	250.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED		400.00	350.00
	PORTION.		1,120.00	670.00
	GRAND TOTAL	4	2,951.52	2,200.40

RECOMMENDED COST OF LUMP SUM REPAIRS	1,750.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/FCI18000985/Uqd3n2

CHUA KANG SENG

Licensed Appraiser