

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

S/R (HOR - BICW)

29/1 10am



Part reserved for; 24/1

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

RE-PRINT

16 JAN 2018

Estimate No.	: b1 45516	Page No. : 1 of 2
Date Estimated	: 16/01/2018	
Prepared By	: Merina Chia San San	

- ESTIMATE REPAIR FOR -	- ACCOUNT - 40000
Yoo Mei Mei Sharon 55A Edgedale Plains #17-16 The Amore Singapore 828680	Cash Sales - Service Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLD7207L	V758249	28/06/2016	218iA/2	0

DESCRIPTION

VALUE

To replace rear bumper including attachments etc and
to knock out dented area caused by accident

1700 2,550.00

To paint rear bumper and bootlid

1730 1,923.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 177.00

To remove and install boot compartment carpet and garnish
to facilitate repairs.

230 271.00

Sundries.

? 80.00

Total Labour 1: **5,001.00**DESCRIPTION

QTY PRIC

VALUE

SET MOUNTS PDC SENSOR REAR

1 62.50 62.50

REAR BUMPER CARRIER

1 375.90 ? 375.90

REAR GUIDE CENTRE

1 40.45 ? 40.45

LH SIDE GUIDE FOR BUMPER

1 46.65 nei 46.65

RH SIDE GUIDE FOR BUMPER

1 46.65 X 46.65

REAR BUMPER TRIM STRIP (LINE SPORT)

1 88.75 cm 88.75

REAR BUMPER PANEL PRIMED (BASIS)

1 933.05 de 933.05

RR FLAP TOWING EYE PRIMED

1 30.30 X 30.30

EMBLEM ADHERED REAR 218I

1 61.05 nei 61.05

GROMMET

2 0.75 nei 1.50

BADGE (BMW)

1 69.50 nei 69.50

DECOUPLING RING PDC TORQUE CONVERTE

4 4.95 nei 19.80

(DG) ADHESIVE SET K6

1 53.05 nei 53.05

Total Parts : **1,829.15**

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

RE-PRINT

Estimate No. : b1 45516
Date Estimated : 16/01/2018
Prepared By : Merina Chia San San

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLD7207L	V758249	28/06/2016	218iA/2	0

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 29/1/18 Excess S\$ _____

Surveyor's Name Tanpin Sign Tanpin

Surveyor's Tel 97495749 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR ☒ Yes / No PML Yes / No _____

Surveyor's E-mail tanpin@lkkauto.com

No. of Working Days Recommend 5 days

Labour 1	:	5,001.00
Parts	:	1,829.15
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	478.11
Grand Total	:	7,308.26

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **