

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9810P -**AAD1801-126***Not Authorised**\$935.00*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB9810P - CANDY

VF1ABL15AUC273444

RENAULT

LATITUDE

10.02.2018

EQ

PART			LIST	
1	1	BUMPER COVER FRT	\$	<i>N</i> 1,259.42
2	1	BUMPER ABSORBER FRT	\$	<i>SL</i> 394.68
3	1	BUMPER BEAM FRT	\$	<i>N</i> 914.08
4	1	BUMPER SPOILER FRT	\$	<i>SL</i> 181.75
5	1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 266.80
6	1	BUMPER FOG LAMP GRILLE LH	\$	<i>SL</i> 207.22
7	1	BUMPER RETAINER FRT LH	\$	<i>SL</i> 151.41
8	1	BUMPER SUPPORT FRT LH	\$	<i>SL</i> 123.88
9	1	HEADLAMP LH	\$	<i>SL</i> 1,184.43
10	1	HEADLAMP PANEL FRT LH	\$	<i>N</i> 152.15
11	1	FENDER PANEL FRT LH	\$	<i>N</i> 783.83
12	1	FENDER INSULATOR LH	\$	<i>SL</i> 130.84
13	1	FENDER BRACKET FRT LH	\$	<i>N</i> 13.02
14	1	FENDER WHEELARCH FRT LH	\$	<i>SL</i> 278.84
15	1	FENDER PANEL BRACKET FRT LH	\$	<i>SL</i> 177.41
16	1	RADAIOR GRILLE	\$	<i>SL</i> 1,707.78
17	1	RADAIOR GRILLE BADGE 'RENAULT'	\$	<i>SL</i> 173.36
18	1	RADAIOR GRILLE FRAME	\$	<i>SL</i> 1,353.75
19	1	FRAME FULL SUPPORT PANEL	\$	<i>N</i> 615.90
20	1	FRAME FULL SUPPORT BRACKET	\$	<i>N</i> 89.79
21	1	BONNET	\$	<i>N</i> 1,941.63
22	1	BONNET INSULATOR	\$	<i>SL</i> 405.73
23	1	DOOR MIRROR LH	\$	<i>SL</i> 1,483.40
24	1	DOOR MIRROR GLASS LH	\$	<i>SL</i> 242.33
25	1	DOOR MIRROR BACK COVER LH	\$	<i>SL</i> 218.46
26	1	DOOR MIRROR LAMP LH	\$	<i>SL</i> 194.18
27	1	DOOR PANEL FRT LH	\$	<i>N</i> 2,844.66

TOTAL	\$	17,490.74
10%	\$	1,749.07
	\$	15,741.67

Special Nett

TRANS-CAB AUTO SERVICES PTE LTD**AAD1801-126**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9810P -

1	1SET	FRONT BUMPER CLIP	\$	na	66.00	} X
2	1SET	WHEELARCH CLIP LH	\$	na	66.00	
3	1	TOW COVER FRT	\$	sn	14.50	
4	1	CAP HUB LH FRT	\$	sn	35.00	
5	1	RIM LH FRT	\$	sn	385.00	
6	1	TYRE LH FRT	\$	sn	330.00	
7	1	DOOR SEAL CLIP FRT LH	\$	na	4.68	} X
8	1	DOOR STICKER "Trans-cab"	\$	sn	80.00	
9	1	DOOR STICKER "Classic"	\$	na	30.00	15sn
10	1SET	BUMPER SUPPORT FRT CLIP LH	\$	na	9.80	X
11	1SET	BUMEPR RETAINER FRT CLIP LH	\$	na	12.50	X

TOTAL	\$	1,033.48
TOTAL PARTS	\$	16,775.15

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,800.00 2001

To Check Electrical Lighting Concerned.

\$ na 170.00 X

Putty and spray painting of the affected portion.

\$ 3,000.00 6601

To rust-proofing of the affected areas.

\$ na 170.00 X

To check steering geometry and computer wheel alignment

\$ na 220.00 X

To transfer of tire, rim and on wheel balancing.

\$ na 170.00 X

To transfer of door fittings, attachment and perform water seepage test.

\$ na 170.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ na 380.00 X

To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.

\$ na 170.00 X

To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.

\$ na 170.00 X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1801-126**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9810P -

Towing fees

\$ *120.00* X**TOTAL \$ 7,540.00****Over All Total \$ 24,315.15****(PARTS BY PARTS) Repair Days**~~10 Days~~*2 day*