

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5154X - AXA**AAD1801-140***Not Authored**1/1 Rm & 4,400.00*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC5154X - JHOW

VF1ABL15AUC276543

RENAULT

LATITUDE

11.01.2018

*AXA***PART****LIST**

1	1	BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46 <i>not for</i> ✓
2	1	BUMPER LOWER REAR	\$	768.84 ✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>SL</i> 113.47 X
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97 X
5	1	BUMEPR RETAINER RH REAR	\$	<i>SL</i> 44.99 X
6	1	BUMPER REFLECTOR RH	\$	<i>SL</i> 43.61 X
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97 X
8	1	BUMEPR RETAINER LH REAR	\$	<i>SL</i> 44.99 X
9	1	BUMPER REFLECTOR LH	\$	<i>SL</i> 43.61 X
10	1	BUMPER BEAM REAR	\$	SVC 777.52 X
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>N</i> 225.95 X
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>N</i> 225.95 X
13	1	BOOT REAR	\$	<i>Bu</i> 2,872.68 ✓
14	1	BOOT FINISHER	\$	<i>SL</i> 470.06 } X
15	1	BOOT WHEATERSTRIP	\$	<i>SL</i> 323.05 }
16	1	BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 493.35 }
17	1	BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 493.35 }
18	1	BOOT BADGE 'RENAULT'	\$	NN <i>N</i> 225.36 }
19	1	BOOT BADGE	\$	NN <i>N</i> 225.36 }
20	1	BOOT STRUT LH	\$	<i>SL</i> 276.08 }
21	1	BOOT STRUT RH	\$	<i>SL</i> 276.08 }
22	1	BOOT HINGE LH	\$	<i>N</i> 367.84 }
23	1	BOOT HINGE RH	\$	<i>N</i> 367.84 }
24	1	BOOT INNER TRIM	\$	<i>SL</i> 586.45 }
25	1	BOOT SWITCH	\$	<i>SL</i> 168.13 }
26	1	BOOT LOCK	\$	<i>N</i> 202.67 }
27	1	BOOT LOCK CATCH	\$	<i>N</i> 74.40 }
28	2	LICENCE PLATE LAMP	\$	<i>SL</i> 50.52 }
29	2	BOOT RUBBER PLUG	\$	<i>SL</i> 221.81 }
30	1	FENDER PANEL INNER TRIM REAR LH	\$	<i>SL</i> 671.45 }
31	1	FENDER PANEL REAR LH	\$	<i>N</i> 3,299.13 }
32	1	WHEELARCH REAR LH	\$	<i>SL</i> 543.47 }
33	1	FENDER PANEL INNER TRIM REAR RH	\$	<i>SL</i> 671.45 }
34	1	FENDER PANEL REAR RH	\$	<i>N</i> 3,299.13 }

TRANS-CAB AUTO SERVICES PTE LTD

AAD1801-140

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5154X -

35	1	WHEELARCH REAR RH	\$	S ₂	543.47	} X
36	1	TAILLAMP RH	\$	S ₂	552.55	
37	1	TAILLAMP PANEL RH	\$	N	986.70	
38	1	TAILLAMP LH	\$	S ₂	552.55	
39	1	TAILLAMP PANEL LH	\$	N	986.70	
40	1	OUTER PANEL REAR (End Panel)	\$	N	1,471.77	
41	1	OUTER PANEL REAR (End Panel)TRIM	\$	S ₂	404.56	
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	N	2,189.88	
43	1	SPARE WHEEL PANEL TRIM	\$	S ₂	612.21	
44	1	EXHAUST REAR	\$	N	7,489.05	
45	1	EXHAUST CAP REAR	\$	N	230.49	

TOTAL	\$	35,868.94
10%	\$	3,586.89
	\$	32,282.05

Specical Nett

1	1SET	PARKING AID	\$	S ₂	700.00	X
2	1SET	REAR BUMPER CLIP	\$	N ₂	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	N ₂	33.00	—
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	N ₂	10.00	X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	N ₂	20.00	X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	N ₂	10.00	X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	N ₂	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	N ₂	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	N ₂	66.00	—
10	1	EXHAUST MOUNTING REAR	\$	S ₂	17.82	X
11	1SET	BOOT FINISHER CLIP	\$	N ₂	24.20	X
12	1	BOOT STICKER "Trans-cab"	\$	N ₂	30.00	—
13	1	BOOT STICKER "6555-3333"	\$	N ₂	30.00	—
14	1	BOOT INNER TRIM CLIP	\$	N ₂	45.00	} X
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	N ₂	35.00	
16	1SET	FENDER WHEELARCH REAR LH CLIP	\$	N ₂	35.00	
17	1	FENDER INNER TRIM CLIP LH	\$	N ₂	28.00	
18	1	FENDER INNER TRIM CLIP LH	\$	N ₂	28.00	
19	1	TAILLAMP CLIP RH	\$	N ₂	5.00	
20	1	TAILLAMP CLIP LH	\$	N ₂	5.00	
21	2	REAR WINDSCREEN SELANT	\$	N ₂	80.00	
22	1	WINDSCREEN MOULDING	\$	S ₂	100.00	
23	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	S ₂	100.00	
24	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	S ₂	385.00	

TRANS-CAB AUTO SERVICES PTE LTD

AAD1801-140

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5154X -

25	1	SPARE TYRE	\$	330.00	X
----	---	------------	----	--------	---

TOTAL	\$	2,225.02
TOTAL PARTS	\$	34,507.07

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	440
---	----	----------	-----

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00	400
---	----	----------	-----

To Rust-Proofing Of The Affected Areas.	\$	170.00	30
---	----	--------	----

To reinstall rear bumper parking sensor.	\$	170.00	60
--	----	--------	----

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	60
--	----	--------	----

To repair and realign rear exhaust pipe.	\$	170.00	X
--	----	--------	---

To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	X
--	----	--------	---

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X
--	----	--------	---

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	X
--	----	--------	---

To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	X
--	----	--------	---

To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	X
---	----	--------	---

Towing Fees	\$	120.00	X
-------------	----	--------	---

To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	X
---	----	--------	---

To check steering geometry and computer wheel alignment	\$	220.00	X
---	----	--------	---

LKK Auto Consultants hence notify

the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

* Third party survey is on a "Without Prejudice" basis

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TRANS-CAB AUTO SERVICES PTE LTD

AAD1801-140

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5154X -

TOTAL	\$	8,260.00
Over All Total	\$	42,767.07

(PARTS BY PARTS)**Repair Days****10 Days**

P : \$4,749.98
-10%

	\$4,274.98
S/N : \$	225.00
L : \$	990.00
	\$ 5,489.98

L/S \$4,400.00 #