



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com

Website: www.nhtmotor.com

Tel: 6747 9241

Fax: 6741 7276

UEN: 201718370K

SAM LIM SOH HOON

Blk 1 Kaki Bukit Ave 6

# 01-43

Singapore 417883

TP Direct Asia

15/01/2018

Xiao Tony

JN1TAA B30Z0200162

Accident date: 14/01/2018

Estimated repair cost for vehicle no: SJT5985B NISSAN LAFESTA 2.0 A '09

| S/n | Qty | Items / Nett                             | U/price  | Amount     |      |
|-----|-----|------------------------------------------|----------|------------|------|
| 1   | 1   | Rear Boot Lid Deformed.                  |          | \$2,321.70 | ✓ L  |
| 2   | 2   | Rear Boot Lid Hinge New                  | \$62.20  | \$124.40   | x L  |
| 3   | 2   | Rear Boot Lid Shock Absorber New         | \$241.10 | \$482.20   | x N  |
| 4   | 1   | Rear Boot Lid Emblem Logo } New          |          | \$64.60    | ✓ N  |
| 5   | 1   | Rear Boot Lid Lafesta Logo }             |          | \$88.80    | ✓ N  |
| 6   | 2   | Rear Boot Lid Side Reflector New         | \$263.80 | \$527.60   | x N  |
| 7   | 1   | Rear Boot Lid Number Plate Best          |          | \$50.00    | ✓ N  |
| 8   | 1   | Rear Boot Lid Inner Lock Dented.         |          | \$195.30   | ✓ N  |
| 9   | 1   | Rear Boot Lid Inner Rubber Lt            |          | \$134.40   | ✓ N  |
| 10  | 1   | Rear Boot Lid Inner Trim Board New       |          | \$318.20   | x L  |
| 11  | 2   | Rear Tail Lamp New                       | \$290.10 | \$580.20   | x N  |
| 12  | 4   | Rear Tail Lamp Clip New                  | \$6.50   | \$26.00    | x N  |
| 13  | 1   | Rear Bumper Deformed.                    |          | \$726.60   | ✓ L  |
| 14  | 8   | Rear Bumper Clip New                     | \$6.50   | \$52.00    | 30 L |
| 15  | 2   | Rear Bumper Side Retainer New            | \$35.20  | \$70.40    | ✓ L  |
| 16  | 1   | Rear Bumper Reinforcement Best           |          | \$281.90   | ✓ L  |
| 17  | 1   | Rear End Panel Dented.                   |          | \$482.60   | ✓ L  |
| 18  | 1   | Rear End Panel Top Garnish Deformed.     |          | \$184.00   | ✓ N  |
| 19  | 2   | Rear Fender Inner Trim Board Deformed    | 137.20   | \$274.40   | NO L |
| 20  | 1   | Rear Spare Tyre Panel Repair             |          | \$1,244.90 | x L  |
| 21  | 1   | Rear Spare Tyre Panel Top Cover Deformed |          | \$396.00   | ✓ N  |
| 22  | 1   | Rear Spare Tyre Panel Tool Box Deformed. |          | \$353.20   | ✓ N  |
| 23  | 1   | Rear Spare Tyre Bracket Best             |          | \$85.20    | ✓ N  |

Subtotal :- \$9,227.40

09/09/2018

| S/n         | Qty | Items / Special Nett                                | U/price | Amount                       |
|-------------|-----|-----------------------------------------------------|---------|------------------------------|
| 24          | 1   | Rear Boot Lid Windscreen Seal <i>Ne</i>             |         | <del>\$105.00</del> 6062     |
| 25          | 1   | Rear Boot Lid Camera <i>Ne</i>                      |         | <del>\$680.00</del> X (SN)   |
| 26          | 1   | Rear Bumper Reverse Sensor <i>Damaged</i>           |         | <del>\$250.00</del> 200 (SN) |
| 27          | 1   | Rear Spare Tyre Panel & End Panel Sealant <i>Ne</i> |         | <del>\$155.00</del> 60 (SN)  |
| 28          | 1   | Rear Exhaust <i>Best</i>                            |         | <del>\$604.00</del> X        |
| 29          | 1   | Rear Centre Exhaust <i>Best</i>                     |         | <del>\$525.20</del> X N      |
| 30          | 1   | Spare Tyre Panel Insulation Pads <i>Ne</i>          |         | <del>280</del> 250 SN        |
| 31          | 2   | Rear Bumper Reinforcement Straps <i>Best</i>        |         |                              |
| Subtotal :- |     |                                                     |         | \$2,419.20                   |

### Labour charges

|                                         |                                     |                                     |            |                            |
|-----------------------------------------|-------------------------------------|-------------------------------------|------------|----------------------------|
| To remove & refit cushion               | List : 4623.20<br>Len 30% : 3236.24 | Nett : 2798.10<br>Len 10% : 2518.29 | S.N. : 570 | <del>\$280.00</del> 80     |
| To remove & refit reverse sensor        |                                     |                                     |            | <del>\$100.00</del> 60     |
| To remove & refit rear & centre exhaust |                                     |                                     |            | <del>\$380.00</del> 60     |
| To remove & refit rear camera           |                                     |                                     |            | <del>\$180.00</del> 50     |
| To remove & refit rear windscreen       |                                     |                                     |            | <del>\$120.00</del> ✓      |
| Gum                                     |                                     |                                     |            | <del>\$50.00</del> ✓       |
| To check wiring                         |                                     |                                     |            | <del>\$100.00</del> 30     |
| Tuff kote                               |                                     |                                     |            | <del>\$150.00</del> 50     |
| Towing fee                              |                                     |                                     |            | <del>\$100.00</del> X      |
| Panel beating                           |                                     |                                     |            | <del>\$1,400.00</del> 1100 |
| Spray painting                          |                                     |                                     |            | <del>\$1,400.00</del> 850  |

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Subtotal :- \$4,260.00

Total :- \$15,906.60

total : 8774.58

h/b: 7K  
07 days

16841.20

7K  
07 days