

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHF 725R

ROEL

Not Authorised
1.B.1
81322-66
Resurvey B4 paint

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHF 725R - ROEL

VF1ABL15AUC281190
 RENAULT
 LATITUDE
 28.11.15
 ANG

		PART		LIST
1	1	BUMPER COVER FRT	\$	R 968.78 X
2	1	BUMPER RETAINER FRT LH	\$	See 116.47 X
3	1	BUMPER BRACKET FRT LH	\$	R 139.81 X
4	1	BUMPER FOG LAMP GRILLE LH	\$	See 159.40 X
5	1	HEADLAMP LH	\$	See 911.10 X
6	1	FENDER PANEL FRT LH	\$	R 602.95 ✓
7	1	FENDER WHEELARCH FRT LH (Linner)	\$	See 107.33 X
8	1	AIR CLEANER LOWER	\$	See 271.26 X

TOTAL	\$	3,277.10
10%	\$	327.71
	\$	2,949.39

Specical Nett

1	1SET	FRONT BUMPER CLIP	\$	See 66.00 X
2	1SET	FRONT WHEELARCH CLIP LH	\$	See 30.50 X
3	1	RIM LH FRT	\$	See 385.00 X
4	1	TYRE LH FRT	\$	See 330.00 X
5	1	CAP HUB LH FRT	\$	See 35.00 X

TOTAL	\$	846.50
TOTAL PARTS	\$	3,795.89

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,800.00 *3000*

To Check Electrical Lighting Concerned.

\$ 170.00 *100*

Putty and spray painting of the affected portion.

\$ 3,000.00 *4400*

To rust-proofing of the affected areas.

\$ 170.00 *300*

TRANS-CAB AUTO SERVICES PTE LTD
NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
TEL NO.6287 6666 FAX NO.6366 8862
CO/GST REG NO.201019626G
SHF 725R

ROEL

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 X

To transfer of tire, rim and on wheel balancing.

\$ *nn* 170.00 X

TOTAL	\$	6,530.00
Over All Total	\$	10,325.89

(PARTS BY PARTS) Repair Days

10 Days

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: