

REF CS/EQI18001011/ Atdzer

Adrian  
Bazlin Ahmad

ASSIGNMENT (ORIG)

EQI

17/01/2018 @ 10:32am

① TP-WS / TP-RS / OD-RS / EVA / INV / NV / CS

To Inspect Vehicle No

SFL 60804

68485725

at Workshop No

Spark Car Care

of 320 ubi rd 3, 408649

Policy No

DM18H000134

Sum Insured

\$3,500

Make of Veh

(Client's Record)

3pm @ owner waiting

CA / REV / REP. / REV 24 HRS

Date Time 10:35am @ 17/1/18

Person Contacted

jasmine

Date Time

Action/Instructions

✓

By Note

SFL 60804-X

18/1 - Revert via email.

21/1/18 @ 10.10am Lynn Informed C/A by email

21/1/18 @ 10.18am Informed Jasmine C/A & EX: \$3500 by email.

Part by Part \$7867.95, 6days (Red: 3506.75 ! 30%)

EQI

17/01/18

SFL6080U

2013 March

Date

Estimated Cost

① TP WS TPRES CD RES EVA INV MV

To inspect Vehicle No

SFL 6080U

At Location No

Comfort Delgro

By

320 Ubi Rd 3, 408 649

Insured

Policy No

Claims No

Sum Insured

Excess

\$3,500.00

Claims Record

Make of Vehicle

Policy Condition

Remark: The veh had commenced its repair at the time of inspection.

Set on Market Value

90K

DAD Accident Report

Consistent? Yes or No

DAD PR Seen

Consistent? Yes or No

Est. Repairs

days

Pass Yes or No

Est. Sum

%

Valid Yes or No

CA

REV

REP: 24 HRS

Date

Person Contacted

Vehicle IN / OUT

Date / Time

Action / Instruction

OD EQ.

Make

① M/Cycle Bus/Van/Long Taxi/Prime/Other

Truck/Trolley

Make

Mercedes Benz C180 1595

Color

Brown

Sp. Reading

92309

Eng No

Chassis

WDD2040312A823243

Gen. Cond. Good Fair Poor Burnt

Steering Good Jammed / Leaked / Burnt

Brake Good Jammed / Leaked / Burnt

Mod. Nil / SIRIM / STD A/B/C/D

Tire Size

R

225/45R17

R

225/45R17

ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ① SUMI

TOYO / YOKO or

Front

Rear

R.Ba

06

mm

R.Ba

06

L.Ba

06

mm

L.Ba

06

D.O.A.

D.O.

17/01/18

Survey report

Comfort (Ubi)

Des. of Damages ① Rear / O/S / N/S / U/O / Roof/Bo

The U/O / Chassis/frame / Body/Structure affected due to collision

RECEIVED 07 MAY 2018

One Time Fee Paid



Prelim. Report

Final Report

Cash / Cheque / Remittance

Q

Add Fee

Site Fee

Travel Fee

Fuel Fee

Misc Fee

Days Of Repair

Resurvey No. of Trip

Surveys Fee

Resurvey Fee

Resurvey Fee

Resurvey Fee

Resurvey Fee

Resurvey Fee

Resurvey Fee

Resurvey Fee

OD

7868.95

6  
2

230

230

## Nivitha (LKK Auto)

**From:** Shu Pei (LKKAuto) <shupe@lkkauto.com>  
**Sent:** Wednesday, 17 January 2018 10:32 AM  
**To:** assignments  
**Subject:** FW: REF : DM18HO00134 - SFL6080U DOA: 13/01/2018 - REQ FOR SURVEY (OD)  
**Attachments:** img-116155244-0001.pdf; Amended GIA Report-SFL6080U.PDF

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupe@lkkauto.com](mailto:shupe@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Bazlin Ahmad [mailto:[bazlin.ahmad@eqinsurance.com.sg](mailto:bazlin.ahmad@eqinsurance.com.sg)]  
**Sent:** Wednesday, 17 January 2018 10:30 AM  
**To:** Janet Tan <[janet.tan@eqinsurance.com.sg](mailto:janet.tan@eqinsurance.com.sg)>; CDGE Ubi Private Cars Crash Repair Counter <[ubi\\_cr@sparkcarcare.com](mailto:ubi_cr@sparkcarcare.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
**Subject:** REF : DM18HO00134 - SFL6080U DOA: 13/01/2018 - REQ FOR SURVEY (OD)

Dear LKK

We refer to the above new OD assignment, please find attached.

**OD EXCESS :**

- Un-Named Driver **\$1,000** (before 50% discount & GST)
- YEID **\$3,000** (before GST)
- **TOTAL : \$3,500 (before GST)**

Thank You.

Regards,

**Lynn Ahmad**

Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road, #17-00 Tower Block, MND Complex, Singapore 069110

did 65 6496 9881 | tel 65 6223 9433 ext 881 | fax 65 6223 4190

[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)



A Member of Citystate



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies

**From:** Janet Tan  
**Sent:** Wednesday, January 17, 2018 9:43 AM  
**To:** CDGE Ubi Private Cars Crash Repair Counter; Bazlin Ahmad  
**Subject:** FW: SFL6080U DOA: 13/01/2018 - REQ FOR SURVEY (OD)

***Without Prejudice  
Save As To Costs***

Dear Anikka

For Pre-repair survey, please email to [bazlin.ahmad@eqinsurance.com.sg](mailto:bazlin.ahmad@eqinsurance.com.sg); [elaine.cheong@eqinsurance.com.sg](mailto:elaine.cheong@eqinsurance.com.sg) and [janet.tan@eqinsurance.com.sg](mailto:janet.tan@eqinsurance.com.sg)  
Or fax direct to 62234190.

Lynn,  
Fyna.

Regards,

**Janet Tan**  
Senior Executive | Claims



**EQ Insurance Company Limited**  
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110  
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190  
[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)

 A Member of Citystate



*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies*

**From:** CDGE Ubi Private Cars Crash Repair Counter [[mailto:ubi\\_cr@sparkcarcare.com](mailto:ubi_cr@sparkcarcare.com)]  
**Sent:** Tuesday, January 16, 2018 4:23 PM  
**To:** Janet Tan <[janet.tan@eqinsurance.com.sg](mailto:janet.tan@eqinsurance.com.sg)>  
**Subject:** SFL6080U DOA: 13/01/2018 - REQ FOR SURVEY (OD)

Dear Sir / Madam,

Attached pls find the GIA report & estimate repair cost for your necessary action. Pls call to arrange the appointment as the vehicle is not in our premises.

Thanks and Regards,

Anikka Lai  
Customer Service Specialist  
CDGE Ubi Branch  
Main: 6746 0666, Direct: 68485725, Fax: 6743 6072  
Email: [ubi\\_cr@sparkcarcare.com](mailto:ubi_cr@sparkcarcare.com)

## Denise Tay (LKKAUTO)

---

**From:** Denise Tay (LKKAUTO)  
**Sent:** Thursday, 18 January 2018 12:07 PM  
**To:** Admin-D (LKKAUTO); 'Bazlin Ahmad'; assignments  
**Cc:** SUR  
**Subject:** RE: REF : DM18HO00134 - SFL6080U DOA: 13/01/2018 - REQ FOR SURVEY (OD)  
**Attachments:** PRELI ADVISED SFL 6080U.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SFL 6080U**

**We have not authorise repair, kindly let us have the authorization.**

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Wednesday, 17 January 2018 10:38 AM  
**To:** 'Bazlin Ahmad' <[bazlin.ahmad@eqinsurance.com.sg](mailto:bazlin.ahmad@eqinsurance.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: REF : DM18HO00134 - SFL6080U DOA: 13/01/2018 - REQ FOR SURVEY (OD)

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shu Pei (LKKAUTO) [<mailto:shupeil@lkkauto.com>]  
**Sent:** Wednesday, 17 January 2018 10:32 AM  
**To:** assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Subject:** FW: REF : DM18HO00134 - SFL6080U DOA: 13/01/2018 - REQ FOR SURVEY (OD)

Best Regards,

**Shu Pei** | Admin

**LKK Auto Consultants Pte Ltd**

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Monday, 22 January 2018 10:18 AM  
**To:** 'CDGE Ubi Private Cars Crash Repair Counter'  
**Cc:** SUR  
**Subject:** RE: REF : DM18HO00134 - SFL6080U DOA: 13/01/2018 - REQ FOR SURVEY (OD)

Dear Jasmine,

As instructed by our client, please proceed to repair the insured vehicle **SFL 6080U (excess \$3,500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** CDGE Ubi Private Cars Crash Repair Counter [[mailto:ubi\\_cr@sparkcarcare.com](mailto:ubi_cr@sparkcarcare.com)]  
**Sent:** Friday, 19 January 2018 5:07 PM  
**To:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
**Subject:** Fw: REF : DM18HO00134 - SFL6080U DOA: 13/01/2018 - REQ FOR SURVEY (OD)

Hi Nivitha

Kindly update authorised repair ,vehicle survey on 17/01/18

Thank you

----- Forwarded by CDGE Ubi Private Cars Crash Repair Counter/sparkcarcare/cdge/delgronotes on 01/19/2018 05:06 PM -----

**From:** Bazlin Ahmad <[bazlin.ahmad@eqinsurance.com.sg](mailto:bazlin.ahmad@eqinsurance.com.sg)>  
**To:** Janet Tan <[janet.tan@eqinsurance.com.sg](mailto:janet.tan@eqinsurance.com.sg)>, "CDGE Ubi Private Cars Crash Repair Counter" <[ubi\\_cr@sparkcarcare.com](mailto:ubi_cr@sparkcarcare.com)>, "LKK AUTOCONSULTANTS ([admin-a@lkkauto.com](mailto:admin-a@lkkauto.com))" <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
**Date:** 01/17/2018 10:31 AM  
**Subject:** REF : DM18HO00134 - SFL6080U DOA: 13/01/2018 - REQ FOR SURVEY (OD)

Dear LKK

We refer to the above new OD assignment, please find attached.

**OD EXCESS:**

- Un-Named Driver **\$1,000** (before 50% discount & GST)
- YEID **\$3,000** (before GST)
- **TOTAL : \$3,500 (before GST)**

## Shiau Chan (LKKAUTO)

---

**From:** Bazlin Ahmad <bazlin.ahmad@eqinsurance.com.sg>  
**Sent:** Monday, 22 January 2018 10:10 AM  
**To:** Denise Tay (LKKAUTO); Admin-D (LKKAUTO); assignments  
**Cc:** SUR; Janet Tan  
**Subject:** RE: REF : DM18HO00134 - SFL6080U DOA: 13/01/2018 - REQ FOR SURVEY (OD)

Dear Denise

Please proceed.

Thank You.

Regards,

**Lynn Ahmad**  
Executive | Claims



**EQ Insurance Company Limited**  
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110  
did 65 6496 9881 | tel 65 6223 9433 ext 881 | fax 65 6223 4190  
[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)



*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies.*

---

**From:** Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]  
**Sent:** Friday, January 19, 2018 1:58 PM  
**To:** Admin-D (LKKAUTO); Bazlin Ahmad; assignments  
**Cc:** SUR; Janet Tan  
**Subject:** RE: REF : DM18HO00134 - SFL6080U DOA: 13/01/2018 - REQ FOR SURVEY (OD)

Dear Ms Bazlin,

We have not authorise repair, kindly let us have the authorization.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CS/CTI18000971/Atd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 16-01-2018	
			Code : CTI	
<b>1. Policy Particulars :- OWN DAMAGE</b>				
Insured Veh.	Veh. Inspected		GBB 2710L	
Policy No.	DMCVSN159461702	Coverage (\$)	0.00	
Claim No.	SNM18D00227C01	Excess (\$)	500.00	
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	16/01/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	11/01/2018	Inspection Date		
Survey held at	AUTO N CARS SERVICES PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883.			
<b>5a. Remarks</b>				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 8191B

### Vehicle Details

Vehicle No.: SFL6080U

Vehicle to be Exported: No

Intended De-registration Date: 18 Jan 2018

Vehicle Make: MERCEDES BENZ

Vehicle Model: C 180 BLUEEFFICIENCY

Primary Colour: Brown

Manufacturing Year: 2012

Engine No.: 27491030036714

Chassis No.: WDD2040312A823243

Maximum Power Output: 115.0 kW (154 bhp)

Open Market Value: \$31,873.00

Original Registration Date: 08 Mar 2013

First Registration Date: 08 Mar 2013

Transfer Count: 0

Actual ARF Paid: \$26,873.00

### Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 07 Mar 2023

PARF Rebate Amount: \$20,154.00

### Intended COE Rebate Details

COE Expiry Date: 07 Mar 2023

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$78,301.00

COE Rebate Amount: \$40,183.00

**Total Rebate Amount: \$60,337.00**

The information contained herein is correct as at 18 Jan 2018

OK



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: DM18HO00134

Date: 18/1/2018

Our Ref: CS/EQI18001011/Atd3

The Motor Claims Department  
EQ INSURANCE COMPANY LTD

Dear Sirs/Mdm


**PRELIMINARY ADVICE OF VEHICLE NO. SFL 6080U.**

Please be informed that we had conducted the inspection of the above-mentioned vehicle on 17/01/2018 at the premises of M/s Spark car Care and have the following to report: -

Workshop Estimate Amount	: S\$ <u>10,110.70</u>
Revised Estimate Amount	: S\$ <u>6,433.80</u>
"Check" Items Amount	: S\$ <u>1,023.00</u>
Market Value	: S\$ <u>90,000.00</u>
LTA Reimbursement Value	: S\$ <u>60,337.00</u>
Nett Value	: S\$ <u>29,663.00</u>

**Description of Damage:**

The vehicle sustained damages at the front portion.



**Comments/ Present Status:**

Damages Consistent.  
We have not authorized repair.  
Repair cost economical

Yours faithfully

Adrian  
Automotive Assessor

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	14/01/2018 17:33
Date Of Accident	13/01/2018 22:10
Exact Location Of Accident	PIE TOWARDS TUAS AFTER THE STEVEN RD EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFL6080U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	GAN CHENG HUAN
NRIC No	S1578191B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98266747
Alternative Phone No	OFFICE-98266747

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C180
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	PRIVATE CAR
------------------	-------------

### Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPPHQ17-000896
Cover Note Number	

### Driver

Name of Driver	GAN HANQIANG LOUIS
NRIC No	S9339278G
Date Of Birth	23/10/1993
Occupation	INDOOR
Date Of Driving Pass	14/03/2013
Driving Experience	4 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98266747
Fax Number	
Contact Number	
E Mail Address	DIMENSION1234@HOTMAIL.COM

Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I was driving along PIE towards Tuas after Stevens Road Exit. A BMW in front of my car starting to slow down and I followed to slow down. However, the BMW suddenly jammed brake and I immediately jammed my brake as well. Unfortunately my front bumper was damaged. I was told by Ms Chan(Nissan juke driver) that there was a taxi in front of her car (Nissan Juke) which suddenly jammed brake to which the Nissan Juke jammed brake and managed to avoid collision with the taxi. However, a Mazda collided with the Nissan Juke and the BMW which was in front of mine collided with the Mazda. From the photo, the rear of the BMW seemed not damaged. I have exchanged particulars with the Drivers of Nissan, Mazda and BMW. There were no injuries involved and we were told by the Traffic Police to clear off the site.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKB9800H
Vehicle Make/Model/Colour	BMW/ 523I A/BLACK
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ONG KONG WEE
NRIC/Passport Number	S7711790C
Contact Number	98205940
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKQ7843T
Vehicle Make/Model/Colour	MAZDA/3 4-DOOR SEDAN
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	AARON
NRIC/Passport Number	S9211981E
Contact Number	81809261
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SKS1031Z
Vehicle Make/Model/Colour	NISSAN/JUKE 1.6
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHAN WA YIN
NRIC/Passport Number	S1598095H
Contact Number	90074400
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1


# Sketch Plan

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that:  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and  
(c) my Personal Information may be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time: 14/1/13  
 Driver's Signature / Date & Time: 14/1/13  
 VERIFIED BY AJAX MARS  
 REPORTING OFFICER  
 Mohammad Azaly Bin Abdullah  
 Witnessed by Reporting Centre Personnel

## Sketch Plan



ACCIDENT STATEMENT (2000 characters)

Refer to statement which will forward to us.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
EUGENE KOH YEW KIAT

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

13 January 2018 at 4:30 PM

Date/Time:

13 January 2018 at 4:30 PM

**Meilin**

---

**From:** W G <dimension1234@hotmail.com>  
**Sent:** Monday, 15 January, 2018 12:05 PM  
**To:** Meilin  
**Subject:** Re: GIA Report - SFL6080U

Hi Meilin

We spoke.

This is to inform you that I wish to claim for own damage claim. Pls assist to amend the report and re-send to me. I'm now at your authorised workshop at ComfortDelbo Engrg at Ubi.

Tks.

*Sent from my Mobile*

----- Original message-----

**From:** Meilin  
**Date:** Mon, 15 Jan 2018 11:19  
**To:** dimension1234@hotmail.com.  
**Cc:**  
**Subject:** GIA Report - SFL6080U

Dear Sir/Madam,

Please find attached file, the GIA Accident Report for your perusal.

Kindly ignore, if you find the statement, 'Your NCD will be affected due to late reporting' found on the right top corner of the report.

The date and time of your call to Mobile Accident Response Service (MARS) will be taken as the time you reported your accident to the insurer which is within 24 hours from the time of accident as required under the Motor Claims Framework (MCF).

If you require any further clarification on the matter, please do not hesitate to contact us at 6333 2222.

Thank You,

Mobile Accident Response Service (MARS)  
Tel: 6333 2222



Computerized Engineering

320 UBI ROAD 3 SINGAPORE 408649

### ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : OD

Vehicle No. : SFL6080U

Make & Model : MERCEDES BENZ C 180

Year of Manufacture : 2012

Chassis No. : WDD2040312A823243

Engine No. : 27491030036714

Policy No. : \_\_\_\_\_

Time of Accident : \_\_\_\_\_

Ins Company : EQ INSURANCE

Excess : \_\_\_\_\_

Date of Accident : 13/01/2018

Suggested Days of Repair : \_\_\_\_\_

In-house Vehicle Assessor : \_\_\_\_\_

Case Owner : ANIKKA

Signature : \_\_\_\_\_

Contact No : \_\_\_\_\_

#### Repair Estimates

Parts (a) Cost / List Price Items \$5,737.00 <sup>6842</sup>

Plus/Less 10% \$573.70

Total of Cost / List \$6,310.70 <sup>78653</sup>

(b) Nett Price Items \$-

Less \_\_\_\_\_

Total of Nett Item \_\_\_\_\_

(c) Special Nett Items \$-

Total Parts Cost (Appendix A) \$6,310.70

Labour (Appendix B) \$3,800.00

Total Repair Cost \$10,110.70 <sup>11213-30</sup>

68485725 - ANIKKA

68485726 - JASMINE CHNG

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Adrian Lij  
 Company : LKIC  
 Survey conducted on : 17/01/18 at \_\_\_\_\_

#### Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 06 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ 3500

(e) Signature of surveyor : [Signature]

Date: \_\_\_\_\_

# Spark Car Care

ComfortDelGro Engineering Pte Ltd  
320 UBI ROAD 3 SINGAPORE 408649  
TEL :68438723/68438736 Fax:67436072

## Spare Parts

Vehicle No : **SFL6080U** Case Owner : **ANIKKA**  
Make & Model : **MERCEDES BENZ C 180**  
**BLUEEFFICIENCY** Year Manufacture : **2012**  
Chassis No : **WDD2040312A823243** Engine No : **27491030036714**  
Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_  
Order By : \_\_\_\_\_ Type of Claim : **OD**

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposit Surveyo
1	BONNET <i>Dented</i>	1	\$1,050.00	✓			
2	BONNET INSULATOR CLIPS <i>new</i>	10	\$40.00	✓			
4	LOGO EMBLEM <i>new</i>	1	\$42.00	✓			
5	"STAR" LOGO <i>not nec</i>	2	\$90.00	✗			
6	BONNET LOCK <i>new</i>	1	\$45.00	✗			
7	FRONT BUMPER <i>replaced</i>	1	\$740.00	✓			
8	FRONT BUMPER SPONGE <i>replaced</i>	1	\$60.00	✓			
9	FRONT BUMPER REINFORCEMENT <i>Best</i>	1	\$155.00	✓			
10	FRONT BUMPER SIDE BRACKET LH <i>green</i>	1	\$45.00	✓			
11	FRONT BUMPER SIDE BRACKET RH	1	\$45.00	✓			
12	FRONT BUMPER CLIPS <i>new</i>	10	\$40.00	✓			
13	FRONT SUPPORT PANEL <i>Buckled</i>	1	\$66.00	✓			
14	SUPPORT PANEL TOP GARNISH <i>cracked</i>	1	\$35.00	✓			
15	HEAD LAMP ASSY LH <i>cracked</i>	1	\$540.00	✓			
16	HEAD LAMP ASSY RH <i>cracked</i>	1	\$540.00	✓			
17	HEAD LAMP BRACKET LH <i>not nec</i>	1	\$125.00	✗			
18	HEAD LAMP BRACKET RH <i>not nec</i>	1	\$125.00	✗			
19	FRONT BUMPER LOWER GRILLE (CTR) <i>new</i>	1	\$80.00	✗			
20	FRONT BUMPER LOWER GRILLE (LH) <i>green</i>	1	\$30.00	✗			
21	FRONT BUMPER LOWER GRILLE (RH) <i>green</i>	1	\$30.00	✗			
22	FOG LAMP - CHROME (LH) <i>green</i>	1	\$62.00	✗			
23	FOG LAMP - CHROME (RH)	1	\$62.00	✗			
24	CONDENSOR <i>Dented</i>	1	\$650.00	✓			
25	RADIATOR <i>new</i>	1	\$680.00	✗			
26	RADIATOR GRILLE <i>cracked</i>	1	\$320.00	✓			
27	TOWING COVER <i>new</i>	0	\$40.00	✗			
28		0					
29		0					
30		0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**ComfortDelGro Engineering Pte Ltd**  
320 UBI ROAD 3 SINGAPORE 408649  
Tel: 68438723/68438736 FAX : 67436072

Vehicle No. : **SFL6080U**  
Make & Model : **MERCEDES BENZ C 180 BLUEEFFICIENCY**

: ANIKKA

: 2012

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

# Spark Car Care

ComfortDelgro Engineering Pte Ltd  
320 UBI ROAD 3 SINGAPORE 408649  
Tel: 68438723/68438736 FAX : 67436072

Finalization Form

Attn to : EQ ADRIAN LING Vehicle Number : SFL6080U  
Type Of Claim : OD

A. Spare parts	<u>\$4,373.00</u>	F. Total Parts	<u>\$6,338.95</u>
B. Supplementary	<u>\$1,100.00</u>	G. Total Labour	<u>\$1,530.00</u>
C. Nett Price	<u>\$-</u>	H. Total Repair	<u>\$7,868.95</u>
D. Supp Nett Price	<u>\$-</u>	I. Excess	<u>                    </u>
E. S/Nett	<u>\$45.00</u>	P/P Total	<u>7,868.95</u>

Total Spare Parts Price		<u>\$5,473.00</u>
Cost plus / List Down	<u>15%</u>	<u>820.95</u>
Total		<u>6,293.95</u>

Total Nett Price		<u>\$-</u>
Nett Price Less	<u>                    </u>	<u>\$-</u>
Total		<u>-</u>

Lump Sum Less                      \$-

Lump Sum Rounding                     

Total Finalized \$7,868.95

*N.B. If we DO NOT receive your reply within 2 weeks, we shall treat the above finalized amount as confirmed & correct.*

Remarks : Please confirm and revert by Fax or Email

Date In : <u>                    </u>	Total Repair Day <u>                    </u>
Date Survey : <u>                    </u>	LOU/ Day <u>                    </u>
Date Out : <u>                    </u>	Total LOU <u>                    </u>
Sat/Sun/Ph. : <u>                    </u>	Rental/Day <u>                    </u>
Authorized Repair Day <u>6</u>	Total Rental <u>                    </u>

Submitted By / Date :                     

Confirmed By / Date :

# Spark Car Care

ComfortDelGro Engineering Pte Ltd  
320 UBI ROAD 3 SINGAPORE 408649  
TEL :68438723/68438736 Fax:67436072

## Spare Parts

Vehicle No : SFL6080U Case Owner : 0

Make & Model : MERCEDE BEND C180 Year Manufacture : 2012

Chassis No : WDD2040312A823243 Engine No : 27491030036714

Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim : OD

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	BONNET	1	\$1,050.00 ✓				
2	BONNET INSULATOP CLIPS	10	\$40.00 ✓				
3	LOGO EMBLEM	1	\$42.00 ✓				
4	STAR" EMBLEM	1					
5	BONNET LOCK	1					
6	FRONT BUMPER	1	\$740.00 ✓				
7	FRONT BUMPER SPONGE	1	\$65.00 ✓				
8	FRONT BUMPER REINFORCEMENT	1	\$155.00				
9	FRONT BUMPER SIDE BRACKET LH	1	\$45.00				
10	FRONT BUMPER SIDE BRACKET RH	1	\$45.00				
11	FRONT BUMPER CLIPS	10	\$40.00				
12	FRONT UUPPORT PANEL	1	\$66.00				
13	SUPPORT PANEL TOP GARNISH	1	\$35.00				
14	HEADLAMP LH	1	\$540.00				
15	HEADLAMP RH	1	\$540.00				
16	HEADLAMP BRACKET LH	1					
17	HEADLAMP BRACKET RH	1					
18	FRONT BUMPER LOWER GRILLE (CTR)	1					
19	FRONT BUMPER LOWER GRILLE LH	1					
20	FRONT BUMPER LOWER GRILLE RH	1					
21	FOGLAMP CHROME LH	1					
22	FORLAMP CHROME RH	1					
23	CONDENSOR	1	\$650.00				
24	RADIATOR	1					
25	RADIATOR GRILLE	1	\$320.00				
26	TOWING COVER	1					
27	FRONT NUMBER PLATE	1				\$45.00	CR(20)
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**ComfortDel** Engineering Pte Ltd  
320 UBI ROAD, #03-01, UBI TECH CENTRE 408649  
Tel: 68438723 Fax: 67436072

Vehicle No. : **SFL6080U**  
Make & Model : **MERCEDES BENZ C 180 BLUEEFFICIENCY**

: \_\_\_\_\_ ANIKKA

: \_\_\_\_\_ 2012

*Note: The above estimate of repair is based on visual inspection of the affected areas. Any additional damages observed during the course of the repair shall be reported as a supplementary.*

ComfortDelGro Engineering Pte Ltd

Tel: 68438723/68438736 FAX : 67436072

Vehicle No. :	<u>SFL6080U</u>	Case Owner :	<u>0</u>
Make & Model :	<u>MERCEDE BEND C180</u>	Year of Manufacture :	<u>2012</u>

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

## Spark Car Care

ComfortDelGro Engineering Pte Ltd  
320 UBI ROAD 3 SINGAPORE 408649  
Tel: 68438723/68438736 Fax: 67436072

### Supplementary 1

Vehicle No : <u>SFL6080U</u>	Case Owner : <u>0</u>
Make & Model : <u>MERCEDE BEND C180</u>	Year Manufacture : <u>2012</u>
Chassis No : <u>WDD2040312A823243</u>	Engine No : <u>27491030036714</u>
Sales Order : <u>0</u>	Supplier : <u>0</u>
Order By : _____	Type of Claim : <u>OD</u>

S/No	Part Description	QTY	Cost Price	List Price	Nett Item	S/N	Dispos Survey
1	FRONT FENDER <i>Buckled</i>	1	\$420.00	✓			
2	FRONT NUMBER PLATE GARNISH <i>Weld</i>	1	\$60.00	✓			
3	BONNET STOPPER LH <i>3 new</i>	1	\$18.00	✓			
4	BONNET STOPPER RH <i>3 new</i>	1	\$18.00	✓			
5	FRONT BUMPER BRACKET LH <i>3 new</i>	1	\$24.00	✓			
6	FRONT BUMPER BRACKET RH <i>3 new</i>	1	\$24.00	✓			
7	FRONT SUPPORT PANEL LH <i>headlamp</i>	1	\$130.00	✓			
8	RIVET <i>new</i>	8	\$8.00	✓			
9	RADIATOR CLIPS <i>new</i>	2	\$14.00	✓			
10	FRONT BUMPER RIVET <i>new</i>	4	\$8.00	✓			
11	HEADLAMP PANEL RH <i>best</i>	1	\$130.00	✓			
12	AIR GUIDE BAFFLE <i>deland</i>	1	\$35.00	✓			
13	RAD GRILLE BRACKET <i>best</i>	1	\$12.00	✓			
14	SUPPORT HOOK <i>best</i>	1	\$48.00	✓			
15	LOWER GRILLE CTR <i>deland</i>	1	\$95.00	✓			
16	ROD BEAM CLIPS <i>new</i>	2	\$32.00	✓			
17	BONNET LOCK CATCH <i>best</i>	1	\$24.00	✓			
18	<i>Front number plate</i>				\$45		
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CS/EQI18001011/Atd3e2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 08-05-2018		
		Code : EQI		
<b>1. Policy Particulars :- OWN DAMAGE</b>				
Insured Veh.		Veh. Inspected	SFL 6080U	
Policy No.	DMPPHQ17-000896	Coverage (\$)	0.00	
Claim No.	DM18HO00134	Excess (\$)	3,500.00	
Assign From	BAZLIN AHMAD	Assign Date	17/01/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MERCEDES BENZ C 180	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	WDD2040312A823243	Colour	BROWN	
Odometer	92309	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	PIRELLI	6 mm	
L/H Front Tyre	225/45 R17	PIRELLI	6 mm	
R/H Rear Tyre	225/45 R17	PIRELLI	6 mm	
L/H Rear Tyre	225/45 R17	PIRELLI	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	13/01/2018	Inspection Date	17/01/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD NO : 320 UBI ROAD 3 SINGAPORE 408649			
<b>5a. Remarks</b>				
A)THE MARKET VALUE IS S\$90,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFL 6080U**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	BONNET	DENTED	1,050.00	1,050.00
10	BONNET INSULATOR CLIPS	NECESSARY	40.00	40.00
1	LOGO EMBLEM	NECESSARY	42.00	42.00
2	"STAR" LOGO	NOT NECESSARY	90.00	-
1	BONNET LOCK	NOT NECESSARY	45.00	-
1	FRONT BUMPER	DEFORMED	740.00	740.00
1	FRONT BUMPER SPONGE	DEFORMED	65.00	65.00
1	FRONT BUMPER REINFORCEMENT	BENT	155.00	155.00
1	FRONT BUMPER SIDE BRACKET LH	NECESSARY	45.00	45.00
1	FRONT BUMPER SIDE BRACKET RH	NECESSARY	45.00	45.00
10	FRONT BUMPER CLIPS	NECESSARY	40.00	40.00
1	FRONT SUPPORT PANEL	BUCKLED	66.00	66.00
1	SUPPORT PANEL TOP GARNISH	CRACKED	35.00	35.00
1	HEAD LAMP ASSY LH	CRACKED	540.00	540.00
1	HEAD LAMP ASSY RH	CRACKED	540.00	540.00
1	HEAD LAMP BRACKET LH	NOT NECESSARY	125.00	-
1	HEAD LAMP BRACKET RH	NOT NECESSARY	125.00	-
1	FRONT BUMPER LOWER CENTRE (CTR)	NOT NECESSARY	80.00	-
1	FRONT BUMPER LOWER GRILLE (LH)	NOT NECESSARY	30.00	-
1	FRONT BUMPER LOWER GRILLE (RH)	NOT NECESSARY	30.00	-
1	FOG LAMP - CHROME (LH)	NOT NECESSARY	62.00	-
1	FOG LAMP - CHROME (RH)	NOT NECESSARY	62.00	-
1	CONDENSOR	DENTED	650.00	650.00
1	RADIATOR	NOT NECESSARY	680.00	-
1	RADIATOR GRILLE	CRACKED	320.00	320.00
1	TOWING COVER	NOT NECESSARY	40.00	-
1	FRONT FENDER (ADDITIONAL)	BUCKLED	420.00	420.00
1	FRONT NUMBER PLATE GARNISH (ADDITIONAL)	DEFORMED	60.00	60.00
1	BONNET STOPPER LH (ADDITIONAL)	NECESSARY	18.00	18.00
1	BONNET STOPPER RH (ADDITIONAL)	NECESSARY	18.00	18.00
1	FRONT BUMPER BRACKET LH (ADDITIONAL)	DAMAGED	24.00	24.00

Report Ref No. CS/EQI18001011/Atd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER BRACKET RH (ADDITIONAL)	DAMAGED	24.00	24.00
1	FRONT SUPPORT PANEL LH HEADLAMP (ADDITIONAL)	BENT	130.00	130.00
8	RIVET (ADDITIONAL)	NECESSARY	8.00	8.00
2	RADIATOR CLIPS (ADDITIONAL)	NECESSARY	14.00	14.00
4	FRONT BUMPER RIVET (ADDITIONAL)	NECESSARY	8.00	8.00
1	HEADLAMP PANEL RH (ADDITIONAL)	BENT	130.00	130.00
1	AIR GUIDE BAFFLE (ADDITIONAL)	DEFORMED	35.00	35.00
1	RAD GRILLE BRACKET (ADDITIONAL)	BENT	12.00	12.00
1	SUPPORT HOOK (ADDITIONAL)	BENT	48.00	48.00
1	LOWER GRILLE CTR (ADDITIONAL)	DEFORMED	95.00	95.00
2	ROD BEAM CLIPS (ADDITIONAL)	NECESSARY	32.00	32.00
1	BONNET LOCK CATCH (ADDITIONAL)	BENT	24.00	24.00
	COST PLUS 15%		1,026.30	820.95
			7,868.30	6,293.95
	<b>SPECIAL NETT ITEMS</b>			
1	FRONT NUMBER PLATE (SN) (ADDITIONAL)	NECESSARY	45.00	45.00
			45.00	45.00
	<b>LABOUR</b>			
	TO KNOCK, STRAIGHTEN, REMOVE & REFIX DAMAGE PARTS.		1,800.00	800.00
	TO PUTTY & SPRAY PAINTING ON THE BONNET, FRONT BUMPER FRONT SUPPORT PANEL & AFFECTED AREAS.		1,800.00	600.00
	TO CHECK WIRING.		100.00	30.00
	TO REMOVE & REFIX CONDENSOR TO ASSIST WORKLOAD.		100.00	100.00
			-	-
			-	-
			3,800.00	1,530.00
	<b>GRAND TOTAL</b>		<b>11,713.30</b>	<b>7,868.95</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>7,868.95</b>
	<b>LESS EXCESS</b>			<b>-3,500.00</b>
	<b>NETT LIABILITY</b>			<b>4,368.95</b>

Report Ref No. CS/EQI18001011/Atd3e2



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.