Spark Car Care

ComfortDelGro Engineering Pte Ltd 320 UBI ROAD 3 SINGAPORE 408649

Tel: 68438723/68438736 FAX: 67436072

ANIKKA

e No.	:	SFL6080U	Case Owner

MERCEDES BENZ C 180

ake & Model : BLUEEFFICIENCY Year of Manufacture : 2012

ake a	Model: BLUEFFICIENCY Year of Manufacture		:	
S/No	Labour Description	Esimated Price	Adjusted Price	
1 T	O KNOCK, STRAIGHTEN, REMOVE & REFIX DAMAGE PARTS	\$1,800.00	805	
		1		
		104 000 00	600'	
	O PUTTY & SPRAY PAINTING ON THE BONNET, FRONT BUMPER	\$1,800.00	600	
	RONT SUPPORT PANEL & AFFECTED AREA	+		
3 T	O CHECK WIRING	\$100.00	30	
4 TO RE	O REMOVE & REFIX CONDENSOR TO ASSIST WORKLOAD	\$100.00		
	· · · · · · · · · · · · · · · · · · ·		 	
			 	
			 	
			· 	
		+		
	LKK Auto Consultants hence notify	+	 	
	I TO Repairer of the following:	+		
	To resurrey before/after earry pointing To display damaged part(s) during resurvey			
	Parts prices are subject to confirmation Third party survey is on a "Without Projudies" basis			
	No illegal modification(s) is allowed.			
	* Supplementary Harriss) must be resurveyed and is subject to final approval from insurance Company			
	Acknowledged by Repairer			
	Signature:	-}	<u> </u>	
				
		+		
		-		
		+		
		+		
$\neg \uparrow$		 		
$\overline{}$		 		

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.