## Spark Car Care

ComfortDelGro Engineering Pte Ltd 320 UBI ROAD 3 SINGAPORE 408649 Tel: 68438723/68438736 Fax:67436072

## Supplementary 1

Vehicle No	: SFL6080U	Case Owner	: <u>0</u>
Make & Model	: MERCEDE BEND C180	Year Manufacture	: <u>2012</u>
Chassis No	: WDD2040312A823243	Engine No	: 27491030036714
Sales Order	: 0	Supplier	: 0
Order By	;	Type of Claim	: <u>OD</u>

S/No	Part Description	QTY	Cost	List	Nett		Dispos
			Price	Price	Item	S/N	Surve
	FRONT FENDER Buckey	1	\$420.00	/			
7/07/2/	FRONT NUMBER PLATE GARNISH 🖟	1	\$60.00	/			
	BONNET STOPPER LH 2 No.	1	\$18.00	/			
	BONNET STOPPER RH	1	\$18.00				
	FRONT BUMPER BRACKET LH Fland	1	\$24.00	/			
	FRONT BUMPER BRACKET RH	1	\$24.00				
	FRONT SUPPORT PANEL LH Headlamp	1	\$130.00	~			
	RIVET NEW	8	\$8.00				
	RADIATOR CLIPS New	2	\$14.00				
10	FRONT BUMPER RIVET HELD	4	\$8.00				
100	HEADLAMP PANEL RH	1	\$130.00				
	AIR GUIDE BAFFLE pelond	1	\$35.00	~			
	RAD GRILLE BRACKET 🌬	1	\$12.00				
14	SUPPORT HOOK	1	\$48.00	V			
15	LOWER GRILLE CTR	1	\$95.00	1			
16	ROD BEAM CLIPS No	2	\$32.00	/			
17	BONNET LOCK CATCH BUY	1	\$24.00		40		
18	Front number plate				\$45		
19							37
20			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				
21				1.000			
22							
23				-			
24			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				
25					1.2		
26					Te de la constant de		
27				LANCE OF THE SECOND SEC			
28							
29						1	
30						1	

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.