

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0066/2018/CCS
Date	:	16-Jan-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mdm Tan Toh Heah
Address	:	322 Laurel Wood Ave Singapore 275944
Telephone	:	HP +65 93801103
Type of Claim	:	Own Damage Claims
Policy No.	:	2100342574-04000
Vehicle No	:	SKK 1215 C
Model Code	:	Audi A4 2.0 TFSI QU
Model / Year	:	Jun-13
Engine No	:	CDN 331188
Chassis No	:	WAUZZZ8K6DA212647
Mileage	:	
Date In	:	15-Jan-18
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	13-Jan-18
Place of Accident	:	PIE

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKK 1215 C.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headadlights, horns, fog lamps, outside temparature sensor and headlight washer assy.	S/N \$ 360.00	✓
2	To remove and transfer aircon condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum / regas and to pressurise cooling system.	S/N \$ 1,100.00	✓
3	To dismantle front bumper, both front fenders, bonnet and headlights. Renew front lock carrier and align to position. Renew damaged panels. Re-organise fron crash management components. Reinstall all parts removed.	\$ 5,400.00	3000.
4	To respray front bumper, both front fenders and bonnet and hinges.	\$ 3,300.00	1650.
5	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 10,352.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKK 1215 C.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Distorted</i>	\$ 2,420.00	✓
2	FRONT BUMPER CLOSING ELEMENT - LOWER CTR <i>na</i>	\$ 195.00	+
3	FRONT BUMPER GRILLE - LOWER CTR <i>na</i>	\$ 287.00	+
4	FRONT BUMPER CLOSING ELEMENT - UPPER CTR <i>na</i>	\$ 167.00	+
5	RADIATOR GRILLE <i>Crushed</i>	\$ 956.00	✓
6	FRONT REINFORCEMENT BEAM <i>Bent</i>	\$ 770.00	✓
7	REINFORCEMENT BEAM BOLT ?	4 \$ 47.00	?
8	FRONT REINFORCEMENT BEAM BRACKET - LH/RH ?	2 \$ 390.00	?
9	FRONT BUMPER SUPPORT - LH/RH ?	2 \$ 21.00	?
10	FRONT BUMPER GUIDE - LH/RH <i>na</i>	2 \$ 62.00	+
11	FRONT BUMPER TOP COVER <i>Replaced</i>	\$ 109.00	✓
12	CAUTION ' STICKER <i>na</i>	\$ 12.00	✓
13	FRONT BUMPER FOAM - INNER <i>Crushed</i>	\$ 107.00	✓
14	FRONT BUMPER GRILLE - LH/RH	2 \$ 1,012.00	
15	FRONT FENDER - LH/RH <i>RH Buckled</i>	2 \$ 1,720.00 860.	
16	FRONT FENDER BRACKET - FRONT LH/RH <i>3 na</i>	2 \$ 92.00	+
17	FRONT FENDER BRACKET - REAR LH/RH	2 \$ 86.00	+
18	FRONT FENDER RIVET SET <i>na</i>	\$ 24.00	+
19	FRONT FENDER BRACE - LH/RH <i>na</i>	2 \$ 206.00	+
20	FRONT FENDER STONE CHIP GUARD - LH/RH <i>21 na</i>	2 \$ 78.00 39.	
SUB-TOTAL SPARE PARTS		\$ 8,761.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKK 1215 C.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	FRONT FENDER ' S-LINE ' INSCRIPTION <i>RH New</i>	2 \$ 215.00 107.50	
22	HEADLIGHT - LH/RH <i>Cracked</i>	2 \$ 4,152.00	✓
23	HEADLIGHT BRACKET - LH/RH ?	2 \$ 184.00	?
24	HEADLIGHT MOUNTING - LH/RH ?	2 \$ 206.00	?
25	HEADLIGHT WASH CYLINDER - LH/RH ?	2 \$ 368.00	?
26	WASH CYLINDER ELBOW FITTING <i>new</i>	2 \$ 45.00	+
27	BONNET <i>Det Buckled</i>	\$ 2,357.00	✓
28	BONNET PROTECTIVE FILM - FRONT <i>new</i>	\$ 40.00	✓
29	BONNET HINGE - LH/RH <i>new</i>	2 \$ 130.00	+
30	BONNET CATCH HOOK ?	\$ 122.00	?
31	BONNET EDGE PROTECTION - FRONT ?	\$ 24.00	?
32	BONNET LOCK <i>new</i>	\$ 188.00	+
33	STICKER FOR AIR CONDITIONER <i>new</i>	\$ 21.00	✓
34	FRONT LOCK CARRIER <i>Cracked</i>	\$ 891.00	✓
35	FRONT LOCK CARRIER AIR GUIDE - LH/RH ?	2 \$ 44.00	?
36	A/C CONDENSER <i>Best</i>	\$ 651.00	✓
37	A/C CONDENSER VALVE <i>new</i>	\$ 46.00	+
38	A/C CONDENSER PRESSURE SENSOR <i>new</i>	\$ 165.00	+
39	CHARGE AIR COOLER <i>new</i>	\$ 492.00	+
40	COOLANT RADIATOR ?	\$ 1,206.00	?
SUB-TOTAL SPARE PARTS		\$ 11,547.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKK 1215 C.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	RADIATOR RUBBER BUSH SET ?	\$ 41.00 ?	
42	RADIATOR SUPPORT - LH/RH ?	2 \$ 66.00 ?	
43	COOLANT <i>mu</i>	\$ 133.00 ✓	
44	TWIN FAN RING ?	\$ 226.00 ?	
45	RADIATOR FAN - 400MM ?	\$ 772.00 ?	
46	RADIATOR FAN - 350MM ?	\$ 667.00 ?	
47	FRONT NUMBER PLATE <i>no Bert</i>	S/N \$ 25.00 ✓	
48	SUNDRIES ?	\$ 400.00 ?	
TOTAL SPARE PARTS		: \$ 22,638.00	
TOTAL LABOUR CHARGES		\$ 10,352.00	
GRAND TOTAL		\$ 32,990.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :

Surveyed Date :

Authorised Date :

Excess Cost :

Liability :

Remarks :

Adrian
16/01/18

Not Authorised, 08 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant