

REF:

CC3/ALH18001013 / Anber

ASSIGNMENT

From:

Date:

Veh No:

8KK1215C

In Page:

2013 June

Estimated Cost:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

Make:

Audi A4

Yr:

1984

at Workshop m/s

Colour:

Bronze

A/C:

Insured / Std / NI / NA

of

Sp. Reading

49606

T. Radio:

Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

2100342574 - 04000

C. No:

WAUZZZ8K6DA212647.

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

800

(Client's Record)

Steering: Ind / Jammed / Leaked / Burnt or

Make of Veh:

Brake: Ind / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Tyre Size:

F: 255/35R19.

R: 255/35R19.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Bal. or Market Value:

98K.

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

06

mm

R/Bal.

06

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

06

mm

L/Bal.

06

mm

Est. Repairs:

11/8/18 days

Res.:

Yes or No

D.O.A.

13/1/18

D.O.I.

16/01/18

Lump Sum:

%

3 Val.:

Yes or No

Survey held at

Premium.

CA / REV / REP. / 24 HRS

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

DD AUG.

8KK1215C - X

RECEIVED 13 APR 2018

17/1/18 Revert by merimen, pending repair cost from reparer.

17/1/18 @ 5:17pm Kee Siang request for repair cost \$22K

17/1/18 Recc approved. \$19,950.50. Repair limit not exceeding \$22,000

17/1/18 Informal Kee Siang repair limit \$22k on part by part ex \$800 by email

31/3/18 Final fig \$20,708.92 (Red 12,310.08, 377)

Confirmed by email

Date/Time. File Pass to?

☐

Preli. Report

Days Of Repair:

11

☐

Final Report

Resurvey No. of Trip:

1

Survey Fee:

Date/Time. File Return to?

Transponder

2. 13/4 - typist

Add Fee:

☐

Site Insp. \$

☐

Inter. ev. \$

☐

Tech. ins. \$

☐

Reserv. \$

LUB - PS (LUB)

Photos

Other

Report Format:

merimen

Lump Sum / L.B.I. \$

20,708.92

200

10

210

Survey Department Check List (Case Handler)

Reference No. : CC3 | A19 | 18001013 | Avb

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)				
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess	✓			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases	✓			
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 31/3/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



The all-new Audi Q2

#untaggable



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Wednesday, 17 January, 2018 1:50 PM
To: Claims; SUR
Subject: RE: OD CLAIM FOR SKK 1215 C

Dear Tony,

Kindly check vehicle able to repair at part by part not exceeding \$20K

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [<mailto:claims@premiumauto.com.sg>]
Sent: Tuesday, 16 January 2018 4:14 PM
To: SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: OD CLAIM FOR SKK 1215 C

Dear all,

Kindly assist follow up on repair approval. Adrian had done the survey just now.

Thank you.

Best Regards,

Tony Foong

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



The all-new Audi Q2

#untaggable



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

View Received Message

This mail is associated with :

***SKK1215C (1436770649SG)**

OD

Jan 13 2018 8:40AM

[TAN TOH HEAH]

Premium Automobiles Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 17/01/2018 14:42 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$19952.50) - SKK1215C - Claim Handler: Dally Amri, Mimi Zarina

Approved:19952.50:Repair limit not exceeding \$22,000.00. Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: **AIG Asia Pacific Insurance Pte. Ltd.**
AIG Building
78 Shenton Way #07-16
Singapore 079120From: **LKK Auto Consultants Pte Ltd**
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: **17 Jan 2018****Preliminary Advice**

Vehicle No	: SKK1215C	Accident Date	: 13/01/2018
Make	: AUDI A4	Policy No.	: 2100342574-04000
Assignment Date	: 17/01/2018	Excess	: S\$0.00
Date of Inspection	: 16/01/2018	Est. Duration of Repair	: 8.00
Inspection At	PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	32,990.00
Revised Amount	:S\$	19,952.50
Check Items (Estimated)	:S\$	5,796.00
Total	:S\$	25,748.50
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	98,000.00
COE / PARF Rebate	:S\$	75,452.00
Salvage Value	:S\$	
Margin for Repair	:S\$	22,548.00

Remarks

() The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(x) Other comments : Pending repair cost from repairer.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 5968J

Vehicle Details

Vehicle No.: SKK1215C
Vehicle to be Exported: No
Intended De-registration Date: 17 Jan 2018
Vehicle Make: AUDI
Vehicle Model: A4 2.0 TFSI QU (NAVIGATION)
Primary Colour: Grey
Manufacturing Year: 2013
Engine No.: CDN331188
Chassis No.: WAUZZZ8K6DA212647
Maximum Power Output: 155.0 kW (207 bhp)
Open Market Value: \$42,583.00
Original Registration Date: 11 Jun 2013
First Registration Date: 11 Jun 2013
Transfer Count: 0
Actual ARF Paid: \$46,617.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 10 Jun 2023
PARF Rebate Amount: \$34,962.00

Intended COE Rebate Details

COE Expiry Date: 10 Jun 2023
COE Category: B - Car (1601cc & above)

COE Period(Years):	10
QP Paid:	\$75,000.00
COE Rebate Amount:	\$40,490.00
Total Rebate Amount:	\$75,452.00

The information contained herein is correct as at 17 Jan 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/01/2018 15:16
Date Of Accident	13/01/2018 08:40
Exact Location Of Accident	PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKK1215C
Insured/Policyholder	
Name Of Registered Owner	TAN TOH HEAH
NRIC No	S1295968J
Email Address	TOHHEAH@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-93801103
Alternative Phone No	HOME-64682640

Vehicle Particulars

Manufacturer	AUDI
Model	A4 2.0 TFSI QU
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100342574-04000
Cover Note Number	


Driver

Name of Driver	TAN JIAN'EN JULIAN @ GOH JULIAN
NRIC No	S9231362Z
Date Of Birth	28/08/1992
Occupation	INDOOR
Date Of Driving Pass	20/06/2012
Driving Experience	5 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90224333
Fax Number	
Contact Number	
Email Address	SQUEEZEPROOF@GMAIL.COM

Sketch Plan #2

SKETCH PLAN

A: SKK 1215C
B: Unknown
C: Unknown
D: SKA 1396R



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Approximately 8.40 am, driving on PIE toward Changi, past Ormat road
Banyan, slippery roads a van driver had hit the middle curb on the expressway
causing 3 vehicle prior to me to swerve and get into a chain collision. I
was the 4th vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature

Date & Time

15/1/18

Driver's Signature

(If driver is not the policyholder)

Date & Time

15/1/18



Reporting Centre Personnel's Signature

Name: Lam Kok Siang

NRIC/FIN No: 64552641M


Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo





CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.1

AUDI AUTO PROTECTOR

CERTIFICATE NO. 2100342574-04000

OWN DAMAGE EXCESS S\$800.00 (1)
WINDSCREEN EXCESS S\$100.00
(for policies with effect from 1st November 2002)

SUM INSURED Market Value
INSURING WITH COE/PARF No
SKK1215C

1) VEHICLE REGISTRATION NO.

2) NAME OF INSURED

TAN TOH HEAH

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

11 Jun 2017

4) DATE OF EXPIRY OF INSURANCE

10 Jun 2018

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *
SUBJECT TO AGE CONDITION :All Age Condition

a) The Insured.

b) Any other person who is driving on the Insured's order or with his permission.

This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions.

A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the

Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said

Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE *

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)

4. Ethoz - 30 Bukit Batok Cras (Tel: 66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only

6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)

8. Moya Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)

10. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre

NAMED DRIVER NA

HIRE PURCHASE COMPANY NA
/ EMPLOYER'S LOAN

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 19 May 2017

AIG Asia Pacific Insurance Pte. Ltd.

504125-200
PREMIUM LEASING - AP
281 ALEXANDRA ROAD
AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

AUTHORISED REPRESENTATIVE

ORIGINAL

SSPLUS.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1295968J



Name

TAN TOH HEAH



陈在霞

Race

CHINESE

Date of Birth

29-01-1958

Sex

F

Country of Birth

SINGAPORE



0578461



NRIC No. S1295968J



Blood Group

O+

Date of issue

24-06-1994

322 LAUREL WOOD AVENUE
SINGAPORE 275944

NRIC No: S1295968J

Date: 04-03-2003

No: 4639038

REPUBLIC OF SINGAPORE DRIVING LICENCE



002079380A

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS

Class 3 Motor Cars $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of the driver; and other motor vehicles $\leq$ 2500kg 20 Jun 2012

NP 428A



Licence No: S9231362Z

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0066/2018/CCS
Date : 16-Jan-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mdm Tan Toh Heah
Address : 322 Laurel Wood Ave
Singapore 275944
Telephone : HP +65 93801103
Type of Claim : Own Damage Claims
Policy No. : 2100342574-04000
Vehicle No : **SKK 1215 C**
Model Code : Audi A4 2.0 TFSI QU
Model / Year : Jun-13
Engine No : CDN 331188
Chassis No : WAUZZZ8K6DA212647
Mileage :
Date In : 15-Jan-18
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 13-Jan-18
Place of Accident : PIE

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKK 1215 C.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headadlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓ ✓
2	To remove and transfer aircon condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum / regas and to pressurise cooling system.	S/N \$ 1,100.00	✓ ✓
3	To dismantle front bumper, both front fenders, bonnet and headlights. Renew front lock carrier and align to position. Renew damaged panels. Re-organise fron crash management components. Reinstall all parts removed.	\$ 5,400.00	3000 ✓
4	To respray front bumper, both front fenders and bonnet and hinges.	\$ 3,300.00	1650 . 2000
5	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 10,352.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKK 1215 C.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Distorted</i>	\$ 2,420.00	✓ 1936
2	FRONT BUMPER CLOSING ELEMENT - LOWER CTR <i>mm</i>	\$ 195.00	+
3	FRONT BUMPER GRILLE - LOWER CTR <i>mm</i>	\$ 287.00	+
4	FRONT BUMPER CLOSING ELEMENT - UPPER CTR <i>mm</i>	\$ 167.00	✓ 133.20
5	RADIATOR GRILLE <i>mm</i>	\$ 956.00	✓ 764.80
6	FRONT REINFORCEMENT BEAM <i>Bent</i>	\$ 770.00	✓ 616
7	REINFORCEMENT BEAM BOLT <i>Not New</i>	4 \$ 47.00	3x
8	FRONT REINFORCEMENT BEAM BRACKET - LH/RH <i>Not New</i>	2 \$ 390.00	2x
9	FRONT BUMPER SUPPORT - LH/RH <i>Damaged</i>	2 \$ 21.00	? 16.80
10	FRONT BUMPER GUIDE - LH/RH <i>mm</i>	2 \$ 62.00	+
11	FRONT BUMPER TOP COVER <i>Replaced</i>	\$ 109.00	✓ 87.00
12	CAUTION ' STICKER <i>mm</i>	\$ 12.00	✓ 9.28
13	FRONT BUMPER FOAM - INNER <i>mm</i>	\$ 107.00	✓ 85.00
14	FRONT BUMPER GRILLE - LH/RH <i>RH missing</i>	2 \$ 1,012.00	404.40
15	FRONT FENDER - LH/RH <i>RH Buckled</i>	2 \$ 1,720.00	860.688
16	FRONT FENDER BRACKET - FRONT LH/RH <i>2 mm</i>	2 \$ 92.00	+
17	FRONT FENDER BRACKET - REAR LH/RH	2 \$ 86.00	+
18	FRONT FENDER RIVET SET <i>mm</i>	\$ 24.00	+
19	FRONT FENDER BRACE - LH/RH <i>mm</i>	2 \$ 206.00	+
20	FRONT FENDER STONE CHIP GUARD - LH/RH <i>21 mm</i>	2 \$ 78.00	39. 31.00
SUB-TOTAL SPARE PARTS		\$ 8,761.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKK 1215 C.

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
21	FRONT FENDER 'S-LINE' INSCRIPTION <i>RH New</i>	2 \$	215.00 107.50	SG
22	HEADLIGHT - LH/RH <i>Cracked</i>	2 \$	4,152.00	✓ 3321.60
23	HEADLIGHT BRACKET - LH/RH <i>Cracked</i>	2 \$	184.00	? 147.04
24	HEADLIGHT MOUNTING - LH/RH <i>Cracked</i>	2 \$	206.00	? 164.80
25	HEADLIGHT WASH CYLINDER - LH/RH <i>2H Cracked</i>	2 \$	368.00	? 147.20
26	WASH CYLINDER ELBOW FITTING <i>new</i>	2 \$	45.00	+
27	BONNET <i>Dist Buckled</i>	\$	2,357.00	✓ 1885.60
28	BONNET PROTECTIVE FILM - FRONT <i>new</i>	\$	40.00	✓ 31.28
29	BONNET HINGE - LH/RH <i>new</i>	2 \$	130.00	+
30	BONNET CATCH HOOK <i>Best</i>	\$	122.00	? 97.60
31	BONNET EDGE PROTECTION - FRONT <i>new</i>	\$	24.00	? 18.88
32	BONNET LOCK <i>new Dargd.</i>	\$	188.00	+
33	STICKER FOR AIR CONDITIONER <i>new</i>	\$	21.00	✓ 16.16
34	FRONT LOCK CARRIER <i>Cracked</i>	\$	891.00	✓ 710.80
35	FRONT LOCK CARRIER AIR GUIDE - LH/RH <i>Cracked</i>	2 \$	44.00	? 34.72
36	A/C CONDENSER <i>Best</i>	\$	651.00	✓ 506.40
37	A/C CONDENSER VALVE <i>new Dargd</i>	\$	46.00	+
38	A/C CONDENSER PRESSURE SENSOR <i>new Dargd</i>	\$	165.00	+
39	CHARGE AIR COOLER <i>new Dargd</i>	\$	492.00	+
40	COOLANT RADIATOR <i>Dargd</i>	\$	1,206.00	? 964.80
SUB-TOTAL SPARE PARTS			\$ 11,547.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKK 1215 C.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	RADIATOR RUBBER BUSH SET <i>Not New</i>	\$ 41.00	? X
42	RADIATOR SUPPORT - LH/RH <i>Not New</i>	2 \$ 66.00	? X
43	COOLANT <i>in</i>	\$ 133.00	✓ 106.34
44	TWIN FAN RING <i>Not New</i>	\$ 226.00	? X
45	RADIATOR FAN - 400MM <i>Not New</i>	\$ 772.00	? X
46	RADIATOR FAN - 350MM <i>Not New</i>	\$ 667.00	? X
47	FRONT NUMBER PLATE <i>Not Best</i>	S/N \$ 25.00	✓ 25
48	SUNDRIES <i>New</i>	\$ 400.00	? 92.32
TOTAL SPARE PARTS		\$ 22,638.00	
TOTAL LABOUR CHARGES		\$ 10,352.00	
GRAND TOTAL		\$ 32,990.00	33,019

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 16/01/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 08 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKK 1215 C.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Distorted</i>	\$ 2,420.00	✓
2	FRONT BUMPER CLOSING ELEMENT - LOWER CTR <i>mm</i>	\$ 195.00	+
3	FRONT BUMPER GRILLE - LOWER CTR <i>mm</i>	\$ 287.00	+
④	FRONT BUMPER CLOSING ELEMENT - UPPER CTR <i>mm</i>	\$ 167.00	✓ CPA ✓
5	RADIATOR GRILLE <i>Crushed</i>	\$ 956.00	✓
6	FRONT REINFORCEMENT BEAM <i>Best</i>	\$ 770.00	✓
7	REINFORCEMENT BEAM BOLT ?	4 \$ 47.00	?
8	FRONT REINFORCEMENT BEAM BRACKET - LH/RH ?	2 \$ 390.00	?
⑨	FRONT BUMPER SUPPORT - LH/RH ?	2 \$ 21.00	? CPA ✓
10	FRONT BUMPER GUIDE - LH/RH <i>mm</i>	2 \$ 62.00	+
11	FRONT BUMPER TOP COVER <i>Rehnd</i>	\$ 109.00	✓
12	CAUTION ' STICKER <i>mm</i>	\$ 12.00	✓
13	FRONT BUMPER FOAM - INNER <i>Crushed</i>	\$ 107.00	✓
14	FRONT BUMPER GRILLE - LH/RH	2 \$ 1,012.00	
15	FRONT FENDER - LH/RH <i>RH Buckled</i>	2 \$ 1,720.00 860.	
16	FRONT FENDER BRACKET - FRONT LH/RH <i>3mm</i>	2 \$ 92.00	+
17	FRONT FENDER BRACKET - REAR LH/RH	2 \$ 86.00	+
18	FRONT FENDER RIVET SET <i>Rec</i>	\$ 24.00	+
19	FRONT FENDER BRACE - LH/RH <i>Abn</i>	2 \$ 206.00	+
20	FRONT FENDER STONE CHIP GUARD - LH/RH <i>Rit</i>	2 \$ 78.00 39.	
SUB-TOTAL SPARE PARTS		\$ 8,761.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKK 1215 C.

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
21	FRONT FENDER 'S-LINE' INSCRIPTION <i>RH New</i>	2 \$	215.00 107.50	
22	HEADLIGHT - LH/RH <i>Cracked</i>	2 \$	4,152.00	✓
23	HEADLIGHT BRACKET - LH/RH ?	2 \$	184.00 ?	CRA ✓
24	HEADLIGHT MOUNTING - LH/RH ?	2 \$	206.00 ?	CRA ✓
25	HEADLIGHT WASH CYLINDER - LH/RH ?	2 \$	368.00 ?	CRA ✓
26	WASH CYLINDER ELBOW FITTING <i>new</i>	2 \$	45.00	+
27	BONNET <i>Det Buckled</i>	\$	2,357.00	✓
28	BONNET PROTECTIVE FILM - FRONT <i>new</i>	\$	40.00	✓
29	BONNET HINGE - LH/RH <i>new</i>	2 \$	130.00	+
30	BONNET CATCH HOOK ?	\$	122.00 ?	PA ✓
31	BONNET EDGE PROTECTION - FRONT ?	\$	24.00 ?	CPA ✓
32	BONNET LOCK <i>new</i>	\$	188.00	+ PA ✓
33	STICKER FOR AIR CONDITIONER <i>new</i>	\$	21.00	✓
34	FRONT LOCK CARRIER <i>Cracked</i>	\$	891.00	✓
35	FRONT LOCK CARRIER AIR GUIDE - LH/RH ?	2 \$	44.00 ?	CRA ✓
36	A/C CONDENSER <i>Best</i>	\$	651.00	✓
37	A/C CONDENSER VALVE <i>new</i>	\$	46.00	+ new ✓
38	A/C CONDENSER PRESSURE SENSOR <i>new</i>	\$	165.00	+ CRA ✓
39	CHARGE AIR COOLER <i>new</i>	\$	492.00	+ PA ✓
40	COOLANT RADIATOR ?	\$	1,206.00 ?	PA ✓
SUB-TOTAL SPARE PARTS		:	\$ 11,547.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKK 1215 C.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	RADIATOR RUBBER BUSH SET ?	\$ 41.00	?
42	RADIATOR SUPPORT - LH/RH ?	2 \$ 66.00	?
43	COOLANT <i>ru</i>	\$ 133.00	✓
44	TWIN FAN RING ?	\$ 226.00	?
45	RADIATOR FAN - 400MM ?	\$ 772.00	?
46	RADIATOR FAN - 350MM ?	\$ 667.00	?
47	FRONT NUMBER PLATE <i>new Best</i>	S/N \$ 25.00	✓
48	SUNDRIES ?	\$ 400.00	?
TOTAL SPARE PARTS		: \$ 22,638.00	
TOTAL LABOUR CHARGES		\$ 10,352.00	
GRAND TOTAL		\$ 32,990.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0066/2018/CCS 23-Jan-18 CHANG 1 of 1 SKK 1215 C Audi A4 2.0 TFSI QU
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	OUTER TEMPERATURE SEN. BRACKET	\$ 15.00	MIS CR4 ✓
2	A/C PRESSURE SENSOR CONNECTOR	\$ 14.00	CR4 ✓
TOTAL PARTS :		\$ 29.00	
GRAND TOTAL :		\$ 29.00	

For Premium Automobiles Pte Ltd



Authorised Signature

25/1/18

by Rasul.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0066/2018/CCS
Date : 16-Jan-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mdm Tan Toh Heah
Address : 322 Laurel Wood Ave
Singapore 275944
Telephone : HP +65 93801103
Type of Claim : Own Damage Claims
Policy No. : 2100342574-04000
Vehicle No : **SKK 1215 C**
Model Code : Audi A4 2.0 TFSI QU
Model / Year : Jun-13
Engine No : CDN 331188
Chassis No : WAUZZZ8K6DA212647
Mileage :
Date In : 15-Jan-18
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 13-Jan-18
Place of Accident : PIE

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKK 1215 C.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headadlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	\$ 360.00
2	To remove and transfer aircon condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum / regas and to pressurise cooling system.	S/N	\$ 1,100.00	\$ 1,100.00
3	To dismantle front bumper, both front fenders, bonnet and headlights. Renew front lock carrier and align to position. Renew damaged panels. Re-organise from crash management components. Reinstall all parts removed.		\$ 5,400.00	\$ 3,000.00
4	To respray front bumper, both front fenders and bonnet and hinges.		\$ 3,300.00	\$ 2,200.00
5	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 10,352.00</u>	<u>\$ 6,852.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKK 1215 C.

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		<u>S/Nett</u>	<u>Remark</u>
1	FRONT BUMPER	\$ 2,420.00	\$ 1,936.00
2	FRONT BUMPER CLOSING ELEMENT - LOWER CTR	\$ 195.00	
3	FRONT BUMPER GRILLE - LOWER CTR	\$ 287.00	
4	FRONT BUMPER CLOSING ELEMENT - UPPER CTR	\$ 167.00	\$ 133.20
5	RADIATOR GRILLE	\$ 956.00	\$ 764.80
6	FRONT REINFORCEMENT BEAM	\$ 770.00	\$ 616.00
7	REINFORCEMENT BEAM BOLT	4 \$ 47.00	
8	FRONT REINFORCEMENT BEAM BRACKET - LH/RH	2 \$ 390.00	
9	FRONT BUMPER SUPPORT - LH/RH	2 \$ 21.00	\$ 16.80
10	FRONT BUMPER GUIDE - LH/RH	2 \$ 62.00	
11	FRONT BUMPER TOP COVER	\$ 109.00	\$ 87.20
12	CAUTION ' STICKER	\$ 12.00	\$ 9.28
13	FRONT BUMPER FOAM - INNER	\$ 107.00	\$ 85.20
14	FRONT BUMPER GRILLE - LH/RH	2 \$ 1,012.00	\$ 404.40
15	FRONT FENDER - LH/RH	2 \$ 1,720.00	\$ 688.00
16	FRONT FENDER BRACKET - FRONT LH/RH	2 \$ 92.00	
17	FRONT FENDER BRACKET - REAR LH/RH	2 \$ 86.00	
18	FRONT FENDER RIVET SET	\$ 24.00	
19	FRONT FENDER BRACE - LH/RH	2 \$ 206.00	
20	FRONT FENDER STONE CHIP GUARD - LH/RH	2 \$ 78.00	\$ 31.20
SUB-TOTAL SPARE PARTS		\$ 8,761.00	\$ 4,772.08

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKK 1215 C.

S/N	Parts Description	c/f	<u>Damaged Parts & Prices</u>	
			<u>S/Nett</u>	<u>Remark</u>
				4,772.08
21	FRONT FENDER ' S-LINE ' INSCRIPTION	2 \$	215.00	\$ 86.00
22	HEADLIGHT - LH/RH	2 \$	4,152.00	\$ 3,321.60
23	HEADLIGHT BRACKET - LH/RH	2 \$	184.00	\$ 147.04
24	HEADLIGHT MOUNTING - LH/RH	2 \$	206.00	\$ 164.80
25	HEADLIGHT WASH CYLINDER - LH/RH	2 \$	368.00	\$ 147.20
26	WASH CYLINDER ELBOW FITTING	2 \$	45.00	
27	BONNET	\$	2,357.00	\$ 1,885.60
28	BONNET PROTECTIVE FILM - FRONT	\$	40.00	\$ 31.28
29	BONNET HINGE - LH/RH	2 \$	130.00	
30	BONNET CATCH HOOK	\$	122.00	\$ 97.60
31	BONNET EDGE PROTECTION - FRONT	\$	24.00	\$ 18.88
32	BONNET LOCK	\$	188.00	\$ 150.40
33	STICKER FOR AIR CONDITIONER	\$	21.00	\$ 16.16
34	FRONT LOCK CARRIER	\$	891.00	\$ 712.80
35	FRONT LOCK CARRIER AIR GUIDE - LH/RH	2 \$	44.00	\$ 34.72
36	A/C CONDENSER	\$	651.00	\$ 520.40
37	A/C CONDENSER VALVE	\$	46.00	\$ 36.40
38	A/C CONDENSER PRESSURE SENSOR	\$	165.00	\$ 132.00
39	CHARGE AIR COOLER	\$	492.00	\$ 393.60
40	COOLANT RADIATOR	\$	1,206.00	\$ 964.80
SUB-TOTAL SPARE PARTS		:	\$ 11,547.00	\$ 13,633.36

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKK 1215 C.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
		c/f	\$ 13,633.36
41	RADIATOR RUBBER BUSH SET	\$ 41.00	
42	RADIATOR SUPPORT - LH/RH	2 \$ 66.00	
43	COOLANT	\$ 133.00	\$ 106.24
44	TWIN FAN RING	\$ 226.00	
45	RADIATOR FAN - 400MM	\$ 772.00	
46	RADIATOR FAN - 350MM	\$ 667.00	
47	FRONT NUMBER PLATE	S/N \$ 25.00	\$ 25.00
48	SUNDRIES	\$ 400.00	\$ 92.32
TOTAL SPARE PARTS		\$ 22,238.00	\$ 13,856.92
TOTAL LABOUR CHARGES		\$ 10,352.00	\$ 6,852.00
GRAND TOTAL		\$ 32,590.00	\$ 20,708.92

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0066/2018/CCS 23-Jan-18 CHANG 1 of 1 SKK 1215 C Audi A4 2.0 TFSI QU
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	OUTER TEMPERATURE SEN. BRACKET { <i>new</i>	\$ 15.00	X X
2	A/C PRESSURE SENSOR CONNECTOR	\$ 14.00	X X
TOTAL PARTS :		\$ 29.00	sundries
GRAND TOTAL :		\$ 29.00	

For Premium Automobiles Pte Ltd

Adrian Ling
868.

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Saturday, 31 March 2018 11:47 AM
To: Boo seng yak; Carrine Leong; Nora Khai; SUR
Subject: RE: FINAL REVISION SKK1215C - OD AIG - SURVEYED 16 JAN 18

Dear Mr Boo,

Confirm repair cost of \$20,708.92 before excess \$800 and GST @ 11 days of repairs.

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [mailto:boojohnny@gmail.com]
Sent: Monday, 19 March 2018 3:52 PM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Nora Khai <nora.khai@premiumauto.com.sg>
Subject: FINAL REVISION SKK1215C - OD AIG - SURVEYED 16 JAN 18

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$20708.92 @ 11 days of repairs exclude 2 Sundays.

Mr. Rasul re-inspected vehicle on 25 Jan 18.

Your early closure is appreciated.

Best regards - jb

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SKK 1215 C

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0066/2018/MAS

12 April 2018

Dear Sir,

RE: INSURANCE CLAIM FOR SKK 1215 C, Audi A4 2.0 TFSI Qu

With reference to the above-mentioned vehicle, no. **SKK 1215 C**, claimant, **Mdm. Tan Toh Heah**, please find the related document per attached.

1. A copy of the Original invoice no. 85012321 – S\$21,302.54
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SKK 1215 C

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408693
Telephone 6388 2323
Telefax 6441 1890

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INSURANCE INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 1 15:01

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012321 Date : 09/04/2018 Order : SKK1215C Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SKK1215C (V 20615) Regn Date: 11/06/2013 Mileage: 49606 WIP No.: 52228
Model: A4 2.0 TFSI QU 8K206Y (YOM 201 Chassis: WAUZZZ8K6DA212647 Engine: CDN 331188 Dept: U
VSB No.:
You have been assisted by :- UB-Carrine (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	360.00	1.00	360.00
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE.	25.00	1.00	25.00
Q	EXC	M: 8888 Insurance Excess/Liability	-800.00	1.00	-800.00
S	BODYWORK	M: TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, CHARGED AIR COOLER, ELECTRICAL FANS AND CONTROL UN TO CARRY OUT VACUUM / REGAS AND TO PRESSURISE COOLING SYSTEM.	1100.00	1.00	1,100.00
S	BODYWORK	M: TO DISMANTLE FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND HEADLIGHTS. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW DAMAGED PANELS. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL	3000.00	1.00	3,000.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408619
Telephone 6388 2223
Telefax 6841 1123

Customer Service
Service Appointment
2-hour Breakdown Service
Email customer.care@premiumauto.com.sg
6366 2323
9828 1233

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 2 15:01

Invoice: 85012321	Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD	AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT	MOTOR CLAIM DEPT
AIG BUILDING	AIG BUILDING
78 SHENTON WAY	78 SHENTON WAY
#07-16	#07-16
SINGAPORE 079120 079120	SINGAPORE 079120
Date : 09/04/2018	
Order : SKK1215C	
Term : 30	

Regn No.: SKK1215C (V 20615) Regn Date: 11/06/2013 Mileage: 49606 WIP No.: 52228

Model: A4 2.0 TFSI QU 8K206Y (YOM 201 Chassis: WAUZZZ8K6DA212647 Engine: CDN 331188 Dept: U

VSB No.:

You have been assisted by :- UB-Carrine (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	PARTS REMOVED. M: TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS AND BONNET.	2200.00	1.00	2,200.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK.	192.00	1.00	192.00
X	AG A13A8JM1	COOLANT ADDITIVE	4.00	33.20	106.24
X	A8K0853651E T94	GRILLE(A)	1.00	956.00	764.80
X	A8K0145805P	COOLER	1.00	492.00	393.60
X	A8K0941043D	HEADLAMP	1.00	2076.00	1,660.80
X	A8K0941044D	HEADLAMP	1.00	2076.00	1,660.80
X	A8K0821106J	FENDER	1.00	680.00	688.00
X	A8K0807001D 989	COVER	1.00	109.00	87.20
X	A8K0121251AJ	RADIATOR	1.00	1206.00	964.80
X	A8T0260403F	CONDENSER	1.00	650.50	520.40
X	A8K0805594L	CARRIER	1.00	891.00	712.80
X	A8K0807113F	BEAM	1.00	770.00	616.00
X	A8K0823029H	HOOD	1.00	2357.00	1,885.60

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408679
Telephone 6388 2223
Telefax 6411 4785

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

Page 3 15:01

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Invoice: 85012321	Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD	AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT	MOTOR CLAIM DEPT
AIG BUILDING	AIG BUILDING
78 SHENTON WAY	78 SHENTON WAY
#07-16	#07-16
SINGAPORE 079120 079120	SINGAPORE 079120
Date : 09/04/2018	
Order : SKK1215C	
Term : 30	

Regn No.: SKK1215C (V 20615)	Regn Date: 11/06/2013	Mileage: 49606	WIP No.: 52228
Model: A4 2.0 TFSI QU BK206Y (YOM 201	Chassis: WAUZZZ8K6DA212647	Engine: CDN 331188	Dept: U
VS8 No.:			
You have been assisted by :- UB-Carrine (33)			

		Details	Qty	Unit Price	Amount
X	A8K0807065E GRU	COVER Less 020%	1.00	2420.00	1,936.00
X	A8K0973703	HOUSING Less 020%	1.00	14.20	11.36
X	AN 90342504	SPEED NUT Less 020%	2.00	2.00	3.20
X	A4E0260749B	WASHER Less 020%	1.00	4.20	3.36
X	A8K0807550E	FOAM INSER Less 020%	1.00	106.50	85.20
X	A4H0121268	MOUNTING Less 020%	2.00	11.10	17.76
X	A8N0853601A	INSCRIPTION 'S-LINE' Less 020%	1.00	107.50	86.00
X	A8K0807333B	SUPPORT Less 020%	2.00	10.50	16.80
X	A8T0823480	HOCK Less 020%	1.00	122.00	97.60
X	A8K0121275C	MOUNTING Less 020%	2.00	5.60	8.96
X	A8K0121276A	MOUNTING Less 020%	2.00	2.80	4.48
X	A8K0820536D	BRACKET Less 020%	1.00	15.60	12.48
X	A8K0823509G	LOCK Less 020%	1.00	188.00	150.40
X	A8T0823544	FOIL Less 020%	1.00	39.10	31.28
X	A8K0805607B	MOUNTING Less 020%	1.00	103.00	82.40
X	A8K0805608B	MOUNTING Less 020%	1.00	103.00	82.40
X	A8K0807233G	PLATE Less 020%	1.00	166.50	133.20
X	A4E0260749A	WASHER Less 020%	1.00	3.20	2.56
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408679
Telephone 6388 2223
Telefax 6411 1750

Customer Service
Service Appointment
24-hour Breakdown Service
Email customer.care@premiumauto.com.sg
6366 2323
9828 1233

Page 4 15:01

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012321 Date : 09/04/2018 Order : SKK1215C Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SKK1215C (V 20615) Regn Date: 11/06/2013 Mileage: 49606 WIP No.: 52228

Model: A4 2.0 TFSI QU 8K206Y (YOM 201 Chassis: WAUZZZ8K6DA212647 Engine: CDN 331188 Dept: U

USB No.:

You have been assisted by :- UB-Carrine (33)

		Details	Qty	Unit Price	Amount
X	ABK0823126J	EDGING	1.00	23.60	18.80
X	ABT0823433B	BUMPER	2.00	8.30	13.28
X	A7H0820096	SEAL	2.00	2.30	3.68
X	ABA0820855AA	VALVE	1.00	45.50	36.40
X	ABK0853824	STONEGUARD	1.00	39.00	31.20
X	ABK0807682M 01C	GRILLE	1.00	505.50	404.40
X	ABK0955101D	CYLINDER	1.00	184.00	147.20
X	A4H0959126B	PRESSENS	1.00	165.00	132.00
X	ABK0010520A	PLATE	1.00	11.60	9.28
X	ABK0010515AK	STICKER	1.00	20.20	16.16
X	ABK0121284S	AIR DUCT	1.00	21.70	17.36
X	ABK0121283S	AIR DUCT	1.00	21.70	17.36
X	ABT0941454D	BRACKET	1.00	91.90	73.52
X	AWHT001506A	BOLT	2.00	1.40	2.24
X	AN 90765701	RIVET	4.00	1.30	4.16
X	AN 90683302	BOLT	2.00	1.50	2.40
X	AN 10442003	BOLT	2.00	0.50	0.80
X	AN 10347204	BOLT	2.00	1.00	1.60

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore

281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre

281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre

55 Ubi Road 1
Singapore 408619
Telephone 6388 2223
Telefax 6441 1185

Customer Service

Service Appointment
24-hour Breakdown Service
Email

6366 2323
9828 1233

customer.care@premiumauto.com.sg

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 5 15:01

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012321 Date : 09/04/2018 Order : SKK1215C Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SKK1215C (V 20615) Regn Date: 11/06/2013 Mileage: 49606 WIP No.: 52228

Model: A4 2.0 TFSI QU 8K206Y (VOM 201 Chassis: WAUZZZ8K6DA212647 Engine: CDN 331188 Dept: U

VSB No.:

You have been assisted by :- UB-Carrine (33)

		Details	Qty	Unit Price	Amount
X	ABT0941453D	BRACKET Less 020%	1.00	91.90	73.52

Parts 13,831.92
Labour 0.00
Sublet 6,877.00
Menus 0.00
Lubricant 0.00

Sub-Total 19,908.92

7% GST 1,393.62

Grand Total 21,302.54



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SKX 1215 C

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0066/2018/GW
01 February 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 2.0 TFSI Qu
Vehicle Chassis No. : WAUZZZ8K6DA212647
Vehicle Regn No. : **SKX 1215 C**
Vehicle Mileage : 49606 KM
Vehicle Owner : Mdm.Tan Toh Heah
Certificate No : 2100342574-04000
Policy Excess : **S\$856** (inclusive 7% GST)
Accident Date : 13/01/2018
Place : PIE
Repair Cost : \$ 21,302.54
WIP No. : **52228**
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :

1/2/18

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1295968J



Name

TAN TOH HEAH



陈在霞

Race

CHINESE

Date of Birth


29-01-1958

Sex

F


Country of Birth

SINGAPORE



0578461

NRIC No. S1295968J



Blood Group

O+

Date of issue

24-06-1994

322 LAUREL WOOD AVENUE
SINGAPORE 275944

NRIC No: S1295968J

Date: 04-03-2003

No: 4639038

REPUBLIC OF SINGAPORE DRIVING LICENCE

VEN KUN JULIAN

28 Aug 1982

20 Jun 2012

002079380A

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of the driver; and other motor vehicles $\leq$ 2500kg 20 Jun 2012

NP 428A

Licence No: S92313622



HOTLINE TEL: (65) 6419 3000
FAX: (65) 6415-3723

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT(CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.1

AUDI AUTO PROTECTOR

CERTIFICATE NO. 2100342574-04000

OWN DAMAGE EXCESS S\$800.00 (1)
WINDSCREEN EXCESS S\$100.00
(for policies with effect from 1st November 2002)

SUM INSURED Market Value
INSURING WITH COE/PARF No
SKK1215C

TAN TOH HEAH

11 Jun 2017

10 Jun 2018

- 1) VEHICLE REGISTRATION NO.
- 2) NAME OF INSURED
- 3) EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT
- 4) DATE OF EXPIRY OF INSURANCE
- 5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *
SUBJECT TO AGE CONDITION :All Age Condition

a) The Insured.

b) Any other person who is driving on the Insured's order or with his permission.

This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions.

A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the

Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said

Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE *

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)

4. Ethoz - 30 Bukit Batok Cres (Tel: 66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only

6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)

8. Mova Automotive - 1098 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)

10. SME Motor - 1 Kaki Bukit Ave 6 Bld D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre

NAMED DRIVER NA

HIRE PURCHASE COMPANY / EMPLOYER'S LOAN NA

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 19 May 2017

AIG Asia Pacific Insurance Pte. Ltd.

504125-200
PREMIUM LEASING - AP
281 ALEXANDRA ROAD
AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

AUTHORISED REPRESENTATIVE

ORIGINAL

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Jan 2018 12:15		17 Jan 2018 11:17 Edit Adj Rpt	S\$20,708.92 Edit Estimates	S\$20,708.92 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TAN TOH HEAH , ID: S1295968J, Tel: +6593801103								
Vehicle Reg. No.:	SKK1215C	Date of Loss:	13/01/2018 00:00 - :59 [55 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 1436770649SG	Policy/Cover Note No.:	2100342574 (Comprehensive)						
		Excess:	S\$800.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Daily Amri, Mimi Zarina] MimiZarina.DailyAmri@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 26/01/2018]								
Driver/Custodian:	TAN JIAN'EN JULIAN @ GOH JULIAN (25 / Male), NRIC: S9231362Z, Tel: +6590224333								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (27/03/2018): Alert - Adj Mandate Approved (S\$20708.92) - SKK1215C - Claim Handler: Daily Amri... - AIG_SG (17/01/2018): Alert - Adj Mandate Approved (S\$19952.50) - SKK1215C - Claim Handler: Daily Amri... - AIG_SG (17/01/2018): SKK1215C / OD / 13/01/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS ☐ View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKK1215C (1436770649SG)
 OD
 Jan 13 2018 12:00AM
 [TAN TOH HEAH]
 Premium Automobiles Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser v	
Assessment Reports						1 per page v	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	17/01/18 13:45	Adjuster Immediate Advice		 Load HTM			
Photos/Images						3 per page v	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	17/01/18 12:25	General View		 Load JPG	☒		
2	17/01/18 12:25	General View		 Load JPG	☒		
3	17/01/18 12:25	General View		 Load JPG	☒		
4	17/01/18 12:25	General View		 Load JPG	☒		
5	17/01/18 12:25	General View		 Load JPG	☒		
6	17/01/18 12:25	General View		 Load JPG	☒		
7	17/01/18 12:25	General View		 Load JPG	☒		
8	17/01/18 12:25	General View		 Load JPG	☒		
9	17/01/18 12:25	General View		 Load JPG	☒		
10	17/01/18 12:25	General View		 Load JPG	☒		
11	17/01/18 12:25	General View		 Load JPG	☒		
12	17/01/18 12:25	General View		 Load JPG	☒		
13	17/01/18 12:25	General View		 Load JPG	☒		
14	17/01/18 12:25	General View		 Load JPG	☒		
15	17/01/18 12:25	General View		 Load JPG	☒		
16	17/01/18 12:26	General View		 Load JPG	☒		
17	17/01/18 12:26	General View		 Load JPG	☒		
18	17/01/18 12:26	General View		 Load JPG	☒		
19	17/01/18 12:26	General View		 Load JPG	☒		
20	17/01/18 12:26	General View		 Load JPG	☒		
21	17/01/18 12:26	General View		 Load JPG	☒		
22	17/01/18 12:26	General View		 Load JPG	☒		
23	17/01/18 12:26	General View		 Load JPG	☒		
24	17/01/18 12:26	General View		 Load JPG	☒		
25	17/01/18 12:26	General View		 Load JPG	☒		
26	17/01/18 12:26	General View		 Load JPG	☒		
27	17/01/18 12:26	General View		 Load JPG	☒		
28	17/01/18 12:26	General View		 Load JPG	☒		
29	17/01/18 12:26	General View		 Load JPG	☒		
30	19/03/18 18:40	Reinspection Photo		 Load JPG	☒		
31	19/03/18 18:40	Reinspection Photo		 Load JPG	☒		
32	19/03/18 18:40	Reinspection Photo		 Load JPG	☒		
33	19/03/18 18:40	Reinspection Photo		 Load JPG	☒		
34	19/03/18 18:40	Reinspection Photo		 Load JPG	☒		
35	19/03/18 18:40	Reinspection Photo		 Load JPG	☒		

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
37	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
38	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
39	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
40	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
41	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
42	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
43	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
44	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
45	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
46	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
47	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
48	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
49	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
50	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
51	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
52	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
53	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
54	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
55	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
56	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
57	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
58	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
59	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
60	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
61	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
62	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
63	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
64	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
65	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
66	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
67	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
68	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
69	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
70	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
71	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
72	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
73	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
74	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
75	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
76	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
77	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
78	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
79	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
80	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
81	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
82	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
83	19/03/18 18:40	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	17/01/18 12:28	Singapore Accident Statement		Load PDF
2	17/01/18 12:28	Certificate of Insurance		Load PDF
3	17/01/18 12:29	Driver's Driving License		Load PDF
4	17/01/18 12:29	ESTIMATE		Load PDF
5	20/03/18 10:17	1ST ESTIMATE		Load PDF
6	23/03/18 17:18	Supplementary		Load PDF
7	16/04/18 09:04	Workshop Invoice		Load PDF
8	16/04/18 09:04	Discharge Voucher		Load PDF

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail Print
1	15/01/18 15:57	Accident Statement		Load HTM
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail Print
1	15/01/18 15:57	Accident Photo		Load JPG ☒
2	15/01/18 15:57	Accident Photo		Load JPG ☒
3	15/01/18 15:57	Accident Photo		Load JPG ☒
4	15/01/18 15:57	Accident Photo		Load JPG ☒
5	15/01/18 15:57	Accident Photo		Load JPG ☒
6	15/01/18 15:57	Accident Photo		Load JPG ☒
7	15/01/18 15:57	Accident Photo		Load JPG ☒
8	15/01/18 15:57	Accident Photo		Load JPG ☒
9	15/01/18 15:57	Accident Photo		Load JPG ☒
10	15/01/18 15:57	Accident Photo		Load JPG ☒
11	15/01/18 15:57	Accident Photo		Load JPG ☒
12	15/01/18 15:57	Accident Photo		Load JPG ☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail Print
1	15/01/18 15:29	Sketch Plan		Load JPG ☒
2	15/01/18 15:29	Sketch Plan #2		Load JPG ☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18001013/AVBE2

Date: 16/04/2018

REFERENCE

Insured/Claimant: TAN TOH HEAH Policy No: 2100342574
Date of Loss: 13/01/2018 Nature of Claim: OD Claim No: 1436770649SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKK1215C**
Make & Model: AUDI A4, 2.0 (A) Engine No: CDN331188
Reg. Date: 11/06/2013 (Man. Year: 2013) Chassis No: WAUZZZ8K6DA212647
Colour: Bronze Odometer: 49606 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$98,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 255/35 R19 Rear Tyre Size: 255/35 R19
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,667.00	13,856.92	8,810.08	38.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,352.00	6,852.00	3,500.00	33.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	33,019.00	20,708.92	12,310.08	37.28
- Excess (\$\$)	800.00	800.00	0.00	0.00
(\$\$)	32,219.00	19,908.92	12,310.08	38.21
+ GST 7.00/7.00% (\$\$)	2,255.33	1,393.62	861.71	38.21
Nett Amount (\$\$)	34,474.33	21,302.54	13,171.79	38.21

INSPECTION

Date of Assignment: 17/01/2018
Date Inspected: 16/01/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 11.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Distorted	2,420.00 FS	*1,936.00 FS
2	1	*FRONT BUMPER CLOSING ELEMENT - LOWER CTR	Not Necessary	195.00 FS	*- FS
3	1	*FRONT BUMPER GRILLE - LOWER CTR	Not Necessary	287.00 FS	*- FS
4	1	*FRONT BUMPER CLOSING ELEMENT - UPPER CTR	Necessary	167.00 FS	*133.20 FS
5	1	*RADIATOR GRILLE	Cracked	956.00 FS	*764.80 FS
6	1	*FRONT REINFORCEMENT BEAM	Bent	770.00 FS	*616.00 FS
7	4	*REINFORCEMENT BEAM BOLT	Not Necessary	47.00 FS	*- FS
8	2	*FRONT REINFORCEMENT BEAM BRACKET - LH/RH	Not Necessary	390.00 FS	*- FS
9	2	*FRONT BUMPER SUPPORT - LH/RH	Damaged	21.00 FS	*16.80 FS
10	2	*FRONT BUMPER GUIDE - LH/RH	Not Necessary	62.00 FS	*- FS
11	1	*FRONT BUMPER TOP COVER	Deformed	109.00 FS	*87.20 FS
12	1	*CAUTION STICKER	Necessary	12.00 FS	*9.28 FS
13	1	*FRONT BUMPER FOAM - INNER	Cracked	107.00 FS	*85.20 FS
14	1	*FRONT BUMPER GRILLE - LH / RH	O/S Missing	1,012.00 FS	*404.40 FS
15	1	*FRONT FENDER - LH/RH	O/S Buckled	1,720.00 FS	*688.00 FS
16	2	*FRONT FENDER BRACKET - FRONT LH / RH	Not Necessary	92.00 FS	*- FS
17	2	*FRONT FENDER BRACKET - REAR LH / RH	Not Necessary	86.00 FS	*- FS
18	1	*SET FRONT FENDER RIVET	Not Necessary	24.00 FS	*- FS
19	2	*FRONT FENDER BRACE - LH/RH	Not Necessary	206.00 FS	*- FS
20	1	*FRONT FENDER STONE CHIP GUARD - LH/RH	O/S Necessary	78.00 FS	*31.20 FS
21	1	*FRONT FENDER S-LINE INSCRIPTION	O/S Necessary	215.00 FS	*86.00 FS
22	2	*HEADLIGHT - LH/RH	Cracked	4,152.00 FS	*3,321.60 FS
23	2	*HEADLIGHT BRACKET - LH/RH	Cracked	184.00 FS	*147.04 FS
24	2	*HEADLIGHT MOUNTING - LH / RH	Cracked	206.00 FS	*164.80 FS
25	2	*HEADLIGHT WASH CYLINDER - LH/RH	N/S Cracked	368.00 FS	*147.20 FS
26	2	*WASH CYLINDER ELBOW FITTING	Not Necessary	45.00 FS	*- FS
27	1	*BONNET	Buckled	2,357.00 FS	*1,885.60 FS
28	1	*BONNET PROTECTIVE FILM- FRONT	Necessary	40.00 FS	*31.28 FS
29	2	*BONNET HINGE - LH/RH	Not Necessary	130.00 FS	*- FS
30	1	*BONNET CATCH HOOK	Bent	122.00 FS	*97.60 FS
31	1	*BONNET EDGE PROTECTION - FRONT	Necessary	24.00 FS	*18.88 FS
32	1	*BONNET LOCK	Damaged	188.00 FS	*150.40 FS
33	1	*STICKER FOR AIR CONDITIONER	Necessary	21.00 FS	*16.16 FS
34	1	*FRONT LOCK CARRIER	Cracked	891.00 FS	*712.80 FS
35	2	*FRONT LOCK CARRIER AIR GUIDE - LH/RH	Deformed	44.00 FS	*34.72 FS
36	1	*A/C CONDENSER	Bent	651.00 FS	*520.40 FS
37	1	*A/C CONDENSER VALVE	Damaged	46.00 FS	*36.40 FS
38	1	*A/C CONDENSER PRESSURE SENSOR	Damaged	165.00 FS	*132.00 FS
39	1	*CHARGE AIR COOLER	Dented	492.00 FS	*393.60 FS
40	1	*COOLANT RADIATOR	Dented	1,206.00 FS	*964.80 FS
41	1	*SET RADIATOR RUBBER BUSH	Not Necessary	41.00 FS	*- FS
42	2	*RADIATOR SUPPORT - LH/RH	Not Necessary	66.00 FS	*- FS
43	1	*COOLANT	Necessary	133.00 FS	*106.24 FS
44	1	*TWIN FANRING	Not Necessary	226.00 FS	*- FS
45	1	*RADIATOR FAN - 400MM	Not Necessary	772.00 FS	*- FS
46	1	*RADIATOR FAN - 350MM	Not Necessary	667.00 FS	*- FS
47	1	*FRONT NUMBER PLATE	Bent	25.00 FS	*25.00 FS
48	1	*SUNDRIES	Necessary	400.00 FS	*92.32 FS
49	1	*OUTER TEMPERATURE SEN.BRACKET	Not Necessary	15.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*A/C PRESSURE SENSOR CONNECTOR	Not Necessary	14.00 FS	*- FS
F=Franchise part. S=SpcNett.						
				Total Parts (S\$)	22,667.00	13,856.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, CHARGED AIR COOLER, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM / REGAS AND TO PRESSURISE COOLING SYSTEM	New	1,100.00	1,100.00
3	TO DISMANTLE FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND HEADLIGHTS. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW DAMAGED PANELS. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,400.00	3,000.00
4	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS AND BONNET AND HINGES	New	3,300.00	2,200.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			10,352.00	6,852.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >