



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2017 HONDA VEZEL 1.5 (SLP4366S)

Date of Loss

11 January 2018

Time of Loss

13.25

Loss Description

SLP4366S (INSD) C/W SLR1438C(TP)

Comment

Workshop Details

Total Rebate Amount

54413

Nett Loss Amount

\$40,587.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

06/05/2018



Days of work completion *

109



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SLP4366S

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

05/06/2017



Mileage

Age of Vehicle

0

CATEGORY

Manufacturing Year

Driver Details

POLICY INFORMAT... 2017

CATEGORY

Driver Name

ASSESSMENT INFO...

2017

FNOL INFORMATI...

TAN CHUAN MUAN

CATEGORY Make

POLICY INFORMAT... HONDA

ASSESSMENT INFO... HONDA

CATEGORY Model

POLICY INFORMAT... VEZEL 1.5

ASSESSMENT INFO... VEZEL HYBRID 1.5X AUTO

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... RU31245249

POST SURVEY INF...

CATEGORY Date of Birth

FNOL INFORMATI... 27 November 1952

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 65

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO...

CATEGORY Engine No

POLICY INFORMAT... LEB5945266

ASSESSMENT INFO...

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO...

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO...

FNOL INFORMATI... 47

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI... 1 January 1971

POST SURVEY INF... 

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY Address

FNOL INFORMATI... BLK 461 CHOA CHU KANG AVE 4 #03-81, 680461, Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Personal Correspondence

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Male

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

S0136746C



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

17/01/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

700

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

215/60R16

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

215/60R16

Front left side

DUNLOP8mm

Rear left side

DUNLOP8mm

Front right side

DUNLOP8mm

Rear right side

DUNLOP8mm



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

Add

Approve

Deny

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)
		1	1			FRONT BUMPER			Deformed	1127.5		20		902	Review
		2	1			FRONT BUMPER SIDE RETAINERS N/S			Damaged	43		20		34.4	Review
		3	1			FRONT BUMPER SIDE RETAINERS O/S			Serviceable	0	0	0	0	0	Deny
		4	1			FRONT BUMPER TOW HOOD COVER			Serviceable	0	0	0	0	0	Deny
		5	1			FRONT BUMPER LOWER GRILLE			Serviceable	0	0	0	0	0	Deny
		6	2			FRONT BUMPER FOG LAMPS			Serviceable	0	0	0	0	0	Deny
		7	2			FRONT BUMPER FOG LAMP GRILLES			Serviceable	0	0	0	0	0	Deny
		8	1			FRONT BUMPER LOWER DIFFUSER			Serviceable	0	0	0	0	0	Deny
		9	1			FRONT BUMPER REINFORCEMENT			Serviceable	0	0	0	0	0	Deny
		10	1			HEADLAMP N/S			Cracked	1995.4		20		1596.32	Review
		11	1			HEADLAMP O/S			Serviceable	0	0	0	0	0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		12	2			HEADLAMP LOWER BRACKETS			Serviceable	0	0	0	0	0	Deny
		13	1			FRONT GRILLE			Damaged	350		20		280	Review
		14	1			FRONT GRILLE EMBLEM			Necessary	43.3		20		34.64	Review
		15	1			BONNET			Repair	0	0	0	0	0	Deny
		16	2			BONNET HINGES			Repair	0	0	0	0	0	Deny
		17	1			LH FRONT FENDER			Repair	0	0	0	0	0	Deny
		18	1			LH FRONT FENDER INNER SHIELD			Serviceable	0	0	0	0	0	Deny
		19	1			LH FRONT FENDER ARCH GARNISH			Serviceable	0	0	0	0	0	Deny
		20	1			FRONT SUPPORT PANEL TOP GARNISH			Serviceable	0	0	0	0	0	Deny

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	RI
		1		CHECK ELECTRICAL WIRINGS AND HEADLAMP FOCUS	30	0	0	Reviewing		1
		2		REPAIR DAMAGES AND RENEW PARTS	400	0	0	Reviewing		1
		3		SPRAY PAINT ON AFFECTED PORTIONS	540	0	0	Reviewing		1

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Add

Approve

Deny

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	DAYS OF REPAIR : 4 DAYS	Reviewing			
		2	FRONT GRILLE TOP GARNISH (DISC 20%)	Reviewing	316.16	(CRACKED) SUPPLEMENTARY	
		3	SET FRONT BUMPER CLIPS	Reviewing	35	NECESSARY	

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount \$3,468.52

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$970.00	\$970.00
Spare Parts	\$2,847.36	\$2,847.36
Miscellaneous	\$351.16	\$351.16
Excess	-\$700.00	-\$700.00

Submit for Review