

ASSIGNMENT

Surveyor:

Kenneth

DOI:

17-01-18

Date / Time:

17-01-18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GRD 991 U

Name of Insured:

MINDX VALVES & FITTINGS P/L

Insured Tel No.:

HP:

Excess Sec II : SS

D.O.A.:

15/01/18

Is driver the owner?

(YES / ☒ NO)

Nature of Accident:

If NO, Driver Name / Age:

SAHARUDIN BN ISMAIL

Driver Tel No.:

97928308

(V/L: ☒ YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

DMCPH17-002624

MSPAN CARIAT

10 KAPI BUKIT ROAD 2 7 WOODLAND

OI GIA REPORT: ☒ YES / NO ; TP GIA REPORT: ☒ YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

LHMK



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

17/1/18

SOT 991A. 04/11/17 13:30/18/21/22; 04/11/18

GRD 991 U. X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List / Handler / Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher: NO DV

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / ^(*):

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

10:08 @ am.

Spoke to OI (Mr Saharudin). Confirmed accident details and OI received info opposite lane and collided onto opposite lane and collided onto TP vehicle. OI will send an additional photo via email. Informed abt TP claim, award of RMK claim and agree to settle. Send letter to OI.

18-12-18

LUD IN. FOR MANDATE

MANDATE APPROVED

TP ACCEPTED OFFER.

ALL DOCS IN ORDER.

TO CLOSE.

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

P/P

SS 7,471.30

(11 days)

Reduction:

15 %

Email ☐Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

JENNY

Email ☒Call ☐

Final Liability:

% 100

(Agreed / Assessed)

BOLA S/N No.: 416

If NO or B 28, Ass. Lia:

Repair Cost:

SS

7,994.24

Loss of Rental (LOR):

SS

-

(days)

Loss of Use (LOU):

SS

1,400.00 x 14 days

Loss of Income (LOI):

SS

-

(\$ x days)

LOR only ☐LOU only ☒LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

7.49

Medical:

SS

-

Disbursement:

SS

-

Legal Cost

SS

-

Total:

SS

9,401.78

Global Sum SS:

9,200.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐Call ☐

Payee 1:

SS

9,200.00

Name 1:

LAI HUI (CHENG KEE) MOTOR PTE LTD

Payee 2: (Strike if N.A.)

SS

-

Name 2:

-

Payee 3: (Strike if N.A.)

SS

-

Name 3:

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

17/7

400.00

EQI

09 10

17/01/2018

SDJ 901A

Estimate/Order

02 12 WS TR RES CO RES EVA INV MS

To: 2007 VEHIC

SDJ 901A

At: 160 Sin Ming Drive #04-01/04-02

Lai Huet (Meng Kee)

Phone:

Fax:

Damage:

Sum Insured


Excess

Damage Paid:

Make of Van

Policy Condition

Remark: The van had commenced its repair at the time of inspection.



Seller/Owner/Lease

C/O Accident Report Consistent? Yes or No

C/O PP Book Consistent? Yes or No

Est. Repair 11 days Fee Yes or No

Lmt Sum 1.81 k 3 Yr Yes or No

C/O REV REP 24 HRS ^{wp}

Date Person Contacted

Vehicle IN/OUT

Type: Car/Motor Bus Van/Truck/Bus Small Motor

Truck/Tractor

Year

Lexus A 15250 2500

Color

M. Black

Seating

111945

Eng No

CNC

JTHBK 262502100394

Car Type: 2000 Pet Pet/Burnt

Seating: Injured Jammed Leaked/Burnt

Brake: Injured Jammed Leaked/Burnt

Mod: Nil (S/R) STC (R) or

Tire Size: R

245/45R17

ES/DUN/EXNOVA/GY/PS/LIZA/MIC/O-TSU/PIR/BLM

TOYOTA/DAIHATSU

Front

Rear

R/R

R/R

L/R

L/R

C/O

C/O

Surveyed at:

Des of Damages: Frt. Res: OS NS UC Roched or

old body

The U/C Chassis frame Body Structure affected due to collision

Date Time Action Instruction

18/11 File pass to Carter

PLP

7,471.30

Cred: 1,324.00/15%

See The Report



Prel. Report



Final Report

See The Report

Days Of Repair

Resurvey No. of Trc

Link Fee

Add Fee

Add Fee



See Net



See Net



See Net



See Net

Repair Report

Repair Report



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 4715G

Vehicle Details

Vehicle No.: SDJ901A
Vehicle to be Exported: Yes
Intended De-registration Date: 15 Jan 2018
Vehicle Make: TOYOTA
Vehicle Model: LEXUS IS250 AUTO STD
Primary Colour: Purple
Manufacturing Year: 2010
Engine No.: 4GR0693622
Chassis No.: JTHBK262502100394
Maximum Power Output: 153.0 kW (205 bhp)
Open Market Value: \$38,845.00
Original Registration Date: 30 Sep 2010
First Registration Date: 30 Sep 2010
Transfer Count: 0
Actual ARF Paid: \$38,845.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 29 Sep 2020
PARF Rebate Amount: \$23,307.00

Intended COE Rebate Details

COE Expiry Date: 29 Sep 2020
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$43,334.00
COE Rebate Amount: \$11,724.00
Total Rebate Amount: \$35,031.00

The information contained herein is correct as at 15 Jan 2018

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST No EST0018317
Liong Julia

Page 1 of 3
Your ref TP-GBD 991U EQ
Job No 69156
Our ref 18.01.26
Payment
Date 16/1/2018

Attn

Vehicle No SDJ 901A
Vehicle Model Lexus IS250
Accident on 15/1/2018

*Not Authorized
Survey By phone
1/1 days*

Quantity	Unit	Description	Unit price	Disc. pct	Amount
Supply of Parts					
1.00	Pc	Front fender RH	300.00		300.00
1.00	Pc	Front fender garnish upright RH	38.00		38.00
1.00	Pc	Front door RH	450.00		450.00
1.00	Pc	Front door weatherstrip RH	110.00		110.00
1.00	Pc	Front door lock RH	195.00		195.00
1.00	Pc	Front door lock cover gasket RH	8.00		8.00
1.00	Pc	Front door lock outer handle RH	165.00		165.00
1.00	Pc	Front door outer lock cover (key) RH	20.00		20.00
1.00	Pc	Front door outer lock (key) RH	125.00		125.00
1.00	Pc	Front door glass RH	280.00		280.00
1.00	Pc	Front door glass outer moulding RH	65.00		65.00
1.00	Pc	Front door window frame garnish RH	50.00		50.00
1.00	Pc	Front door wing mirror RH	480.00		480.00
1.00	Pc	Front door glass regulator RH	105.00		105.00
1.00	Pc	Front door hinge, top RH	33.00		33.00
1.00	Pc	Front windscreen side moulding RH	50.00		50.00
1.00	Pc	Front door window glass channel rubber RH	75.00		75.00
1.00	Pc	Rear door RH	350.00		350.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

Acknowledged by Repairer

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0018317
Liong Julie

Page 2 of 3
Your ref TP-G8D 991U EQ
Job No 69156
Our ref 18.01.26
Payment
Date 18/1/2018

Attr

Vehicle No SDJ 901A
Vehicle Model Lexus IS250
Accident on 15/1/2018

Quantity	Unit	Description	Unit price	Disc. pct	Amount	
1.00	Pc	Rear door glass outer moulding RH	65.00		65.00	✓
1.00	Pc	Rear door glass RH	200.00		200.00	✓
1.00	Pc	Rear door window frame garnish RH	65.00		65.00	✓
1.00	Pc	Rear fender RH	420.00		420.00	✓
1.00	Pc	Rear fender stone guard decal RH	18.00		18.00	✓
1.00	Pc	Rear windscreen moulding	55.00		55.00	✓
Total amount of parts supplied - S\$3,722.00						
1.00		15% of parts supplied	558.30		558.30	
Labour & Misc						
1.00		Towing fee	105.00		105.00	✓
1.00		To reset fault code	50.00		50.00	✓
1.00		To remove + renew rear windscreen	140.00		140.00	✓
1.00		To supply rear windscreen sealant	40.00		40.00	✓

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大快修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST No: EST0018317
Liong Julie

Page 3 of 3
Your ref: TP-GBD 991U EQ
Job No: 69156
Our ref: 18 01 26
Payment
Date: 16/1/2018

Attn:

Vehicle No: SDJ 901A
Vehicle Model: Lexus IS250
Accident on: 15/1/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To remove + refix roof top lining	180.00		180.00 <i>12d</i>
1.00		To check wheel alignment	80.00		80.00 <i>6d</i>
1.00		Tuff coat	160.00		160.00 <i>12d</i>
1.00		To dismantle + refix rear passenger seat, speaker board, rear fender inner trim, carpet, etc	160.00		160.00 <i>14d</i>
1.00		To straighten side body including cutting and welding, to knock dents on rear fender inner panel RH, rear door centre pillar RH, front windscreen side frame RH and renew of parts	1,800.00		1,800.00 <i>140d</i>
1.00		To spray paint	1,800.00		1,800.00 <i>150d</i>
Sub-Total					8,795.30
GST 7.00%					615.67
Total				SS	9,410.97

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大快修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

TAX INVOICE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg


Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6531 1388

Account Detail	Account No	Customer Detail
Bodyshop Retail Cash Sales LXR TCBC Lexus Bodyshop Retail Cash Sales LXR TCBC Lexus	c0110036 / FBPLEX Document No 36004720 Document Date 15/01/2018	Ms Liang Julie 15 Upper Boon Keng Road #02-1057 Singapore 380015 Mobile: 96698478

Year	Make	Model	Reg Date	Vch Reg No	Kilometers	WIP No	Order No/Remarks
10	AETLHW	S2	GSE20R	30/09/2010	SDJ0901A	107787	14885 61TOW/SDJ0901A
Chassis No	Engine No	TWC No	Term	Lexus Consultant	Vehicle In	Collected On	
JTHBK262502100394	4GR0693622	00	Carine Yeo C L	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TOWING FEE				105.00
2	T	RECORD FOR RECORD PURPOSE. - TOWED OUT DUE TO POLICY CONDITION - AIG AUTO PLUS POLICY				

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 0.00	105.00
		Labour 105.00	GST 7.00% 7.35
		Materials 0.00	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 112.35

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 15/01/2018
TIME 14:12

VEHICLE NO SDJ0901A

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Thank you



Lai Mei Ling Deborah has successfully logged out.

Your last login date and time was 16 Jan 2018, 09:08:55.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

<u>S/No.</u>	<u>Asset Type</u>	<u>Asset ID</u>	<u>Asset Owner ID</u>	<u>Transaction Type</u>	<u>Transaction Amount(S\$)</u>	<u>Log Date/Time</u>
1	Vehicle	GBD991U	-	18.32 Insurance Enquiry (GIRO Payment)	7.49	16 Jan 2018 / 09:11:19

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Wednesday, 17 January 2018 9:02 AM
To: assignments
Subject: FW: Request for Survey - Your Ref: GBD991U / Our Ref: SDJ901A (Date of Accident: 15.01.2018)
Attachments: SDJ 901A.PDF; SDJ901A 15.01.2018.pdf; GBD991U 15.01.2018.pdf

9:13am @ 17/01/2018
vehicle in
person @ Jenny
sur @ Kenneth

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Bazlin Ahmad [mailto:bazlin.ahmad@eqinsurance.com.sg]
Sent: Wednesday, 17 January 2018 8:58 AM
To: Admin A <admin-a@lkkauto.com>
Cc: Elaine Cheong <elaine.cheong@eqinsurance.com.sg>
Subject: RE: Request for Survey - Your Ref: GBD991U / Our Ref: SDJ901A (Date of Accident: 15.01.2018)

Dear LKK

We refer to the above new assignment. Please find below email and attachments for easy reference.
Case OIC is Ms Elaine Cheong.

Thank You.

Regards,

Lynn Ahmad

Executive | Claims

eqnsurance

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6496 9881 | tel 65 6223 9433 ext 881 | fax 65 6223 4190

www.eqinsurance.com.sg

 A Member of Citystate

 you've got a friend

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

From: Jenny Lim [mailto:jenny.lim@laihuat.com.sg]
Sent: Tuesday, January 16, 2018 6:25 PM

To: Bazlin Ahmad

Subject: RE: Request for Survey - Your Ref: GBD 991U / Our Ref: SDJ 901A (Date of Accident: 15.01.2018)

Dear Bazlin

Please arrange LKK to survey.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267

From: Bazlin Ahmad [<mailto:bazlin.ahmad@eqinsurance.com.sg>]

Sent: Tuesday, 16 January, 2018 5:51 PM

To: Jenny Lim

Subject: RE: Request for Survey - Your Ref: GBD 991U / Our Ref: SDJ 901A (Date of Accident: 15.01.2018)

Without Prejudice

Dear Sir,

We refer to your Notice of Accident of even date.

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please revert within 2 working days if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd Tel: 6255 0808 Fax: 6849 9155 Contact person : Joey/Joseh	2) Automobile Inspection Services Pte Ltd Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia
3) LBS Automotive Appraisal Pte Ltd L.B.S. Auto Consultants Pte Ltd Tel: 6281 6690 / 62832866 Fax: 6281 8748 Contact Person: Amy/ Grace	4) Priority Services Tel: 62934822 Fax: 62963283 Contact Person: Sharon Kho

5) RT Appraisal Pte Ltd Tel: 67486076 Fax: 67480361 Contact Person: Ricky Teng	6) LKK Auto Consultants Pte Ltd Tel: 6256-3561 Fax: 6741-4108
7) Kelvin Automotive Appraising Services Tel: 81825263 Fax: 67461148 Contact Person: Kelvin	8) Automotive Appraiser & Surveying Services Tel: 96623655 Fax: 67655662 Contact Person: Mr Chee
9) JP Knights Pte Ltd Tel: 63450068 Fax: 63445328 Contact Person: Edna Lee	

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Thank You.

Regards,

Lynn Ahmad

Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block, MND Complex, Singapore 069110

did 65-6496 9881 | tel 65 6223 9433 ext 881 | fax 65 6223 4190

www.eqinsurance.com.sg

 A Member of Citystate



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

From: Jenny Lim [<mailto:jenny.lim@laihuat.com.sg>]

Sent: Tuesday, January 16, 2018 4:55 PM

To: Bazlin Ahmad

Subject: Request for Survey - Your Ref: GBD 991U / Our Ref: SDJ 901A (Date of Accident: 15.01.2018)

Importance: High

Without Prejudice

Dear Bazlin

We refer to the above matter.

Please can you arrange for survey of our client's vehicle no. SDJ 901A?

Our client's vehicle is in workshop and supporting documents are enclose for your reference.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267

Mei Kwan (LKKAUTO)

From: Mei Kwan (LKKAUTO)
Sent: Friday, 19 January, 2018 8:39 AM
To: 'Elaine Cheong'
Cc: Hsiao Tong (LKKAUTO); Zaini (LKK Auto); Admin A; 'Bazlin Ahmad'
Subject: RE: Request for Survey - Your Ref: GBD991U / Our Ref: SDJ901A (Date of Accident: 15.01.2018)
Attachments: Preliminary Advice.pdf; TP ESTIMATE + TOWING.pdf; LKK SURVEY PHOTO.pdf
Categories: HMK

WITHOUT PREJUDICE

Your ref: TBA
LKK ref: CC4/EQ118001027/Kka3

Dear Elaine,

We refer to the above matter.

This is a third party direct settlement case.

Enclosed revert of vehicle: SDJ 901A

Date of survey: 17.01.2018

Enclosed for your perusal is:

- TP estimate (marked)
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

We have not authorized repairs.

Kindly take note that the case handler in-charge is Zaini and he can be contacted at DID: 6841 2132.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 17 January, 2018 9:16 AM
To: 'Bazlin Ahmad' <bazlin.ahmad@eqinsurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: Request for Survey - Your Ref: GBD991U / Our Ref: SDJ901A (Date of Accident: 15.01.2018)

Dear Sir/Mdm,

Thank you for the assignment.

From: Bazlin Ahmad [mailto:bazlin.ahmad@eqinsurance.com.sg]

Sent: Tuesday, 16 January, 2018 5:51 PM

To: Jenny Lim

Subject: RE: Request for Survey - Your Ref: GBD 991U / Our Ref: SDJ 901A (Date of Accident: 15.01.2018)

Without Prejudice

Dear Sir,

We refer to your Notice of Accident of even date.

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please revert within 2 working days if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd Tel: 6255 0808 Fax: 6849 9155 Contact person : Joey/Joseh	2) Automobile Inspection Services Pte Ltd Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia
3) LBS Automotive Appraisal Pte Ltd L.B.S. Auto Consultants Pte Ltd Tel: 6281 6690 / 62832866 Fax: 6281 8748 Contact Person: Amy/ Grace	4) Priority Services Tel: 62934822 Fax: 62963283 Contact Person: Sharon Kho
5) RT Appraisal Pte Ltd Tel: 67486076 Fax: 67480361 Contact Person: Ricky Teng	6) LKK Auto Consultants Pte Ltd Tel: 6256-3561 Fax: 6741-4108
7) Kelvin Automotive Appraising Services Tel: 81825263 Fax: 67461148 Contact Person: Kelvin	8) Automotive Appraiser & Surveying Services Tel: 96623655 Fax: 67655662 Contact Person: Mr Chee

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267

來發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722
Tel: 64538110 Fax: 64596267
UEN: 199407592C

Your Ref: GBD 991U
Our Ref: SDJ 901A - 2018/JL

16 November 2018

EQ Insurance Company Ltd
5 Maxwell Road
#17-00 Tower Block
MND Complex
Singapore 069110
Attention: Motor Claims

WITHOUT PREJUDICE

Dear Sir

ACCIDENT INVOLVING VEHICLE NOS. SDJ 901A AND GBD 991U ON 15/01/2018 AT KAKI BUKIT ROAD 2

We refer to the above matter wherein your insured's vehicle no. GBD 991U was involved in an accident with our client's vehicle no. SDJ 901A.

As the accident was caused by your insured's negligence, our client is now claiming for the following losses:

- Repair cost: \$7,994.29 (include GST)
- Loss of use: \$1,500.00 (15 days x \$100 per day)
- LTA search fee: \$ 7.49
- Total: \$9,501.78**


Relevant documents in support of our client's claim are enclosed for your reference.

Please do not hesitate to contact Jenny Lim at telephone 64533757 or email jenny.lim@laihuat.com.sg should you need any additional information.

Meanwhile, we look forward to receiving your affirmative response soon enough.

Thank you.

Yours faithfully



LAI HUAT (MENG KEE) MOTOR PTE LTD

encs



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC4/EQ118001027/Kka3

24 JANUARY 2018

MINOX VALVES & FITTINGS PTE LTD
32 OLD TOH TUCK ROAD
#04-01
SINGAPORE 597658
ATTN: HR / MANAGEMENT

Dear Sir/Madam,

ACCIDENT INVOLVING GBD 991U AND SDJ 901A ON 15.01.2018

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,


Zaini
Case Handler
DID: 6841 2132
FAX: 6741 4108
Email: Zaini@lkkauto.com

c.c. **EQ INSURANCE COMPANY LIMITED**
(Motor Claims Dept)

LETTER OF AUTHORITY

To: Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722

Dear Sirs

ACCIDENT INVOLVING VEHICLE NOS: SDJ 901A & GBD 991U ON 15/01/2018
AT KAKI BUKIT ROAD 2

This is to confirm that on 15/01/2018, I / We gave you instructions to repair my / our vehicle no. SDJ 901A which was damaged in the above accident.

In consideration of your agreement to repair my vehicle no. SDJ 901A, pay for my other expenses and to defer demanding for payment of the costs of repair which was damaged as a result of the above accident, I / We hereby authorise you and/or your solicitors as my / our representative to write, negotiate and settle the accident claim on my / our behalf against any part involved in the abovementioned accident.

I / We hereby undertake to co-operate with you and render you all the assistance (including having my / our vehicle re-inspected and being a witness at trial) that may be necessary for you to recover the cost of repairs and the loss of use to my / our vehicle. I / We further undertake to keep you informed at all times of any communication received from any party involved in the abovementioned accident.

I / We hereby confirm that by signing this Letter of Authority, I / We are not entitled in law to receive any payment. If a cheque is sent to me, I / We shall return the same to the sender as I am precluded in law from accepting any payment.


In the event of my / our claim against any party involved in the abovementioned accident being unsuccessful for any reason whatsoever, I / We shall bear the repair / excess cost payable to Lai Huat (Meng Kee) Motor Pte Ltd either by cash / cheque or claim against my / our insurance policy.

I / We hereby authorise the payment of my / our claim (including any or all medical related invoices / receipts) to be made directly to my / our representative, Lai Huat (Meng Kee) Motor Pte Ltd accordingly.

In relation to the personal and vehicle information collected or otherwise provided during the course of the claim process (including by way of recordings), I agree and consent that Lai Huat (Meng Kee) Motor Pte Ltd may use, disclose and process my personal data for the purpose of responding and administering all activities related to my insurance claim.

Yours faithfully

Signature:



Name:

Liong Julie

NRIC No:

S1814715G

来發 (明 记) 摩 哆 有 限 公 司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Sin Ming Autocity Singapore 575722. Tel: 6453 8110 Fax: 6459 6267
UEN: 199407592C

TAX INVOICE

EST No.: EST0018317
Liong Julie

GST Reg No: M2-0128609-3
Page: 1 of 3
Number: INV0020361
Your ref.: TP-GBD 991U EQ
Job No.: 69156
Our ref: 18.01.26
Payment
Date: 6/11/2018

Attn

Vehicle No: SDJ 901A
Vehicle Model : Lexus IS250
Accident on ...: 15/1/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Front fender RH	300.00		300.00
1.00	Pc	Front fender garnish upright RH	38.00		38.00
1.00	Pc	Front door RH	450.00		450.00
1.00	Pc	Front door weatherstrip RH	110.00		110.00
1.00	Pc	Front door lock RH	195.00		195.00
1.00	Pc	Front door lock cover gasket RH	8.00		8.00
1.00	Pc	Front door lock outer handle RH	165.00		165.00
1.00	Pc	Front door outer lock cover (key) RH	20.00		20.00
1.00	Pc	Front door outer lock (key) RH	125.00		125.00
1.00	Pc	Front door glass RH	280.00		280.00
1.00	Pc	Front door glass outer moulding RH	65.00		65.00
1.00	Pc	Front door window frame garnish RH	50.00		50.00
1.00	Pc	Front door wing mirror RH	480.00		480.00
1.00	Pc	Front door hinge, top RH	33.00		33.00
1.00	Pc	Front windscreen side moulding RH	50.00		50.00
1.00	Pc	Front door window glass channel rubber RH	75.00		75.00
1.00	Pc	Rear door RH	350.00		350.00
1.00	Pc	Rear door glass outer moulding RH	65.00		65.00
1.00	Pc	Rear door glass RH	200.00		200.00
1.00	Pc	Rear door window frame garnish RH	65.00		65.00
1.00	Pc	Rear fender RH	420.00		420.00

本公司拥有最先进的 CAROLINER MARK IV 机械。可提供给多种款式的车身及给于快速与准确的测量方式和大快修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明 记) 嘜 哆 有 限 公 司 LAI HUAT (MENG KEE) MOTOR PTE LTD

180 Sin Ming Drive #04-01, #04-02 & #07-03 Sin Ming Autocity Singapore 575722. Tel: 6453 8110 Fax: 6459 6267
UEN: 199407592C

TAX INVOICE

EST No.: EST0018317
Liong Julie

GST Reg No: M2-0128609-3
Page: 2 of 3
Number: INV0020361
Your ref.: TP-GBD 991U EQ
Job No.: 69156
Our ref: 18.01.26
Payment
Date: 6/11/2018

Attn

Vehicle No: SDJ 901A
Vehicle Model : Lexus IS250
Accident on ...: 15/1/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00	Pc	Rear fender stone guard decal RH	18.00		18.00
Total amount of parts supplied - S\$3,562.00					
1.00		15% of parts supplied:	534.30		534.30
Labour & Misc:					
1.00		Towing fee	105.00		105.00
1.00		To reset fault code	50.00		50.00
1.00		To check wheel alignment	60.00		60.00
1.00		Tuff coat	120.00		120.00
1.00		To dismantle + refix rear passenger seat, speaker board, rear fender inner trim, carpet, etc	140.00		140.00
1.00		To straighten side body including cutting and welding, to knock dents on rear fender inner panel RH, rear door centre pillar RH,	1,400.00		1,400.00

本公司拥有最先进的 CAROLINER MARK IV 机械。可提供给多种款式的车身及给予快速与准确的测量方式和大快修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明 记) 摩 哆 有 限 公 司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Sin Ming Autoody Singapore 575722. Tel: 6453 8110 Fax: 6459 6267
UEN: 199407592C

TAX INVOICE

EST No.: EST0018317
Liong Julie

GST Reg No: M2-0128609-3
Page: 3 of 3
Number: INV0020361
Your ref.: TP-GBD 991U EQ
Job No.: 69156
Our ref: 18.01.26
Payment
Date: 6/11/2018

Attn

Vehicle No: SDJ 901A
Vehicle Model : Lexus IS250
Accident on ...: 15/1/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
		front windscreen side frame RH and renew of parts			
1.00		To spray paint	1,500.00		1,500.00

Sub-Total 7,471.30
GST 7.00% 522.99
Total S\$ 7,994.29

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

Thank you



Lai Mei Ling Deborah has successfully logged out.

Your last login date and time was 16 Jan 2018, 09:08:55.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

<u>S/No.</u>	<u>Asset Type</u>	<u>Asset ID</u>	<u>Asset Owner ID</u>	<u>Transaction Type</u>	<u>Transaction Amount(S\$)</u>	<u>Log Date/Time</u>
1	Vehicle	GBD991U	-	18.32 Insurance Enquiry (GIRO Payment)	7.49	16 Jan 2018 / 09:11:19

Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
GBD991U	15 Jan 2018 / 10:30:00	Successful	E04	EQ INSURANCE COMPANY LTD

[Previous](#) [OK](#)

Joy Irene (LKKAuto)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Thursday, 14 March 2019 7:37 PM
To: Joy Irene (LKKAuto)
Subject: RE: INSURED GBD 991 U ON 15.01.2018 (TP SDJ 901A) (DM18HO00147-JG)

Dear Joy

Please proceed to resolve this matter up to S\$9,401.78.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Joy Irene (LKKAuto) [mailto:JoyIrene@lkkauto.com]
Sent: Wednesday, March 13, 2019 10:32 AM
To: EQI PRS
Cc: Janet Tan
Subject: INSURED GBD 991 U ON 15.01.2018 (TP SDJ 901A)

Policy No. : DMCPHQ17-002624

Dear Sirs,

This is a swerving to the other scenario. Our insured swerved/changed lane (opposite direction) to where TP was travelling straight.

We had notified OI where OI confirmed accident details, aware NCD issue and agreed to settle.

Summary to offer to repairer "LAI HUAT (MENG KEE) MOTOR PTE LTD" is as follows:

	Claimed Amount	Revised Amount
Cost of Repair	\$8,795.30 (per estimate)	\$ 7,994.29 (w/GST)
Loss of Use	\$ 1,500.00 (\$100 x 15 days)	\$ 1,400.00 (\$100 x 14 days)
LTA/GIA Search Fee	\$ 7.49	\$ 7.49

Total	\$ 10,302.79	\$ 9,401.78
--------------	---------------------	--------------------

For your approval.

Thank you.

Best Regards,

Joy Irene | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

Total Control Panel

[Login](#)

To: eqiprs@eqinsurance.com.sg

[Remove lkkauto.com from my allow list](#)

From: joyirene@lkkauto.com

You received this message because the domain lkkauto.com is on your allow list.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 01/08/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	GBD 991U (Insd Veh)	Your Ref. No. : DM18HO00147-JG
	SDJ 901A (TP Veh)	Our Ref. No. : CC4/EQI18001027/Kha3q2
Date of Accident	15/1/2018	

Liability	100%	
Final Repair Cost	: \$ 7,994.29	
Loss of Use	: \$ 1,400.00	14 days
Rental (If any)	: \$	days
Others:	: \$ 7.49	
	: \$	
	9,401.78	
Final Settlement Sum	: \$ 9,200.00	GLOBAL SUM
Remarks	:	

Payment Instruction: Payee's Breakdown

1)	LAI HUAT (MENG KEE) MOTOR PTE LTD	: \$ 9,200.00
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC4/EQ18001027/Kha3q2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 01-08-2019		
		Code : EQI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 991U	Veh. Inspected	SDJ 901A	
Policy No.	DMCPHQ17-002624	Coverage (\$)	0.00	
Claim No.	DM18HO00147-JG	Excess (\$)	0.00	
Assign From	ELAINE	Assign Date	17/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	LEXUS IS250 (A)	c.c	2500	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	JTHBK262502100394	Colour	METALLIC BLACK	
Odometer	111945	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/45 R17	BRIDGESTONE	8 mm	
L/H Front Tyre	245/45 R17	BRIDGESTONE	8 mm	
R/H Rear Tyre	245/45 R17	BRIDGESTONE	7 mm	
L/H Rear Tyre	245/45 R17	BRIDGESTONE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/01/2018	Inspection Date	17/01/2018	
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		11 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDJ 901A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT FENDER RH (WCP)	BENT	300.00	300.00
1	FRONT FENDER GARNISH UPRIGHT RH (WCP)	CRACKED	38.00	38.00
1	FRONT DOOR RH (WCP)	BENT	450.00	450.00
1	FRONT DOOR WEATHERSTRIP RH (WCP)	CUT	110.00	110.00
1	FRONT DOOR LOCK RH (WCP)	DENTED	195.00	195.00
1	FRONT DOOR LOCK COVER GASKET RH (WCP)	NECESSARY	8.00	8.00
1	FRONT DOOR LOCK OUTER HANDLE RH (WCP)	CRACKED	165.00	165.00
1	FRONT DOOR OUTER LOCK COVER (KEY) RH (WCP)	DENTED	20.00	20.00
1	FRONT DOOR OUTER LOCK (KEY) RH (WCP)	DENTED	125.00	125.00
1	FRONT DOOR GLASS RH (WCP)	CUT	280.00	280.00
1	FRONT DOOR GLASS OUTER MOULDING RH (WCP)	DENTED	65.00	65.00
1	FRONT DOOR WINDOW FRAME GARNISH RH (WCP)	DENTED	50.00	50.00
1	FRONT DOOR WING MIRROR RH (WCP)	MISSING	480.00	480.00
1	FRONT DOOR GLASS REGULATOR RH (WCP)	NOT NECESSARY	105.00	-
1	FRONT DOOR HINGE, TOP RH (WCP)	BENT	33.00	33.00
1	FRONT WINDSCREEN SIDE MOULDING RH (WCP)	DENTED	50.00	50.00
1	FRONT DOOR WINDOW GLASS CHANNEL RUBBER RH (WCP)	CUT	75.00	75.00
1	REAR DOOR RH (WCP)	BENT	350.00	350.00
1	REAR DOOR GLASS OUTER MOULDING RH (WCP)	CUT	65.00	65.00
1	REAR DOOR GLASS RH (WCP)	CUT	200.00	200.00
1	REAR DOOR WINDOW FRAME GARNISH RH (WCP)	DENTED	65.00	65.00
1	REAR FENDER RH (WCP)	BENT	420.00	420.00
1	REAR FENDER STONE GUARD DECAL RH (WCP)	NECESSARY	18.00	18.00
1	REAR WINDSCREEN MOULDING (WCP)	NOT NECESSARY	55.00	-
	COST PLUS 15%		558.30	534.30
			4,280.30	4,096.30
LABOUR				
	TOWING FEE.		105.00	105.00
	TO RESET FAULT CODE.		50.00	50.00
	TO REMOVE + RENEW REAR WINDSCREEN.	NOT NECESSARY	140.00	-

Report Ref No. CC4/EQI18001027/Kha3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SUPPLY REAR WINDSCREEN SEALANT.	NOT NECESSARY	40.00	-
	TO REMOVE + REFIX ROOF TOP LINING.	NOT NECESSARY	180.00	-
	TO CHECK WHEEL ALIGNMENT.		80.00	60.00
	TUFF COAT.		160.00	120.00
	TO DISMANTLE & REFIX REAR PASSENGER SEAT,SPEAKER BOARD,REAR FENDER INNER TRIM CARPET,ETC.		160.00	140.00
	TO STRAIGHTEN SIDE BODY INCLUDING CUTTING AND WELDING,TO KNOCK DENTS ON REAR FENDER INNER PANEL RH,REAR DOOR CENTRE PILLAR RH FRONT WINDSCREEN SIDE FRAME RH AND RENEW OF PARTS.		1,800.00	1,400.00
	TO SPRAY PAINT.		1,800.00	1,500.00
			4,515.00	3,375.00
GRAND TOTAL			8,795.30	7,471.30
RECOMMENDED COST OF REPAIRS				7,471.30

Report Ref No. CC4/EQ18001027/Kha3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Joanne Lee (LKK Auto)

From: Joanne Lee (LKK Auto) <report@lkkauto.com>
Sent: Monday, 5 August 2019 1:31 PM
To: 'Joel Goh'
Cc: 'Vic (LKKAuto)'
Subject: TP Direct Settlement - Accident Involving GBD 991U (OI) and SDJ 901A (TP) on 15/01/2018
Attachments: LKK REPORT & PHOTO.pdf; TP DS SUPPORTING DOCUMENT.pdf

Dear Sir/Madam,

Please be informed that the above-mentioned case had been settled.

Enclose herewith final report & relevant documents for your necessary action please.

Thank you.

Best Regards,

JOANNE | Reports

LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: report@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 Singapore 408933