

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1772T
Ref. No : TAX/01/18/2066
Reg. Date : 10/11/2014
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : TOH THIAM POH
Type of Accident : HEAD TO REAR
Date / Time of Accident : 11/01/2018 09:35:00 PM
Accident Reported Date / Time : 12/01/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024094059
Special Instruction to ARC,if any :
SHC5680T(TRANSCAB)AXA
Prepared Date : 12/01/2018 10:07:55 AM



Repair after repair

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U805752635

Mileage :


0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 845.00	0.00
Total Spray Painting Charges	: 1,116.00	0.00
Total Material Charges	: 2,495.94	2,495.94
Other Charges	: 600.00	0.00
TOTAL	: 5,056.94	0.00
Lum Sum Total	: 5,050.00	0.00
No. of Repair Days	: 6.00	0.00 4 days / repair
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 12/01/2018 07:08:47 PM	01/01/1900 12:00:00 AM


16/01/18 @ 1525

Prepared / Adjusted Date :

Remarks :

Prepared Date : 12/01/2018 07:08:47 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	845.00	0.00 400
Total Labour	845.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY BUMPER BEAM	180.00	0.00 100? check
TO RESPRAY REAR PANEL	180.00	0.00 100
TO RESPRAY TAIL GATE	378.00	0.00 X
Total Spray Painting & Panel Beating	1,116.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 60
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 40
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 60
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 30
Total Other Costs	600.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace <i>DE</i>	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace <i>an</i>	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace <i>?</i>	No
76087-47020		6505618	BUMPER LIP COVER RR/RH	1	118.10	25.00	88.57	Replace	Replace <i>?</i>	No
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace <i>an</i>	No
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace <i>an</i>	No
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace <i>?</i>	No
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace <i>?</i>	No
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace <i>?</i>	No
58307-47060		6505522	END PANEL	1	602.10	25.00	451.57	Replace	Replace <i>Repair</i>	No
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace <i>X</i>	No
37881-47022			TAILGATE DOOR WEATHER STRIP	1	353.40	25.00	265.05	Replace	Replace <i>X</i>	No
37005-47241			TAILGATE ASY	1	1,007.90	25.00	755.92	Replace	Replace <i>X</i>	No
39350-47030			TAILGATE DOOR LOCK	1	444.10	25.00	333.07	Replace	Replace <i>X</i>	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace <i>X</i>	No
TOTAL MATERIALS								3,119.95	3,119.92	
TOTAL MATERIALS(Discounted)							2,495.94	2,495.94		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									