

15/5/2018

INS. CASE OWNER:

CC 3

Asm

AXA

800 1034

Kpa332

LKK:

IDAC:

26915

ASSIGNMENT

Surveyor:

KSC

DOI:

16-1-18

Date / Time:

16-1-18

Registered in Merimen:

Pre-assign / CCU / FTE

SCP 3858C



Insured Vehicle No.:

Name of Insured:

MOHAMMAD AIDIL BIN MAON

Insured Tel No.:

HP:

47591984

Excess Sec II :SS

D.O.A.:

15-01-18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

S8M00750

GAXE2601

H. STREAM

Along SLB

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SHF 693Z



INSRS:

WSP:

Tel:

Liability:

RMKS:

Trans-cab



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

201
CH

SHF 693Z - X; SCP 3858C - X

2011 pending O/S

31/1/18 @ 12.44pm

called OI, Mr. Mohammad Aidil. Confirm rear ended TP. Inform TP claim. Agreed to settle by ANDRE NCD issue

4/1/18

PV sent

10/1/18

File/loss to new lvan to close

RECEIVED 10 SEP 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

H. Stream 31/1/18

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

201

Jm

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

days Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

2782.00

Loss of Rental (LOR):

S\$

304.30

(3 days)

X \$101.46

Loss of Use (LOU):

S\$

(S - x - days)

Loss of Income (LOI):

S\$

150.00

(S50 x 3 days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

S\$

5.35

Medical:

S\$

Disbursement:

S\$

Legal Cost

S\$

(e.g. Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$750.00

Total:

S\$

3241.73

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

3241.73

Name 1:

Trans-cab Auto Services Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

ASS. REC. BY:

REF: ALA/

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

QD/TP/WS/TP RES/QD RES/EVA/INV/MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

02 days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: S/HF 693XYr Regn: 12, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Renaultc.c. 1995Colour: M. white/Red

A/C: Insured / Std / NI / NA

Sp. Reading: 436610

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VFIABL15AUC 281172Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Falken

Front

Rear

R/Bal. 2 mmR/Bal. 7 mmL/Bal. 2 mmL/Bal. 7 mmD.O.A. 15/1/18D.O.A. 16/1/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

17/1

File pass to Carline

7/18/18

41 Lmp @ 2600 C.A. final Tarline. (2 x 101.46 + 100)

(Rear 401.67 x 94%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

) \$ + RS \$

) Photos

) Others

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$) _____

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC3/ASM18001034/Kpa3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 17-01-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SCP 3858C	Veh. Inspected	SHF 693Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M00750	Excess (\$)	0.00	
Assign From		Assign Date	17/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	15/01/2018	Inspection Date	16/01/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHF693Z -

AAD1801-169

Not Authorised
6/1/2018 @ 2600.00

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHF693G - JHOW
 VF1ABL15AUC281172
 RENAULT
 LATITUDE
 15.01.2018
AXA

PART

LIST

1	1	BUMPER COVER REAR	\$	<i>Budlem</i> 1,108.46 ✓
2	1	BUMPER LOWER REAR	\$	<i>nd</i> 768.84 ✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47 X
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97 X
5	1	BUMEPR RETAINER RH REAR	\$	<i>Sn</i> 44.99 X
6	1	BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61 X
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97 X
8	1	BUMEPR RETAINER LH REAR	\$	<i>Sn</i> 44.99 X
9	1	BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61 X
10	1	BUMPER BEAM REAR	\$	<i>R</i> 777.52 ✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>nd</i> 225.95 ✓
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95 X
13	1	BOOT REAR	\$	<i>R</i> 2,872.68
14	1	BOOT FINISHER	\$	<i>Sn</i> 470.06
15	1	BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05
16	1	BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35
17	1	BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35
18	1	BOOT BADGE 'RENAULT'	\$	<i>nd</i> 225.36
19	1	BOOT BADGE	\$	<i>nd</i> 225.36
20	1	BOOT STRUT LH	\$	<i>Sn</i> 276.08
21	1	BOOT STRUT RH	\$	<i>Sn</i> 276.08
22	1	BOOT HINGE LH	\$	<i>R</i> 367.84
23	1	BOOT HINGE RH	\$	<i>R</i> 367.84
24	1	BOOT INNER TRIM	\$	<i>Sn</i> 586.45
25	1	BOOT SWITCH	\$	<i>Sn</i> 168.13
26	1	BOOT LOCK	\$	<i>R</i> 202.67
27	1	BOOT LOCK CATCH	\$	<i>R</i> 74.40
28	2	LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52
29	2	BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81
30	1	FENDER PANEL INNER TRIM REAR LH	\$	<i>Sn</i> 671.45
31	1	FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13
32	1	WHEELARCH REAR LH	\$	<i>Sn</i> 543.47
33	1	FENDER PANEL INNER TRIM REAR RH	\$	<i>Sn</i> 671.45
34	1	FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13

35	1	WHEELARCH REAR RH	\$	543.47	} X
36	1	TAILLAMP RH	\$	552.55	
37	1	TAILLAMP PANEL RH	\$	986.70	
38	1	TAILLAMP LH	\$	552.55	
39	1	TAILLAMP PANEL LH	\$	986.70	
40	1	OUTER PANEL REAR (End Panel)	\$	1,471.77	
41	1	OUTER PANEL REAR (End Panel)TRIM	\$	404.56	
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	2,189.88	
43	1	SPARE WHEEL PANEL TRIM	\$	612.21	
44	1	EXHAUST REAR	\$	7,489.05	} X
45	1	EXHAUST CAP REAR	\$	230.49	

TOTAL	\$	35,868.92
10%	\$	3,586.89
	\$	32,282.03

Specical Nett

1	1SET	PARKING AID	\$	700.00	X
2	1SET	REAR BUMPER CLIP	\$	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	33.00	✓
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	10.00	X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	20.00	X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	10.00	X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	66.00	✓
10	1	EXHAUST MOUNTING REAR	\$	17.82	} X
11	1SET	BOOT FINISHER CLIP	\$	24.20	
12	1	BOOT STICKER "Trans-cab"	\$	30.00	
13	1	BOOT STICKER "6555-3333"	\$	30.00	
14	1	BOOT INNER TRIM CLIP	\$	45.00	
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	35.00	
16	1SET	FENDER WHEELARCH REAR LH CLIP	\$	35.00	
17	1	FENDER INNER TRIM CLIP LH	\$	28.00	
18	1	FENDER INNER TRIM CLIP LH	\$	28.00	
19	1	TAILLAMP CLIP RH	\$	5.00	} X
20	1	TAILLAMP CLIP LH	\$	5.00	
21	2	REAR WINDSCREEN SELANT	\$	80.00	
22	1	WINDSCREEN MOULDING	\$	100.00	
23	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	
24	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	385.00	

25 1 SPARE TYRE \$ *330.00 X*

TOTAL	\$	2,225.02
TOTAL PARTS	\$	34,507.02

Putty And Spray Painting Of The Affected Portion. \$ 3,000.00 *2201*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same \$ 2,800.00 *201*

To Rust-Proofing Of The Affected Areas. \$ *170.00 X*

To reinstall rear bumper parking sensor. \$ 170.00 *601*

To transfer of bootlid fittings, attachments and perform water seepage test. \$ *170.00 X*

To repair and realign rear exhaust pipe. \$ *170.00 X*

To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe. \$ *170.00 X*

To transfer of rear end panel fittings, attachment and perform water seepage test. \$ *170.00 X*

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test. \$ *170.00 X*

To supply and re-do rear luggage floor panel insulation padding. \$ *380.00 X*

To transfer of rear fender fittings, attachment and perform water seepage test. \$ *380.00 X*

Towing Fees \$ *120.00 X*

To transfer of rear windscreen fittings and conduct water seepage test. \$ *170.00 X*

TRANS-CAB AUTO SERVICES PTE LTD
NO.2 ANG MO KIO ST63 SINGAPORE 569111
TEL NO. 6287 6666 FAX NO. 6257 1330
CO/GST REG NO. 201019626G
SHF693Z -

AAD1801-169

To check steering geometry and computer
wheel alignment

\$ *220.00* X

TOTAL	\$	8,260.00
Over All Total	\$	42,767.00

(PARTS BY PARTS)
Repair Days

10 Days

2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: S8M0075O

Our ref: CC3/ASM18001034/Kpa3

Date: 25.01.2018

The Motor Claims Department
M/s AXA INSURANCE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHF 693Z


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 16.01.2018 at the premises of M/s Trans-cab Auto Services Pte Ltd (Ang Mo Kio) and have the following to report:-

Workshop Estimate Amount	: S\$	42,767.07
Revised Estimate Amount	: S\$	2,600.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2.0 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser



<SEEK MANDATE> - S8M00750 [ACCIDENT INVOLVING SCP 3858C(OI) & SHF 693Z(TP) ON 15/01/2018]

Type

🔗 Question

Message

Liability: 100%. Insured rear-ended third party. Inform OI about third party claim. Agreed to settle and aware NCD issue. We seek your mandate up to \$3,243.87(all-in). IA with mandate had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong - 11 Aug 2018

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 4, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 11.08.2018

Survey Details:

Date of loss	15.01.2018
Date of appointment	16.01.2018
Date of survey	16.01.2018
Location of survey	TRANS-CAB AUTO SERVICES PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SHF 693Z
Make and Model	Renault Latitude (1995cc)
Date of registration	31.12.2014
Excess	
Market Value	
Parf/COE Rebate	
Nett Loss	

Repair details:

Initial Estimate	\$ 42,767.07
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 2,757.69
Check items (estimate)	NIL
Labour	\$ 480.00
Supplementary	NIL
Total	\$ 3,237.69
Lump Sum(if applicable)	\$ 2,600.00

Number of days for repair	<u>2</u>
---------------------------	----------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Date: 11.08.2018

Remarks:

--

Mandate:

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$ 2,782.00	
Loss of use	NIL	
Loss of rental	\$ 304.38	(3days x \$101.46)
Loss of income	\$ 150.00	(3days x \$50.00)
LTA/GIA search fees	\$ 7.49	
Others	NIL	
Proposed Total	\$ 3,243.87	



Re:<SEEK MANDATE> - S8M0075O [ACCIDENT INVOLVING SCP 3858C(OI) & SHF 693Z(TP) ON 15/01/2018]

Type

 Information

Message

Pls proceed

Reply

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Tuesday, 28 August 2018 9:49 AM
To: 'jasminetan@transcab.com.sg'; 'Ng Wai Yin'; 'Zhe Wei' (zhewei.kek@transcab.com.sg); claims@transcab.com.sg
Subject: Your Ref: AAD1801-169 (SHF 693Z) *Our Ref: CC3/ASM18001034/Kpa3 [ACCIDENT INVOLVING SCP 3858C(AXA) & SHF 693Z ON 15/01/2018]

Your Ref: **AAD1801-169 (SHF 693Z)**
Our Ref: CC3/ASM18001034/Kpa3

Without Prejudice

Dear Sirs/Madam,

ACCIDENT INVOLVING SCP 3858C(AXA) & SHF 693Z ON 15/01/2018

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 2,782.00
2. Loss of Rental (3days x \$101.46)	\$ 304.38
3. Loss of Income (3days x \$50.00)	\$ 150.00
4. LTA/ GIA Search Fee	\$ 5.35
TOTAL	<u>\$ 3,241.73</u>

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAUTO)

From: Jasmine Tan <jasminetan@transcab.com.sg>
Sent: Friday, 31 August 2018 8:05 AM
To: Hsiao Tong (LKKAUTO); 'Ng Wai Yin'; 'Zhe Wei'; claims@transcab.com.sg
Subject: RE: Your Ref: AAD1801-169 (SHF 693Z) *Our Ref: CC3/ASM18001034/Kpa3 [ACCIDENT INVOLVING SCP 3858C(AXA) & SHF 693Z ON 15/01/2018]

Without Prejudice

Dear Hsiao Tong

Please proceed to send us the DV.

Thank you
Best Regards
Jasmine Tan



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line : (65) 6287 6666 Fax Line: (65) 6257 1330
Direct Line : (65) 6603 1250
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Tuesday, 28 August 2018 9:49 AM
To: 'jasminetan@transcab.com.sg' <jasminetan@transcab.com.sg>; Ng Wai Yin <waiyin.ng@transcab.com.sg>; 'Zhe Wei' (zhewei.kek@transcab.com.sg) <zhewei.kek@transcab.com.sg>; claims@transcab.com.sg
Subject: Your Ref: AAD1801-169 (SHF 693Z) *Our Ref: CC3/ASM18001034/Kpa3 [ACCIDENT INVOLVING SCP 3858C(AXA) & SHF 693Z ON 15/01/2018]

Your Ref: **AAD1801-169 (SHF 693Z)**
Our Ref: CC3/ASM18001034/Kpa3

Without Prejudice

Dear Sirs/Madam,

ACCIDENT INVOLVING SCP 3858C(AXA) & SHF 693Z ON 15/01/2018

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 2,782.00
2. Loss of Rental (3days x \$101.46)	\$ 304.38
3. Loss of Income (3days x \$50.00)	\$ 150.00
4. LTA/ GIA Search Fee	\$ 5.35
TOTAL	<u>\$ 3,241.73</u>

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SCP 3858C (Insd veh)	Model:	RENAULT
	SHF 693Z (TP veh)		LATITUDE 2.0L DCI AUTO
Date of Accident:	15/01/2018		D/AB 4DR

Global Sum Settlement	:	[]	Yes	[X]	No	
Repair Estimate	:	\$				45,760.74
Final Repair Cost	:	\$				2,782.00
Loss of Token Sum	:	\$				150.00
						3 days at \$50.00 per day
Rental (if any)	:	\$				304.38
						3 days
LTA / GIA Search Fee	:	\$				5.35

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	3,241.73

Is Third Party Workshop GIA Registered?		[]	YES	[X]	NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability ____ 100 ____ (%)				
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: ____				
BOLA Liability: ____ (%)		Assessed Liability (*): ____ (%)				
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.						
Remarks PLEASE SEND THE CHEQUE PAYMENT TO TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111						

Payment Instruction: Payee's Breakdown		
1)	TRANS-CAB AUTO SERVICES PTE LTD	3,241.73

NUR SHAQILAH BTE ABDOL
WAHAB

03/10/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

Service Request Details

Claim	S8M00750			
Reference				
CC3/ASM18001034/Kpa3c2	Loss Date			
January 15, 2018	Request Date			
August 31, 2018	Due Date			
October 31, 2018	Vendor Name			
LKK AUTO CONSULTANTS PTE LTD (TP)	Type of Loss			
Third Party Vehicle Damage	Services			
Pending verification - Direct Settlement				
Additional Instructions				
Name	Type	Sub-Type	Author	Date Uploaded
Accident Statement	Reports & Statement	Morimen		

<< Service Request Details

Claim	S8M0075Q
Reference	
CC3/ASM18001034/Kpa3s2	Loss Date
January 15, 2018	Request Date
August 31, 2018	Due Date
October 31, 2018	Vendor Name
LKK AUTO CONSULTANTS PTE LTD (TP)	Type of Loss
Third Party Vehicle Damage	Services
Pending verification - Direct Settlement	

Auto

Actions

Next Step Finish the work Completed Work

More

Vehicle Information

Incident Vehicle Registration # SHF693Z

Make

Service Address

...

TPVD RENAULT

Model

LATITUDE-2.0 DCI AUTO DIAB Primary Contact/Insured

MOHAMAD AIDIL BIN MAON
BLK 522A, #17-07, 521522, Singapore
97591984

Claim Handler

ANG Richard

richard.ang@bs@axa.com.sg

Additional Instructions

Messages Invoices History Documents
Assessment Metrics Notes

CLONE

STATUS

APPROVED AMOUNT

ESTIMATED AMOUNT

VERSION DATE

CREATED USER

SHARE

User Portal

10/3/18 2:45 PM

2600

2600

Open

Share

Clone

Assessment Details

General & Workshop DetailsVehicle & Driver DetailsVehicle ConditionTaxes & RatioParts & LabourMiscellaneousSummary

Vehicle & Driver Details

Vehicle Registration#	SHF693Z	Purchase Date	mm/dd/yyyy
Registration State	SINGAPORE	Registration Date	12/31/2014
Mileage	436610	Age of Vehicle	3

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	FNOL INFORMATION	POST SURVEY INFORMATION
Manufacturing Year		2014		
Make	TPVD RENAULT	RENAULT	YEOW TECK SAN	
Model	LATITUDE 2.0 DCI AUTO D/AB	LATITUDE 2.0L DCI AUT	Date of Birth	December 31, 1899 mm/dd/yyyy
Type			Age	118
Type of Paint			Occupation	Unknown
Chassis No		VF1ABL15AUC281172	Education Qualification	Other
Engine No		M9R8839C002477	Driving Experience	0
Engine Capacity		1995 cc	Driver License #	

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Detailed Assessment						
Inspection Date *	01/16/2018		Condition of Vehicle at time of survey		Good	
Total Loss	Yes No		Steering (Serviceable)		Yes No	
Towing Charges	0		Footbrake (Serviceable)		Yes No	
Voluntary Excess	0		Handbrake (Serviceable)		Yes No	
Compulsory Excess	0		Engine Modification		Yes No	
Young/Inexperienced/Unlicensed Driver Excess	0		Pre-accident condition		Good	
Other Excess			Tyre Condition			
Age of Tyres			Spare wheel			
Front Tyre Size	215/60R16		Rear Tyre Size		215/60R16	
Front left side	FALKEN 8mm		Rear left side		FALKEN 7mm	
Front right side	FALKEN 8mm		Rear right side		FALKEN 7mm	

SERVICE REQUESTS MESSAGES CLAIMS

Assessment Details

General & Workshop Details					Vehicle & Driver Details		Vehicle Condition		Taxes & Ratio		Parts & Labour		Miscellaneous		Summary		Parts	
	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPRJ BTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE		
		1	1			BUMPER COVER REAR			Buckled	1108.46		10		997.61	Reviewing			
		2	1			BUMPER LOWER REAR			Dented	768.84		10		691.96	Reviewing			
		3	1			BUMPER BRACKET CTR REAR			Serviceable	0		10		0	Reviewing			
		4	1			BUMPER BRACKET SIDE RH REAR			Serviceable	0		10		0	Reviewing			
		5	1			BUMPER RETAINER RH REAR			Serviceable	0		10		0	Reviewing			
		6	1			BUMPER REFLECTOR RH			Serviceable	0		10		0	Reviewing			
		7	1			BUMPER BRACKET SIDE LH REAR			Serviceable	0		10		0	Reviewing			
		8	1			BUMPER RETAINER LH REAR			Serviceable	0		10		0	Reviewing			
		9	1			BUMPER REFLECTOR LH			Serviceable	0		10		0	Reviewing			
		10	1			BUMPER BEAM REAR			Bent	777.52		10		699.77	Reviewing			
		11	1			BUMPER BEAM BRACKET LH REAR			Damaged	225.96		10		203.36	Reviewing			

EDIT	SR NO	QUAN TITY	MATERIAL	SGE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPRJ BTRN%	DISC QUNTY%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	29	2			BOOT RUBBER PLUG			Serviceable	0		10		0	Reviewing	
	30	1			FENDER PANEL INNER TRIM REAR LH			Serviceable	0		10		0	Reviewing	
	31	1			FENDER PANEL REAR LH			Repair	0		10		0	Reviewing	
	32	1			WHEELARCH REAR LH			Serviceable	0		10		0	Reviewing	
	33	1			FENDER PANEL INNER TRIM REAR RH			Serviceable	0		10		0	Reviewing	
	34	1			FENDER PANEL REAR RH			Repair	0		10		0	Reviewing	
	35	1			WHEELARCH REAR RH			Serviceable	0		10		0	Reviewing	
	36	1			TAILLAMP RH			Serviceable	0		10		0	Reviewing	
	37	1			TAILLAMP PANEL RH			Repair	0		10		0	Reviewing	
	38	1			TAILLAMP LH			Serviceable	0		10		0	Reviewing	
	39	1			TAILLAMP PANEL LH			Repair	0		10		0	Reviewing	
	40	1			OUTER PANEL REAR (END PANEL)			Repair	0		10		0	Reviewing	
	41	1			OUTER PANEL REAR (END PANEL) TRIM			Serviceable	0		10		0	Reviewing	
	42	1			SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)			Repair	0		10		0	Reviewing	
	43	1			SPARE WHEEL PANEL TRIM			Serviceable	0		10		0	Reviewing	
	44	1			EXHAUST REAR			Repair	0		10		0	Reviewing	

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	13		TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	0	0	0	Reviewing		
	14		TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	0	0	0	Reviewing		

SERVICE REQUESTS MESSAGES CLAIMS

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR	Reviewing		2	
	2	SET PARKING AID	Reviewing	0	SERVICEABLE	
	3	SET REAR BUMPER CLIP	Reviewing	66	NECESSARY	
	4	SET BUMPER BRACKET CTR CLIP	Reviewing	33	NECESSARY	
	5	SET BUMPER BRACKET SIDE CLIP RH RR	Reviewing	0	NOT NECESSARY	
	6	SET BUMPER RETAINER RH CLIP RR	Reviewing	0	NOT NECESSARY	
	7	SET BUMPER BRACKET SIDE CLIP LH RR	Reviewing	0	NOT NECESSARY	
	8	SET BUMPER RETAINER CLIP LH RR	Reviewing	0	NOT NECESSARY	
	9	SET BUMPER LOWER REAR RIVET	Reviewing	0	NOT NECESSARY	

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	23	WINDSCREEN MOULDING	Reviewing	0	NOT NECESSARY	
	24	REAR WINDSCREEN INNER SPONGE SEAL	Reviewing	0	NOT NECESSARY	
	25	SPARE TYRE RIM (ROUE 7J 16H 2547)	Reviewing	0	SERVICEABLE	
	26	SPARE TYRE	Reviewing	0	SERVICEABLE	

SERVICE REQUESTS MESSAGES CLAIMS

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount

\$3,237.70

Claim Amount

\$3,237.70

CATEGORY	ESTIMATE	REVISED AMOUNT
Spare Parts	\$2,592.70	\$2,592.70
Labour	\$480.00	\$480.00
Miscellaneous	\$165.00	\$165.00

Submit for Review

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE

	1	Reviewing	2500			
FINAL LUMP SUM						