

15/5/2010

INS. CASE OWNER:

Belliana Lim

CC3/AXA130 01447/K2 #3

LKK:
IDAC:

ASSIGNMENT

Surveyor:

Kenneth

DOI:

21/1/13

Assg Date:

21/01/13

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJA 6778B

Claim No.:

C 0259268

Name of Insured:

YEE WAH KEDNG

Policy No.:

P1111186

Insured Tel No.:

-

HP:

9320 0088

Make / Model:

WERC-BENZ

Excess Sec II :S\$

-

D.O.A.:

08/01/13

Place of Accident:

269 DRIVEWAY TOH GUAN RD

Is driver the owner? (YES/NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES/NO ; TP GIA REPORT: YES/NO

Driver Tel No.:

(V/L: YES/NO) Insured Liability:

% Final ? Yes / No

SHC5406U



INSRS:

WSP: Trans-cab

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

FOR CSO ONLY:

Is driver the owner?

(YES/NO)

If NO, Driver Name / Age:

Driver's Own Vehicle Number: Insurance Company:

SHC 5406U - CC4/AIG 0702339/KCS DOA 18/10/07

SJA 6778B - X

8/2/13

called OI. at 9320 0088 not pick up.

8/09/13

called OI. spoke to Mr Yee. Informed about the claim. Confirmed the accident. OI said TP swerved into his lane after go over the hump. Coupled into his car. Vehicles were shifted after accident. but no photo, no evidence, no video nor witness.

OI said he did not see any fault in taxi. He will make a claim at C&C. Aware of WCD issue.

Letter sent out.

case handler - TP reported he got witness. Ask TP to do S/O. fire transfer to Aitchin

05/03/13

04/04/13

(Email) to Transcab in order to get the witness statement - 5/9/13 Wait for SD

FINAL SETTLEMENT		Date:	Confirm with	
Repair Cost:	S\$		Final Liability	50 % (Agreed / Assessed)
Loss of Rental:	S\$	(days)		BOLA S/N No.: 32
Loss of Use:	S\$	(\$ x days)		If NO or B 28, Ass. Lia:
Disbursement:	S\$			Submit W.P. Report
Total:	S\$		Global Sum: S\$	# 250

No response from TP workshop

04/10/13 file pass to typist to close.

COPY SENT
04/10/13

ASS. REC. BY:

REF:

AKA/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____ Trans Ceb

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record) _____

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 01 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHC 54084 Yr Regn: 11, 05Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy Crown C.C. 2986Colour White / Red A/C: Insured / Std / NI / NASp. Reading 920767 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: LX 912 - 0021359Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 175/80R14

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WESTLAKFront 2 mm Rear 2 mmR/Bal. 2 mm L/Bal. 2 mmL/Bal. 2 mm D.O.A. 8/1/13 D.O.I. 21/1/13Survey held at ✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

15/05/13 L/S \$500 Cred \$4003.02 / 497.1

16/5/13 L/S \$500 Confirmed Jammed (1 x 81.32 + 50)
KIV lia

Date/Time, File Pass to?

Date/Time, File Return to?

1) _____ 2) _____

3) _____ 4) _____

5) _____ 6) _____

Prel. Report

Final Report

TOTAL
LOSSKIV FOR
LOD

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

Jet Ting (Admin-B)

From: Tan Tiong Beng [tantiong.beng@axa.com.sg]
Sent: Saturday, 26 January, 2013 1:34 PM
To: admin-b@lkkauto.com
Cc: Belliana Lim
Subject: Direct Settlement / Trans-Cab Auto / C0259268 / OD SJA6778B / TP SHC5406U / 08.01.13 / EST \$4503.02 / LB
Attachments: Preliminary Advice.pdf; Estimated..pdf; SHC 5406U - - TP GIA REPORT..pdf; SJA6778B - 080113.pdf

Follow Up Flag: Follow up
Flag Status: Flagged

Categories: OI GIA.

Dear Belliana,

Pls input VTP & affect the NCD in AS400. Thank you.

From: Jet Ting (Admin-B) [mailto:admin-b@lkkauto.com]
Sent: Tuesday, 22 January, 2013 2:42 PM
To: Winnie Ho Ping Ping; Tan Tiong Beng; Kitty Teo Poh Guek
Cc: 'Jesslyn Soh'
Subject: Direct Settlement - Acc Invl SJA 6778B (OI) & SHC 5406U (TP) ON 08/01/2013 (LKK Ref : CC3/AXA13001447/Kv1f3)

Dear Sir/Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHC 5406U AT M/s Trans-Cab Auto Service.

Enclosed herewith a copy of TP's GIA report, estimated cost of repair and preliminary advise for your perusal.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Jesslyn and she can be contacted at DID: 6841 6051

Thanks & Regards,

Jet Ting

LKK Auto Consultants PL
DID: 6841 1972
FAX: 6741 4108

Jet Ting (Admin-B)

From: Jet Ting (Admin-B) [admin-b@lkkauto.com]
Sent: Tuesday, 22 January, 2013 2:42 PM
To: 'Winnie Ho Ping Ping'; 'Tan Tiong Beng'; 'Kitty Teo Poh Guek'
Cc: 'Jesslyn Soh'
Subject: Direct Settlement - Acc Invl SJA 6778B (OI) & SHC 5406U (TP) ON 08/01/2013 (LKK Ref : CC3/AXA13001447/Kv1f3)
Attachments: Preliminary Advice.pdf, Estimated..pdf, SHC 5406U - - TP GIA REPORT..pdf

Dear Sir/Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHC 5406U AT M/s Trans-Cab Auto Service.

Enclosed herewith a copy of TP's GIA report, estimated cost of repair and preliminary advise for your perusal.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Jesslyn and she can be contacted at DID: 6841 6051

Thanks & Regards,

Jet Ting

LKK Auto Consultants PL

DID: 6841 1972

FAX: 6741 4108



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To be advised
Our ref: CC3/AXA13001447/Kv1f3

Date: 22/01/2013

The Motor Claims Department
M/s AXA Insurance Singapore Pte Ltd

Dear Sir/Madam

PRELIMINARY ADVICE OF VEHICLE NO.

SHC 5406U


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on
21.01.13 at the premises of M/s TRANS-CAB and have the following to report:-

Workshop Estimate Amount	: S\$	4,503.02
Revised Estimate Amount	: S\$	653.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Front O/S Portion.



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 1 days

Yours faithfully,

Kenneth

Licensed Appraiser

Status of Driving Licence

Licence Number: S8414572F

Status of Driving Licence: Valid

Classes of Licence: 2B,3

Expiry Date: Valid for life unless revoked, suspended or disqualified.

The above information is accurate as at 28/01/2013 12:01 AM

[Print](#) [Back](#)

TRANS-CAB AUTO SERVICES PTE LTD
 NO.58 DEFU LANE 1 SINGAPORE 539498
 TEL NO.6287 6666 FAX NO.6281 1400
 CO/GST REG NO.201019626G
 SHC5406U -

LI DAN

Not Authorised
Lib B 500

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHC 5406U - LI DAN
 LXS12-00021359*
 TOYOTA
 CROWN TAXI
 08.01.2013
 AXA

PART			LIST	
1	1	Front Bumper Assembly	\$	<i>B/L/M</i> 417.40 ✓
2	1	Front Bumper Reinforcement / Beam	\$	<i>R</i> 269.35 X
3	1	Front Side Lamp RH	\$	<i>CM</i> 170.60 —
4	1	Front Headlamp RH	\$	<i>sn</i> 411.54 X
5	1	Front Support Panel Assy	\$	<i>R</i> 626.30 ✓
6	1	Front Fender RH	\$	<i>R</i> 732.83 X
			\$	2,628.02
			25% \$	657.01
TOTAL			\$	1,971.02

Specical Nett

1 Set	Front Bumper Fastener Clip	\$	<i>mu</i> 12.00 ✓
TOTAL		\$	12.00
TOTAL PARTS		\$	1,983.02

Panel Beating, Knocking And Straightening
 The Necessary Portion, Remove And
 Renewal Of Parts, Adjust And Realign The
 Same

\$ 1,000.00 *180*

To Rust-Proofing Of The Affected Areas.

\$ *mu* 200.00 X

To Check Electrical Lighting Concerned.

\$ 100.00 *20*

Putty And Spray Painting Of The Affected
 Portion.

\$ *mu* 720.00 X

TRANS-CAB AUTO SERVICES PTE LTD**LI DAN**

NO.58 DEFU LANE 1 SINGAPORE 539498

TEL NO.6287 6666 FAX NO.6281 1400

CO/GST REG NO.201019626G

SHC5406U -

*To Remove And Refit Interior Fittings,
Trimings, Garnish, Fittings And Other, To
Enable repair.*

\$

nn 250.00 X

*To Transfer Of Fender Fittings, Attachments
And Perform Water Seepage Test.*

\$

nn 150.00 X

Towing Fees.

\$

nn 100.00 X

TOTAL \$ 2,520.00

Over All Total \$ 4,503.02

Total Repair Days

*04 Days**1 day*

Ai Chin

From: Belliana Lim [belliana.lim@axa.com.sg]
Sent: Monday, 15 April, 2013 10:39 AM
To: Ai Chin
Subject: RE: Your ref: C0259268;Our ref: CC3/AXA13001447/Kef3

Follow Up Flag: Follow up
Flag Status: Flagged

Without Prejudice

Hi Ai Chin

We refer to your below e-mail.

Please proceed to offer based on 50:50 and please write to Insured first before confirming any settlement with TP.

Thank you.

Belliana Lim
Executive – Motor Claims
AXA Insurance Singapore Pte Ltd
8 Shenton Way, #27-01 AXA Tower, Singapore 068811
belliana.lim@axa.com.sg
DID: (65) 6880 4269 Fax: (65) 6880 4838
Website: www.axa.com.sg



redefining / insurance

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorised disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From 14 March 2011, AXA Insurance will be located at 8 Shenton Way, #27-01 Singapore 068811. Our Customer Service Centre will be located at #B1-01. All contact numbers remain unchanged.



Please consider the environment before printing this email

From: Ai Chin [<mailto:chaiac@lkkauto.com>]
Sent: Friday, April 12, 2013 7:43 PM
To: Belliana Lim
Subject: Your ref: C0259268;Our ref: CC3/AXA13001447/Kef3

Your ref: C0259268

Our ref: CC3/AXA13001447/Kef3

Dear Ms. Belliana Lim,

ACCIDENT INVOLVING SJA 6778B AND SHC 5406U ON 08 JANUARY 2013.

We refer to the above matter.

We have inspected TP vehicle at M/S **TRANSCAB AUTO SERVICES PTE LTD**. The estimate cost of repair is S\$ 4,503.02.

TP reported that he was travelling straight at Carpark Driveway between BLK 269-267A Toh Guan Road. There are two humps before the bend, so he slowed down and turn left. Suddenly vehicle B, SJA 6778B made a sharp turn from opposite direction and cut into his lane and collided onto his taxi's right front portion.

OI reported that he was driving along the driveway and car B, SHC 5406U went over the bump without slowing down, swerved into his lane and hit the right front portion of his car.

We called up to OI verified the accident happened, he mentioned that TP swerved into his lane and resulted the collision but no proof/evidence. Furthermore, he mentioned that he did not see any passenger in taxi.

However, we have received a copy of witness statement from TP workshop. See attachment. Based on BOLA 32, this case should be 50/50% liability.

Kindly let us have your instruction regarding this matter.

Thank You.

*Best Regards,
Ai Chin
LKK Auto Consultants Pte Ltd
Tel : 6841 2132
Fax : 6741 4108*



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AXA13001447/Kv1f3
AXA Claim No: C0259268

13/02/2013

YEE WAI KEONG

Block 270 Toh Guan Road
#12-105
Singapore 600270

Dear Sir/Madam,

ACCIDENT INVOLVING SJA 6778B & SHC 5406U ON 08/01/2013

We refer to the above accident where we are acting for AXA Insurance Singapore Pte Ltd (AXA) to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Kindly note that we have reviewed this matter and would like to advise that you and/or your authorized driver may not be absolved from blame for this accident.

If you have evidence/information to proof that we should not settle the third party claim, kindly let us have them in writing within the next 10 days i.e. by 23/02/2013, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Accordingly your No Claim Discount (NCD – if applicable) may not be preserved. However, if you are making a claim against third party and successful with 80% in your favor, our principal will re-instate your NCD.

Please call us if you have further queries.

Yours faithfully,

Zayer
Case Handler
DID: 6749 9635
FAX: 6741 4108
Email: zayyer@lkkauto.com

c.c. AXA Insurance Singapore Pte Ltd
(Motor Claims Dept)

STATEMENT OF A WITNESS TO AN ACCIDENT

NAME OF WITNESS : PEH THIAM BENG

NRIC/PASSPORT NO.: S0193922/2

ADDRESS : BLOCK 243 #04-641
JURONG EAST. S1.24 Spore 600243

TELEPHONE NO. : 4/p : 96938312

E-MAIL ADDRESS : _____

BRIEF FACTS : A motor accident has taken place on 8/1/2013 at about 12:17 pm


along/at junction /location of SEAVICE ROAD OF BLOCK 267A & BLK 269
TOH GUAN ROAD.

between vehicle SJA 6778B and vehicle SHE 5406U I am an eye-witness/passenger

in the taxi and I wish to recount its happening as follows :

As I was the passenger of taxi SHE 5406U
travelling to BLOCK 26A coffee-shop at 12.17 pm
today (8/1/2013). At turning point between
block 261A & 269, another car (SJA 6778B)
speeding at very high speed (about 60 to 70 km/hr)
came crossing into my taxi path and hit the
my front taxi front.

I affirmed the above statement true and correct.


Name : PEH THIAM BENG

IC: S0193922/2

Date : 8/1/2013

Thank You.

Best Regards,

Ai Chin

LKK Auto Consultants Pte Ltd

Tel : 6841 2132

Fax : 6741 4108

From: Belliana Lim [<mailto:belliana.lim@axa.com.sg>]

Sent: Monday, 27 May, 2013 2:22 PM

To: Ai Chin

Subject: RE: Your ref: C0259268;Our ref: CC3/AXA13001447/Kef3

Hi Ai Chin

We maintain our offer at 50% unless TP's witness agrees to sign SD then we will re-consider the matter.
Alternatively, since quantum is rather small, you can offer to TP based on global sum (around 60% liability maximum).

Thank you.

Belliana Lim

Executive – Motor Claims

AXA Insurance Singapore Pte Ltd

8 Shenton Way, #27-01 AXA Tower, Singapore 068811

belliana.lim@axa.com.sg

DID: (65) 6880 4269 Fax: (65) 6880 4838

Website: www.axa.com.sg



redefining / insurance

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorised disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

*From 14 March 2011, AXA Insurance will be located at 8 Shenton Way, #27-01 Singapore 068811.
Our Customer Service Centre will be located at #B1-01. All contact numbers remain unchanged.*



Please consider the environment before printing this email

From: Ai Chin [<mailto:chaiac@lkkauto.com>]

Sent: Thursday, May 16, 2013 4:42 PM

To: Belliana Lim

Subject: FW: Your ref: C0259268;Our ref: CC3/AXA13001447/Kef3

Dear Ms. Belliana Lim,

Before we seek instruction from you, we had sent out the letter to insured on 13 February 2013. However, no response from insured up to date. Enclosed the letter to insured for your perusal.

Furthermore, TP repairer do not agreed to settle of equal liability due to got the witness statement and cost of repair only \$ 500.

Kindly let us have your instruction please.

Thank You.

Best Regards,
Ai Chin
LKK Auto Consultants Pte Ltd
Tel : 6841 2132
Fax : 6741 4108

From: Belliana Lim [<mailto:belliana.lim@axa.com.sg>]
Sent: Monday, 15 April, 2013 10:39 AM
To: Ai Chin
Subject: RE: Your ref: C0259268;Our ref: CC3/AXA13001447/Kef3

Without Prejudice

Hi Ai Chin

We refer to your below e-mail.

Please proceed to offer based on 50:50 and please write to Insured first before confirming any settlement with TP.

Thank you.

Belliana Lim
Executive – Motor Claims
AXA Insurance Singapore Pte Ltd
8 Shenton Way, #27-01 AXA Tower, Singapore 068811
belliana.lim@axa.com.sg
DID: (65) 6680 4269 Fax: (65) 6880 4838
Website: www.axa.com.sg



This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorised disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From 14 March 2011, AXA Insurance will be located at 8 Shenton Way, #27-01 Singapore 068811. Our Customer Service Centre will be located at #B1-01. All contact numbers remain unchanged.

 Please consider the environment before printing this email

From: Ai Chin [<mailto:chaiac@lkkauto.com>]
Sent: Friday, April 12, 2013 7:43 PM
To: Belliana Lim
Subject: Your ref: C0259268;Our ref: CC3/AXA13001447/Kef3

Your ref: C0259268

Our ref: CC3/AXA13001447/Kef3

Dear Ms. Belliana Lim,

ACCIDENT INVOLVING SJA 6778B AND SHC 5406U ON 08 JANUARY 2013.

We refer to the above matter.

We have inspected TP vehicle at M/S **TRANSCAB AUTO SERVICES PTE LTD**. The estimate cost of repair is S\$ 4,503.02.

TP reported that he was travelling straight at Carpark Driveway between BLK 269-267A Toh Guan Road. There are two humps before the bend, so he slowed down and turn left. Suddenly vehicle B, SJA 6778B made a sharp turn from opposite direction and cut into his lane and collided onto his taxi's right front portion.

OI reported that he was driving along the driveway and car B, SHC 5406U went over the bump without slowing down, swerved into his lane and hit the right front portion of his car.

We called up to OI verified the accident happened, he mentioned that TP swerved into his lane and resulted the collision but no proof/evidence. Furthermore, he mentioned that he did not see any passenger in taxi.

However, we have received a copy of witness statement from TP workshop. See attachment. Based on BOLA 32, this case should be 50/50% liability.

Kindly let us have your instruction regarding this matter.

Thank You.

Best Regards,
Ai Chin
LKK Auto Consultants Pte Ltd
Tel : 6841 2132
Fax : 6741 4108

Ai Chin

From: Belliana Lim [belliana.lim@axa.com.sg]
Sent: Friday, 4 October, 2013 1:48 PM
To: Ai Chin
Subject: RE: Your ref: C0259268;Our ref: CC3/AXA13001447/Kef3

Dear Ai Chin

Noted, please send us your survey report and invoice.

Thanks.

Belliana Lim
Executive – Motor Claims
AXA Insurance Singapore Pte Ltd
8 Shenton Way, #27-01 AXA Tower, Singapore 068811
belliana.lim@axa.com.sg
DID: (65) 6880 4269 Fax: (65) 6880 4838
Website: www.axa.com.sg



redefining / insurance

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorised disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

*From 14 March 2011, AXA Insurance will be located at 8 Shenton Way, #27-01 Singapore 068811.
Our Customer Service Centre will be located at #B1-01. All contact numbers remain unchanged.*

Please consider the environment before printing this email

From: Ai Chin [mailto:chaiac@lkkauto.com]
Sent: Friday, October 04, 2013 11:48 AM
To: Belliana Lim
Subject: RE: Your ref: C0259268;Our ref: CC3/AXA13001447/Kef3

Your ref: C0259268

Dear Ms. Belliana Lim,

We refer to the below email.

Kindly be informed that TP repairer , M/s Trans-cab Auto Service Pte Ltd for, is not willing to accept our offer and mentioned that will produce the witness statement in SD form.
However during our several round table meetings with them, they are still unable to produce the document.

In view of above, we intend to close the file temporary. If there are any new development in future, please inform us and we will follow up if required.

For your approval please.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE SINGAPORE PTE LTD		Ref : CC3/AXA13001447/Keb3y	
8 SHENTON WAY #27-01 SINGAPORE 068811		Date : 07-10-2013	
ATTN: BELLIANA LIM		Code : AXA2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJA 6778B	Veh. Inspected	SHC 5406U
Policy No.	P1111186	Coverage (\$)	0.00
Claim No.	C0259268	Excess (\$)	0.00
Assign From		Assign Date	21/01/2013
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA CROWN	c.c	2986
Engine No.	HIDDEN	Year of Reg.	2005
Chassis No.	LXS120021359	Colour	WHITE / RED
Odometer	920767	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	175/80R14	WEST LAKE	8 mm
L/H Front Tyre	175/80R14	WEST LAKE	8 mm
R/H Rear Tyre	175/80R14	WEST LAKE	2 mm
L/H Rear Tyre	175/80R14	WEST LAKE	2 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	08/01/2013	Inspection Date	21/01/2013
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD 58 DEFU LANE 1 SINGAPORE 539498		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5406U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER ASSEMBLY (CONSISTENT)	BENT / CRACKED	417.40	417.40
1	FRONT BUMPER REINFORCEMENT/BEAM (CONSISTENT)	TO REPAIR SEE LABOUR	269.35	-
1	FRONT SIDE LAMP RH (CONSISTENT)	CRACKED	170.60	170.60
1	FRONT HEADLAMP RH (CONSISTENT)	SERVICEABLE	411.54	-
1	FRONT SUPPORT PANEL ASSY (CONSISTENT)	TO REPAIR SEE LABOUR	626.30	-
1	FRONT FENDER RH (CONSISTENT)	TO REPAIR SEE LABOUR	732.83	-
	LESS 25% DISCOUNT		-657.00	-147.00
			1,971.02	441.00
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER FASTENER CLIP (SN) (CONSISTENT)	NECESSARY	12.00	12.00
			12.00	12.00
	<u>LABOUR</u>			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT/BEAM, FRONT SUPPORT PANEL ASSY AND FRONT FENDER RH.		1,000.00	180.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	200.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		100.00	20.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	NOT NECESSARY	720.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	250.00	-
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	150.00	-
	TOWING FEES.	NOT NECESSARY	100.00	-
			2,520.00	200.00
	GRAND TOTAL		4,503.02	653.00

Report Ref No. CC3/AXA13001447/Keb3y



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			500.00
---	--	--	--------

Report Ref No. CC3/AXA13001447/Keb3y

KONG SENG CHEONG

KONG SENG CHEONG & CO. (FIRM) LTD.

KONG SENG CHEONG & CO. (FIRM) LTD.

KONG SENG CHEONG & CO. (FIRM) LTD.

KONG SENG CHEONG & CO. (FIRM) LTD.

KONG SENG CHEONG & CO. (FIRM) LTD.

KONG SENG CHEONG & CO. (FIRM) LTD.

KONG SENG CHEONG & CO. (FIRM) LTD.

KONG SENG CHEONG & CO. (FIRM) LTD.

KONG SENG CHEONG & CO. (FIRM) LTD.

KONG

KONG SENG CHEONG & CO. (FIRM) LTD.

KONG SENG

KONG SENG CHEONG & CO. (FIRM) LTD.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.