



Ethicarz Pte. Ltd. 56 Loyang Way, Singapore (508775) #04-04
Loyang Enterprise Building, Email: johnong@ethicarz.sg
Tel: 63844404, FAX: 63840444

VECHICLE NUM:	GBC2315P
MAKE & MODEL:	TOYOTA HIACE AUTO (2011)
MILEAGE:	
TYRE:	YOKOHAMA 195/R15C
CHASSIS NUM:	JTFHT02P30-0076792

ATTN:		
CHASSIS NUM:		0111102100 0070792
QTY	DESCRIPTION - PARTS	PRICE
1	FRONT WINDSCREEN MOULDING X NN	242.5
1	FRONT BONNET X Repair.	
1	FRONT BONNET LOGO (TOYOTA) / MC	68.3
2	FRONT BONNET HINGE (L+R) X NN	
1	FRONT BONNET LOCK X	
1	FRONT GRILLE / BR	483.2
1	FRONT GRILLE CLIPS / MC	10X10PCS
1	FRONT GRILLE INNER TOP R / RL	
1	FRONT GRILLE INNER BOTTOM R NN	
2	HEADLAMP CLIPS (L+R) LH - CRA, RH X NN	782.6X2PCS
2	HEADLAMP GARNISH (L+R) X NN	548.2X2PCS
2	HEADLAMP PANEL (L+R) X Repair	242.6X2PCS
1	FRONT BUMPER / RL	528.9
2	FRONT BUMPER CLIP / MC	10X10PCS
2	FRONT BUMPER RETAINER LH / RL, RH X NN	
2	FRONT BUMPER BRACKET X NN	342.8X2PCS
2	FRONT BUMPER AIR DUCT X NN	363.4X2PCS
1	FRONT BUMPER BEAM R / BT	198.6
1	FRONT BUMPER REINFORCMENT BAR X NN	382.1
1	FRONT BUMPER SPONGE X NN	
1	FRONT BUMPER FOG LAMP COVER (LH) R / RL	
10	FRONT BUMPER FOG LAMP COVER CLIP (LH) X NN	
1	FRONT BUMPER LOWER GRILLE TOP R / RL	
1	FRONT BUMPER LOWER GRILLE BOTTOM X NN	
1	FRONT QUARTER PANEL (LH) X NN	
1	FRONT DOOR (LH) X Repair.	
1	FRONT DOOR SIDE MIRROR ASSY (LH) X NN	
1	FRONT DOOR GLASS(LH) X	
1	FRONT DOOR GLASS RUBBER(LH) X	} NN
1	FRONT DOOR GLASS GARNISH (LH) X	
1	FRONT DOOR OPENER(LH) X	

1	FRONT DOOR LOCK (LH)	X	
1	FRONT DOOR BOARD(LH)	X	
1	FRONT DOOR BOARD CLIP (LH)	X	
1	FRONT DOOR REGULATOR (LH)	X	
1	FRONT DOOR POWER MOTOR(LH)	X	
1	FRONT DOOR CHECKER(LH)	X	
1	FRONT DOOR HINGE (UP + DOWN)	X	
1	FRONT DOOR WEATHER STRIP(LH)	X	
1	FRONT DOOR STEP GARNISH (LH)	- Cut	
10	FRONT DOOR STEP GARNISH CLIP (LH)	X	NN
1	FRONT SUPPORT PANEL	X	NN

QTY	DESCRIPTION - SPECIAL NETT	PRICE
1	FRONT WINDSCREEN SEALANT X NN	X 120
1	FRONT BONNET STICKER X / 4 ABC	100 400
1	FRONT DOOR STICKER (BIZ SAFE) - 4 ABC	60 250
1	FRONT DOOR STICKER (BRIGHTNESS SOLUTION) - ABC	15 80

QTY	DESCRIPTION - LABOUR	PRICE
1	TO RNR ACCIDENT AFFECTED FRONT	600 1800
1	TO PUTTY AND RESPRAY ACCIDENT AFFECTED FRONT	600 1700
1	TO RUST PROOF ACCIDENT AFFECTED FRONT	X 150
1	TO RNR FRONT WINDSCREEN	X 120
1	TO CHECK WIRING LAYOUT AND HEADLAMP FUNCTION	30 120
1	TO RNR FRONT DOOR MECHINISM	X NN 120

5 Days.

Insurance Repair

After repair.

Eno Riane - 8288 0282

18/1/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: