

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5185L
Ref. No : TAX/01/18/2091
Reg. Date : 01/11/2017
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS4
Name of Driver : MOHAMED RAMZAN BIN MOHD DALI
Type of Accident : HEAD TO SIDE
Date / Time of Accident : 16/01/2018 08:30:00 AM
Accident Reported Date / Time : 16/01/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024094122
Special Instruction to ARC, if any :
SKE1728X
Prepared Date : 16/01/2018 01:58:21 PM



40 days.

Guo Qiang - 82880282

Guo Qiang @ lkk auto. com

17/1/18.

part by pt.

before paint photos.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FUX03573209

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	676.00	0.00
Total Spray Painting Charges :	1,314.00	0.00
Total Material Charges :	5,663.68	5,663.68
Other Charges :	340.00	0.00
TOTAL :	7,993.68	0.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	5.00	0.00
Prepared / Adjusted By :		
Arc / Surveyor Sign Off Date :	16/01/2018 05:08:47 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 16/01/2018 05:08:47 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	676.00	0.00 <i>400</i>
Total Labour	676.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 <i>200</i>
TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00 <i>?</i>
TO REPSRAY FRONT HOOD	378.00	0.00 <i>200</i>
TO RESPRAY FRONT FENDER LH	378.00	0.00 <i>200</i>
Total Spray Painting & Panel Beating	1,314.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 <i>30</i>
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 <i>X</i>
TO REPLACE SUNDRY PARTS	100.00	0.00 <i>X</i>
TO WASH AND VACUUM	60.00	0.00 <i>X</i>
Total Other Costs	340.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
5211947962			COVER, FR BUMPER <i>CRA</i>	1	495.50	25.00	371.62	Replace	Replace	No
5212847906			COVER, FR BUMPER LH <i>Mis</i>	1	28.10	25.00	21.07	Replace	Replace	No
5310147080			GRILLE SUB-ASSY <i>De</i>	1	335.60	25.00	251.70	Replace	Replace	No
8118547691			UNIT, HEADLAMP, LH <i>CRA</i>	1	2,558.90	10.00	2,303.01	Replace	Replace	No
8122047020			LAMP ASSY, FOG, LH <i>Wt</i>	1	910.20	10.00	819.18	Replace	Replace	No
5211647050			SUPPORT, FR ? BUMPER LH	1	82.30	25.00	61.72	Replace	Replace	No
5321447050			SUPPORT, RADIATOR UPPER LH ?	1	76.70	25.00	57.52	Replace	Replace	No
1656337010			SEAL, RADIATOR TO LH ?	1	24.80	25.00	18.60	Replace	Replace	No
5320347901			SUPPORT S/A LH ?	1	237.00	25.00	177.75	Replace	Replace	No
5261147140			ABSORBER, FR BUMPER <i>De</i>	1	70.30	25.00	52.72	Replace	Replace	No
5330147110			HOOD SUB-ASSY <i>X Repair</i>	1	938.40	25.00	703.80	Replace	Replace	No
5341047130			HINGE ASSY, HOOD, RH <i>BT</i>	1	57.00	25.00	42.75	Replace	Replace	No
5342047130			HINGE ASSY, HOOD, LH <i>BT</i>	1	57.00	25.00	42.75	Replace	Replace	No
5380247100			FENDER SUB-ASSY, FR, LH <i>X Repair</i>	1	933.10	25.00	699.82	Replace	Replace	No
7537447140			EMBLEM, SIDE PANEL (HYBRID) <i>Mc</i>	1	52.90	25.00	39.67	Replace	Replace	No
TOTAL MATERIALS								5,663.72	5,663.68	
TOTAL MATERIALS(Discounted)								5,663.68	5,663.68	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									